[redacted]

11724604

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustai	**PRIMARY WORK LOCATION**	ACE COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - W SYSTEM MX - P	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 7		
TASK TYPE		**PRINTED DATE**	PM
EST HOURS		**PLANNED END**	
TASK NAME	3A - 9001 D11 U	LOWING - REPAIR - R	582-4496
TASK DESCRIPTION	RESTROOM OV 10AUG2022 094 10AUG2022 095 HEATER AND DR TASK	L ALREADY ON SITE M IS NOT OVERFLOW	ORKING ON A WATER ANCEL THIS WORK
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precau __ Digging Permit Required	ordination Required __Environmental Coordination Required	/COMM/_____ Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS WT 11724604

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS WT 11724604

ASSET DETAILS WT 11724604

WARRANTY DETAILS WT 11724604

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11724604

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11724604

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Primary Maintenance Reason Code **WT 11724604**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11724604**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11724604**

Additional Notes: **WT 11724604**

PROCEDURE STEP DETAILS **WT 11724604**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

K TASK 12008170

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**STATUS** / **RACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TI CO
RESPONSIBLE ORG	TINKER AFB - WA SYSTEM MX - PLU BMC		FUELS BOS-	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TIN		9000 - 63G		
TASK TYPE		**T CLASS**	Building Services	**PRINTED DATE**	Fe
EST HOURS		**D START**	10/06/2022 11:29:57	**PLANNED END**	10 11
TASK NAME	3A		E 215 - WT - INT PLUMB - SINK DRAIN IS LEAKING -		- 736-8784
TASK DESCRIPTION	SIN 120 12 13 AN		R, INCH AND A HALF STEEL P TRAP, HAS BAD WAS MARSHALL NSITE OTES:TAIL PIECE CAME APART-REPLACED WITH NEW NUT & SLIP WASHER. UP OR. NO PARTS FROM CEMAS.		DRIP
FOREMAN'S NOTES TO CRAFTSMEN	__	ed	__Multi-Shop Coordination Required __Environmental Coordination Required	__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required	

SERVICE REQUES **WT 12008170**

REQUEST	C	ED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJEC **WT 12008170**

ASSET DETAILS **WT 12008170**

WARRANTY DETAILS **WT 12008170**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 12008170**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ **WT 12008170**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Primary Maintenance Reason Code **WT 12008170**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12008170**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12008170**

Additional Notes: **WT 12008170**

PROCEDURE STEP DETAILS **WT 12008170**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

WORK TASK 139 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMA LOCAT**	PACE 1
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPO PERSO**	(NU)
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTE**	46 PM
EST HOURS		**PLANNED START**	05/23/2022 12:42:54	**PLANN**	
TASK NAME	3B - 9001 POST 2G39 - WT - INT PLUMB - TOILET CLOG - Repair -				049
TASK DESCRIPTION	TOILET BACKING UP INTO WOMENS RESTROOM				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required
__Multi-Shop Coordination Required
__ FD/SFS/COMM/_____ Coordination Required
__ Digging Permit Required
__Environmental Coordination Required
__Travel/Access Clearance Required

SERVICE REQUEST DETAILS — WT 11397851

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — WT 11397851

ASSET DETAILS — WT 11397851

WARRANTY DETAILS — WT 11397851

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11397851

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11397851**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Primary Maintenance Reason Code **WT 11397851**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11397851**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11397851**

Additional Notes: **WT 11397851**

PROCEDURE STEP DETAILS **WT 11397851**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

[redacted] 11604964

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**PRIMARY WORK LOCATION**	OSPACE 001
RESPONSIBLE ORG	TINKER AFB - WATE SYSTEM MX - PLUMB BMC	**RESPONSIBLE PERSON**	NU)
CUSTOMER ORG	TINKER AFB - 76 MX		
TASK TYPE	Corrective R	**PRINTED DATE**	3:09 PM
EST HOURS	0 P	**PLANNED END**	
TASK NAME	3B - 9001 POST 2J23 LUMB - LEAKING TOILET AND 2 OTHE PRESSURE - REPAIR 622-7846 - SR# 3015174		DUE TO LOW WATER
TASK DESCRIPTION	3B - B9001 2J23, there WRR b9001 post 2J23 and 2 other bag forcefully enough.		ecause they don't flush

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions R __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11604964

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE
3015174	07/08/2022 11:13:03	LESLIE BROWN	(405) 622-7846

FACILITY PROJECT DETAILS

WT 11604964

ASSET DETAILS

WT 11604964

WARRANTY DETAILS

WT 11604964

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11604964

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ WT 11604964

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

Primary Maintenance Reason Code **WT 11604964**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11604964**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11604964**

Additional Notes: **WT 11604964**

PROCEDURE STEP DETAILS **WT 11604964**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 148 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMA LOCA**	KER AEROSPACE MPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPO PERSO**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINT**	1, 2023, 2:38 PM
EST HOURS		**PLANNED START**	06/10/2022 13:32:20	**PLANN**	0/2022 2:20
TASK NAME	3B - 9001 & POST 2J23 - WT - INT PLUMB - STOP LEAK - Repair - [redacted] - 3230319				
TASK DESCRIPTION	AT POST 2J23 IN THE WOMENS RESTROOM THERE IS A TOILET ING FROM THE WALL, MEDIUM				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11483651

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11483651

ASSET DETAILS

WT 11483651

WARRANTY DETAILS

WT 11483651

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11483651

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11483651

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11483651**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11483651**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11483651**

Additional Notes: **WT 11483651**

PROCEDURE STEP DETAILS **WT 11483651**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

K TASK 11622069

WORK TASK DETAILS

TASK PRIORITY	3B - Med Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	ROSPACE 9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER SYSTEM BMC		D FUELS T - BOS-	**RESPONSIBLE PERSON**	(NU)
CUSTOMER ORG	TINKER		AC 9000 - 63G		
TASK TYPE	Corrective	**EST CLASS**	Other Plumbing Need	**E**	, 9:52 PM
EST HOURS	0	**NED START**	07/13/2022 01:00:00		
TASK NAME	3B - 9001 REPAIR -		- INT PLUMB - LOW WATER FL 622-7846 - SR# 3021632	LOGG	AGGED TOILETS -
TASK DESCRIPTION	3B - 9001 completely		w water flow, several clogged/bag	e the	nough water pressure to
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety P quired		__Multi-Shop Coo		__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required		__Environmental C	red	__ Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11622069

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3021632	07/12/2022 15:24:17	(405) 622-7846

FACILITY PROJECT DETAILS

WT 11622069

ASSET DETAILS

WT 11622069

WARRANTY DETAILS

WT 11622069

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11622069

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11622069

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11622069**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11622069**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11622069**

Additional Notes: **WT 11622069**

PROCEDURE STEP DETAILS **WT 11622069**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11435811

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS TRACKING STATUS**	Completed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	CES				
TASK TYPE		**REQUEST CLASS**	Leaks	**PRINTED DATE**	Mar 1, 2023, 1:58 PM
EST HOURS	[redacted]	**PLANNED START**	06/02/2022 01:00:00	**PLANNED END**	06/02/2022 01:00:00
TASK NAME	2 2T43 CUBE #86 - WT - HONEYWELL - F/U 11403540 - PIPE CHASE UNIT LEAKING - Repair - - 582-4496 - SR# 2953494				
TASK DESCRIPTION	2 2T43 CUBE #86 - WT - HONEYWELL -F/U 11403540- PIPE CHASE UNIT LEAKING - Repair - - 582-4496 ED AND MARKED HONEYWELLS FRO [redacted] TECHS. AND 75				
FOREMAN'S NOTES TO CRAFTSMEN	ns Required __Multi-Shop Co [redacted] __ FD/SFS/COMM/_____ Coordination Required equired __Environmental [redacted] ed __Travel/Access Clearance Required				

SERVICE REQU **WT 11435811**

REQUE	CREATED DATE/TIME	WORK PHONE
29534	06/01/2022 12:27:26	405-582-4496

FACILITY PROJ **WT 11435811**

ASSET DETAILS **WT 11435811**

WARRANTY DETAILS **WT 11435811**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11435811**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ **WT 11435811**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11435811**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11435811**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11435811**

Additional Notes: **WT 11435811**

PROCEDURE STEP DETAILS **WT 11435811**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11766930

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	PACE
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	FB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Clogs	**PRINTED DATE**	:09 PM
EST HOURS		**PLANNED START**	08/22/2022 07:09:14	**P** **D**	
TASK NAME	OST 2V40 WRR - WT - INT PLUMB - HANDICAP			ED	582-4196
TASK DESCRIPTION	p stall in the women's restroom is clogged and w ost 2V40				
FOREMAN'S NOTES TO CRAFTSMEN	ecautions Required ermit Required		__Multi-Shop Coor __Environmental C		__ FD/SFS/COMM/_____ Coordination Required ired __Travel/Access Clearance Required

SERVICE REQU **LS** **WT 11766930**

REQUE	CREATED DATE/TIME	WORK PHONE
30899	08/22/2022 07:06:54	405-582-4196

FACILITY PROJ **LS** **WT 11766930**

ASSET DETAILS **WT 11766930**

WARRANTY DETAILS **WT 11766930**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11766930**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ **WT 11766930**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11766930**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11766930**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11766930**

Additional Notes: **WT 11766930**

PROCEDURE STEP DETAILS **WT 11766930**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee

[redacted]

WORK TASK 11711175

WORK TASK DETAIL

TASK PRIORITY	3C -	**STATUS**	Rejected	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TIN UNI		USTOMER SERVICE	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TIN		CS		
TASK TYPE	Corr	**REQUEST CLASS**	Leaks	**TE**	Mar 1, 2023, 6:15 PM
EST HOURS	0	**PLANNED START**	08/08/2022 09:22:14	**D**	08/08/2022 09:22:14
TASK NAME	REJE		ACHINES BELONG TO M.A.D. - DEFAUL		mplate - Corrective Maintenance-Leaks
TASK DESCRIPTION	Ice m POC		king in the breakroom in Bldg 9001 post 2 405-582-4196		
FOREMAN'S NOTES TO CRAFTSMEN	__ Sa		tions Required	__Multi-Shop Coo	d __ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required			__Environmental	uired __Travel/Access Clearance Required

SERVICE REQUEST DETAILS WT 11711175

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3062108	08/08/2022 09:16:09	405-582-4196

FACILITY PROJECT DETAILS WT 11711175

ASSET DETAILS WT 11711175

WARRANTY DETAILS WT 11711175

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11711175

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11711175

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee

Primary Maintenance Reason Code **WT 11711175**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11711175**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11711175**

Additional Notes: **WT 11711175**

PROCEDURE STEP DETAILS **WT 11711175**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11977934

WORK TASK D					
TASK PRIORITY	ow Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINK ACE COM
		TRACKING STATUS			
RESPONSIBLE ORG	ER AFB - SPEC MX TM - TAC CTURES - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	ER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	ctive	**REQUEST CLASS**	Other Interior Need	**PRINTED DATE**	Mar M
EST HOURS		**PLANNED START**	10/01/2022 01:00:00	**PLANNED END**	10/0 01:0
TASK NAME	001 A22 foyer - WT - TAC STRUC - Check for leaks and repair as needed, replac g tiles 622-7846 - SR3161337				
TASK DESCRIPTION	001 A22 foyer - Check for leaks and repair as needed, replace stained ceiling tile 22.7846/323.0319				
FOREMAN'S NOTES TO CRAFTSMEN	afety Precautions Required		__Multi-Shop Coordination Required		M/__ n Req
	__ Digging Permit Required		__Environmental Coordination Required	__Tr	aranc red

SERVICE REQUEST DETAILS 1197

REQUEST ID	CREATED DATE/TIME	FULL NAME	PHO
3161337	09/30/2022 17:24:56	LESLIE BROWN	622-78

FACILITY PROJECT DETAILS W 1197

ASSET DETAILS W 11977

WARRANTY DETAILS WT 11977934

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11977934

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11977934

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11977934**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11977934**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11977934**

Additional Notes: **WT 11977934**

PROCEDURE STEP DETAILS **WT 11977934**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11775843

WORK TASK DE					
TASK PRIORITY	dium	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	AFB - WATER AND FUELS MX - PLUMB INT - BOS-			**RESPONSIBLE PERSON**	
CUSTOMER ORG	AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	ve	**REQUEST CLASS**	Leaks	**TE**	Mar 1, 2023, 6:37 PM
EST HOURS		**PLANNED START**	08/24/2022 01:00:00	**D**	08/24/2022 01:00:00
TASK NAME	1 A32 Facility Managers Office WRR - WT - INT P - 622-7846				coming from back of toilet/wal
TASK DESCRIPTION	1 A32 Facility Managers Office WRR - water leak				of toilet/wall
FOREMAN'S NOTES TO CRAFTSMEN	_ ty Precautions Required		__Multi-Shop Co		__ FD/SFS/COMM/_ Coordination Re
	__ Digging Permit Required		__Environmental		ired __Travel/Access Clearan d

SERVICE REQUEST DETAILS WT 117

REQUEST ID	CREATED DATE/TIME	WORK PH
3094725	08/23/2022 13:46:22	(405) 622-

FACILITY PROJECT DETAILS WT 117

ASSET DETAILS WT 117

WARRANTY DETAILS WT 11775843

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11775843

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11775843

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11775843**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11775843**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11775843**

Additional Notes: **WT 11775843**

PROCEDURE STEP DETAILS **WT 11775843**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TA	11413850

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STA**	
		TRACK STA	
PRIMARY WORK LOCATION	TINKER AEROSPACE COMPLEX-9001		
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC		
RESPONSIBLE PERSON			
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000		
TASK TYPE		**REQUEST CL**	vices
PRINTED DATE	Feb 28, 2023, 9:20 PM		
EST HOURS		**PLANNED STA**	
PLANNED END	05/26/2022 02:44:05		
TASK NAME	3C - 9001 POST A33 CMXG FACIL CEILING TILES - REPAIR - T5825 -		TRUC - CHECK FOR LEAKS & REPLACE STAINED/MISSING - 622-7846
TASK DESCRIPTION	CHECK FOR LEAKS, REPAIR AS N CMXG FACILITY MANAGER OFFIC		PLACE STAINED/MISSING CEILING TILES; LOCATION: A33 AIL
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	_	p Coordination Required
	__ FD/SFS/COMM/_____ Coordination Required		
	__ Digging Permit Required	__ Env	ental Coordination Required
	__ Travel/Access Clearance Required		

SERVICE REQUEST DETAILS — WT 11413850

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — WT 11413850

ASSET DETAILS — WT 11413850

WARRANTY DETAILS — WT 11413850

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11413850

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — WT 11413850

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11413850**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11413850**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11413850**

Additional Notes: **WT 11413850**

PROCEDURE STEP DETAILS **WT 11413850**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TA [redacted] 11413851

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STA TRACK STA**	
PRIMARY WORK LOCATION	TINKER AEROSPACE COMPLEX-9001		
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000		
TASK TYPE	**REQUEST CL** [redacted] vices	**PRINTED DATE**	Mar 1, 2023, 1:35 PM
EST HOURS	**PLANNED STA** [redacted]	**PLANNED END**	05/26/2022 02:46:55
TASK NAME	3C - 9001 POST A33 S CORNER O [redacted] TRUC - CHECK FOR LEAKS & REPLACE STAINED/MISSING CEILING TILES - REPAIR - T5826 - [redacted] - 622-7846		
TASK DESCRIPTION	CHECK FOR LEAKS, REPAIR AS N [redacted] D EPLACE STAINED/MISSING CEILING TILES; LOCATION: A33 SOUTH CORNER OFFICE - SENT V		

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required _ i- p Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __ Enviro ental Coordination Required __ Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11413851

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11413851

ASSET DETAILS

WT 11413851

WARRANTY DETAILS

WT 11413851

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11413851

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11413851

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11413851**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11413851**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11413851**

Additional Notes: **WT 11413851**

PROCEDURE STEP DETAILS **WT 11413851**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TA[redacted] 11413853

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**ST TRAC ST**	
PRIMARY WORK LOCATION	TINKER AEROSPACE COMPLEX-9001		
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TA STRUCTURES - BOS-BMC	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 900		
TASK TYPE	**REQUEST C** [redacted] vices	**PRINTED DATE**	Mar 1, 2023, 1:41 PM
EST HOURS	**PLANNED S** [redacted]	**PLANNED END**	05/26/2022 02:49:59
TASK NAME	3C - 9001 POST A33 CENTER AD[redacted] TRUC - CHECK FOR LEAKS & REPLACE STAINED/MISSING CEILING TILES - REPAIR - T5827 [redacted] - 622-7846		
TASK DESCRIPTION	CHECK FOR LEAKS, REPAIR AS [redacted] PLACE STAINED/MISSING CEILING TILES; LOCATION: A33 CENTER ADMIN AREA - SENT VI		
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	[redacted] p Coordination Required	__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required	__ En [redacted] ental Coordination Required	__ Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11413853

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11413853

ASSET DETAILS

WT 11413853

WARRANTY DETAILS

WT 11413853

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11413853

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11413853

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11413853**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11413853**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11413853**

Additional Notes: **WT 11413853**

PROCEDURE STEP DETAILS **WT 11413853**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11413843

WORK TASK D					
TASK PRIORITY	ain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	- SPEC MX TM - TAC S - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	- 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Feb 28, 2023, 9:18 PM
EST HOURS		**PLANNED START**	05/26/2022 02:33:30	**PLANNED END**	05/26/2022 02:33:30
TASK NAME	t A33, WRR NW - WT - Tac Struc - Check for leaks & replace stained / missing ceiling tile - repair - T5824 - 622-7846				
TASK DESCRIPTION	s, repair as needed. Replace stained / missing ceiling tile. Location A33, WRR NW corner of South Admin - il				

FOREMAN'S NOTES TO CRAFTSMEN

cautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS — WT 11413843

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — WT 11413843

ASSET DETAILS — WT 11413843

WARRANTY DETAILS — WT 11413843

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11413843

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11413843**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11413843**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11413843**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11413843**

Additional Notes: **WT 11413843**

PROCEDURE STEP DETAILS **WT 11413843**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK DETAILS

TASK PRIORITY	3A - Hig [redacted] osed		TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	TINKER [redacted] AND SYSTEM [redacted] AFT BOS-BM [redacted]		
CUSTOMER ORG	TINKER [redacted] TAC		
TASK TYPE	[redacted] uilding Services	**P** [redacted]	Feb 28, 2023, 8:20 PM
EST HOURS	[redacted] /12/2022 :32:40	**P** [redacted]	09/12/2022 16:32:40
TASK NAME	3A - 900 [redacted] s A34 [redacted] ed water line leaking [redacted] 23-0072		
TASK DESCRIPTION	9001 S A [redacted] een [redacted] 35, old cafeteria ent [redacted] ater line leaking, trying to contain Notified [redacted] and Downey es was sh [redacted] ual water was leaking out. Work being done by Contractor.		
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety rec Require	__Multi-Shop Coordination Required	__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required	__Environmental Coordination Required	__Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11866374

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11866374

ASSET DETAILS

WT 11866374

WARRANTY DETAILS

WT 11866374

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11866374

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11866374

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11866374**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11866374**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11866374**

Additional Notes: **WT 11866374**

PROCEDURE STEP DETAILS **WT 11866374**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11868479

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS** / **TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	R CES				
TASK TYPE	ti	**REQUEST CLASS**	General Repairs	**PRINTED DATE**	Mar 1, 2023, 8:44 PM
EST HOURS	[redacted]	**PLANNED START**	09/13/2022 07:35:36	**PLANNED END**	09/13/2022 07:35:36
TASK NAME	- WT - TAC HVAC - F/U 11866374 CHECK FOR WATER LEAK TO DETERMINE IF HVAC ISSUE - - 582-4496				
TASK DESCRIPTION	WT- TAC HVAC- F/U 11866374 CHECK FOR WATER LEAK TO DETERMINE IF HVAC ISSUE - -582-4496				
FOREMAN'S NOTES TO CRAFTSMEN	ns Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required equired __Environmental Coordination Required __Travel/Access Clearance Required				

SERVICE REQU — **WT 11868479**

REQUE	CREATED DATE/TIME	FULL NAME	WORK PHONE
3128	09/13/2022 07:33:49	RACHEL STRAWN	405-582-4496

FACILITY PROJ — **WT 11868479**

ASSET DETAILS — **WT 11868479**

WARRANTY DET — **WT 11868479**

ID	AL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11868479**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11868479**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11868479**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11868479**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11868479**

Additional Notes: **WT 11868479**

PROCEDURE STEP DETAILS **WT 11868479**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WO K K **871631**

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**S** Close **G** **S**	**ARY WO ATION** SPACE 1
RESPONSIBLE ORG	TINKER AFB - WATER SYSTEM MX - PLUMB BMC		**ONSIBLE ON**
CUSTOMER ORG	TINKER AFB - 76 M		
TASK TYPE			**ED DAT** 46 PM
EST HOURS			**NED END**
TASK NAME	CO - 3A - 9001 POS		**ER LEAK** 622-7846
TASK DESCRIPTION	S ADMIN AREA BE NOTES FROM 118 Contractor. THDR STATES LE CONTAIN AFTER PLEASE CONTAC 13SEP2022 1213 - 13SEP2022 1230 - 13SEP2022 1504 - RETURNING IN TH		NTRANC & residual a out. Work being done by OCCUPANT PUT DOWN 55 GAL TRASH CAN TO UT DOWN OVERFLOWED & MADE A MESS. N SITE VE OFF. GOT PARTS TO REPAIR. CARRY OVER, STOR. 2.5 HOURS LABOR
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautio __ Digging Permit R d		n Required __ FD/SFS/COMM/_____ Coordination Required ation Required __ Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11871631

REQUEST ID	EATED DA	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11871631

ASSET DETAILS

WT 11871631

WARRANTY DETAILS

WT 11871631

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11871631

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ **WT 11871631**

Primary Maintenance Reason Code **WT 11871631**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11871631**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11871631**

Additional Notes: **WT 11871631**

PROCEDURE STEP DETAILS **WT 11871631**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11810600

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER A COMPLE
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	Air Force Materiel Command				
TASK TYPE	Corrective	**REQUEST CLASS**	General Repairs	**E**	Mar 1, 202
EST HOURS	0	**PLANNED START**	08/31/2022 07:35:12	**0**	08/31/202 07:35:12
TASK NAME	3B - 9001 POSTS A46-A47 - WT - TAC STRUC - LEAK FRO			KS LIKE OIL -	736-5233
TASK DESCRIPTION	Oil leaking from the ceiling between posts A46-A47				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coor __Environmental C	__ FD/ Coordination R ired __Travel/Access Clear	ed Required

SERVICE REQUEST DETAILS

WT 1 00

REQUEST ID	CREATED DATE/TIME	WORK P E
3109346	08/31/2022 07:33:08	405-736

FACILITY PROJECT DETAILS

WT 1 00

ASSET DETAILS

WT 11 00

WARRANTY DETAILS

WT 11810600

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11810600

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11810600

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11810600**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11810600**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11810600**

Additional Notes: **WT 11810600**

PROCEDURE STEP DETAILS **WT 11810600**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11843564

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	72 CES				
TASK TYPE		**REQUEST CLASS**	General Repairs		Mar 1, 2023, 8:37 PM
EST HOURS	[redacted]	**PLANNED START**	09/08/2022 08:49:25	[redacted]	09/08/2022 08:49:25
TASK NAME		S A46-A47 - WT - TAC HVAC - ASSIST TA - 736-5233			EAK FROM CEILING, LOOKS LIKE OIL -
TASK DESCRIPTION		S A46-A47 - WT - TAC HVAC - ASSIST TA - 736-5233			EAK FROM CEILING, LOOKS LIKE OIL -
FOREMAN'S NOTES TO CRAFTSMEN		utions Required it Required	__Multi-Shop Coo __Environmental		__ FD/SFS/COMM/_____ Coordination Required ed __Travel/Access Clearance Required

SERVICE REQU — **WT 11843564**

REQU	CREATED DATE/TIME	WORK PHONE
3121	09/08/2022 08:47:59	405-582-4496

FACILITY PRO — **WT 11843564**

ASSET DETAIL — **WT 11843564**

WARRANTY DE — **WT 11843564**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11843564**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11843564**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11843564**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11843564**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11843564**

Additional Notes: **WT 11843564**

PROCEDURE STEP DETAILS **WT 11843564**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

RK TASK 11844625

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SP HVAC - BOS-BMC		TM - TAC	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER A				
TASK TYPE	Correctiv	**EST CLASS**	General Repairs		Mar 1, 2023, 8:40 PM
EST HOURS	0	**NED START**	09/08/2022 10:29:57		09/08/2022 10:29:57
TASK NAME	3B - 900 LIKE OIL		- WT - TAC HVAC - ASSIST - 736-5233		ITH LEAK FROM CEILING, LOOKS
TASK DESCRIPTION	3B - 900 LIKE OIL		- WT - TAC HVAC - ASSIST - 736-5233		ITH LEAK FROM CEILING, LOOKS
FOREMAN'S NOTES TO CRAFTSMEN	__ Safet	uired	__Multi-Shop C		__ FD/SFS/COMM/_____ Coordination Required
	__ Diggi	d	__Environmenta	d	__Travel/Access Clearance Required

SERVICE REQUEST DE WT 11844625

REQUEST I	ATED DATE/TIME	WORK PHONE
312160	08/2022 10:28:58	405-582-4496

FACILITY PROJECT DE WT 11844625

ASSET DETAILS WT 11844625

WARRANTY DETAILS WT 11844625

ID	EAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11844625

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11844625

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11844625**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11844625**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11844625**

Additional Notes: **WT 11844625**

PROCEDURE STEP DETAILS **WT 11844625**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11656146

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AER COMPLEX-9
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 72 CS				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks	**E**	Mar 1, 2023,
EST HOURS	0	**PLANNED START**	07/21/2022 10:19:07	**D**	07/21/2022 10:19:07
TASK NAME	3B- 9001 Post AA40 - WT - TAC HVAC - air conditioner is le			reakroom - repair -	582-4196
TASK DESCRIPTION	air conditioner is leaking in outside breakroom Bldg 9001 Po				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coor		__ FD/SFS / Coordination R ___ ed
	__ Digging Permit Required		__Environmental C	ired	__Travel/Access Cleara Required

SERVICE REQUEST DETAILS

WT 11 46

REQUEST ID	CREATED DATE/TIME	WORK PH E
3038611	07/21/2022 09:57:35	405-582-

FACILITY PROJECT DETAILS

WT 11 46

ASSET DETAILS

WT 116 46

WARRANTY DETAILS

WT 11656146

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11656146

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11656146

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11656146**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11656146**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11656146**

Additional Notes: **WT 11656146**

PROCEDURE STEP DETAILS **WT 11656146**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 191252

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY W LOCATION**	AEROSPACE X-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC			**RESPONSIE PERSON**	
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE	Corrective	**REQUEST CLASS**	General Repairs		
EST HOURS	0	**PLANNED START**	09/20/2022 09:43:43		
TASK NAME	3C - 9001 AA48 - WT- TAC STRUC - REPAIR MULTIPLE				96
TASK DESCRIPTION	3C - 9001 AA48 - WT- TAC STRUCTURES- REPAIR MUL				82-4496
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Co		M/_____ Required
	__ Digging Permit Required		__Environmental		arance Required

SERVICE REQUEST DETAILS

11912529

REQUEST ID	CREATED DATE/TIME	PHONE
3141565	09/20/2022 09:42:41	82-4496

FACILITY PROJECT DETAILS

11912529

ASSET DETAILS

11912529

WARRANTY DETAILS

WT 11912529

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11912529

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11912529

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11912529**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11912529**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11912529**

Additional Notes: **WT 11912529**

PROCEDURE STEP DETAILS **WT 11912529**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1818 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS** / **TRACKING STATUS**	Closed	**PRIMAR... LOCATI...**	AEROSPACE X-9001
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPON... PERSON...**	
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE	Corrective	**REQUEST CLASS**	General Repairs		023, 6:58 PM
EST HOURS	0	**PLANNED START**	09/01/2022 08:10:35		22
TASK NAME	3C - 9001 ASH 52 - WT - TAC HVAC - REPAIR CONDEN				N - 582-4496
TASK DESCRIPTION	3C- 9001 ASH 52- WT- TAC HVAC- REPAIR CONDENSA				582-4496
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Co __Environmental		FD/SFS/COMM/_____ Coordination Required vel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11818595

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3112055	09/01/2022 08:08:10	405-582-4496

FACILITY PROJECT DETAILS

WT 11818595

ASSET DETAILS

WT 11818595

WARRANTY DETAILS

WT 11818595

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11818595

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11818595

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11818595**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11818595**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11818595**

Additional Notes: **WT 11818595**

PROCEDURE STEP DETAILS **WT 11818595**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11555350

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC CONTROLS - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE	Corrective	**REQUEST C**	airs		Mar 1, 2023, 2:44 PM
EST HOURS	0	**PLANNED S**	[redacted]		06/28/2022 01:00:00
TASK NAME	3B- 9001 ASH HOUSE 211 - WT CONDENSATE LEAK - REPAIR -	AD 58			ASH HOUSE 211 TO PREVENT
TASK DESCRIPTION	3B- 9001 ASH HOUSE 211 - WT CONDENSATE LEAK - REPAIR -	D 5			ASH HOUSE 211 TO PREVENT
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Require	C ta		d	__ FD/SFS/COMM/_____ Coordination Required __ Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11555350

REQUEST ID	CREATED D	WORK PHONE
2996858	6/27/2022	405-582-4496

FACILITY PROJECT DETAILS

WT 11555350

ASSET DETAILS

WT 11555350

[redacted]

WARRANTY DETAILS

WT 11555350

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11555350

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11555350

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11555350**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11555350**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11555350**

Additional Notes: **WT 11555350**

PROCEDURE STEP DETAILS **WT 11555350**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11843031

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS** / **TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER A COMPLEX
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	FB - 72 CES				
TASK TYPE		**REQUEST CLASS**	General Repairs		Mar 1, 202
EST HOURS		**PLANNED START**	09/08/2022 07:37:39		09/08/202 07:37:39
TASK NAME	SH 73 - WT - TAC HVAC - WATER LEAKING				INTO BLDG -
TASK DESCRIPTION	SH 73-WT-TAC HVAC-WATER LEAKING FR 82-4496				BUILDING
FOREMAN'S NOTES TO CRAFTSMEN	recautions Required Permit Required		__Multi-Shop C __Environmenta		_ FD C d __Travel/

SERVICE REQU ILS 1

REQU	CREATED DATE/TIME	P
3120	09/08/2022 07:36:38	82

FACILITY PRO ILS 1

ASSET DETAIL 1

WARRANTY DE WT 11843031

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11843031

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11843031

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11843031**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11843031**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11843031**

Additional Notes: **WT 11843031**

PROCEDURE STEP DETAILS **WT 11843031**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11752944

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WO LOCATION**	ACE
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBL PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	HVAC Service		PM
EST HOURS	0	**PLANNED START**	08/17/2022 08:21:24		
TASK NAME	3B - 9001 ASH 203 - WT - TAC HVAC - CLEAN CLOGGE				734-2328
TASK DESCRIPTION	3B - 9001 ASH 203 - WT - TACHVAC - CLEAN CLOGGED ORIGINAL WT 11659195 17AUG22 AVW FLOW LOW, ST BE CLOGGED				OIL APPEARS TO
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Co		MM/_____ ion Required
	__ Digging Permit Required		__Environmental		learance Required

SERVICE REQUEST DETAILS

T 11752944

REQUEST ID	CREATED DATE/TIME	RK PHONE
3082778	08/17/2022 08:19:09	4 5-734-2328

FACILITY PROJECT DETAILS

T 11752944

ASSET DETAILS

WT 11752944

WARRANTY DETAILS

WT 11752944

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11752944

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11752944

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11752944**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11752944**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11752944**

Additional Notes: **WT 11752944**

PROCEDURE STEP DETAILS **WT 11752944**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11785669

WORK TASK D

TASK PRIORITY	**STATUS** Completed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
	TRACKING STATUS		
RESPONSIBLE ORG	MX TM - TAC BMC	**RESPONSIBLE PERSON**	
CUSTOMER ORG	ES		
TASK TYPE	**REQUEST CLASS** General Repairs		Mar 1, 2023, 6:41 PM
EST HOURS	**PLANNED START** 08/26/2022 01:00:00		11/22/2022 12:00:00
TASK NAME	- TAC CONTROLS - HOT WATER P 582-4496		KING COORDINATION WITH 11785684 -
TASK DESCRIPTION	AC HVAC CONTROLS- HOT WATE		EAKING- RACHEL STRAWN-582-4496
FOREMAN'S NOTES TO CRAFTSMEN	ns Required __Multi-Shop C __ Digging Permit Required __Environmenta		__ FD/SFS/COMM/_____ Coordination Required ed __Travel/Access Clearance Required

[redacted]

SERVICE REQUEST DETAILS — WT 11785669

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3099947	08/25/2022 13:15:47	405-582-4496

FACILITY PROJECT DETAILS — WT 11785669

ASSET DETAILS — WT 11785669

WARRANTY DETAILS — WT 11785669

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11785669

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11785669**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11785669**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11785669**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11785669**

Additional Notes: **WT 11785669**

PROCEDURE STEP DETAILS **WT 11785669**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11785684

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS** / **TRACKING STATUS**	Completed / Materiel Required	**PRIMARY WOR LOCATION**	OS 001
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE	Corrective	**REQUEST CLASS**	General Repair		6:4
EST HOURS	0	**PLANNED START**	08/26/2022 01:00:00		
TASK NAME	3C - 9001 B51 - WT - TAC HVAC - (SEALS 09-07/10-25 - 582-4496				NG
TASK DESCRIPTION	3C-9001 B51- WT- TAC HVAC- HOT WATER PUMP #				-58
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop C __Environmen		FS/ din ess

SERVICE REQUEST DETAILS

REQUEST ID	CREATED DATE/TIME	W
3099950	08/25/2022 13:16:51	40

FACILITY PROJECT DETAILS

W

ASSET DETAILS

WT 11785684

WARRANTY DETAILS

WT 11785684

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11785684

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11785684

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11785684**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11785684**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11785684**

Additional Notes: **WT 11785684**

PROCEDURE STEP DETAILS **WT 11785684**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K 11381498

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain osed	**PRIMARY WORK LOCATION**	TINKER AEROSP COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - W SYSTEM MX - P BMC	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76		
TASK TYPE		**PRINTED DATE**	Mar 1, 2023, 9:43 P
EST HOURS	22	**PLANNED END**	05/18/2022 15:13:23
TASK NAME	3A - 9001 POST - TOILET OVERFLOWED & CLOGGED - Repair -		
TASK DESCRIPTION	3A - 9001 KC46 M 18MAY2022 1526 18MAY2022 1530 18MAY2022 1600 UP WATER; TOILET WAS NOT CLOGGED ONCE I A FLUSHED ALL TO AKE SURE NOTHING WAS CLOGGED; CHARGE .5H COMPLETE.		
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precaut hop Coordination Required __ FD/SFS/COMM Coordination __ Digging Permit nmental Coordination Required __ Travel/Access Clea d		

SERVICE REQUEST DETAILS

WT 1

REQUEST ID	/T E	FULL NAME	WORK

FACILITY PROJECT DETAILS

WT 1

ASSET DETAILS

WT 1

WARRANTY DETAILS

WT 11381498

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11381498

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ WT 11381498

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11381498**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11381498**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11381498**

Additional Notes: **WT 11381498**

PROCEDURE STEP DETAILS **WT 11381498**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11384047

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	E
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks	E	M
EST HOURS	0	**PLANNED START**	05/19/2022 08:45:26		
TASK NAME	3B - 9001 POST B55 - WT - TAC PIPE - WATER LEAK - SR#2934794 - REF#T5879				
TASK DESCRIPTION	9001 Chill Water Leak. Post B55. Buckets containing wate PLUMBERS WENT OUT TO VERIFY THAT IT IS THE CI				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Co __Environmenta		

SERVICE REQUEST DETAILS

WT 11384047

REQUEST ID	CREATED DATE/TIME	RK PHONE
2934794	05/19/2022 08:43:55	5-582-4496

FACILITY PROJECT DETAILS

WT 11384047

ASSET DETAILS

WT 11384047

WARRANTY DETAILS

WT 11384047

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11384047

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11384047

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11384047**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11384047**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11384047**

Additional Notes: **WT 11384047**

PROCEDURE STEP DETAILS **WT 11384047**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1373189

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	SPACE 01
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	HVAC Service	**ED DATE**	9:02 PM
EST HOURS		**PLANNED START**	05/17/2022 09:52:59	**ED END**	
TASK NAME	3B - 9001 POST BB23 - WT - TAC HVAC - ASH HOUSE			**REPAIR -**	323-0319
TASK DESCRIPTION	Ongoing water leak coming from what we think is either A just SW o B23. Buckets and pigmats are catching the water. Request that techs conta to discuss viosu work orders K6449, K6785., & K7204. - SENT VIA EMAIL				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop C equired		__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required		__Environmenta n Required		__Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11373189

REQUEST ID	CREATED DATE/TIME	AME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11373189

ASSET DETAILS

WT 11373189

WARRANTY DETAILS

WT 11373189

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11373189

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11373189

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11373189**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11373189**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11373189**

Additional Notes: **WT 11373189**

PROCEDURE STEP DETAILS **WT 11373189**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1372970

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WO LOCATION**	SPACE 01
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Roof Leak		9:00 PM
EST HOURS		**PLANNED START**	05/17/2022 09:18:13		
TASK NAME	3B - 9001 POST BB24 - WT - TAC HVAC - ASH HOUSE 76 L				582-4105
TASK DESCRIPTION	LEAK DIRECTLY UNDER ASH HOUSE 76 NEAR POST BB2				ENT VIA EMAIL

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coord _ FS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Co Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11372970

REQUEST ID	CREATED DATE/TIME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11372970

ASSET DETAILS

WT 11372970

WARRANTY DETAILS

WT 11372970

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11372970

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11372970

Primary Maintenance Reason Code

WT 11372970

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

NOTES TO R&O ON ASSETS & LOCATION			WT 11372970
ASSET STATUS	**GEOSPATIAL LOCATION**		
__SMS Update Required (Record Comments in Asset Notes)	___ Point	___ Line	___ Area
__Asset Condition Changed __ Removed Asset	Primary Latitude: _____		Secondary Lat: _____
__Asset Replaced/Added	Primary Longitude: _____		Secondary Lon: _____

Asset Notes:	WT 11372970

Additional Notes:	WT 11372970

PROCEDURE STEP DETAILS			WT 11372970
STEP	**PROCEDURE TEXT**	**DURATION**	**PROCEDURE ID**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1373324

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WO LOCATION**	SPACE 01
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Roof Leak	**PRINTED DAT**	9:04 PM
EST HOURS		**PLANNED START**	05/17/2022 10:10:58	**PLANNED END**	
TASK NAME	3B - 9001 POST BB26 - WT - TAC HVAC - ASH HOUSE 77 LEAK- REPAIR -				582-4105
TASK DESCRIPTION	ASH HOUSE 77 LEAK NEAR POST BB26, WATER IS DRIPPING DIRECTLY				TING MATERIAL IN THE
	REACT STORAGE CAGE - SENT VIA EMAIL				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required _ FS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11373324

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11373324

ASSET DETAILS

WT 11373324

WARRANTY DETAILS

WT 11373324

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11373324

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11373324

Primary Maintenance Reason Code

WT 11373324

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

NOTES TO R&O ON ASSETS & LOCATION			WT 11373324
ASSET STATUS	**GEOSPATIAL LOCATION**		
__SMS Update Required (Record Comments in Asset Notes)	___ Point	___ Line	___ Area
__Asset Condition Changed __ Removed Asset	Primary Latitude: _____		Secondary Lat: _____
__Asset Replaced/Added	Primary Longitude: _____		Secondary Lon: _____

Asset Notes:	WT 11373324

Additional Notes:	WT 11373324

PROCEDURE STEP DETAILS			WT 11373324
STEP	**PROCEDURE TEXT**	**DURATION**	**PROCEDURE ID**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 2

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Clo
		TRACKING STATUS	
		PRI LOC	K TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	**RES PER**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G		
TASK TYPE	Corrective	**REQUEST CLASS**	Lea
			Mar 1, 2023, 9:06 PM
EST HOURS	0	**PLANNED START**	10/ 01:0
			10/13/2022 01:00:00
TASK NAME	3C - 9001 BB38 - WT - INT PLUMB - Hot wa		622-7846 - SR3179417
TASK DESCRIPTION	3C- 9001 BB38 - hot water heater is leaking -		0319
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required _M		__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required _En		red __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 12031612

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3179417	10/12/2022 16:50:1	(405) 622-7846

FACILITY PROJECT DETAILS

WT 12031612

ASSET DETAILS

WT 12031612

WARRANTY DETAILS

WT 12031612

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12031612

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12031612

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12031612**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12031612**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12031612**

Additional Notes: **WT 12031612**

PROCEDURE STEP DETAILS **WT 12031612**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 12013466

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AERO COMPLEX-90
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE	Corrective	**REQUEST CLASS**	General Repairs		Mar 1, 2023, 9
EST HOURS	0	**PLANNED START**	10/08/2022 01:00:00		10/08/2022 01:00:00
TASK NAME	3C - 9001 BETWEEN BB & CC 51 - WT - TAC STRUC - 582-4496				ND DRAIN AREA
TASK DESCRIPTION	3C - 9001 BETWEEN BB & CC 51- WT- TAC STRCUTU STRAWN-582-4496				AROUND DRAIN A
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop C __Environmenta		__ FD/SFS/CO Coordinatio ed __Travel/Access Cl

SERVICE REQUEST DETAILS

WT

REQUEST ID	CREATED DATE/TIME	WOR
3173223	10/07/2022 12:39:18	405-

FACILITY PROJECT DETAILS

WT

ASSET DETAILS

WT

WARRANTY DETAILS

WT 12013466

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12013466

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12013466

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12013466**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12013466**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12013466**

Additional Notes: **WT 12013466**

PROCEDURE STEP DETAILS **WT 12013466**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11363650

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER A COMPLEX
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Plumbing	T	Feb
EST HOURS	0	**PLANNED START**	05/14/2022 01:00:00		05/1 01:0
TASK NAME	3B - 9001 Post BB55/CC56 South - WT - PLUMB INT- D [redacted] aking - R [redacted] 582-4496 - SR#2925951				
TASK DESCRIPTION	Bldg 9001 post BB55 South - Domestic Water lines are le [redacted] e filled - [redacted] n 2 6				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop C __Environment		OMM tion ired Clea Required

SERVICE REQUEST DETAILS

T 1 650

REQUEST ID	CREATED DATE/TIME	RK	E
2925951	05/13/2022 15:04:31	5-73	7

FACILITY PROJECT DETAILS

T 1 650

ASSET DETAILS

T 1 650

WARRANTY DETAILS

WT 11363650

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11363650

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11363650

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11363650**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11363650**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11363650**

Additional Notes: **WT 11363650**

PROCEDURE STEP DETAILS **WT 11363650**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK		11413909	
WORK TASK DETAILS			
TASK PRIORITY	3C - Low Sustain	**PRIMARY WORK LOCATION**	CE COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - WATER AND F SYSTEM MX - PLUMB INT - B	**RESPONSIBLE PERSON**	(NU)
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9		
TASK TYPE	**REQUES** g Services	**PRINTED DATE**	M
EST HOURS	**PLANNE** 2022	**PLANNED END**	
TASK NAME	3C - 9001 POST C10 - WT - IN R DRAINS OVERFLOW WHEN J BUCKETS - REPAIR - T6112 - - 622-7846 - -		HEIR MOP
TASK DESCRIPTION	MENS AND WOMENS RESTR RAINS SOMETIMES OVERFLOW BUCKETS DOWN THE DRAIN RS CLOSET, NOT CLOGGED AS		POUR THEIR MOP
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Require i-Shop Coordination Required __ Digging Permit Required _ vironmental Coordination Required		OMM/_____ tion Required learance Required

SERVICE REQUEST DETAILS — **WT 11413909**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — **WT 11413909**

ASSET DETAILS — **WT 11413909**

WARRANTY DETAILS — **WT 11413909**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11413909**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _____ — **WT 11413909**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11413909**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11413909**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11413909**

Additional Notes: **WT 11413909**

PROCEDURE STEP DETAILS **WT 11413909**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11864

WORK TASK DE

TASK PRIORITY	Sustain	**STATUS**	Closed	**PRIMAR LOCAT**	RK PACE 1
		TRACKING STATUS			
RESPONSIBLE ORG	AFB - WATER AND FUELS MX - PLUMB INT - BOS-			**RESPO PERSO**	s(NU)
CUSTOMER ORG	AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	e	**REQUEST CLASS**	Clogs		:15 PM
EST HOURS		**PLANNED START**	09/13/2022 01:00:00		
TASK NAME	MENS RR POST C10 - WT - INT PLUMB - URIN - 405.622.7846/323.0319			GGE	BAGGED
TASK DESCRIPTION	MRR C10 - urinal drain is clogged, has been ba			405.	.0319
FOREMAN'S NOTES TO CRAFTSMEN	_ ty Precautions Required __ Digging Permit Required		__Multi-Shop Co __Environmental	red	__ FD/SFS/COMM/ Coordination R __ Travel/Access Cleara ed

SERVICE REQUEST DETAILS WT 11

REQUEST ID	CREATED DATE/TIME	WORK PH
3126979	09/12/2022 12:49:51	(405) 622

FACILITY PROJECT DETAILS WT 11

ASSET DETAILS WT 118

WARRANTY DETAILS WT 11864232

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11864232

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11864232

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11864232**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11864232**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11864232**

Additional Notes: **WT 11864232**

PROCEDURE STEP DETAILS **WT 11864232**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11406098

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	Jeffrey Jefferies(NU)
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Feb 28, 2023, 9:16 PM
EST HOURS		**PLANNED START**	05/24/2022 18:32:31	**PLANNED END**	05/24/2022 18:32:31
TASK NAME	3C - 9001 POST C-35 - WT - INTPLUMB - LEAKING WATER OUTLET - REPAIR - K7919 - GARY BURKETT - 405-274-2656				
TASK DESCRIPTION	WATER OUTLET WILL NOT TURN OFF COMPLETELY AND IS DRIPPING ON THE FLOOR. SENT VIA EMAIL				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11406098

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11406098

ASSET DETAILS

WT 11406098

WARRANTY DETAILS

WT 11406098

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11406098

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11406098

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11406098**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11406098**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11406098**

Additional Notes: **WT 11406098**

PROCEDURE STEP DETAILS **WT 11406098**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11727468

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY WOR LOCATION**	SPACE 01
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC			**RESPONSIBLE PERSON**	[redacted]
CUSTOMER ORG	T AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	C e	**REQUEST CLASS**	Other Plumbing Need	T	59 PM
EST HOURS	0	**PLANNED START**	08/11/2022 01:00:00		
TASK NAME	3 - WT - PLUMB INT - F/U 11708771 UNCLOG U				405-734-7098
TASK DESCRIPTION	3 - WT - PLUMB INT - F/U 11708771 UNCLOG U 1 2 D otes - All urinals flushing as they should.				405-734-7098
FOREMAN'S NOTES TO CRAFTSMEN	_ Precautions Required _ g Permit Required		__Multi-Shop Co __Environmental		/COMM/_____ nation Required s Clearance Required

SERVICE REQUE AILS **WT 11727468**

REQUES	CREATED DATE/TIME	ORK PHONE
307086	08/10/2022 15:14:26	(405) 739-5767

FACILITY PROJE AILS **WT 11727468**

ASSET DETAILS **WT 11727468**

WARRANTY DETA **WT 11727468**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11727468**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11727468**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11727468**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11727468**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11727468**

Additional Notes: **WT 11727468**

PROCEDURE STEP DETAILS **WT 11727468**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

11724573

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**PRIMARY WORK LOCATION**	TINKER AEROS 001
RESPONSIBLE ORG	TINKER AFB - WAT SYSTEM MX - PLU	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 M		
TASK TYPE		**PRINTED DATE**	Mar 6, 2023, 6:33
EST HOURS		**PLANNED END**	08/10/2022 09:39:22
TASK NAME	3B - 9001 C70 MR 7846		WING ONTO THE FLOOR - REPAIR - 22-
TASK DESCRIPTION	URINAL OVERFLO 10AUG2022 0948 10AUG2022 0955 10AUG2022 1053 OVERFLOWING; C WILL CHECK BAC		ON SITE ALREADY ACKED UP; URINAL WAS NOT RUNN SO THE FLOOR WAS WET BUT THE HR LABOR
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautio __ Digging Permit R		ination Required __ FD/SFS/COMM/_____ Coordination Required oordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11724573

REQUEST ID	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11724573

ASSET DETAILS

WT 11724573

WARRANTY DETAILS

WT 11724573

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11724573

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11724573

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11724573**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11724573**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11724573**

Additional Notes: **WT 11724573**

PROCEDURE STEP DETAILS **WT 11724573**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11931313

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WO LOCATION**	ACE
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	U)
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**AT**	9 PM
EST HOURS	0	**PLANNED START**	09/22/2022 10:41:35	**ND**	
TASK NAME	3B - 9001 POST C70 WOMENS RR - WT - INT PLUMB - CLO			**ET**	7839
TASK DESCRIPTION	Clogged toilet women's RR @ post C70 Randy Bird 582-9046/695-2901 Account 451				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coord __Environmental Co	red quired	__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11931313

REQUEST ID	CREATED DATE/TIME		WORK PHONE
3146854	09/22/2022 10:36:50	D	(405) 622-7839

FACILITY PROJECT DETAILS

WT 11931313

ASSET DETAILS

WT 11931313

WARRANTY DETAILS

WT 11931313

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11931313

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11931313

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11931313**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11931313**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11931313**

Additional Notes: **WT 11931313**

PROCEDURE STEP DETAILS **WT 11931313**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WO[redacted]

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	[redacted]ed	P[redacted]CE
RESPONSIBLE ORG	TINKER AFB - WATER SYSTEM MX - PLUMB I BMC		R[redacted]NU)
CUSTOMER ORG	TINKER AFB - 76 MXW		
TASK TYPE	Corrective	REQ[redacted]s	[redacted]M
EST HOURS	0	PLA[redacted]2/2022 0:00	
TASK NAME	3C - 9001 CC44 - WT - In[redacted]oor drain - Repa[redacted]S		
TASK DESCRIPTION	Clogged floor Drain CC-4[redacted]582-4105 refere[redacted]		

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Re[redacted] _ ulti-Shop Coord[redacted]d __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental C[redacted]uired __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11352627

REQUEST ID	CREATED DATE/TIME	WORK PHONE
2921199	05/11/2022 13:11:41	(405) 734-2753

FACILITY PROJECT DETAILS

WT 11352627

ASSET DETAILS

WT 11352627

WARRANTY DETAILS

WT 11352627

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11352627

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11352627

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11352627**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11352627**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11352627**

Additional Notes: **WT 11352627**

PROCEDURE STEP DETAILS **WT 11352627**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 13636

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY LOCATION**	AEROSPACE EX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONS PERSON**	
CUSTOMER ORG	76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Clogs		2023, 9:36 PM
EST HOURS		**PLANNED START**	05/14/2022 01:00:00		022 0
TASK NAME		CC44 - WT - INT PLUMB - CLOGGED DRA			- 405-582-4196 - SR#2925946
TASK DESCRIPTION		using flooding in shop area and main aisle, 405-582-4196 EQUIRED			
FOREMAN'S NOTES TO CRAFTSMEN		tions Required t Required	__Multi-Shop Coor __Environmental C	ired	__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required

SERVICE REQU **WT 11363640**

REQUE	CREATED DATE/TIME	WORK PHONE
29259	05/13/2022 14:58:49	405-734-3761

FACILITY PROJ **WT 11363640**

ASSET DETAILS **WT 11363640**

WARRANTY DETAILS **WT 11363640**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11363640**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11363640**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11363640**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11363640**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11363640**

Additional Notes: **WT 11363640**

PROCEDURE STEP DETAILS **WT 11363640**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11411058

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER COMPLE
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**E**	Mar
EST HOURS	0	**PLANNED START**	05/26/2022 01:00:00		05/2 01:0
TASK NAME	3B - 9001 POST CC44 - WT - PLUMB INT-F/U T6008- RO 5824496 - SR#2945381				ED - RE -
TASK DESCRIPTION	3B-9001 POST CC44-WT-PLUMB INT-F/U T6008- ROOF				REPAIR 496
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Co		–
	__ Digging Permit Required		__Environmenta		ed __T quired

SERVICE REQUEST DETAILS

REQUEST ID	CREATED DATE/TIME
2945381	05/25/2022 13:56:45

FACILITY PROJECT DETAILS

ASSET DETAILS

WARRANTY DETAILS

WT 11411058

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11411058

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11411058

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11411058**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11411058**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11411058**

Additional Notes: **WT 11411058**

PROCEDURE STEP DETAILS **WT 11411058**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11690556

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIM LOC**	**RY WORK ION** TINK COMP
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC			**RES PER**	**NSIBLE N**
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks	**TE**	Mar 1
EST HOURS	0	**PLANNED START**	08/01/2022 10:12:55	**D**	08/01 10:12
TASK NAME	3B - 9001 POST D8 - WT - INT PLUMB - RELIEF V				REPAIR - 582-4105 - SR# 3054254
TASK DESCRIPTION	Bldg 9001, Post D8, Relief valve is leaking water. M weekend a ge puddle of water on the floor. Have noticed a little bit of residua ottom the valve but not alot. Might have dumped a lot of water at one time. Any questions c 05 01Aug2022 Downey notes - Inspected backflow. Relief valve w aks @ time of inspection.				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-S		__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required		__Environ	ired	__ Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11690556

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3054254	08/01/2022 10:10:0	(405) 582-4105

FACILITY PROJECT DETAILS

WT 11690556

ASSET DETAILS

WT 11690556

WARRANTY DETAILS

WT 11690556

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11690556

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11690556

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11690556**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11690556**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11690556**

Additional Notes: **WT 11690556**

PROCEDURE STEP DETAILS **WT 11690556**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	ORK TASK		**11977856**	
WORK TASK D				
TASK PRIORITY	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINK
	TRACKING STATUS			
RESPONSIBLE ORG	AND FUELS INT - BOS-BMC		**RESPONSIBLE PERSON**	
CUSTOMER ORG	TAC 9000 - 63G			
TASK TYPE	**QUEST CLASS**	Building Services	**PRINTED DATE**	Mar 6
EST HOURS	**ANNED START**	09/30/2022 16:41:03	**PLANNED END**	09/30 16:41
TASK NAME	and Womens RR - WT - INT PLUMB - restrooms are flooding -			
TASK DESCRIPTION	room are overflowing, at least one urinal clogged and water com 1645, onsite 1700 pped urinal with cable, went to CEMAS for santeen and put it in te			

FOREMAN'S NOTES TO CRAFTSMEN Required __Multi-Shop Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS **WT 11977856**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS **WT 11977856**

ASSET DETAILS **WT 11977856**

WARRANTY DETAILS **WT 11977856**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11977856**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11977856**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11977856**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11977856**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11977856**

Additional Notes: **WT 11977856**

PROCEDURE STEP DETAILS **WT 11977856**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11779542

WORK TASK DE			
TASK PRIORITY	**STATUS** Closed **TRACKING STATUS**	**PRIMARY WORK LOCATION**	TIN COM
RESPONSIBLE ORG	B - WATER AND FUELS X - PLUMB INT - BOS-	**RESPONSIBLE PERSON**	
CUSTOMER ORG	B - 76 MXW TAC 9000 - 63G		
TASK TYPE	**REQUEST CLASS** Clogs	E	Mar
EST HOURS	**PLANNED START** 08/24/2022 10:11:28	D	08/2 10:1
TASK NAME	RTC OFFICE POST DX33 - WT - INT PLUMB	OGGED -	- 622-7846
TASK DESCRIPTION	ORTC Office south Admin post Dx33 - ACAP D 405.622.7846	d drains slo ,	h use drain -
FOREMAN'S NOTES TO CRAFTSMEN	recautions Required __Multi-Shop Co __ Digging Permit Required __Environmental		__ FD/SFS/COMM/_____ Coordination Required ired __Travel/Access Clearance Required

SERVICE REQUEST DETAILS — WT 11779542

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3096644	08/24/2022 10:08:50	(405) 622-7846

FACILITY PROJECT DETAILS — WT 11779542

ASSET DETAILS — WT 11779542

WARRANTY DETAILS — WT 11779542

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11779542

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — WT 11779542

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11779542**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11779542**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11779542**

Additional Notes: **WT 11779542**

PROCEDURE STEP DETAILS **WT 11779542**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1194172

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY W LOCATION**	R AEROSPACE LEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC			**RESPONSI PERSON**	
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE	Corrective	**REQUEST CLASS**	General Repairs		2 , 8:52 PM
EST HOURS	0	**PLANNED START**	09/24/2022 01:00:00		
TASK NAME	3C - 9001 D-44- WT - TAC STRUC- LEAKING AT THE S				-582-4496
TASK DESCRIPTION	3C - 9001 D-44- WT - TAC STRUC- LEAKING AT THE S				-582-4496
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop C		FS/COMM/_____ rdination Required
	__ Digging Permit Required		__Environmenta		ess Clearance Required

SERVICE REQUEST DETAILS

WT 11941722

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3149695	09/23/2022 14:26:52	405-582-4496

FACILITY PROJECT DETAILS

WT 11941722

ASSET DETAILS

WT 11941722

WARRANTY DETAILS

WT 11941722

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11941722

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11941722

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11941722**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11941722**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11941722**

Additional Notes: **WT 11941722**

PROCEDURE STEP DETAILS **WT 11941722**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11626550

WORK TASK DE				
TASK PRIORITY		**STATUS** Closed **TRACKING STATUS**	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	C MX TM - TAC		**RESPONSIBLE PERSON**	
CUSTOMER ORG	XW TAC 9000 - 63G			
TASK TYPE		**REQUEST CLASS** Building Services	**PRINTED DATE**	Mar 1, 2023, 3:15 PM
EST HOURS		**PLANNED START** 07/13/2022 12:40:48	**PLANNED END**	07/13/2022 12:40:48
TASK NAME	ST D56 WAREHOUSE SR57 - WT - TAC HVAC - WATER LEAKING FROM CEILING - Repair - 541-9535			
TASK DESCRIPTION	V R B	FROM CEILING - NOT SURE IF ITS FROM PIPES OR HVAC SYSTEM - LEAK IS CONTAINED AND S THERE IS MULTIPLE SPOTS POC DARRELL POOLS 405-610-3706 MAKE CONTACT WITH POC G WORK.		

FOREMAN'S NOTES TO CRAFTSMEN

_ ions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS — WT 11626550

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — WT 11626550

ASSET DETAILS — WT 11626550

WARRANTY DETAILS — WT 11626550

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11626550

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — WT 11626550

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11626550**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11626550**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11626550**

Additional Notes: **WT 11626550**

PROCEDURE STEP DETAILS **WT 11626550**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 12063019

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	TIN COM E
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks		Mar
EST HOURS	0	**PLANNED START**	10/26/2022 11:38:10		10/2 11:3
TASK NAME	3B - 9001 DD26-DD27 - WT - TAC STRUC - Smoke damp SR3191376				ne rain
TASK DESCRIPTION	Bldg 9001, Between posts DD26 and DD27 smoke dampe 582-4105.				e rain. A at
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Co		__ FD/SFS/CO Coordinati
	__ Digging Permit Required		__Environmenta		d __Travel/Access C d

SERVICE REQUEST DETAILS

WT

REQUEST ID	CREATED DATE/TIME	WOR
3191376	10/26/2022 11:36:38	405

FACILITY PROJECT DETAILS

WT

ASSET DETAILS

WT

WARRANTY DETAILS

WT 12063019

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12063019

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12063019

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12063019**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12063019**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12063019**

Additional Notes: **WT 12063019**

PROCEDURE STEP DETAILS **WT 12063019**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K

WORK TASK DETAILS

TASK PRIORITY	3A - High Susta	Closed	K TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - SYSTEM MX - BMC		
CUSTOMER ORG	TINKER AFB	G	
TASK TYPE		Building Services	Feb 28, 2023, 8:22 PM
EST HOURS		07/12/2022 11:45:02	07/12/2022 11:45:02
TASK NAME	3A - 9001 DD	OP LEAK - Repai	5826491
TASK DESCRIPTION	IN BREAKRO ALREADY C	E IS A LEAK COM G M NORTH AND CENTER WALL, IT HAS LE.
	12JUL22 12 12JUL22 1:4 THE ICE MA CLOSE WOR	L ON SITE FOR WATER LEA LOCATED WATER FROM BROKEN ICE MACHINE DRAIN, D TO SIDE, REAT CHED/REPAIRED DRAIN LINE. CLEANED UP WATER
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Pr __ Digging P	__Multi-Shop Co ination Required __ FD/SFS/COMM/_____ Coordination Required __Environmental ordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAI

WT 11620030

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAI

WT 11620030

ASSET DETAILS

WT 11620030

WARRANTY DETAILS

WT 11620030

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11620030

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11620030

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11620030**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11620030**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11620030**

Additional Notes: **WT 11620030**

PROCEDURE STEP DETAILS **WT 11620030**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

W ASK 18523

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**PRIMARY LOCATION**	EROSPACE -9001
RESPONSIBLE ORG	TINKER AFB - WATE SYSTEM MX - PLUM BMC	**RESPONS PERSON**	
CUSTOMER ORG	TINKER AF MX		
TASK TYPE	R Services	**PRINTED D**	023, 8:29 PM
EST HOURS	P 22	**PLANNED**	2
TASK NAME	3A - 9001 4	FLOOD BREAKROOM	5824196
TASK DESCRIPTION	IN THE BR O THE BREA	S A LEAK COMING FRO	SINK THAT IS FLOODING
	9SEP22 8 F 9SEP22 8 E	ONSITE	
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety n	hop Coordination Required	__ FD/SFS/COMM/_____ Coordination Required
	__ Digging e	nmental Coordination Required	__ Travel/Access Clearance Required

SERVICE REQUEST DET **WT 11852318**

REQUEST I	C	DA	FULL NAME	WORK PHONE

FACILITY PROJECT DETA **WT 11852318**

ASSET DETAILS **WT 11852318**

WARRANTY DETAILS **WT 11852318**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11852318**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ **Outage** **Outage Event ID#** __ __ __ __ __ **WT 11852318**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11852318**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11852318**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11852318**

Additional Notes: **WT 11852318**

PROCEDURE STEP DETAILS **WT 11852318**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11413918

WORK TASK D					
TASK PRIORITY		**STATUS**	Closed	**PRIMARY WORK LOCATION**	CE
		TRACKING STATUS			
RESPONSIBLE ORG	ATER AND FUELS LUMB INT - BOS-			**RESPONSIBLE PERSON**	s(NU)
CUSTOMER ORG	MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	M PM
EST HOURS		**PLANNED START**	05/26/2022 04:24:37	**PLANNED END**	0 0
TASK NAME	DD52 - WT - INTPLUMB - TOILET FLUSH VALVE LEAKING IN T - REPAIR - T6114 - - 622-7846 - -				
TASK DESCRIPTION	ALVE LEAKING IN THE WOMENS RESTROOM				

FOREMAN'S NOTES TO CRAFTSMEN

utions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11413918

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11413918

ASSET DETAILS

WT 11413918

WARRANTY DETAILS

WT 11413918

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11413918

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11413918

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11413918**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11413918**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11413918**

Additional Notes: **WT 11413918**

PROCEDURE STEP DETAILS **WT 11413918**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

W [redacted] 11599164

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain [redacted] sed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - WATER SYSTEM MX - PLUMB BMC	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW		
TASK TYPE	Corrective **RE** [redacted] ks	**E**	Mar 1, 2023, 2:48 PM
EST HOURS	0 **PL** [redacted] 08/2022 00:00		07/08/2022 01:00:00
TASK NAME	3C - 9001 2ND FLR R.R [redacted] ORS CLOSE 9001-WH-D10 - REPAIR [redacted] - 405-734-70		[redacted] - F/F REPAIR WATER HEATER LEAK
TASK DESCRIPTION	3C- 9001 2ND FLR R.R [redacted] ORS CLOSE 9001-WH-D10 - REPAIR [redacted] - 405-734-70		[redacted] - F/F REPAIR WATER HEATER LEAK
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions R [redacted] Multi-Shop Co		__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Requ [redacted] Environmenta [redacted] red		__ Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11599164

REQUEST ID	R [redacted] ED [redacted] E	WORK PHONE
3013129	20	(405) 739-5767

FACILITY PROJECT DETAILS

WT 11599164

ASSET DETAILS

WT 11599164

WARRANTY DETAILS

WT 11599164

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11599164

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ WT 11599164

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11599164**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11599164**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11599164**

Additional Notes: **WT 11599164**

PROCEDURE STEP DETAILS **WT 11599164**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

K TASK 11599115

WORK TASK DETAILS

TASK PRIORITY	3C - Low	**STATUS** / **TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	TINKER SYSTEM BMC	D FUELS - BOS-		**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER	C 9000 - 63G			
TASK TYPE	Correctiv	**EST CLASS**	Leaks		Mar 1, 2023, 2:46 PM
EST HOURS	0	**NED START**	07/08/2022 01:00:00		07/08/2022 01:00:00
TASK NAME	3C - 9001 REPAIR -	. DOGLEG JANITORS CLOSE - 405-734-7098			NT - REPAIR LEAK ON MIXING VAVLE -
TASK DESCRIPTION	3C - 9001 REPAIR -	. DOGLEG JANITORS CLOS - 405-734-7098			NT - REPAIR LEAK ON MIXING VAVLE -
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety __ Diggin	ired __Environmental	__Multi-Shop Co		__ FD/SFS/COMM/_____ Coordination Required ed __Travel/Access Clearance Required

SERVICE REQUEST DET

WT 11599115

REQUEST I	TED DATE/TIME	WORK PHONE
301311	7/2022 13:00:02	(405) 739-5767

FACILITY PROJECT DET

WT 11599115

ASSET DETAILS

WT 11599115

WARRANTY DETAILS

WT 11599115

ID	AL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11599115

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ WT 11599115

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11599115**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11599115**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11599115**

Additional Notes: **WT 11599115**

PROCEDURE STEP DETAILS **WT 11599115**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11690408

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	ACE
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	T R AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	C tive	**REQUEST CLASS**	Clogs	E M	PM
EST HOURS	[redacted]	**PLANNED START**	08/01/2022 09:35:10	D 0 0	
TASK NAME	01 E30 MRR - WT - INT PLUMB - TOLET CLOGG 0			AIR -	622-7846 - SR#
TASK DESCRIPTION	01 E30 - MRR toilet is clogged/bagged 022 y notes - Replaced toilet spud with new one to corr			ue.	
FOREMAN'S NOTES TO CRAFTSMEN	ty Precautions Required ing Permit Required	__Multi-Shop Co __Environmenta		ired	__ FD/SFS/COMM/_____ Coordination Required __ Travel/Access Clearance Required

SERVICE REQU TAILS

WT 11690408

REQUES	CREATED DATE/TIME	WORK PHONE
30541	08/01/2022 09:34:04	(405) 622-7846

FACILITY PROJE TAILS

WT 11690408

ASSET DETAILS

WT 11690408

WARRANTY DETAILS

WT 11690408

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11690408

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11690408

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11690408**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11690408**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11690408**

Additional Notes: **WT 11690408**

PROCEDURE STEP DETAILS **WT 11690408**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11660711

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINK COMP CE
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks	E	Mar 1 PM
EST HOURS	0	**PLANNED START**	07/23/2022 01:00:00	D	07/23 01:00
TASK NAME	3B - 9001 Posts E67 & E68 - WT - TAC HVAC - repair leaki ne - repair - - 622-7846 - SR3041475				
TASK DESCRIPTION	3B - 9001 E67-68 - HVAC chilled water line is leaking onto m below. leak d.				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi-Shop Coo		__ FD/SFS/COMM/_____ Coordination Required	
	__ Digging Permit Required	__Environmental C	ired	__Travel/Access Clearance Required	

SERVICE REQUEST DETAILS

WT 11660711

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3041475	07/22/2022 16:42:54	(405) 622-7846

FACILITY PROJECT DETAILS

WT 11660711

ASSET DETAILS

WT 11660711

WARRANTY DETAILS

WT 11660711

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11660711

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11660711

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11660711**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11660711**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11660711**

Additional Notes: **WT 11660711**

PROCEDURE STEP DETAILS **WT 11660711**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11742688

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS** / **TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TI … CO … CE
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Other Interior Nee…	Ma…	…PM
EST HOURS	0	**PLANNED START**	08/15/2022 11:02:31	08 … 11 …	
TASK NAME	3C - 9001 EE38 - WT - TAC HVAC - CHECK FOR AND RE…			AIR - …	622-7846
TASK DESCRIPTION	3C - 9001 EE38 - Check for and repair leaks, replace stain…			…tiles in …	…erior doors N38
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Co… __Environmental …	…ed	OMM/_____ Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS — WT 11742688

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3077696	08/15/2022 10:58:35	(405) 622-7846

FACILITY PROJECT DETAILS — WT 11742688

ASSET DETAILS — WT 11742688

WARRANTY DETAILS — WT 11742688

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11742688

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11742688**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11742688**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11742688**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11742688**

Additional Notes: **WT 11742688**

PROCEDURE STEP DETAILS **WT 11742688**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11630467

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS TRACKING STATUS**	Completed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE	Corrective	**REQUEST CLASS**	General Repairs		Mar 1, 2023, 3:34 PM
EST HOURS	0	**PLANNED START**	07/14/2022 10:21:05		07/14/2022 10:21:05
TASK NAME	3C - 9001 POST EE44 - WT - PLUMB INT - F/U T5571 AN STRAWN - 582-4196 - STORM				N DRAIN PIPE - REPAIR
TASK DESCRIPTION	3C - 9001 POST EE44 - WT - PLUMB INT - F/U T5571 AN STRAWN - 582-4196 - STORM				N DRAIN PIPE - REPAIR
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Co __Environmenta		__ FD/SFS/COMM Coordination R ed __Travel/Access Cleara d

[redacted]

SERVICE REQUEST DETAILS

WT 11

REQUEST ID	CREATED DATE/TIME	WORK P
3025484	07/14/2022 10:17:04	405-582- 6

FACILITY PROJECT DETAILS

WT 116 04

ASSET DETAILS

WT 11630467

WARRANTY DETAILS

WT 11630467

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11630467

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11630467

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11630467**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11630467**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11630467**

Additional Notes: **WT 11630467**

PROCEDURE STEP DETAILS **WT 11630467**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 20210

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	
		TRACKING STATUS	
PRIMARY LOCATION	ROSPACE -9001		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	**RESPONS PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G		
TASK TYPE	Corrective	**REQUEST CLASS**	
	3, 9:04 PM		
EST HOURS	0	**PLANNED START**	
TASK NAME	3B - 9001 POST EE-44 - WT - INT PLUM		- 405-582-4105
TASK DESCRIPTION	Bldg 9001, Post EE-44. Overhead pipe le . H bers and putting in work order per their request. Any questions ca at		
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ u i oo __ FD/SFS/COMM/_____ Coordination Required		
	__ Digging Permit Required _Envir al ired __Travel/Access Clearance Required		

SERVICE REQUEST DETAILS

WT 12021068

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3175059	10/11/2022 09:26:0 H	(405) 582-4105

FACILITY PROJECT DETAILS

WT 12021068

ASSET DETAILS

WT 12021068

WARRANTY DETAILS

WT 12021068

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12021068

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12021068

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12021068**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12021068**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12021068**

Additional Notes: **WT 12021068**

PROCEDURE STEP DETAILS **WT 12021068**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 118699

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Active	**PRIMARY LOCATIO**	PAC 1
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPON PERSON**	s(NU
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs		:17 P
EST HOURS	0	**PLANNED START**	09/13/2022 09:47:04		
TASK NAME	3C - 9001 ROOF EE46 - WT - INT PLUMB - ROOF DRAIN - 323-0319				NED S
TASK DESCRIPTION	3C - 9001 Roof EE46 - roof drain is clogged and needs to				6/323.0 19
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Co		__ FD/SFS/COMM/_ Coordination Re
	__ Digging Permit Required		__Environmental		Travel/Access Clearan

SERVICE REQUEST DETAILS

WT 118

REQUEST ID	CREATED DATE/TIME	WORK PHO
3128951	09/13/2022 09:35:14	(405) 622-7

FACILITY PROJECT DETAILS

WT 118 5

ASSET DETAILS

WT 1186 5

WARRANTY DETAILS

WT 11869995

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11869995

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11869995

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11869995**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11869995**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11869995**

Additional Notes: **WT 11869995**

PROCEDURE STEP DETAILS **WT 11869995**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11653169

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS TRACKING STATUS**	Completed Awaiting Scheduling	**PRIMARY WORK LOCATION**	PACE
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	(NU)
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	7 PM
EST HOURS		**PLANNED START**	07/20/2022 13:18:31	**PLANNED END**	
TASK NAME	3C - 9001 F55 - WT - INT PLUMB - LEAK COMING THOUGH METAL FLOOR -				23-0072
TASK DESCRIPTION	SMALL LEAK COMING FROM CEILING, OUTSIDE OF MEZZ 3, ABOVE ROOM WHITE CAST IRON PIPE NEAR SPRINKLER SYSTEM PIPING MAY NEED A LIFT TO TAKE A LOOK AT/REPAIR				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi-Shop Coordination Required		__ FD/SFS/COMM/_____ Coordination Required	
	__ Digging Permit Required	__Environmental Coordination Required		__Travel/Access Clearance Required	

SERVICE REQUEST DETAILS

WT 11653169

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11653169

ASSET DETAILS

WT 11653169

WARRANTY DETAILS

WT 11653169

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11653169

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11653169

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11653169**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11653169**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11653169**

Additional Notes: **WT 11653169**

PROCEDURE STEP DETAILS **WT 11653169**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

RK TASK 1452 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**STATUS**	Closed	**PRIMAR LOCATIO**	ER AEROSPACE LEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - P - BOS-BMC	PS - OTHER		**RESPON PERSON**	
CUSTOMER ORG	TINK 7	AC 9000 - 63G			
TASK TYPE		**UEST CLASS**	Building Services	**PRINTE**	8, 2023, 4:41 PM
EST HOURS		**NNED START**	06/06/2022 08:30:12	**PLANNE**	/2022 :12
TASK NAME	3A -	AC CONTROL - STOP PIPE LEAK - Repair			H - 582-4105
TASK DESCRIPTION	LEA OVE	AT POST G24 IT IS TEMPORARILY CONTA			KET BUT THE BUCKET KEEPS

835 STRAWN
8:55 ON SITE
9:25 IS A PLUMBING ISSUE, BACKFLOW PREVENTER HAS SLOW LEAK ON IT
OPE ORK ORDER FOR INT PLUMBING. CLOSE WORK TASK. CHARGE .50

FOREMAN'S NOTES TO CRAFTSMEN

__ S quired __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ D ed __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST WT 11452995

REQUEST I	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT WT 11452995

ASSET DETAILS WT 11452995

WARRANTY DETAILS WT 11452995

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11452995

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ WT 11452995

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11452995**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11452995**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11452995**

Additional Notes: **WT 11452995**

PROCEDURE STEP DETAILS **WT 11452995**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11482561

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**PRIMARY WORK LOCATION**	PACE
RESPONSIBLE ORG	TINKER AFB - WAT SYSTEM MX - PLUM BMC	**RESPONSIBLE PERSON**	(NU)
CUSTOMER ORG	TINKER AFB - 72 C		
TASK TYPE	uilding Services	**PRINTED DATE**	6 PM
EST HOURS	06/10/2022 0:40:14	**PLANNED END**	
TASK NAME	3C - 9001 G24 - WT- 11472358- REPAIR -	LEAKING AT TOP CONNECTION NOT C - 582-4496	TER TO POLE F/U
TASK DESCRIPTION	FOLLOW UP FROM	TCHING WATER AT THE POLE	

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions
__Multi-Shop Coordination Required
__ FD/SFS/COMM/_____ Coordination Required
__ Digging Permit Required
__Environmental Coordination Required
__Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11482561

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11482561

ASSET DETAILS

WT 11482561

WARRANTY DETAILS

WT 11482561

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11482561

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11482561

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11482561**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11482561**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11482561**

Additional Notes: **WT 11482561**

PROCEDURE STEP DETAILS **WT 11482561**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

ORK TASK 1 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIM** [redacted]	ACE
		TRACKING STATUS		**LOC**	
RESPONSIBLE ORG	TINKER AFB - [redacted] ND FUELS SYSTEM MX - T - BOS- BMC			**RES PER**	U)
CUSTOMER ORG	TINK [redacted] AC 9000 - 63G				
TASK TYPE	[redacted]	**UEST CLASS**	Building Services	**PRIN**	9 PM
EST HOURS	[redacted]	**NED START**	06/06/2022 09:31:27	**PLA**	
TASK NAME	3B - [redacted] LUMB INT - STOP PIPE LEAK - Repair -				
TASK DESCRIPTION	LEA [redacted] AT POST G24 IT IS TEMPORARILY CON OVE				HE BUCKET KEEPS
	835 [redacted] STRAWN 8:55 [redacted] ON SITE 9:25 [redacted] IS A PLUMBING ISSUE, BACKFLOW PREVENTER HAS SLOW LEAK ON IT OPE [redacted] ORK ORDER FOR INT PLUMBING.				
FOREMAN'S NOTES TO CRAFTSMEN	__ S [redacted] quired	__Multi-Shop Coordination Required		__ FD/SFS/COMM/_____ Coordination Required	
	__ D [redacted] ed	__Environmental Coordination Required		__Travel/Access Clearance Required	

SERVICE REQUEST **WT 11453558**

REQUEST I [redacted]	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT **WT 11453558**

ASSET DETAILS **WT 11453558**

WARRANTY DETAILS **WT 11453558**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11453558**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ **WT 11453558**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11453558**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11453558**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11453558**

Additional Notes: **WT 11453558**

PROCEDURE STEP DETAILS **WT 11453558**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 119411

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY LOCATIO**	ACE
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPON PERSON**	NU)
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs		0 PM
EST HOURS	0	**PLANNED START**	09/24/2022 01:00:00		
TASK NAME	3C - 9001 POST G39 BRKRM - WT - INT PLUMB - SINK				- 582-4105
TASK DESCRIPTION	Bldg 9001, Post G-39 breakroom sink drain is clogged. An				05.
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Co		_ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required		__Environmenta		vel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11941144

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3149510	09/23/2022 13:08:12	(405) 582-4105

FACILITY PROJECT DETAILS

WT 11941144

ASSET DETAILS

WT 11941144

WARRANTY DETAILS

WT 11941144

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11941144

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11941144

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11941144**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11941144**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11941144**

Additional Notes: **WT 11941144**

PROCEDURE STEP DETAILS **WT 11941144**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

R SK 11676795

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**TUS** **ING** **TUS**	Closed	**PRIMARY WORK LOCATION**	TI CO E
RESPONSIBLE ORG	TINKER AFB - WA SYSTEM MX - PLU BMC	S		**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB M	6			
TASK TYPE		S u		**PRINTED DATE**	Fe
EST HOURS		R		**PLANNED END**	07 09
TASK NAME	3A - 9001 W		OILET LEAKING - Repair		2742656
TASK DESCRIPTION	WATER CON DOESN'T R 28JUL22 07 28JUL22 07 28JUL22 08	A M D D	RED IN WATER. THERE IS N SITE R, ISSUE RESOLVED CLOSE WORK TASK 1 HOUR LABOR		HE WATER
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Pr __ Digging P		rdination Required Coordination Required	__ FD/SFS/COMM/_____ Coordination Required __ Travel/Access Clearance Required	

SERVICE REQUEST DETAI **WT 11676795**

REQUEST I	C	T	FULL NAME	WORK PHONE

FACILITY PROJECT DETAI **WT 11676795**

ASSET DETAILS **WT 11676795**

WARRANTY DETAILS **WT 11676795**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11676795**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ **WT 11676795**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11676795**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11676795**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11676795**

Additional Notes: **WT 11676795**

PROCEDURE STEP DETAILS **WT 11676795**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

ORK TASK 11693628

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**STATUS TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSP COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - SP X TM - TAC HVAC - BOS-BM			**RESPONSIBLE PERSON**	
CUSTOMER ORG	B 6 T 00 - 63G				
TASK TYPE		**LASS**	Leaks	**TE**	Feb 28, 2023, 8:46
EST HOURS		**TART**	08/02/2022 07:00:00	**D**	08/02/2022 07:00:00
TASK NAME	- WT - TAC HVAC - bas				ignificant leak - repair -
TASK DESCRIPTION	of post H42 has signific 2-4105. nsite plumbing, charge .2 hr				me flooding into the aisle ay
FOREMAN'S NOTES TO CRAFTSMEN	__Multi-Shop Co __Environmenta				__ FD/SFS/COMM/ Coordination R ired __Travel/Access Cleara ed
SERVICE REQU					WT 11
REQUE	30557 0	**ATE/TIME**	06:40:16	**WORK PH**	(405) 582
FACILITY PROJ					WT 116
ASSET DETAILS					WT 116

WARRANTY DETAILS

WT 11693628

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11693628

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11693628

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11693628**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11693628**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11693628**

Additional Notes: **WT 11693628**

PROCEDURE STEP DETAILS **WT 11693628**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K 1 694408

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**S** Closed	**ARY WORK ATION** TINKER AEROSP COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - W SYSTEM MX - P BMC		**PONSIBLE SON**
CUSTOMER ORG	TINKER AFB - 7	G	
TASK TYPE			**TED DATE** Feb 28, 2023, 8:14
EST HOURS			**NNED END** 08/02/2022 11:43:40
TASK NAME	3A - 9001 BASE 582-4105		8 SIGNIFICANT LEAK - REPAIR -
TASK DESCRIPTION	BASE OF POST 2AUG2022 0815 2AUG2022 0839 2AUG2022 0934 CLEANING AND NO MATERIALS		SOME FLOODING INTO THE AIS EW N SITE OSSIBLY SOMEONE FLOODED THE R UP WATER; CHARGE 1HR LABOR AND
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precau __ Digging Perm		n Required __ FD/SFS/COMM/_ Coordination Re ation Required __Travel/Access Clearan

SERVICE REQUEST DETAILS

WT 1169

REQUEST ID	E/	LL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11694408

ASSET DETAILS

WT 11694408

WARRANTY DETAILS

WT 11694408

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11694408

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11694408

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11694408**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11694408**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11694408**

Additional Notes: **WT 11694408**

PROCEDURE STEP DETAILS **WT 11694408**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WO			**119881**		
WORK TASK DETAILS					
TASK PRIORITY	3C - Low Sustain		Completed Maintenance Complete	**PRIMARY LOCATIO**	EX-9001
RESPONSIBLE ORG	TINKER AFB - WATER A SYSTEM MX - PLUMB I			**RESPON PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW				
TASK TYPE	Corrective	**REC**	Other Plumbing Need	**D**	
EST HOURS	0	**PLA**	10/03/2022 11:54:44		
TASK NAME	3C - 9001 H70 - WT - IN 7846		ER ODOR FROM	AIR-	- 622-
TASK DESCRIPTION	3C - 9001 H70 - sewer o to be replaced/repaired -		ump UID 9001-P 05.622.7846/323.0	ndica	needed
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Re		__Multi-Shop Co		__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Require		__Environmental	red	__Travel/Access Clearance Required

SERVICE REQUEST DETAILS — **WT 11988172**

REQUEST ID	CREATED DATE/TIME		WORK PHONE
3163239	10/03/2022 11:45:36		(405) 622-7846

FACILITY PROJECT DETAILS — **WT 11988172**

ASSET DETAILS — **WT 11988172**

WARRANTY DETAILS — **WT 11988172**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11988172**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ **WT 11988172**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11988172**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11988172**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11988172**

Additional Notes: **WT 11988172**

PROCEDURE STEP DETAILS **WT 11988172**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11808432

WORK TASK DE					
TASK PRIORITY	um	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TIN COM
		TRACKING STATUS			
RESPONSIBLE ORG	AFB - SPEC MX TM - TAC OS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	AFB - 72 CES				
TASK TYPE	e	**REQUEST CLASS**	General Repairs		Mar
EST HOURS		**PLANNED START**	08/31/2022 01:00:00		08/3 01:0
TASK NAME	S ADMIN RM 147 - WT - TAC HVAC - UNIT LEA				S RR - 4496
TASK DESCRIPTION	S ADMIN ROOM 147- WT- TAC HVAC- HVAC U -582-4496				WOMEN
FOREMAN'S NOTES TO CRAFTSMEN	y Precautions Required		__Multi-Shop Co		– Coordinatio –
	__ Digging Permit Required		__Environmental		d __Travel/Access Cle quired

SERVICE REQUEST DETAILS WT

REQUEST ID	CREATED DATE/TIME	WORK
3108438	08/30/2022 15:14:38	405-5

FACILITY PROJECT DETAILS WT

ASSET DETAILS WT

WARRANTY DETAILS WT 11808432

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11808432

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11808432

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11808432**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11808432**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11808432**

Additional Notes: **WT 11808432**

PROCEDURE STEP DETAILS **WT 11808432**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11810488

WORK TASK DE					
TASK PRIORITY	edium	**STATUS TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPAC COMPLEX-9001
RESPONSIBLE ORG	R AFB - SPEC MX TM - TAC CTURES - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Leaks		Mar 1, 2023, 6:52 PM
EST HOURS		**PLANNED START**	08/31/2022 07:10:12		08/31/2022 07:10:12
TASK NAME	2 - WT - TAC STRUC - SEVERAL LEA				NG ON LAPTOP CABINET
TASK DESCRIPTION	B C	2 area has several areas where there is at 582-4105 for questions.			nd one is leaking on the lap
FOREMAN'S NOTES TO CRAFTSMEN	_	ns Required equired	__Multi-Shop Coo __Environmental		__ FD/SFS/COMM Coordination R ed __Travel/Access Clear

SERVICE REQUEST WT 11

REQUEST I	CREATED DATE/TIME	WORK P N
310928	08/31/2022 07:08:28	(405) 582 1

FACILITY PROJECT WT 11810

ASSET DETAILS WT 11810

WARRANTY DETAIL WT 11810488

ID	AL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11810488

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11810488

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Primary Maintenance Reason Code **WT 11810488**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11810488**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11810488**

Additional Notes: **WT 11810488**

PROCEDURE STEP DETAILS **WT 11810488**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

WORK TASK 11837164

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TI E COMPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Flood	**PRINTED DATE**	M
EST HOURS		**PLANNED START**	09/07/2022 09:20:59	**PLANNED END**	0 0
TASK NAME	3B - 9001 KC46 AREA - WT - TAC HVAC - REHEAT PUMPS HAVE FLOODED ARE				736-7554
TASK DESCRIPTION					
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Required __Environmental Coordination Required _		M/_____ n Required arance Required

SERVICE REQUEST DETAILS 11837164

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS WT 11837164

ASSET DETAILS WT 11837164

WARRANTY DETAILS WT 11837164

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11837164

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11837164

Primary Maintenance Reason Code WT 11837164

__ Abuse / Malevolent Act	__Accident/Event	__Corrosion	__Solid State	__Off-base Source	__Weather	__Tree/Vegetation
__ Cust Request/Directed	__Environmental	__Mechanical	__Structural	__Operator/Techn	__Wildlife	__Fire/Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

NOTES TO R&O ON ASSETS & LOCATION			WT 11837164
ASSET STATUS	**GEOSPATIAL LOCATION**		
__SMS Update Required (Record Comments in Asset Notes)	___ Point	___ Line	___Area
__Asset Condition Changed __ Removed Asset	Primary Latitude: _____		Secondary Lat: _____
__Asset Replaced/Added	Primary Longitude: _____		Secondary Lon: _____

Asset Notes:	WT 11837164

Additional Notes:	WT 11837164

PROCEDURE STEP DETAILS			WT 11837164
STEP	**PROCEDURE TEXT**	**DURATION**	**PROCEDURE ID**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

[redacted]

1887113

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**IMARY WORK CATION**	TI MPLEX-9001
RESPONSIBLE ORG	TINKER AFB SYSTEM MX	**SPONSIBLE RSON**	
CUSTOMER ORG	TINKER AFB		
TASK TYPE		**INTED DATE**	M
EST HOURS		**LANNED END**	0 0
TASK NAME	CO - 3B - 90	ING ONTO FLOOR	7368784
TASK DESCRIPTION	THE URINAL 15SEP22 095 15SEP22 100 15SEP22 132 DIAPHRAM, U VERIFY DRAI	ST FLOOR MENS R N SITE AND DIAPHRAM F OFF URINAL, RETU	LED ING TO
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required	__Multi-Shop Coordination Required __Environmental Coordination Required	M/_____ Required ance Required

SERVICE REQUEST DETAILS 1887113

REQUEST ID	CREATED DATE/TIME	FULL NAME	PHONE

FACILITY PROJECT DETAILS 11887113

ASSET DETAILS WT 11887113

WARRANTY DETAILS WT 11887113

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11887113

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11887113

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

Primary Maintenance Reason Code **WT 11887113**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11887113**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11887113**

Additional Notes: **WT 11887113**

PROCEDURE STEP DETAILS **WT 11887113**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

WORK TASK 11479573

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	

CES

REQUEST CLASS Leaks — Mar 1, 2023, 2:29 PM

[redacted]

PLANNED START 06/10/2022 01:00:00

06/10/2022 01:00:00

- TAC HVAC - F/U 11403993 ASH HO - 582-4496

FROM 3 DIFFERENT SPOTS - REPAIR-

- TAC HVAC - F/U 11403993 ASH HO - 582-4496

FROM 3 DIFFERENT SPOTS - REPAIR-

ns Required __Multi-Shop Co

__ FD/SFS/COMM/_____ Coordination Required

equired __Environmenta

d __Travel/Access Clearance Required

WT 11479573

CREATED DATE/TIME
06/09/2022 15:57:06

WORK PHONE
405-582-4496

WT 11479573

WT 11479573

WT 11479573

AL PROPERTY WARRANTY NAME	**ID**	**BUILDING EQUIPMENT WARRANTY NAME**

CRAFTSMAN NOTES SECTION

WT 11479573

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11479573

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

Primary Maintenance Reason Code **WT 11479573**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11479573**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11479573**

Additional Notes: **WT 11479573**

PROCEDURE STEP DETAILS **WT 11479573**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

WORK TASK 11481253

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AERO COMPLEX-90
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	HVAC Service	**PRINTED DATE**	Mar 1, 2023, 2
EST HOURS		**PLANNED START**	06/10/2022 07:29:59	**PLANNED END**	06/10/2022 07:29:59
TASK NAME	3B - 9001 ASH HOUSE 32 F/U 11403993 - WT - TAC HVAC - CONDENSATION LEAK - REPAIR 582-4496				
TASK DESCRIPTION	9001 ASH HOUSE 32; CONDENSATION LEAK				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi-Shop Coordination Required		__ FD/SFS/COMM/_ Coordination Re	
	__ Digging Permit Required	__Environmental Coordination Required		__Travel/Access Clearan	

SERVICE REQUEST DETAILS

WT 114

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHO

FACILITY PROJECT DETAILS

WT 114

ASSET DETAILS

WT 114

WARRANTY DETAILS

WT 1148

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11481253

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11481253

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11481253**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11481253**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11481253**

Additional Notes: **WT 11481253**

PROCEDURE STEP DETAILS **WT 11481253**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11776765

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS** / **TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Other Plumbing Need	**TE**	Mar
EST HOURS	0	**PLANNED START**	08/24/2022 01:00:00	[redacted]	08/2 01:0
TASK NAME	3C - 9001 L31 breakroom - WT - Intplumb - Water heater, SR3095246			[redacted]	r leaks - - 622-7846 -
TASK DESCRIPTION	3C - 9001 L31 Breakroom - check water pressure, hot wat			[redacted]	ater leak 622.7846
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Co __Environmental	[redacted]	_____ quired ired __ T ce Required

SERVICE REQUEST DETAILS [redacted] 76765

REQUEST ID	CREATED DATE/TIME	[redacted]	ONE
3095246	08/23/2022 16:16:29		7846

FACILITY PROJECT DETAILS [redacted] 76765

ASSET DETAILS [redacted] 76765

WARRANTY DETAILS WT 11776765

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11776765

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11776765**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11776765**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11776765**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11776765**

Additional Notes: **WT 11776765**

PROCEDURE STEP DETAILS **WT 11776765**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K 11746063

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustai losed	**PRIMARY WORK LOCATION**	TIN COM
RESPONSIBLE ORG	TINKER AFB - S HVAC - BOS-BM	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB -		
TASK TYPE	ervices	**PRINTED DATE**	Mar
EST HOURS		**PLANNED END**	08/1 07:2
TASK NAME	3A - 9001 POST	CONDENSATE DRAIN - Repair -	R 5509580

TASK DESCRIPTION

CONDENSATE DOWN MAKING A PUDDLE MAKI

16AUG2022 072
16AUG2022 074 ON SITE
16AUG2022 094 ONDENSATE LINE COMING OFF OF THE NEW BUILDING WAS
TECHNICALLY G PROPERLY AND IT WAS FILLING THE AUX DRAIN PAN UP
TOP; WE LINED IT SO THAT WATER IS NOW DRAINING AS IT SHOULD BE;
CHAREGE 2HR

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Preca op Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Perm ental Coordination Required __ Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11746063

REQUEST ID	CREATED DATE/TI	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11746063

ASSET DETAILS

WT 11746063

WARRANTY DETAILS

WT 11746063

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11746063

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _

WT 11746063

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11746063**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11746063**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11746063**

Additional Notes: **WT 11746063**

PROCEDURE STEP DETAILS **WT 11746063**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11434312

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS TRACKING STATUS**	Completed	**PRIMARY WORK LOCATION**	PACE
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	(NU)
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE	Corrective	**REQUEST CLASS**	Other Plumbing Need		
EST HOURS	0	**PLANNED START**	06/01/2022 10:11:33		
TASK NAME	3B- 9001 POST M38 - WT - PLUMB INT - F/U 11413950 D [redacted] REP [redacted] 6227846 - SR#2952970				
TASK DESCRIPTION	3B - 9001 POST M-38 -WT - PLUMB INT - F/U 11413950 [redacted] S R [redacted] ND SINK AND NEEDS TO BE CAULKED BEFORE FLOORING CA [redacted] CABIN [redacted] RS.				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Co __Environmental [redacted] ed __ T		_____ uired ce Required

SERVICE REQUEST DETAILS

4312

REQUEST ID	CREATED DATE/TIME	
2952970	06/01/2022 10:09:03	NE 496

FACILITY PROJECT DETAILS

34312

ASSET DETAILS

34312

WARRANTY DETAILS

WT 11434312

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11434312

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11434312

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11434312**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11434312**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11434312**

Additional Notes: **WT 11434312**

PROCEDURE STEP DETAILS **WT 11434312**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

W K TASK 11746065

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
		RACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATE SYSTEM MX - PLUM BOS-BMC		FUELS R HRS -	**RESPONSIBLE PERSON**	
CUSTOMER ORG	T AFB X		9000 - 63G		
TASK TYPE	C ve	**R**	**T CLASS** Clogs	**RINTED DATE**	Mar 1, 2023, 10:04 PM
EST HOURS		**P**	**D START** 08/16 07:26	**LANNED END**	08/16/2022 07:26:19
TASK NAME	PO TOIL		NT PLUMB - HAN ACED - REPAIR	LL TOILET IS CLOGGED AND WON'T FLUSH & 582-4105	
TASK DESCRIPTION	1, P cal 22 note		ap Stall has a toil t 582-4105. ger to clear a ba	and wont flush, also needs toilet seat replaced. Any ow flush issue. All works fine. Tighten toilet seat as well.	
FOREMAN'S NOTES TO CRAFTSMEN	Pre g P	s	ed _Mu _En	tion Required dination Required	__ FD/SFS/COMM/_____ Coordination Required __ Travel/Access Clearance Required

SERVICE REQU AIL **WT 11746065**

REQUES	C	ED DATE/TIME	ULL NAME	WORK PHONE
30797	0	/2022 07:23:4	HAEL SMITH	(405) 582-4105

FACILITY PROJE AIL **WT 11746065**

ASSET DETAILS **WT 11746065**

WARRANTY DETAILS **WT 11746065**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11746065**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ **WT 11746065**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11746065**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11746065**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11746065**

Additional Notes: **WT 11746065**

PROCEDURE STEP DETAILS **WT 11746065**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TAS 11757366

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STAT TRACKIN STAT**	
PRIMARY WORK LOCATION	TINKER AEROSPACE COMPLEX-9001		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 -		
TASK TYPE	Corrective	**REQUEST CLA**	**TE** Mar 1, 2023, 10:07 PM
EST HOURS	0	**PLANNED STAR**	**D** 08/18/2022 08:27:56
TASK NAME	3C - 9001 POST M45 - WT - INT PLU & NEEDS TOILET SEAT REPLACED		TALL TOILET IS CLOGGED/WON'T FLUSH
TASK DESCRIPTION	3C - 9001 POST M45 - WT - INT PLU FLUSH & NEEDS TOILET SEAT REP		TALL TOILET IS CLOGGED AND WON'T 098
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required _ __ Digging Permit Required _En		d __ FD/SFS/COMM/_____ Coordination Required uired __ Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11757366

REQUEST ID	CREATED DATE/TIME		WORK PHONE
3085425	08/18/2022 08:26:2	S	(405) 739-5767

FACILITY PROJECT DETAILS

WT 11757366

ASSET DETAILS

WT 11757366

WARRANTY DETAILS

WT 11757366

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11757366

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ WT 11757366

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11757366**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11757366**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11757366**

Additional Notes: **WT 11757366**

PROCEDURE STEP DETAILS **WT 11757366**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1820646

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WO LOCATION**	OSPACE 001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - DLA AVIATION SS&D				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks		8:33 PM
EST HOURS	4	**PLANNED START**	09/02/2022 01:00:00		
TASK NAME	3B - 9001 POST M60 AND L60 - WT – TAC HVAC - CONDE				- 8553012
TASK DESCRIPTION	between post M-60 and L-60 we have a condensation leak,				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coo		_ /SFS/COMM/_____ Coordination Required
	__ Digging Permit Required		__Environmental C	ired	__Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11820646

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3112959	09/01/2022 12:38:50	405-855-3012

FACILITY PROJECT DETAILS

WT 11820646

ASSET DETAILS

WT 11820646

WARRANTY DETAILS

WT 11820646

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11820646

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11820646

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11820646**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11820646**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11820646**

Additional Notes: **WT 11820646**

PROCEDURE STEP DETAILS **WT 11820646**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	W K	11824762	
WORK TASK D			
TASK PRIORITY	ustain	PRIMARY WORK LOCATION	TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	B - SPEC RES - BOS	RESPONSIBLE PERSON	
CUSTOMER ORG	A N		
TASK TYPE	R S	PRINTED DATE	Feb 28, 2023, 8:31 PM
EST HOURS	E 22	PLANNED END	09/02/2022 14:38:27
TASK NAME	T	2 WATER LEAKING DOWN POLE, 3-4" FROM ELEC BOX	
TASK DESCRIPTION	D DI N	NG. WILL SEND TECH AFTER LUNCH	
FOREMAN'S NOTES TO CRAFTSMEN	red _ __ En	hop Coordination Required nmental Coordination Required	__ FD/SFS/COMM/___ Coordination Requi __Travel/Access Clearance

SERVICE REQUEST WT 118247

REQUEST I	TED DATE/TIME	FULL NAME	WORK PHON

FACILITY PROJECT WT 118247

ASSET DETAILS WT 11824762

WARRANTY DETAIL WT 11824762

ID	L PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11824762

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11824762

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11824762**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11824762**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11824762**

Additional Notes: **WT 11824762**

PROCEDURE STEP DETAILS **WT 11824762**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K 11530439

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustai sed	**PRIMARY WORK LOCATION**	TINKER COMPLE
RESPONSIBLE ORG	TINKER AFB - S HVAC - BOS-BM	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB -		
TASK TYPE	es	**PRINTED DATE**	Feb 28, 2
EST HOURS		**PLANNED END**	06/21/202 13:39:12
TASK NAME	3A - 9001 MEZZ	SATE PUMP LEAKING - REPAIR	S 582-1118
TASK DESCRIPTION	F/U WT IS 1153 CONDENSATE 21JUN2022 135 21JUN2022 140 21JUN2022 150 ISSUE. CLOSE WILL NEED TO	DROPPING WATER INTO THE C ON SITE EARED OUT LINE TO CONDENSATION PUMP TO MITIGATE INAL ISSUE BECAUSE IF LEAK IS NOT CORRECTED WE . 1.0 HR	
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precau __ Digging Perm	oordination Required l Coordination Required	__ FD/SFS/COMM/_____ Coordination Required __ Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11530439

REQUEST ID	CREATED DATE/TIM	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11530439

ASSET DETAILS

WT 11530439

WARRANTY DETAILS

WT 11530439

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11530439

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _

WT 11530439

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11530439**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11530439**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11530439**

Additional Notes: **WT 11530439**

PROCEDURE STEP DETAILS **WT 11530439**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11530905

WORK TASK DE					
TASK PRIORITY	m	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPACE COMPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	FB - SPEC MX TM - TAC S-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	FB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Mar 1, 2023, 2:41 PM
EST HOURS		**PLANNED START**	06/21/2022 14:47:35	**PLANNED END**	06/21/2022 14:47:35
TASK NAME	MEZZ 3 RM 103 - WT - TAC HVAC - FU 11530439 CONDENSATE PUMP LEAKING - REPAIR - 32-1118				
TASK DESCRIPTION	UP TO 11530439 TO MONITOR ORIGINAL ISSUE; IF LEAK IS NOT CORRECTED WE WILL N THE CONDENSATION PUMP				

FOREMAN'S NOTES TO CRAFTSMEN

_ Precautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_ Coordination Re _

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearan uired

SERVICE REQUEST DETAILS

WT 115

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PH

FACILITY PROJECT DETAILS

WT 1153 5

ASSET DETAILS

WT 11530905

WARRANTY DETAILS

WT 11530905

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11530905

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11530905

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11530905**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11530905**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11530905**

Additional Notes: **WT 11530905**

PROCEDURE STEP DETAILS **WT 11530905**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11874756

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	[redacted] CE
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	PM
EST HOURS		**PLANNED START**	09/13/2022 15:43:00	**PLANNED END**	
TASK NAME	3B - 9001 N MEZZ 3 RM 108 - WT - TAC HVAC - LARGE CHILL WATER LEAK -				- 5824497
TASK DESCRIPTION	LARGE CHILL WATER LEAK. This is just comfort cooling, Downgrade to 3B per re				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required OMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11874756

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11874756

ASSET DETAILS

WT 11874756

WARRANTY DETAILS

WT 11874756

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11874756

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11874756

Primary Maintenance Reason Code

WT 11874756

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

NOTES TO R&O ON ASSETS & LOCATION			WT 11874756
ASSET STATUS	**GEOSPATIAL LOCATION**		
__SMS Update Required (Record Comments in Asset Notes)	___ Point	___ Line	___ Area
__Asset Condition Changed __ Removed Asset	Primary Latitude: _____		Secondary Lat: _____
__Asset Replaced/Added	Primary Longitude: _____		Secondary Lon: _____

Asset Notes:	WT 11874756

Additional Notes:	WT 11874756

PROCEDURE STEP DETAILS			WT 11874756
STEP	**PROCEDURE TEXT**	**DURATION**	**PROCEDURE ID**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 12052008

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	[redacted]
		TRACKING STATUS	Maintenance Complete		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corr	**REQUEST CLASS**	Clogs		
EST HOURS	0	**PLANNED START**	10/18/2022 07:11:38		
TASK NAME	3C - [redacted] 405		KITCHEN - WT - INT PLUMB - SINK C [redacted] AIN [redacted] C [redacted] -		
TASK DESCRIPTION	Sink [redacted] kitchen area in Office 215 near confere [redacted] 900 d d POC [redacted] r 405-550-9580				
FOREMAN'S NOTES TO CRAFTSMEN	__ [redacted] ons Required __Multi-Shop Co [redacted] __ FD/SFS/COMM/_ Coordination Re _ [redacted] Required __Environmenta [redacted] d __ Travel/Access Clearan quired				

SERVICE REQUEST

WT 120

REQUEST I	CREATED DATE/TIME	WORK PH
318752	10/18/2022 07:08:09	405-736-8

FACILITY PROJECT

WT 120

ASSET DETAILS

WT 120

WARRANTY DETAIL

WT 12052008

ID	EAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12052008

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12052008

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12052008**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12052008**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12052008**

Additional Notes: **WT 12052008**

PROCEDURE STEP DETAILS **WT 12052008**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11610140

WORK TASK DETAIL

TASK PRIORITY	3B - Sus	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TIN COM PACE
		TRACKING STATUS			
RESPONSIBLE ORG	TIN HVA	EC MX TM - TAC		**RESPONSIBLE PERSON**	
CUSTOMER ORG	TIN	XW TAC 9000 - 63G			
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Mar 2 PM
EST HOURS		**PLANNED START**	07/10/2022 20:19:23	**PLANNED END**	07/1 20:1
TASK NAME	3B -	Post P36 and P37 - WT - TAC HVAC - chilled water line is leaking -			818-6609

TASK DESCRIPTION

Chill leaking, currently contained with pig mats
POC 582-4105

11JU UND CHILLED WATER LINE LEAKING, ISOLATED LEAK. LEAK NEEDS TO BE RECAULKED BUT
NEED RY, DOWNGRADE TO RETURN WHEN DRY. 0.5 HOUR LABOR

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS WT 11610140

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS WT 11610140

ASSET DETAILS WT 11610140

WARRANTY DETAILS WT 11610140

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11610140

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ WT 11610140

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11610140**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11610140**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11610140**

Additional Notes: **WT 11610140**

PROCEDURE STEP DETAILS **WT 11610140**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 149 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**STATUS**	Closed	**PRIMA LOCAT**	KER AEROSPACE MPLEX-9001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC			**RESPO PERSO**	
CUSTOMER ORG	TINKER AFB - 76 M	C 9000 - 63G			
TASK TYPE		**ST CLASS**	Building Services	**PRINT**	28, 2023, 6:40 PM
EST HOURS		**ED START**	06/14/2022 10:26:21	**PLANN**	4/2022 26:21
TASK NAME	3A - 9001 & Q25 A	WT - TAC HVAC - STOP LEAK - Repair			5824105

TASK DESCRIPTION

Q25 AND P25 TH VAC LINE THE IS CONDENSATING AN BOVE TOOL STATIONS, DRIPPING ONTO

14JUN2022 10:30 ON SITE
14JUN2022 10:55 : THE DUCTS ARE LEAKING DUE TO AMBIANT AIR AROUND THEM, DUCTS ARE IN CONDITIONED S THEY OPEN DOOR CONSTANTLY AND PIPES START SWEATING. WILL TALK WITH SUPERVISOR AN AT THE NEXT STEPS SHOULD BE. 0.5 HOUR LABOR INFORMED REQU HAT ONLY SOLUTION IS TO SHUT THE UNIT OFF. UNABLE TO STOP CONDENSATION OTHERWISE.

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precaut ed __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required
__ Digging Permit __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11498449

REQUEST ID	ED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11498449

ASSET DETAILS

WT 11498449

WARRANTY DETAILS

WT 11498449

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11498449

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11498449

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11498449**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11498449**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11498449**

Additional Notes: **WT 11498449**

PROCEDURE STEP DETAILS **WT 11498449**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11626130

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER COMPL
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Clogs	**PRINTED DATE**	Mar 1, 2
EST HOURS		**PLANNED START**	07/13/2022 11:44:58	**PLANNED END**	07/13/20 11:44:58
TASK NAME	3C - 9001 ROOF TOP Q/P 36/37 - WT - TAC STRUC- ROOF DRAIN CLOGGED - REPAIR 622-7846				
TASK DESCRIPTION					

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required
__ Digging Permit Required
__ Multi-Shop Coordination Required
__ Environmental Coordination Required
__ FD/SFS/COMM Coordination R ed
__ Travel/Access Clear Required

SERVICE REQUEST DETAILS

WT 11 130

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PH E

FACILITY PROJECT DETAILS

WT 11626130

ASSET DETAILS

WT 11626130

WARRANTY DETAILS

WT 11626130

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11626130

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11626130

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11626130**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11626130**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11626130**

Additional Notes: **WT 11626130**

PROCEDURE STEP DETAILS **WT 11626130**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11767388

WORK TASK DE					
TASK PRIORITY	Sustain	**STATUS** / **TRACKING STATUS**	Completed	**PRIMARY WORK LOCATION**	TINKER AEROSPAC COMPLEX-9001
RESPONSIBLE ORG	AFB - WATER AND FUELS MX - PLUMB INT - BOS-			**RESPONSIBLE PERSON**	
CUSTOMER ORG	AFB - 72 CES				
TASK TYPE	e	**REQUEST CLASS**	Clogs	E	Mar 1, 2023, 10:11 PM
EST HOURS		**PLANNED START**	08/22/2022 08:29:07		08/22/2022 08:29:07
TASK NAME	I ROOF TOP Q/P 36/37 - WT - INT PLUMB - F/U - 622-7846				IPE CLOGGED - REPAIR
TASK DESCRIPTION					
FOREMAN'S NOTES TO CRAFTSMEN	ty Precautions Required __ Digging Permit Required		__Multi-Shop Co __Environmental		__ FD/SFS/COMM/_ Coordination Re ed __Travel/Access Clearan uired

SERVICE REQUEST DETAILS WT 117

REQUEST ID	CREATED DATE/TIME	WORK PHO
3090294	08/22/2022 08:27:37	405-582-4496

FACILITY PROJECT DETAILS WT 11767388

ASSET DETAILS WT 11767388

WARRANTY DETAILS WT 11767388

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11767388

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11767388

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11767388**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11767388**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11767388**

Additional Notes: **WT 11767388**

PROCEDURE STEP DETAILS **WT 11767388**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11942944

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSPA COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER	TAC 9000 - 63G			
TASK TYPE	Correct	**UEST CLASS**	General Repairs	**TE**	Mar , 10:22
EST HOURS	0	**NNED START**	09/24/2022 01:00:00	**D**	09/ 01:
TASK NAME	3C - 90 405-73	6/37 WT – TAC STRUCTURES -		626130	clog
TASK DESCRIPTION	3C - 90 - 405-7 POC SEAL	36/37 - WT - ROOF - F/U 1176 PLUMBING SHOP 734-2753 -		DRAIN P 622-784	GED REQU
FOREMAN'S NOTES TO CRAFTSMEN	__ Saf __ Dig	quired d	__Multi-Shop Co __ Environmenta	ired __	S/CC dinat ess C

SERVICE REQUEST D **WT**

REQUEST I	ATED DATE/TIME	WOR
314990	23/2022 16:31:24	405

FACILITY PROJECT D **WT**

ASSET DETAILS **WT 11942944**

WARRANTY DETAILS **WT 11942944**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11942944**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11942944**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11942944**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11942944**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11942944**

Additional Notes: **WT 11942944**

PROCEDURE STEP DETAILS **WT 11942944**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11434267

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS TRACKING STATUS**	Completed	**PRIMARY WORK LOCATION**	PACE 1
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	(NU)
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks		
EST HOURS	0	**PLANNED START**	06/01/2022 10:08:24		
TASK NAME	3C- 9001 POST Q38 - WT - PLUMB INT - F/U 11404805 SR#2952957			EP	6227846 -
TASK DESCRIPTION	3C- 9001 POST Q38 - WT - PLUMB INT - F/U 11404805			EP	6227846
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop C __Environmenta	d __T	equired nce Required

SERVICE REQUEST DETAILS 11434267

REQUEST ID	CREATED DATE/TIME	ONE
2952957	06/01/2022 10:05:51	4496

FACILITY PROJECT DETAILS 11434267

ASSET DETAILS 11434267

WARRANTY DETAILS WT 11434267

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11434267

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11434267**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11434267**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11434267**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11434267**

Additional Notes: **WT 11434267**

PROCEDURE STEP DETAILS **WT 11434267**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

11988039

WORK TASK D

TASK PRIORITY	ust	Closed	**PRIMARY WORK LOCATION** TINKER AEROSPACE COMPLEX-9001
RESPONSIBLE ORG	B X		**RESPONSIBLE PERSON**
CUSTOMER ORG	B		
TASK TYPE		Building Services	**PRINTED DATE** Feb 28, 2023, 8:34 PM
EST HOURS		10/03/2022 11:34:49	**PLANNED END** 10/03/2022 11:34:49
TASK NAME		NT PLUMB - SINK SEPERATING FROM WALL CAUSING LEAK	
TASK DESCRIPTION	2 4 K	AWAY FROM THE WALL, THE DRAIN WAS SPLIT, AND THE P AS NG SINK FROM WALL, REPAIRED BRAKCET, REHUNG SINK C LL, REPLACED AP, SILICONED THE SINK TO THE WALL, CLEANED UP MESS, ISSUE ED. NO PARTS ORK TASK. 2.2 HOUR LABOR	
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety P ed __ Digging	__Multi-Shop Coordination Required __Environmental Coordination Required	__ FD/SFS/COMM Coordination R __Travel/Access Clearа uired

SERVICE REQUEST DETA **WT 11**

REQUEST I	C	ED DATE/TIME	FULL NAME	WORK P

FACILITY PROJECT DETA **WT 119880**

ASSET DETAILS **WT 119880**

WARRANTY DETAILS **WT 11988039**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11988039**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ **WT 11988039**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11988039**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11988039**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11988039**

Additional Notes: **WT 11988039**

PROCEDURE STEP DETAILS **WT 11988039**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11690407

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS** / **TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AEROSP COMPLEX-9001
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	T AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	C e	**REQUEST CLASS**	Leaks	**TE**	Mar 1, 2023, 6:01 P
EST HOURS	[redacted]	**PLANNED START**	08/01/2022 09:34:19	**D**	08/01/2022 09:34:19
TASK NAME	[redacted] Q52 - WT - INT PLUMB - MOP CLOSET FAUC - SR# 3054149				TURNED ON - REPAIR -
TASK DESCRIPTION	[redacted] Q52 - mop closet faucet leaks when turned on 2 otes - Replaced Sloan mop sink faucet with new				rks fine now.
FOREMAN'S NOTES TO CRAFTSMEN	[redacted] Precautions Required Permit Required	__Multi-Shop Co __Environmenta		d ired	__ FD/SFS/COMM/_ Coordination Re __ Travel/Access Clearan

SERVICE REQU AILS — **WT 116**

REQUES	CREATED DATE/TIME	WORK PH
30541	08/01/2022 09:32:55	(405) 622-

FACILITY PROJE AILS — **WT 116** 7

ASSET DETAILS — **WT 116** 7

WARRANTY DETAILS — **WT 11690407**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11690407**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ — **WT 11690407**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11690407**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11690407**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11690407**

Additional Notes: **WT 11690407**

PROCEDURE STEP DETAILS **WT 11690407**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 114110

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY LOCATIO**	E
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPON PERSON**	)
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs		M
EST HOURS	0	**PLANNED START**	05/26/2022 01:00:00		
TASK NAME	3B - 9001 POST Q58 - WT - INT PLUMB - ROOF DRAIN SR#2945388				5824496 -
TASK DESCRIPTION	3B-9001 POST Q58-WT-INT PLUMB-ROOF DRAIN CLO				96
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop C		SFS/COMM/_____ ordination Required
	__ Digging Permit Required		__Environmenta		cess Clearance Required

SERVICE REQUEST DETAILS

WT 11411081

REQUEST ID	CREATED DATE/TIME	WORK PHONE
2945388	05/25/2022 14:00:23	405-582-4496

FACILITY PROJECT DETAILS

WT 11411081

ASSET DETAILS

WT 11411081

WARRANTY DETAILS

WT 11411081

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11411081

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ WT 11411081

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11411081**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11411081**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11411081**

Additional Notes: **WT 11411081**

PROCEDURE STEP DETAILS **WT 11411081**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 12087711

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	TINK COMP
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	E	Mar 1
EST HOURS	0	**PLANNED START**	10/31/2022 07:58:42	D	10/31 07:58
TASK NAME	3B - 9001 Q58 - WT - INT PLUMB - UNCLOG ROOF DRAI			OOF LEAK	- 734-2753
TASK DESCRIPTION	Unclog roof drains causing roof leak Q58				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi-Shop Coo			__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required	__Environmental		ired	__Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 12087711

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3202634	10/31/2022 07:57:00	(405) 734-2753

FACILITY PROJECT DETAILS

WT 12087711

ASSET DETAILS

WT 12087711

WARRANTY DETAILS

WT 12087711

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12087711

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12087711

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12087711**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12087711**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12087711**

Additional Notes: **WT 12087711**

PROCEDURE STEP DETAILS **WT 12087711**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1477550

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WC LOCATION**	PACE 1
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIB PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW TAC 9000 - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DA**	50 PM
EST HOURS		**PLANNED START**	06/09/2022 11:17:51	**PLANNED EN**	
TASK NAME	3B - 9001 & MENS RR 113- WT - INT PLUMB - UNCLOG URINAL - Repair				- 7368784
TASK DESCRIPTION	URINAL IN ROOM 133 STOPPED UP, AND IS NOT OVERFLOWING AND H EAST END OF SOUTH ADMIN AREA				VER IT. LOCATED
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi-Shop Coordination Required		__ FD/SFS/COMM/_____ Coordination Required	
	__ Digging Permit Required	__Environmental Coordination Required		__Travel/Access Clearance Required	

SERVICE REQUEST DETAILS

WT 11477550

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11477550

ASSET DETAILS

WT 11477550

WARRANTY DETAILS

WT 11477550

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11477550

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11477550

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.