WORK TASK 11776764

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	R 01
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - AFTER HRS - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 448 SCMW - 66				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	
EST HOURS		**PLANNED START**	08/23/2022 16:14:14	**PLANNED END**	
TASK NAME	3A - 3001 Post 1AB194A Mech room 7 lower - WT - AFTER HVAC - Water leaking				0-6861
TASK DESCRIPTION	Water leaking in and outside mech room 23Aug2022 1623 Contacted Standridge/Aittchakcht, 1645 onsite, 2045 offsite.				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Require __Environmental Coordination Required		S /_____ Required e ce ance Required

SERVICE REQUEST DETAILS 1776764

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS WT 11776764

ASSET DETAILS WT 11776764

WARRANTY DETAILS WT 11776764

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11776764

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ WT 11776764

Primary Maintenance Reason Code WT 11776764

__ Abuse / Malevolent Act	__Accident/Event	__Corrosion	__Solid State	__Off-base Source	__Weather	__Tree/Vegetation
__ Cust Request/Directed	__Environmental	__Mechanical	__Structural	__Operator/Techn	__Wildlife	__Fire/Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

NOTES TO R&O ON ASSETS & LOCATION			WT 11776764
ASSET STATUS	**GEOSPATIAL LOCATION**		
__SMS Update Required (Record Comments in Asset Notes)	___ Point	___ Line	___ Area
__Asset Condition Changed __ Removed Asset	Primary Latitude: _____		Secondary Lat: _____
__Asset Replaced/Added	Primary Longitude: _____		Secondary Lon: _____

Asset Notes: **WT 11776764**

Additional Notes: **WT 11776764**

PROCEDURE STEP DETAILS **WT 11776764**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

ASK **11701632**

WORK TASK DETAILS

TASK PRIORITY	3C - Low	**ATUS CKING ATUS**	Completed Maintenance In Progress	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3001
RESPONSIBLE ORG	TINKER BOS-BMC		OP -	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER				
TASK TYPE		**LASS**	Other Interior Need	**PRINTED DATE**	Mar 3, 2023, 9:01 PM
EST HOURS		**TART**	08/05/2022 16:09:53	**PLANNED END**	08/05/2022 16:09:53
TASK NAME	3C - 3001 REPAIR -		UC - F/U 11699429 REPLACE DAMAGED CEILING TILES FROM HVAC LEAK - 734-9028		
TASK DESCRIPTION	F/U 11699		GED CEILING TILES FROM HVAC LEAK		

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety P __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11701632

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11701632

ASSET DETAILS

WT 11701632

WARRANTY DETAILS

WT 11701632

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11701632

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11701632

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11701632**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11701632**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11701632**

Additional Notes: **WT 11701632**

PROCEDURE STEP DETAILS **WT 11701632**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

35902

WORK TASK DE	
TASK PRIORITY	n
RESPONSIBLE ORG	
CUSTOMER ORG	4
TASK TYPE	
EST HOURS	
TASK NAME	9 6
TASK DESCRIPTION	C 00 10 ED C OR

ARY WORK ATION: TINKER AFB SITE 1-3001

PONSIBLE SON:

TED DATE: Mar 3, 2023, 9:17 PM

NED END: 08/12/2022 11:06:17

AIRS MECH RM STILL LEAKING - REPAIR

19266

ON SITE
NE, POURED A BUNCH OF WATER DOWN
ING PROPERLY AT THIS TIME. 2 HOURS

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required
__ Digging Permit Required
__Multi-Shop Coordination Required
__Environmental Coordination Required
__ FD/SFS/COMM/___ Coordination Requ
__Travel/Access Clearance

SERVICE REQUEST DETAILS WT 117359

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHON

FACILITY PROJECT DETAILS WT 117359

ASSET DETAILS WT 117359

WARRANTY DETAILS WT 11735902

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11735902

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ WT 11735902

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Primary Maintenance Reason Code **WT 11735902**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11735902**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11735902**

Additional Notes: **WT 11735902**

PROCEDURE STEP DETAILS **WT 11735902**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WOR TASK 11699429

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AFB
		BACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - HVAC SHO HRS - BOS-BMC		AFTER	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKE 448 SCMW				
TASK TYPE		**REQU**	**C** ervices	**PRINTED DATE**	Mar 3, 2023, 8
EST HOURS		**PLAN**	**S** 2	**PLANNED END**	08/05/2022 12:29:18
TASK NAME	3A - 3 734-9	4A - WT 21	TE	LEAKING FROM AIR HANDLER - REPAIR	
TASK DESCRIPTION	WAT THE ANY AIR POC 4AUG A LE STOP CLOS DOW CLOS	, CONT RE IS A H WET AN 582-9740 NOTIFIED HE CEILI ALLED T VAC SHO TE AT 173	D E A R W PL N OT	; LOOKS LIKE IT IS COMING FROM THE SE THE VIEW; POC WENT TO THE SECOND F DID NOT FIND ANYTHING, THINK IT MAY BE COMING - ONSITE AT 1651 NOTES: WENT TO POST 1AB1 94A; OND FLOOR MECH ROOM AND FOUND THE FLOOR D AND CLEANED THE FLOOR DRAIN; STOPPED THE L ES TO REPLACE CEILING TILES AT POST; CHARGE 4 MACHINE TO CLEAR CONDENSATE LINE; CHARGE 3	O S N D
FOREMAN'S NOTES TO CRAFTSMEN	__ S __ D	tions Requ d t Require		op Coordination Required ental Coordination Required	__ FD/SFS/COMM/____ Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST WT 11699429

REQUEST I	CREATED D	FULL NAME	WORK PHONE

FACILITY PROJECT D WT 11699429

ASSET DETAILS WT 11699429

WARRANTY DETAILS WT 11699429

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11699429

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11699429**

Primary Maintenance Reason Code **WT 11699429**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11699429**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11699429**

Additional Notes: **WT 11699429**

PROCEDURE STEP DETAILS **WT 11699429**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11430111

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	[redacted]
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	[redacted] N
CUSTOMER ORG	TINKER AFB - 448 SCMW - 66				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	[redacted] P
EST HOURS		**PLANNED START**	05/31/2022 13:26:09	**PLANNED END**	[redacted]
TASK NAME	3B - 3001 POST 1AB1-96H - WT - INT PLUMB - SINKS INOP/TOILET LEAK - RE[redacted]H[redacted]D - 6283214				
TASK DESCRIPTION	WOMENS RESTROOM, HAS 3 BAGGED SINKS INOP AND 1ST STALL TOILET L				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required
__ Multi-Shop Coordination Required
__ FD/SFS/COMM/_____ Coordination Required
__ Digging Permit Required
__ Environmental Coordination Required
__ Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11430111

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11430111

ASSET DETAILS

WT 11430111

WARRANTY DETAILS

WT 11430111

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11430111

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11430111

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11430111**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11430111**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11430111**

Additional Notes: **WT 11430111**

PROCEDURE STEP DETAILS **WT 11430111**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

UI

WORK TAS 11889464

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STA**	Co d	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3001
		TRACK STA	Aw Sc g		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-B			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 448 SCMW - 66				
TASK TYPE	Corrective	**REQUEST CL**	Ot m Ne	**PRINTED DATE**	Mar 6, 2023, 4:06 PM
EST HOURS	0	**PLANNED STA**	09 2 01	**PLANNED END**	09/16/2022 01:00:00
TASK NAME	3C - 3001 1AB1-99A MENS RR - W CLOGGED/BOTH ARE BAGGED -		NT - AIN E		ENSOR NOT WORKING PROPERLY&URINAL - 734-9028
TASK DESCRIPTION	Post Location 1AB1-99A. 1. Men's restroom sink senor not wo g pro DR 2. Men's restroom urinal is clogged. fC b ur				gged the sink.
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__M hop C __Environmen		dination Required __ FD/SFS/COMM/_____ Coordination Required oordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS — WT 11889464

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE
3135183	09/15/2022 14:31:30	KAIN MOTHERSHED	405-734-9028

FACILITY PROJECT DETAILS — WT 11889464

ASSET DETAILS — WT 11889464

WARRANTY DETAILS — WT 11889464

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11889464

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — WT 11889464

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Primary Maintenance Reason Code **WT 11889464**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11889464**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11889464**

Additional Notes: **WT 11889464**

PROCEDURE STEP DETAILS **WT 11889464**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 2063

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Completed	**PRIMAR LOCATIO**	TE 1-3001
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPON PERSON**	II(NU)
CUSTOMER ORG	TINKER AFB - 448 SCMW - 66				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**PRINTE**	6 PM
EST HOURS	0	**PLANNED START**	10/26/2022 11:37:16	**PLANNE**	
TASK NAME	3C - 3001 POST 1AB/106C - WT - INT PLUMB - TOILET IS CLOGGED				- 734-9028
TASK DESCRIPTION	Men's restroom at post 1AB1/106C, middle stall. Commode is clogged				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Re __Environmental Coordination		/COMM/_____ mation Required s Clearance Required

SERVICE REQUEST DETAILS

WT 12063006

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE
3191365	10/26/2022 11:35:04	ERNEST MALDONADO	(405)734-9028

FACILITY PROJECT DETAILS

WT 12063006

ASSET DETAILS

WT 12063006

WARRANTY DETAILS

WT 12063006

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12063006

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12063006

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12063006**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12063006**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12063006**

Additional Notes: **WT 12063006**

PROCEDURE STEP DETAILS **WT 12063006**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 1168465

WORK TASK DETAILS

TASK PRIORITY	1-Eme	**STATUS**	Closed	**PRIMARY W LOCATION**	TINKER AFB SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINK SYST	TER AND FUELS MB INT - BOS-BMC		**RESPONS PERSON**	
CUSTOMER ORG	TINK	SFS			
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED**	ar 6, 2023, 4:45 PM
EST HOURS		**PLANNED START**	07/29/2022 23:30:22	**PLANNED**	7/29/2022 3:30:22
TASK NAME	1 - 30	185 - WT - AFTER PLUMB - sink overflowing - repair -			734-3737
TASK DESCRIPTION	sink o Notifie 0004 - 0049 - becau operat	annot be contained 2329 Arrived and inspected all sinks, found no issues. Fou ter was hitting the floor drain but it just need to be wipe WT			nsate line nearby had a small puddle n is not clogged and everything is
FOREMAN'S NOTES TO CRAFTSMEN	__ Safe	tions Required	__Multi-Shop Coordination Req		__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required		__Environmental Coordination R		_Travel/Access Clearance Required

SERVICE REQUEST DETAILS — WT 11684654

REQUEST ID	CREATED DATE/TIME	FULL NAM	WORK PHONE

FACILITY PROJECT DETAILS — WT 11684654

ASSET DETAILS — WT 11684654

WARRANTY DETAILS — WT 11684654

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11684654

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11684654**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11684654**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11684654**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11684654**

Additional Notes: **WT 11684654**

PROCEDURE STEP DETAILS **WT 11684654**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK SK 1430979

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**TUS** **NG** **US** ompleted aintenance In rogress	**PRIMARY WO LOCATION** KER AFB SITE 1-3001
RESPONSIBLE ORG	TINKER AFB - STRUCTUR BOS-BMC	-	**RESPONSIBL PERSON**
CUSTOMER ORG	TINKER AFB - 4 CMW		
TASK TYPE	**EQUE**	**SS** lding es	**PRINTED DA** 7:27 PM
EST HOURS	**LANN**	**RT** 1/2 7:2	**PLANNED E**
TASK NAME	3B - 3001 POST 3A -	T UC	LEAKING - REPA 734-9868
TASK DESCRIPTION	WALL LEAKING ST 31MAY2022 16 REN DY D ON SITE 1620 p ave no access to the area. 1630 Kennedy/M ffsite ss.		
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Preca Requ ult oordination Requ S/COMM/_____ ination Required __ Digging Perm uire nvi al Coordination R re T ss Clearance Required		

SERVICE REQUEST DETAILS — WT 11430979

REQUEST ID	REAT TE/T	FULL NAM	WORK PHONE

FACILITY PROJECT DETAILS — WT 11430979

ASSET DETAILS — WT 11430979

WARRANTY DETAILS — WT 11430979

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11430979

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ — **WT 11430979**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11430979**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11430979**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11430979**

Additional Notes: **WT 11430979**

PROCEDURE STEP DETAILS **WT 11430979**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

RK TASK 11735317

WORK TASK DETAILS

TASK PRIORITY	3B - Me Sustain	**STATUS TRACKING STATUS**	Completed	**PRIMARY WORK LOCATION**	[redacted] ITE 1-3001
RESPONSIBLE ORG	TINKER [redacted] SYSTEM [redacted] BMC	[redacted] AND FUELS [redacted] NT - BOS-		**RESPONSIBLE PERSON**	[redacted] all(NU)
CUSTOMER ORG	TINKER [redacted]				
TASK TYPE	[redacted]	**QUEST CLASS**	Leaks	**PRINTED DATE**	M[redacted] 16 PM
EST HOURS	[redacted]	**ANNED START**	08/12/2022 09:37:05	**PLANNED END**	0[redacted]/2 0[redacted]:0
TASK NAME	3B - 300 [redacted] REPAIR	[redacted] WT - INT PLUMB - 14 LOWER FLOOR DRAIN HAS SMAL[redacted]A [redacted] CONCRETE - - 405-246-8579			
TASK DESCRIPTION	CAN BE [redacted] /BUCKET				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety ec Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11735317

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11735317

ASSET DETAILS

WT 11735317

WARRANTY DETAILS

WT 11735317

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11735317

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _

WT 11735317

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11735317**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11735317**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11735317**

Additional Notes: **WT 11735317**

PROCEDURE STEP DETAILS **WT 11735317**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

ORK SK 11768300

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3
RESPONSIBLE ORG	TINKER AFB - W AND SYSTEM MX - P NT	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 7 (CS		
TASK TYPE	U	**PRINTED DATE**	Mar 3, 2023, 9:28 PM
EST HOURS	N	**PLANNED END**	08/22/2022 10:36:03
TASK NAME	3A - 3001 MECH 6 4052487122		PLUMB - VERY LARGE WATER LEAK - GER
TASK DESCRIPTION	IN MECH ROOM ER LEAKING. WILL 6		RY LARGE WATER LEAK. PIPE ABOVE
	22AUG2022 103 FIE		
	22AUG2022 120 IL H		N SITE
	22AUG2022 150 H C		STOPPED UP, RAN SEWER MACHINE D N
	ISSUE RESOLV SE		3 HOURS LABOR
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precau equ		ation Required __ FD/SFS/COM Coordination
	__ Digging Perm re		rdination Required __Travel/Access Clea ed

SERVICE REQUEST DETAILS

WT 1 0

REQUEST ID	REA TE	FULL NAME	WORK

FACILITY PROJECT DETAILS

WT 1 0

ASSET DETAILS

WT 11768300

WARRANTY DETAILS

WT 11768300

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11768300

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11768300

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11768300**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11768300**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11768300**

Additional Notes: **WT 11768300**

PROCEDURE STEP DETAILS **WT 11768300**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

11774186

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustai	**PRIMARY WOR LOCATION**	INK FB SITE 1-3001
RESPONSIBLE ORG	TINKER AFB - W SYSTEM MX - P	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 7		
TASK TYPE	g Services	**PRINTED DATE**	ar 3, 9:35 PM
EST HOURS	022 3	**PLANNED END**	/2 :2
TASK NAME	3A - 3001 MECH	PLUMB - 2" DRAIN LEAKING	S 7345856
TASK DESCRIPTION	FLOOR DRAIN L 23AUG2022 103 23AUG2022 123 23AUG2022 153 COMPLETE WOR	R 405-248-7122 E LINE WITH SEWER MACHI	SU SOLVED. 3 HOURS LABOR.
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precau __ Digging Permit Required	_ lti-Shop Coordination Require __Environmental Coordination Requi	/SFS/COMM/_____ oordination Required T ccess Clearance Required

SERVICE REQUEST DETAILS

WT 11774186

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11774186

ASSET DETAILS

WT 11774186

WARRANTY DETAILS

WT 11774186

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11774186

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11774186

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11774186**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11774186**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11774186**

Additional Notes: **WT 11774186**

PROCEDURE STEP DETAILS **WT 11774186**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 12065217

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	E 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	I(NU)
CUSTOMER ORG	TINKER AFB - 448 SCMW - 66				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**PRINTED DATE**	9 PM
EST HOURS	0	**PLANNED START**	10/27/2022 01:00:00	**PLANNED END**	
TASK NAME	3C - 3001 Post 1AD85A - WT - INTPLUMB - handicap stall has clogged toilet - Er				34-9028 - SR3193258
TASK DESCRIPTION	men's restroom located at post 1AD/85A, handicap stall. Commode is clogged.				g.
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Required		/COMM/_____
	__ Digging Permit Required		__Environmental Coordination Required		nation Required s Clearance Required

SERVICE REQUEST DETAILS

WT 12065217

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE
3193258	10/26/2022 13:44:50	ERNEST MALDONADO	(405)734-9028

FACILITY PROJECT DETAILS

WT 12065217

ASSET DETAILS

WT 12065217

WARRANTY DETAILS

WT 12065217

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12065217

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12065217

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12065217**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12065217**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12065217**

Additional Notes: **WT 12065217**

PROCEDURE STEP DETAILS **WT 12065217**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11901564

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	TINKER
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	Chad V [redacted]
CUSTOMER ORG	TINKER AFB - AFSC				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**PRINTED DATE**	Mar 6, 2
EST HOURS	0	**PLANNED START**	09/19/2022 10:02:14	**PLANNED END**	09/19/2 10:02:1
TASK NAME	3B - 3001 MENS RR POST 1AD86 - WT - INT PLUMB - HANDICAP TOILET CLOGGED - 8921				N - 739-
TASK DESCRIPTION	Handicapped toilet clogged, mens restroom1AD 86 - THIS A 3B BECAUSE IT IS A HANDI				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Required		_ ed
	__ Digging Permit Required		__Environmental Coordination Required		__Trave Required

SERVICE REQUEST DETAILS

64

REQUEST ID	CREATED DATE/TIME	FULL NAME	E
3138746	09/19/2022 10:00:52	CHARLES SHELTON	1

FACILITY PROJECT DETAILS

564

ASSET DETAILS

WT 11901564

WARRANTY DETAILS

WT 11901564

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11901564

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ WT 11901564

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11901564**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11901564**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11901564**

Additional Notes: **WT 11901564**

PROCEDURE STEP DETAILS **WT 11901564**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 1901539

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Completed	**PRIMARY WOR LOCATION**	E 1-3001
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	)
CUSTOMER ORG	TINKER AFB - AFSC				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**PRINTED DAT**	0 PM
EST HOURS	0	**PLANNED START**	09/19/2022 10:00:58	**PLANNED END**	
TASK NAME	3C - 3001 MENS RR POST 1AF71 - WT - INT PLUMB - URINAL CLOGGED				N - 739-8921
TASK DESCRIPTION	Urinal clogged, mens restroom post 1AF 71				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Require		/COMM/_____ nation Required
	__ Digging Permit Required		__Environmental Coordination Requi		s Clearance Required

SERVICE REQUEST DETAILS

WT 11901539

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE
3138741	09/19/2022 10:00:02	CHARLES SHELTON	(405)739-8921

FACILITY PROJECT DETAILS

WT 11901539

ASSET DETAILS

WT 11901539

WARRANTY DETAILS

WT 11901539

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11901539

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11901539

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11901539**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11901539**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11901539**

Additional Notes: **WT 11901539**

PROCEDURE STEP DETAILS **WT 11901539**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11559170

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TIN 3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	Fr
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Ma
EST HOURS		**PLANNED START**	06/28/2022 09:38:11	**PLANNED END**	06 09
TASK NAME	3B - 3001 POST 1AF71A - WT - REPAIR - WATER FOUNTAIN CLOGGED - REPAIR				323-0319
TASK DESCRIPTION	WATER FOUNTAIN DRAIN IS CLOGGED AND HAS STANDING WATER; NOT OVE				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Required __Environmental Coordination Required		M/_____ Required __T arance Required

SERVICE REQUEST DETAILS 11559170

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS WT 11559170

ASSET DETAILS WT 11559170

WARRANTY DETAILS WT 11559170

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11559170

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ WT 11559170

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11559170**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11559170**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11559170**

Additional Notes: **WT 11559170**

PROCEDURE STEP DETAILS **WT 11559170**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11692204

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	[redacted]
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	[redacted]
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	[redacted]
EST HOURS		**PLANNED START**	08/01/2022 15:14:17	**PLANNED END**	[redacted]
TASK NAME	3B - 3001 POST AF77A - WT - INT PLUMB - CAMERA SEWER LINE - Repair - A				[redacted]
TASK DESCRIPTION	CAMERA SEWER LINE				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Required __Environmental Coordination Required		[redacted]

SERVICE REQUEST DETAILS 11692204

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS WT 11692204

ASSET DETAILS WT 11692204

WARRANTY DETAILS WT 11692204

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11692204

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ **WT 11692204**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11692204**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11692204**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11692204**

Additional Notes: **WT 11692204**

PROCEDURE STEP DETAILS **WT 11692204**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11460396

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	TINKER AFB SI
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - OC ALC FM				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Mar 3, 2023, 8:0
EST HOURS		**PLANNED START**	06/07/2022 09:37:57	**PLANNED END**	06/07/2022 09:37:57
TASK NAME	3B - 3001 POST 1AF77A - WT - INT PLUMB - JANITOR CLOSET LEAKING FAUCET - REPAIR - [redacted]S - 4172893				
TASK DESCRIPTION	JANITOR FAUCET LEAKING FAUCET, RUNNING INTO SINK				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Required		__ FD/SFS/COMM/___ Coordination Requ
	__ Digging Permit Required		__Environmental Coordination Required		__Travel/Access Clearance

SERVICE REQUEST DETAILS

WT 11460

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHON

FACILITY PROJECT DETAILS

WT 11460

ASSET DETAILS

WT 11460

WARRANTY DETAILS

WT 114603

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11460396

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11460396

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11460396**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11460396**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11460396**

Additional Notes: **WT 11460396**

PROCEDURE STEP DETAILS **WT 11460396**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

11807112

WORK TASK DETAILS

TASK PRIORITY	3A - High Susta	**PRIMARY WORK LOCATION**	T R 3001
RESPONSIBLE ORG	TINKER AFB - BMC	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB -		
TASK TYPE	ces	**PRINTED DATE**	M 2 M
EST HOURS		**PLANNED END**	0 5
TASK NAME	3A - 3001 1AF8	ROM CEILING IN OFFICE	N 7348604
TASK DESCRIPTION	WATER LEAKIN 30AUG22 1312 30AUG22 1319 30AUG22 1440 AND CONDENS TO LET THEM K AT THE MOMEN CREATE FOLLOW UP 3B TO ORDER A NEW CONDENSATE PUMP	ON SITE ND FOUND THAT A COND WE SHUT OFF THE UNIT A ES IT WILL STOP LEAKING W PUMP; CHARGE 1.5 HRS	TE S QUIT WORKING O HE REQUESTER I CREATING CAUSE R E THIS WT;
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required	__Multi-Shop Coordination Required __Environmental Coordination Required	FD/SFS/COMM/_____ Coordination Required el/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11807112

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11807112

ASSET DETAILS

WT 11807112

WARRANTY DETAILS

WT 11807112

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11807112

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11807112

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

Primary Maintenance Reason Code **WT 11807112**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11807112**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11807112**

Additional Notes: **WT 11807112**

PROCEDURE STEP DETAILS **WT 11807112**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11555336

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	K 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**RESPONSIBLE PERSON**	[redacted]
CUSTOMER ORG	TINKER AFB - AFSC				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	6 PM
EST HOURS	504	**PLANNED START**	06/27/2022 14:04:04	**PLANNED END**	18 04
TASK NAME	3B - 3001 POST 1AG72A - WT - HVACC - SEWER SMELL COMING FROM THE 635-7051				C epair - TOM COSTA -
TASK DESCRIPTION	SEWER SMELL COMING FROM THE HVAC VENTS. CHECKED THE LIFT STA SMELL IN THE HALLWAY OR THE RESTROOMS. POC CHUCK SHELTON 417				A DRY. CANNOT 3
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Required __Environmental Coordination Required		COMM/_____ ation Required rav Clearance Required

SERVICE REQUEST DETAILS

WT 11555336

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11555336

ASSET DETAILS

WT 11555336

WARRANTY DETAILS

WT 11555336

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11555336

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11555336

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11555336**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11555336**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11555336**

Additional Notes: **WT 11555336**

PROCEDURE STEP DETAILS **WT 11555336**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

	1 0030
WORK TASK DE	
TASK PRIORITY	Y WORK N TINKER AFB SITE 1-3001
RESPONSIBLE ORG	SIBLE
CUSTOMER ORG	
TASK TYPE	DATE Mar 6, 2023, 3:59 PM
EST HOURS	D END 08/24/2022 11:14:06
TASK NAME	ING FROM MECH ROOM AU16UPPER
TASK DESCRIPTION	NG TILES SATURATED THEN LEAKING N SITE EALED WITH CONCRETE AT THE DRA E CONDENSATE DRAIN SO THAT IT IS OSE WT; STRUCTURES WT IS 1178149
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Preca quired __ FD/SFS/COMM/_____ Coordination Required __ Digging Perm Required __ Travel/Access Clearance Req

SERVICE REQUEST DETAILS WT 11780030

REQUEST ID	AME	WORK PHONE

FACILITY PROJECT DETAILS WT 11780030

ASSET DETAILS WT 11780030

WARRANTY DETAILS WT 11780030

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11780030

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11780030**

Primary Maintenance Reason Code **WT 11780030**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11780030**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11780030**

Additional Notes: **WT 11780030**

PROCEDURE STEP DETAILS **WT 11780030**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 2062

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Completed	**PRIMARY LOCATIO**	3001
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPON PERSON**	
CUSTOMER ORG	TINKER AFB - 448 SCMW - 66				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**PRINTED**	
EST HOURS	0	**PLANNED START**	10/26/2022 11:34:52	**PLANNE**	
TASK NAME	3C - 3001 POST 1AH1/105A - WT - INT PLUMB - TOILET CLOGGED -				028
TASK DESCRIPTION	Men's restroom at post 1AH1/105A, handicap stall. the commode is clo				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Rec		M/_____ Required
	__ Digging Permit Required		__Environmental Coordination	d	arance Required

SERVICE REQUEST DETAILS 12062981

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE
3191344	10/26/2022 11:30:45	ERNEST MALDONADO	(405)734-9028

FACILITY PROJECT DETAILS WT 12062981

ASSET DETAILS WT 12062981

WARRANTY DETAILS WT 12062981

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 12062981

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 12062981**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12062981**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12062981**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12062981**

Additional Notes: **WT 12062981**

PROCEDURE STEP DETAILS **WT 12062981**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11903095

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AFB
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 448 SCMW - 66				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**PRINTED DATE**	Mar 6, 2023,
EST HOURS	0	**PLANNED START**	09/19/2022 11:33:02	**PLANNED END**	09/19/2022 11:33:02
TASK NAME	3C - 3001 POST 1AH1-106C MENS RR - WT - INT PLUMB - 1ST STALL TOILET CLOGGED - [redacted] 734-9028				
TASK DESCRIPTION	Post location: 1AH1-106C. Men's restroom first stall toilet is clogged. 22Sep22 Downey notes - Responded to a "Clog in the first stall". Plunged clog till it went down. All works fine now.				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Required __Environmental Coordination Required		__ FD/SFS/COMM/_ Coordination Req __Travel/Access Clearanc

SERVICE REQUEST DETAILS

WT 1190 5

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PH
3139152	09/19/2022 11:30:24	KOKAIN MOTHERSHED	405-734-9

FACILITY PROJECT DETAILS

WT 1190 5

ASSET DETAILS

WT 1190 5

WARRANTY DETAILS

WT 11903 95

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11903095

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11903095

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11903095**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11903095**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11903095**

Additional Notes: **WT 11903095**

PROCEDURE STEP DETAILS **WT 11903095**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11784604

WORK TASK DE					
TASK PRIORITY	ium	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-300
		TRACKING STATUS			
RESPONSIBLE ORG	AFB - ELECTRICAL S - SPRINKLERS - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	AFB - VACANT				
TASK TYPE	e	**REQUEST CLASS**	Other Interior Need	**PRINTED DATE**	Mar 3, 2023, 10:04 PM
EST HOURS		**PLANNED START**	08/25/2022 10:19:30	**PLANNED END**	08/25/2022 10:19:30
TASK NAME	1 POST 1AH71A - RS71 - WT - SPRINK - FU 11471111 FIRE SUPPERESSION LINE IS LEAKING - 205-0852 - STORM				EY
TASK DESCRIPTION	1 POST 1AH71A - RS71 - WT - SPRINKLER - FIRE SUPPERESSION LIN IS LEAKING. - REPAI - 2050852 - STORM FU 11471111 LISA HAGGARD 734-7083 DE -ADD SPRINKLER SHOP 8-24-2022				EY
FOREMAN'S NOTES TO CRAFTSMEN	ty Precautions Required ing Permit Required	__Multi-Shop Coordination Required __Environmental Coordination Required		__ FD/SFS/COMM/ Coordination R __Travel/Access Clearan	ired

SERVICE REQUEST DETAILS — WT 117

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PH
3099352	08/25/2022 10:17:11	LISA HAGGARD	405 734

FACILITY PROJECT DETAILS — WT 117

ASSET DETAILS — WT 11784604

WARRANTY DETAILS — WT 11784604

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11784604

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11784604**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11784604**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11784604**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11784604**

Additional Notes: **WT 11784604**

PROCEDURE STEP DETAILS **WT 11784604**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11672169

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS** / **TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AF
RESPONSIBLE ORG	TINKER AFB - STRUCTURE SHOP - BOS-BMC			**RESPONSIBLE PERSON**	Marvin King
CUSTOMER ORG	TINKER AFB - 448 SCMW - 66				
TASK TYPE		**REQUEST CLASS**	Other Interior Need	**PRINTED DATE**	Mar 3, 2023
EST HOURS		**PLANNED START**	07/27/2022 07:27:01	**PLANNED END**	07/27/2022 07:27:01
TASK NAME	3B - 3001 1AH84A - WT - STRUC - RELACE RUINED TILES FROM WATER LEAK - REPAIR - - 9906861				
TASK DESCRIPTION	REPLACE APPROX 10 CEILING TILES THAT WERE RUINED BY LEAKING DRAIN FOR AHU				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi-Shop Coordination Required		__ FD/SFS/COMM/___ Coordination Requ	
	__ Digging Permit Required	__Environmental Coordination Required		__Travel/Access Clearance	ed

SERVICE REQUEST DETAILS

WT 11672

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHON

FACILITY PROJECT DETAILS

WT 11672

ASSET DETAILS

WT 11672169

WARRANTY DETAILS

WT 11672169

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11672169

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11672169

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11672169**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11672169**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11672169**

Additional Notes: **WT 11672169**

PROCEDURE STEP DETAILS **WT 11672169**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K 11669244

WORK TASK DETAILS

TASK PRIORITY	3A - High Susta... Completed	**PRIMARY WO LOCATION**	T ... TE 1-3001
RESPONSIBLE ORG	TINKER AFB - BMC	**RESPONSIB PERSON**	
CUSTOMER ORG	TINKER AFB -		
TASK TYPE	ing Services	**PRINTED DA**	M ... 3 PM
EST HOURS		**PLANNED EN**	2022 21 / 0 1
TASK NAME	3A - 3001 1AH	EAK FROM AHU - REPAIR - E	- 9906861
TASK DESCRIPTION	LEAK COMING H, COMING FROM 2ND TO 1 LR 26JUL22 1030 WITH HVAC C 26JUL22 1030 26JUL22 1137 T THE DRAIN HAS STOPPED UP, PLUNGED DRAIN AND GOT IT GOING. NEED S THAT WERE RUINED, NEED FOR IT TO DRY UP FIRST. CLOSE WORK TASK.		
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Preca ti-Shop Coordination Required __ Digging Perm ironmental Coordination Required		__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11669244

REQUEST ID	C E	I	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11669244

ASSET DETAILS

WT 11669244

WARRANTY DETAILS

WT 11669244

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11669244

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _

WT 11669244

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11669244**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11669244**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11669244**

Additional Notes: **WT 11669244**

PROCEDURE STEP DETAILS **WT 11669244**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	WORK	**11672375**	
WORK TASK DE			
TASK PRIORITY	T	**PRIMARY WORK LOCATION**	TE 1-3001
RESPONSIBLE ORG	HVAC SHOP	**RESPONSIBLE PERSON**	(NU)
CUSTOMER ORG	448 SCMW - 6		
TASK TYPE	**REQUES**	ervices **PRINTED DATE**	4 PM
EST HOURS	**PLANNE**	2 **PLANNED END**	
TASK NAME	T 1AH87A - W 628-3214	NSATION DRIP PAN POSSIBLE	REPAIR
TASK DESCRIPTION	IN CLOSET H G; CONTACT	GE; BELIEVE IT IS FROM HVAC TO ACCESS 628-3214 - SENT	ION DRIP
FOREMAN'S NOTES TO CRAFTSMEN	autions Require rmit Required	hop Coordination Required nmental Coordination Required	/COMM/_ ination Req ss Clearanc uired

SERVICE REQUEST DETAILS **WT 1167**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHO

FACILITY PROJECT DETAILS **WT 1167**

ASSET DETAILS **WT 11672**

WARRANTY DETAILS **WT 11672375**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11672375**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ **Outage** **Outage Event ID#** __ __ __ __ __ **WT 11672375**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11672375**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11672375**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11672375**

Additional Notes: **WT 11672375**

PROCEDURE STEP DETAILS **WT 11672375**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

	11735226
WORK TASK DE	
TASK PRIORITY	ain
PRIMARY WORK LOCATION	TINKER AFB SITE 1-3001
RESPONSIBLE ORG	WA PLU
RESPONSIBLE PERSON	
CUSTOMER ORG	72 C
TASK TYPE	
RINTED DATE	Mar 6, 2023, 3:52 PM
EST HOURS	2 1
LANNED END	08/12/2022 09:22:15
TASK NAME	T 1A - 405 15
TASK NAME	OR DRAIN CLOGGED & FLOODING AREA - REPAIR -
TASK DESCRIPTION	927 - 930 J L I
TASK DESCRIPTION	N SITE
FOREMAN'S NOTES TO CRAFTSMEN	autio ti- rmit R d viro
	ation Required __ FD/SFS/COMM/_____ Coordination Required
	rdination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS — **WT 11735226**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — **WT 11735226**

ASSET DETAILS — **WT 11735226**

WARRANTY DETAILS — **WT 11735226**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11735226**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ — **WT 11735226**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11735226**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11735226**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11735226**

Additional Notes: **WT 11735226**

PROCEDURE STEP DETAILS **WT 11735226**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	WO	**ASK**	**11**		
WORK TASK DE					
TASK PRIORITY	ustain	**TATUS**	C	**PR**	INKER AFB SITE 1-3001
		CKING TATUS		**LO**	
RESPONSIBLE ORG	B - E CTR - SP KLE		-BMC	**RE P**	
CUSTOMER ORG	B - C LC				
TASK TYPE	**RE**	**LASS**		**P**	ar 3, 2023, 10:26 PM
EST HOURS	**PL**	**TART**		**P**	9/14/2022 3:17:41
TASK NAME	OST I70 - 417 3	A CON		NK	EAK FROM CEILING - CH
TASK DESCRIPTION	AS H BU TS T FOR	AS C OTES		WA SIT	SUE IS SPRINK. SEE NC
	2 085 AUS 8795	HTY,		AN	ONSITE (ALARM TECH G
	22 143 HA MEASUREMEN F T SYSTEM 3001- S-A PIPE WITH NEW EC BACK ON. WITH HE H HOURS LABOR SUE	A 10 FC KLER P ER MAK SYSTE THE ALA ED. CL		ACC E SH RET WE SYST . NO	AS LEAKING, TOOK A A NEW PIECE. DRAINED SITE AND REPLACED L ND 2123 TO TURN THE P VICE READING ALL NOR
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Preca ns R			dina	__ FD/SFS/COMM/__ Coordination Requ
	__ Digging Perm equ d			Coord	__Travel/Access Clearance d

SERVICE REQUEST DETAILS — **WT 11878692**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — **WT 11878692**

ASSET DETAILS — **WT 11878692**

WARRANTY DETAILS — **WT 11878692**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11878692**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11878692**

Primary Maintenance Reason Code **WT 11878692**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11878692**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11878692**

Additional Notes: **WT 11878692**

PROCEDURE STEP DETAILS **WT 11878692**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

ORK TASK	**11879567**		
WORK TASK DE			
TASK PRIORITY	**STATUS** Closed	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3001
	TRACKING STATUS		
RESPONSIBLE ORG	M SHOP - BOS-	**RESPONSIBLE PERSON**	
CUSTOMER ORG	C FM		
TASK TYPE	**EQUEST CLASS** Leaks	**PRINTED DATE**	Mar 6, 2023, 1:49 PM
EST HOURS	**LANNED START** 09/14/2022 08:17:41	**PLANNED END**	09/14/2022 08:17:41
TASK NAME	0 ANACONDA CONF RM - WT - ALARM - F/U 11878692 ACTIVE WATER LEAK FROM CEILING - - 417-2893		
TASK DESCRIPTION	P WITH WATER LEAK ON WT 11878692 RN ONSITE		
FOREMAN'S NOTES TO CRAFTSMEN	s Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required equired __Environmental Coordination Required __Travel/Access Clearance Required		

SERVICE REQUEST DETAILS — **WT 11879567**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — **WT 11879567**

ASSET DETAILS — **WT 11879567**

WARRANTY DETAILS — **WT 11879567**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11879567**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ — **WT 11879567**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11879567**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11879567**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11879567**

Additional Notes: **WT 11879567**

PROCEDURE STEP DETAILS **WT 11879567**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted] **SK** **11962546**

WORK TASK DETAILS

TASK PRIORITY	3A - H	**ATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3001
		KING ATUS			
RESPONSIBLE ORG	TINK SYS		-BMC	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINK				
TASK TYPE		**LASS**	Leaks	**PRINTED DATE**	Mar 6, 2023, 2:02 PM
EST HOURS		**TART**	09/28/2022 08:07:08	**PLANNED END**	09/28/2022 08:07:08
TASK NAME	3A - SYS	PRINK - HEARING LEAKING IN CEILING, SUSPECTS ITS THE FIRE SUPPRESSION - 736-8707			
TASK DESCRIPTION	EVID	CEILING TILES			
	0830 0930 ON T	E :SPRINKLER PIPE NOT NEAR IT, THINKS IT NEEDS TO GO TO PLUMBERS-WAITED HOW THEM THE LOCATION. 1 HOUR LABOR. NO PARTS			
FOREMAN'S NOTES TO CRAFTSMEN	__ S __ D	t t Required	__Multi-Shop Coordination Required __Environmental Coordination Required	__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required	

SERVICE REQUEST D **WT 11962546**

REQUEST I	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT D **WT 11962546**

ASSET DETAILS **WT 11962546**

WARRANTY DETAILS **WT 11962546**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11962546**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11962546**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11962546**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11962546**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11962546**

Additional Notes: **WT 11962546**

PROCEDURE STEP DETAILS **WT 11962546**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

UI

11 80

WORK TASK DETAILS

TASK PRIORITY	3B - M Susta
RESPONSIBLE ORG	TINK SYS
CUSTOMER ORG	TINK

R ORK

BLE

D
RS

ed

WT 11962880

WARRANTY DETAILS WT 11962880

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11962880

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11962880**

Primary Maintenance Reason Code **WT 11962880**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11962880**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___Area

Primary Latitude:_____ Secondary Lat:_____

Primary Longitude:_____ Secondary Lon:_____

Asset Notes: **WT 11962880**

Additional Notes: **WT 11962880**

PROCEDURE STEP DETAILS **WT 11962880**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11419293

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	[redacted]
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - OC ALC FM				
TASK TYPE		**REQUEST CLASS**	Leaks	**PRINTED DATE**	
EST HOURS		**PLANNED START**	05/27/2022 08:14:10	**PLANNED END**	
TASK NAME	3C - 3001 POST 1AJ75 - WT - INTPLUMB - TOILET LEAKING IN MENS RR - REP 405-417-2893				
TASK DESCRIPTION	MENS RESTROOM MAIN ENTRANCE, DOOR B TOILET IS LEAKING, STANDING FLUSHED				H
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi-Shop Coordination Required		__ FD/SFS/COMM/__ Coordination Req	
	__ Digging Permit Required	__Environmental Coordination Required		__Travel/Access Clearanc	

SERVICE REQUEST DETAILS

WT 1141

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHO

FACILITY PROJECT DETAILS

WT 11419

ASSET DETAILS

WT 11419293

WARRANTY DETAILS

WT 11419293

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11419293

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11419293

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11419293**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11419293**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11419293**

Additional Notes: **WT 11419293**

PROCEDURE STEP DETAILS **WT 11419293**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11655964

WORK TASK D			
TASK PRIORITY	**STATUS** Closed **TRACKING STATUS**	**PRIMARY WORK LOCATION**	1-3001
RESPONSIBLE ORG	B - WATER AND FUELS X - PLUMB INT - BOS-	**RESPONSIBLE PERSON**	NU)
CUSTOMER ORG	B - 76 MXW (CSAG-M) - 63G		
TASK TYPE	**REQUEST CLASS** Leaks	**TE**	PM
EST HOURS	**PLANNED START** 07/21/2022 09:47:35	**D**	
TASK NAME	ntrance E (1AJ-87E) - WT - INTPLUMB - Exterior 405-582-4340	rippi	by hand - Repair -
TASK DESCRIPTION	cet is leaking/dripping. The valve is closed (by ha E" (1AJ-87E).	place	ediately north of
FOREMAN'S NOTES TO CRAFTSMEN	Precautions Required __ Digging Permit Required	__Multi-Shop Coord __Environmental C	__ FD/SFS/COMM/_____ Coordination Required ired __ Travel/Access Clearance Required

SERVICE REQUEST DETAILS — WT 11655964

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3038492	07/21/2022 09:38:50	(405)582-4340

FACILITY PROJECT DETAILS — WT 11655964

ASSET DETAILS — WT 11655964

WARRANTY DETAILS — WT 11655964

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11655964

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11655964**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11655964**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11655964**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11655964**

Additional Notes: **WT 11655964**

PROCEDURE STEP DETAILS **WT 11655964**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1 1517

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Completed	**WORK**	3001
		TRACKING STATUS	Awaiting Scheduling	**N**	
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**IBLE**	
CUSTOMER ORG	TINKER AFB - AFSC				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**DATE**	M
EST HOURS	0	**PLANNED START**	09/19/2022 10:00:01		
TASK NAME	3C - 3001 MENS RR POST 2AB196H - WT - INT PLUMB			- C	- 739-8921
TASK DESCRIPTION	Urinal clogged, mens restroom post 2AB1 96H				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Co __Environmenta	d _	M/_____ n Required arance Required

SERVICE REQUEST DETAILS

11901517

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3138732	09/19/2022 09:58:53	(405)739-8921

FACILITY PROJECT DETAILS

WT 11901517

ASSET DETAILS

WT 11901517

WARRANTY DETAILS

WT 11901517

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11901517

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11901517

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11901517**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11901517**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11901517**

Additional Notes: **WT 11901517**

PROCEDURE STEP DETAILS **WT 11901517**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11441212

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	TINKER
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - OC ALC FM				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Mar 6,
EST HOURS		**PLANNED START**	06/02/2022 11:15:56	**PLANNED END**	06/02/2 11:15:5
TASK NAME	3B - 3001 POST 2AB1/109 MEN'S RR - WT - INT PLUMB - URINAL CLOGGED - REPAIR				N 417-2893
TASK DESCRIPTION	URINAL CLOGGED				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Required		_____ uired
	__ Digging Permit Required		__Environmental Coordination Required		__Trave e Required

SERVICE REQUEST DETAILS 1212

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS WT 11441212

ASSET DETAILS WT 11441212

WARRANTY DETAILS WT 11441212

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11441212

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11441212**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11441212**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11441212**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11441212**

Additional Notes: **WT 11441212**

PROCEDURE STEP DETAILS **WT 11441212**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 19079

WORK TASK DETAILS

TASK PRIORITY	1-Emergency	**STATUS**	Closed	**PRIMARY LOCATION**	B SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC			**RESPONS PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED D**	3, 5:05 PM
EST HOURS		**PLANNED START**	09/19/2022 18:31:11	**PLANNED**	
TASK NAME	1 - 3001 Post 2AE85A - WT - AFTER PLUMB - Men's restroom is flooding				409-2888

TASK DESCRIPTION

Men's restroom is flooding
Notified Frank Downey 1835, onsite 1847
19Sep2022
Downey notes - Responded to a 1A flooding in M.R.R. 2AE96A. No flooding or water on floor. Called requester to verify post location. Location was correct. Found a drip on 3rd urinal from right. It was dripping into urinal & was contained. tighten auto sensor. Stopped leak.

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required
__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11907956

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11907956

ASSET DETAILS

WT 11907956

WARRANTY DETAILS

WT 11907956

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11907956

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ WT 11907956

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11907956**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11907956**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11907956**

Additional Notes: **WT 11907956**

PROCEDURE STEP DETAILS **WT 11907956**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

TASK **11512665**

WORK TASK DETAILS

TASK PRIORITY	3B - Med Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	R 1-3001
		ACKING STATUS			
RESPONSIBLE ORG	TINKER SYSTEM	UELS OS-BMC		**RESPONSIBLE PERSON**	U)
CUSTOMER ORG	TINKER				
TASK TYPE		**T CLASS**	Building Services	**PRINTED DATE**	M
EST HOURS		**START**	06/16/2022 11:15:08	**PLANNED END**	
TASK NAME	3B - 3001 REPAIR -	- WT - INT PLUMB - URINAL CONTINUOUSLY FLU 409-2888			RFLOWING -
TASK DESCRIPTION	2AF76A - OVERFLO	TURN OFF; LAST TIME IT HAPPENED IT FLOODE			CURRENTLY
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety __ Digging	d d	__Multi-Shop Coordination Require __Environmental Coordination Required		MM/_____ ion Required learance Required

SERVICE REQUEST DETAILS **WT 11512665**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS **WT 11512665**

ASSET DETAILS **WT 11512665**

WARRANTY DETAILS **WT 11512665**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11512665**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ **Outage** **Outage Event ID#** __ __ __ __ __ **WT 11512665**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11512665**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11512665**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11512665**

Additional Notes: **WT 11512665**

PROCEDURE STEP DETAILS **WT 11512665**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 206

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Completed	**RIMA OCAT**	SITE 1-3001
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**ESPO ERSO**	NU)
CUSTOMER ORG	TINKER AFB - 448 SCMW - 66				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**RINTE**	4:27 PM
EST HOURS	0	**PLANNED START**	10/26/2022 11:40:20	**LAN**	
TASK NAME	3C - 3001 POST 2AF/71 - WT - INT PLUMB - TOILET IS			**GE**	- 734-9028
TASK DESCRIPTION	men's restroom at post 2AF/71. Clogged commode. Ne			be	
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop C	tio	FS/COMM/_____ ordination Required
	__ Digging Permit Required		__Environment	din	v cess Clearance Required

SERVICE REQUEST DETAILS

WT 12063040

REQUEST ID	CREATED DATE/TIME	U	WORK PHONE
3191396	10/26/2022 11:38:36	ST	(405)734-9028

FACILITY PROJECT DETAILS

WT 12063040

ASSET DETAILS

WT 12063040

WARRANTY DETAILS

WT 12063040

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12063040

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12063040

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12063040**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12063040**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12063040**

Additional Notes: **WT 12063040**

PROCEDURE STEP DETAILS **WT 12063040**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

		TASK	**11934888**		
WORK TASK DETAILS					
TASK PRIORITY	3A - High Susta	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKE 3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SYSTEM MX -		ELS S-BMC	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB -		-M) - 63G		
TASK TYPE		**CLASS**	Building Services	**PRINTED DATE**	Mar 6
EST HOURS		**START**	09/22/2022 15:07:10	**PLANNED END**	09/22 15:07
TASK NAME	3A - 3001 POST		- INT PLUMB - URINALS LEAKING FROM THE BACK -		- 4081339
TASK DESCRIPTION	MENS RESTRO		O URINALS LEAKING FROM THE BACK AGAINST TH		
	22Sep2022 153 to leak. No leak		s onsite, 1606 offsite notes: Flushed urinals several time solved close WT no parts needed.		to get any water
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Preca	d	__Multi-Shop Coordination Required		M/_____ Required
	__ Digging Perm	q d	__Environmental Coordination Required	__Tra	ance Required

SERVICE REQUEST DETAILS			**1934888**
REQUEST ID	**CREATED DATE/TIME**	**FULL NAME**	**PHONE**
FACILITY PROJECT DETAILS			**1934888**

ASSET DETAILS **11934888**

WARRANTY DETAILS **WT 11934888**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11934888**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ **WT 11934888**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11934888**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11934888**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11934888**

Additional Notes: **WT 11934888**

PROCEDURE STEP DETAILS **WT 11934888**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	[redacted] A K	11956927	
WORK TASK DE	[redacted]		
TASK PRIORITY	[redacted]	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3001
RESPONSIBLE ORG	[redacted]	**RESPONSIBLE PERSON**	
CUSTOMER ORG	[redacted]		
TASK TYPE	[redacted] ing	**PRINTED DATE**	Mar 6, 2023, 4:18 PM
EST HOURS	[redacted]	**PLANNED END**	09/28/2022 01:00:00
TASK NAME	[redacted] MB - TOILET CLOGGED & VERY CLOSE TO OVERFLOWING -		
TASK DESCRIPTION	[redacted] SOON !		
	27SEP22 1444 [redacted] ON SITE 27SEP22 1534 [redacted] UNGED TOILET & CLEANED UP AREA. CHARGE .8 HRS & CLOSE WORK NO PARTS REC		
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Preca [redacted] Coordination Required __ Digging Perm [redacted] d ental Coordination Required		__ FD/SFS/COMM/_____ Coordination Required __ Travel/Access Clearance Required

SERVICE REQUEST DETAILS — **WT 11956927**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE
3154410	09/27/2022 12:48:48	PATRICK PETERSEN	(405) 370-1490

FACILITY PROJECT DETAILS — **WT 11956927**

ASSET DETAILS — **WT 11956927**

WARRANTY DETAILS — **WT 11956927**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11956927**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11956927**

Primary Maintenance Reason Code **WT 11956927**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11956927**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11956927**

Additional Notes: **WT 11956927**

PROCEDURE STEP DETAILS **WT 11956927**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11416572

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	E 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	[redacted] (NU)
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Clogs	**PRINTED DATE**	PM
EST HOURS		**PLANNED START**	05/26/2022 12:06:25	**PLANNED END**	
TASK NAME	3B - 3001 POST 2AF73 MEN'S RR - WT - PLUMB INT - TOILET CLOGGED AND 736-8536				IR - RAY CANTWELL
TASK DESCRIPTION	TOILET CLOGGED AND BAGGED; OUT OF ORDER SIGN ON THE STALL DOO				ILET
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Require __Environmental Coordination Required		COMM/_____ ation Required Clearance Required

SERVICE REQUEST DETAILS

WT 11416572

REQUEST ID	CREATED DATE/TIME	FULL NAME	ORK PHONE

FACILITY PROJECT DETAILS

WT 11416572

ASSET DETAILS

WT 11416572

WARRANTY DETAILS

WT 11416572

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11416572

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11416572

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11416572**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11416572**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11416572**

Additional Notes: **WT 11416572**

PROCEDURE STEP DETAILS **WT 11416572**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 1

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**K**	SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC				(NU)
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	HVAC Service		9:31 PM
EST HOURS	168	**PLANNED START**	08/23/2022 01:00:00		
TASK NAME	3B - 3001 2 UPPER - WT - HVACC - 2 UPPER HAS A WA			ULL	56
TASK DESCRIPTION					
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coo __Environmental	red	SFS/COMM/_____ ordination Required cess Clearance Required

SERVICE REQUEST DETAILS

WT 11769912

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3091796	08/22/2022 13:53:42	4057345856

FACILITY PROJECT DETAILS

WT 11769912

ASSET DETAILS

WT 11769912

WARRANTY DETAILS

WT 11769912

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11769912

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11769912

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11769912**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11769912**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11769912**

Additional Notes: **WT 11769912**

PROCEDURE STEP DETAILS **WT 11769912**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed
		TRACKING STATUS	
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC		
CUSTOMER ORG	TINKER AFB - 72 CES		
TASK TYPE	Corrective	**REQUEST CLASS**	General Re
EST HOURS	168	**PLANNED START**	08/24/2022 08:07:47
TASK NAME	3B - 3001 Post 2AF 72A - WT - HVACC - Water leaki A2U		
TASK DESCRIPTION	3B - 3001 Post 2AF 72A - WT - HVACC - Water leaki A2U Air coil leaking a lot of water in side the fan deck & al		
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Sho __Environm

B SITE 1-3001

(NU)

9:51 PM

-9513 - UID 3001-AHU-

-9513 - UID 3001-AHU-

en at 819-2793

SFS/COMM/_____
ordination Required
cess Clearance Required

SERVICE REQUEST DETAILS

WT 11778523

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3096131	08/24/2022 08:00:36	405-734-3117

FACILITY PROJECT DETAILS

WT 11778523

ASSET DETAILS

WT 11778523

WARRANTY DETAILS

WT 11778523

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11778523

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11778523

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11778523**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11778523**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11778523**

Additional Notes: **WT 11778523**

PROCEDURE STEP DETAILS **WT 11778523**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

ORK TASK 11691618

WORK TASK DET

TASK PRIORITY	**STATUS** Closed	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3001
	TRACKING STATUS		
RESPONSIBLE ORG	R AND FUELS B AFTER HRS -	**RESPONSIBLE PERSON**	
CUSTOMER ORG	C FM		
TASK TYPE	**EQUEST CLASS** Building Services	**PRINTED DATE**	Mar 3, 2023, 8:56 PM
EST HOURS	**LANNED START** 08/01/2022 13:27:58	**PLANNED END**	08/01/2022 13:27:58

TASK NAME 3 6A - WT - INT PLUMB - URINAL IS LEAKING AND WATER IS ALL OVER THE FLOOR - REPAIR - - 409-2888

TASK DESCRIPTION U AND WATER IS ALL OVER THE FLOOR. REQUESTER SAYS SHE DOESNT KNOW IF A FLOOR D

02
Downey notes - Replaced diaphragm to correct overflow of water. Adjusted water flow as well.

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS WT 11691618

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS WT 11691618

ASSET DETAILS WT 11691618

WARRANTY DETAILS WT 11691618

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11691618

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ WT 11691618

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11691618**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11691618**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11691618**

Additional Notes: **WT 11691618**

PROCEDURE STEP DETAILS **WT 11691618**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

		K	11894062		
WORK TASK DETAILS					
TASK PRIORITY	3A - High Su	US Closed NG US	**PRIMARY WORK LOCATION**	ITE 1-3001	
RESPONSIBLE ORG	TINKER AFB SYSTEM MX	MC	**RESPONSIBLE PERSON**		
CUSTOMER ORG	TINKER AFB				
TASK TYPE		SS Building Services	**PRINTED DATE**	3 PM	
EST HOURS		RT 09/16/2022 15:09:32	**PLANNED END**		
TASK NAME	3A - 3001 PO	T PLUMB - LEAK IN MENS RESTROOM -		- 205-6973	
TASK DESCRIPTION	LEAK IN MEN THEY DO NO 16SEP22 153 16SEP22 155 PRESENT CL	E ROGERS REPORTED THAT THERE IS A S COMING FROM. ON SITE NE URINAL WAS STUCK OPEN, BUT COU .5 HOUR LABOR		N THE FLOOR AND LEAKS. NO ISSUE	
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Prec __ Digging Permit Required	__Multi-Shop Coordination Require __Environmental Coordination Require		/COMM/_____ nation Required Clearance Required	

SERVICE REQUEST DETAILS — **WT 11894062**

REQUEST ID	CREATED DATE/TIME	FULL NAME	ORK PHONE

FACILITY PROJECT DETAILS — **WT 11894062**

ASSET DETAILS — **WT 11894062**

WARRANTY DETAILS — **WT 11894062**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11894062**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11894062**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11894062**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11894062**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11894062**

Additional Notes: **WT 11894062**

PROCEDURE STEP DETAILS **WT 11894062**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11651515

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	TINKER AFB
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - OC ALC FM				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Mar 6, 2023,
EST HOURS		**PLANNED START**	07/20/2022 09:13:44	**PLANNED END**	07/20/2022 09:13:44
TASK NAME	3C - 3001 POST 2AH1102H MENS RR - WT - INT PLUMB - 1 TOILET IS CLOGGED - Repair - 7398921				
TASK DESCRIPTION	TOILET IS CLOGGED				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Required __Environmental Coordination Required		__ FD/S / Coor __Travel/Acce

SERVICE REQUEST DETAILS

WT 11651

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHO

FACILITY PROJECT DETAILS

WT 11651515

ASSET DETAILS

WT 11651515

WARRANTY DETAILS

WT 11651515

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11651515

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11651515

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11651515**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11651515**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11651515**

Additional Notes: **WT 11651515**

PROCEDURE STEP DETAILS **WT 11651515**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

W TASK 115

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STAT / ACKI / STAT**	**PRIM / LOCA** SITE 1-3001
RESPONSIBLE ORG	TINKER AFB - H BMC	C - B	**RESP / PERS** r(NU)
CUSTOMER ORG	TINKER AFB - 4	6	
TASK TYPE		**T CLA** ces	**PRIN** 30 PM
EST HOURS	504	**D STA** 7 7	**PLAN**
TASK NAME	3B - 3001 & 2AH	VACC S G - Repair -	906861
TASK DESCRIPTION	AT POST 2AH/7 STILL LEAKING. 7JUL22 1238 - M AND S N SITE. 07JUL2022 1538 TES: D AIN LINE; HAD WATER OUT OF DAR A NGRADE TO A MAKE SURE TH BAC A HRS LABOR FO	T AB AKING ONT T	AGED TILES AND IS D GET ALL THE SPECT LINES TO
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precau d u Coordination Req __ Digging Permi nv ntal Coordination		COMM/_____ ation Required Clearance Required

SERVICE REQUEST DETAILS

WT 11598674

REQUEST ID	CREATED DATE/TIME	FULL NAME	ORK PHONE

FACILITY PROJECT DETAILS

WT 11598674

ASSET DETAILS

WT 11598674

WARRANTY DETAILS

WT 11598674

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11598674

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _

WT 11598674

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11598674**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11598674**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11598674**

Additional Notes: **WT 11598674**

PROCEDURE STEP DETAILS **WT 11598674**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11390457

WORK TASK DE					
TASK PRIORITY	m	**STATUS**	Closed	**PRIMARY WORK LOCATION**	ITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	B - SPEC MX TM - R - BOS-BMC			**RESPONSIBLE PERSON**	(NU)
CUSTOMER ORG	TION SS&D				
TASK TYPE		**EST CLASS**	General Repairs	**PRINTED DATE**	M 44 PM
EST HOURS		**NED START**	05/20/2022 10:17:24	**PLANNED END**	0 1
TASK NAME	NSULATOR - F/U 11378870 DUCT WORK IS LEAKING 3				NSULATED - REPAIR -
TASK DESCRIPTION	NSULATOR - F/U 11378870 DUCT WORK IS LEAKING - 734-7083 ROOFERS FOUND AN ACTIVE DUCT LEAKING. ADD INSULATORS TO INSULATE AC				TO BE INSULATED -

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety uired __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Diggin d __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DET — WT 11390457

REQUEST I	TED DATE/TIME	FULL NAME	WORK PHONE
293731	0/2022 10:12:40	LISA HAGGARD	405 734 7083

FACILITY PROJECT DET — WT 11390457

ASSET DETAILS — WT 11390457

WARRANTY DETAILS — WT 11390457

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11390457

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11390457**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11390457**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11390457**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11390457**

Additional Notes: **WT 11390457**

PROCEDURE STEP DETAILS **WT 11390457**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

12080693

WORK TASK DETAILS

TASK PRIORITY	3A - High Susta	**PRIMARY WORK LOCATION**	T
RESPONSIBLE ORG	TINKER AFB - ROOF - BOS-B	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB -		
TASK TYPE		**PRINTED DATE**	M
EST HOURS		**PLANNED END**	
TASK NAME	3A - 3001 POST F/ E FROM CEILING IF FL 405-736-8720		-
TASK DESCRIPTION	3A - 3001 POST HC NG IF FLOODING LAB HVAC RESPON HE 2080508 28OCT22 1453 AND ON SITE 28OCT22 1523 RES WAS CONTAINED AND D T APPLIED. .5HR LABOR FO		0
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required	__Multi-Shop Coordination Required __Environmental Coordination Required	__ FD/SFS/COMM/_ Coordination Re ravel/Access Clearanc ed

SERVICE REQUEST DETAILS

WT 1208

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PH

FACILITY PROJECT DETAILS

WT 1208

ASSET DETAILS

WT 12080693

WARRANTY DETAILS

WT 12080693

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12080693

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12080693

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Primary Maintenance Reason Code **WT 12080693**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12080693**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12080693**

Additional Notes: **WT 12080693**

PROCEDURE STEP DETAILS **WT 12080693**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1 88587

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Active	**RY WORK ION**	SITE 1-3001
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINKER AFB - STRUCTURE SHOP - BOS-BMC			**NSIBLE N**	(NU)
CUSTOMER ORG	TINKER AFB - DLA AVIATION SS&D				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks	**D**	2:31 PM
EST HOURS	0	**PLANNED START**	10/31/2022 11:31:22	**ED**	
TASK NAME	3C - 3001 POST 2G81 - WT - STRUC - RECURRING LE			**NG GL**	- 855-3017
TASK DESCRIPTION	Bldg. 3001, Post 2G81, West Mezzanine, Recurring leak in ceiling, cannot determine if it's a roof le and now have indications of another active leak.			**Ce wa**	ed due to potential mold
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop C __Environmenta	**e on d _**	SFS/COMM/_____ ordination Required ccess Clearance Required

SERVICE REQUEST DETAILS

WT 12088587

REQUEST ID	CREATED DATE/TIME	NA	WORK PHONE
3203059	10/31/2022 11:25:55	M	405-855-3017

FACILITY PROJECT DETAILS

WT 12088587

ASSET DETAILS

WT 12088587

WARRANTY DETAILS

WT 12088587

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12088587

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ WT 12088587

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12088587**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12088587**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12088587**

Additional Notes: **WT 12088587**

PROCEDURE STEP DETAILS **WT 12088587**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted] **RK TASK** **11641544**

WORK TASK DETAIL

TASK PRIORITY	3C -	**STATUS**	Closed	**PRIMARY WO**	N
		TRACKING STATUS		**LOCATION**	SITE 1-3001
RESPONSIBLE ORG	TINK [redacted] SYS		D FUELS T - BOS-BMC	**RESPONSIB PERSON**	
CUSTOMER ORG	TINK				
TASK TYPE		**EST CLASS**	Building Services	**PRINTED DA**	8:46 PM
EST HOURS		**NED START**	07/18/2022 11:21:39	**PLANNED E**	
TASK NAME	3C -	T PLUMB - BREAKROOM SINK LEAK - REPAIR			205-6973
TASK DESCRIPTION	BREA OST 2J111: "For y using a bucket to catch water and the pipe has no e heard that the pipe in the w e t we don't want to try it out in case it leaks." POC M 291-0208 - SEN EM				
FOREMAN'S NOTES TO CRAFTSMEN	__ Sa eca quired	__Multi-Shop Coordination Requir			FS/COMM/_____ rdination Required
	__ Digging Permit Required	__Environmental Coordination Re			ess Clearance Required

SERVICE REQUEST DETAILS **WT 11641544**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS **WT 11641544**

ASSET DETAILS **WT 11641544**

WARRANTY DETAILS **WT 11641544**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11641544**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11641544**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11641544**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11641544**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11641544**

Additional Notes: **WT 11641544**

PROCEDURE STEP DETAILS **WT 11641544**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K 14351 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain [redacted] S Closed	**PRIMARY LOCATIO**	R AFB SITE 1-3001
RESPONSIBLE ORG	TINKER AFB - E SYSTEMS - SPR	**RESPON PERSON**	
CUSTOMER ORG	TINKER AFB - 7		
TASK TYPE	ices	**PRINTED**	2023, 7:30 PM
EST HOURS		**PLANNED**	022 9
TASK NAME	3A - 3001 POST	EAKING - REPAI	- 736-5776
TASK DESCRIPTION	SPRINKER LINE 01JUNE2022 12: 1JUNE2022 1215 01JUNE2022 14: CLOSE WORK T	AYING STREAM ON SITE AK ON FIRE SPRINKLER SYSTEM, ALL OPERATIONAL	TO 50 GAL TRASH CAN
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precau __ Digging Permit	Coordination Required tal Coordination Required	__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11435194

REQUEST ID		FULL NAME	WORK PHONE
	C		

FACILITY PROJECT DETAILS

WT 11435194

ASSET DETAILS

WT 11435194

WARRANTY DETAILS

WT 11435194

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11435194

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ WT 11435194

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11435194**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11435194**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11435194**

Additional Notes: **WT 11435194**

PROCEDURE STEP DETAILS **WT 11435194**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

ORK TASK 1158865

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS TRACKING STATUS**	Closed	**PRIMARY W LOCATION**	AFB SITE 1-3001
RESPONSIBLE ORG	TINKER AF BMC		HOP - C - BOS-	**RESPONSIE PERSON**	ice(NU)
CUSTOMER ORG	TINKE		(CSAG-M) - 63G		
TASK TYPE		**QUEST CLASS**	Building Services	**PRINTED D**	M 023, 8:26 PM
EST HOURS	504	**ANNED START**	07/05/2022 13:57:57	**PLANNED E**	0 22 1
TASK NAME	3B -	WT - HVACC - AHU HAS SMALL LEAK - REPAIR			A - 5824340 -AHUPR65
TASK DESCRIPTION	PER ABLE AHU POC 06Ju 0643 addr	IEVED, THE AHU IS LEAKING FROM CEILING, C ASIDE, HAVE PIG BLANKETS BESIDE 736-8784 d to notify us that the leak has increased to a constant stream from a steady drip. Needs to be out of hand		IN	H CONTAINERS, HAVE BEEN
FOREMAN'S NOTES TO CRAFTSMEN	__ S __ D	equired uired	__Multi-Shop Coordination Required __Environmental Coordination Required	__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required	

SERVICE REQUEST **WT 11588652**

REQUEST I	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT **WT 11588652**

ASSET DETAILS **WT 11588652**

WARRANTY DETAILS **WT 11588652**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11588652**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ **WT 11588652**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11588652**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11588652**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11588652**

Additional Notes: **WT 11588652**

PROCEDURE STEP DETAILS **WT 11588652**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 161 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMAR LOCAT**	TE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**RESPO PERSO**	(NU)
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks	**INT**	2 PM
EST HOURS	168	**PLANNED START**	07/12/2022 07:00:00	**AN**	
TASK NAME	3B - 3001 POST 2P65 - WT - HVACC - HVAC WATER LEAK			**EP**	0
TASK DESCRIPTION	Software office area has a water leak (steady steam) down th Likely HVAC related. This is leaking into office area near and or onto office equipm Mission impact - Yes				-65. n d r area).
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coord __Environmental C		__ FD/SFS/COMM/_____ Coordination Required ired __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11617736

REQUEST ID	CREATED DATE/TIME		WORK PHONE
3019590	07/12/2022 06:47:49	L	(405)582-4340

FACILITY PROJECT DETAILS

WT 11617736

ASSET DETAILS

WT 11617736

WARRANTY DETAILS

WT 11617736

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11617736

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11617736

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11617736**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11617736**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11617736**

Additional Notes: **WT 11617736**

PROCEDURE STEP DETAILS **WT 11617736**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1 903458

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**MARY WORK ATION**	ITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**PONSIBLE SON**	U)
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks	**TED DATE**	56 PM
EST HOURS	168	**PLANNED START**	09/19/2022 11:55:12	**D**	
TASK NAME	3B - 3001 POST 2P83 - WT - HVACC - WATER LEAKING			IT - M	- 7365776
TASK DESCRIPTION	water leaking from the HVAC unit on top of the mezzanine				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Co __Environmenta	ired	S/COMM/_____ ination Required ss Clearance Required

SERVICE REQUEST DETAILS

WT 11903458

REQUEST ID	CREATED DATE/TIME		WORK PHONE
3139249	09/19/2022 11:52:42	E	(405) 736-5776

FACILITY PROJECT DETAILS

WT 11903458

ASSET DETAILS

WT 11903458

WARRANTY DETAILS

WT 11903458

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11903458

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11903458

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11903458**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11903458**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11903458**

Additional Notes: **WT 11903458**

PROCEDURE STEP DETAILS **WT 11903458**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11920040

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TIN -3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Other Climate Control Need	E	Ma
EST HOURS	120	**PLANNED START**	09/21/2022 07:00:00	D	10 04
TASK NAME	3B - 3001 POST 2P83 - WT - BAS - WATER LEAKING FR			REPAIR	- 736-5776
TASK DESCRIPTION	3B - 3001 POST 2P83 - WT - HONEYWELL - WATER LEA PREVIOUS WT# 11903458 12OCT22 / ALLEN HONEYWELL NOTES/ FLUSHED DRA			C UNIT STOR	- 7365776
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Co __Environmental	ired __	M/_____ Required rance Required

SERVICE REQUEST DETAILS

11920040

REQUEST ID	CREATED DATE/TIME	RK PHONE
3143502	09/21/2022 06:13:36	5 734-5815

FACILITY PROJECT DETAILS

T 11920040

ASSET DETAILS

T 11920040

WARRANTY DETAILS

WT 11920040

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11920040

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11920040

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11920040**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11920040**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11920040**

Additional Notes: **WT 11920040**

PROCEDURE STEP DETAILS **WT 11920040**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

TASK 1

WORK TASK DETA

TASK PRIORITY	3A	**STATUS**	C	**PRI**	TINKER AFB SITE 1-3001
		ACKING STATUS		**LOC**	
RESPONSIBLE ORG	TI BM		C - BOS-	**RES PER**	
CUSTOMER ORG	TI		- 63G		
TASK TYPE		**SS**		**PRI**	Mar 3, 2023, 9:02 PM
EST HOURS		**RT**		**PLA**	08/05/2022 16:32:02
TASK NAME	3A	Po		- repair	736-8536 - ACCESS

TASK DESCRIPTION

Ce g to AC leak
PO 75-9
Not with 1652
05A
Stan cke his is an office in blad 3001. The doors are locked. We called
the re ha are closeing the night hvac shop and turning this over to the
day h
08AU N S
8AUG ATE FOUND THE DRAIN WAS STOPPED UP, THE PAN WAS
OVER IES AND VACCUUMS; USED NITROGEN TO FLUSH LINES
AND O C N OUT FOR THE UNIT; THE DRAINS ARE NOW CLEAR,
LEAK O G MORE MAINTENANCE TO DOUBLE CHECK AND MAKE
SURE ROP CREATE FOLLOW UP 3C WT; CHARGE 6HRS LABOR
AND W ; AVE SUBMIT A WT FOR STRUCTURES

FOREMAN'S NOTES TO CRAFTSMEN	__ Sa ns Requ	__Multi-Sh rdination Required	__ FD/SFS/COMM/_____ Coordination Required	
	__ Dig Require	__Environ Coordination Required	__Travel/Access Clearance Required	

SERVICE REQUEST D **WT 11701763**

REQUEST I	CREAT	E/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT D **WT 11701763**

ASSET DETAILS **WT 11701763**

WARRANTY DETAILS **WT 11701763**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11701763**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11701763**

Primary Maintenance Reason Code **WT 11701763**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11701763**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11701763**

Additional Notes: **WT 11701763**

PROCEDURE STEP DETAILS **WT 11701763**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee

WORK TASK 11770475

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	
		TRACKING STATUS	Maintenance Complete		
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - OC ALC FM				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	
EST HOURS	504	**PLANNED START**	08/22/2022 15:05:52	**PLANNED END**	
TASK NAME	3B - 3001 2Q73 - WT - HVACC - WATER LEAK REPEATEDLY SOAKING CEILIN [redacted] L 408-1339				
TASK DESCRIPTION	WATER LEAK FROM HVAC IS REPEATEDLY SOAKING CEILING TILES; FIRST [redacted] C, LINES FLUSHED; SECOND WT# FOR HVAC 11715106; REQUESTER IS STATING THA [redacted] RE STILL SAGGING AND ACTIVELY LEAKING EVEN AFTER BOTH OF THESE WORK TA [redacted] D; THERE IS AN OPEN WORK TASK FOR CEILING TILES TO BE REPLACED (11730114) BU [redacted] SE TILES REPLACED UNTIL THE HVAC ISSUE IS SOLVED;				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi-Shop Coordination Required		_ /S oo	_____ equired
	__ Digging Permit Required	__Environmental Coordination Required		__Travel/Access Clearance Required	

SERVICE REQUEST DETAILS

WT 11770475

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11770475

ASSET DETAILS

WT 11770475

WARRANTY DETAILS

WT 11770475

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11770475

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11770475

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee

Primary Maintenance Reason Code **WT 11770475**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11770475**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11770475**

Additional Notes: **WT 11770475**

PROCEDURE STEP DETAILS **WT 11770475**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

R T K	1812

WORK TASK DETAILS

TASK PRIORITY	3A - Hig lo	**PRIMAR LOCATIO**	R AFB SITE 1-3001
RESPONSIBLE ORG	TINKER BMC	**RESPON PERSON**	
CUSTOMER ORG	TINKER		
TASK TYPE		**PRINTED**	2023, 10:17 PM
EST HOURS		**PLANNE**	2022 25
TASK NAME	C/O - 3	HVAC LEAK -	- 736-8536
TASK DESCRIPTION	CEILING MXSG NOTES 31AUG NOT & 31AUG2 31AUG2 CONDE LABOR 1Sep22 up. No p	KING ONTO S 11701763, W ECH OUT AFT LU ONSITE ED AND SATURATED THE CEILING TILES, BLEW OUT TOMORROW TO ENSURE DRAINING PROPERLY. 1.5 HOUR pan. Adjusted inlet water valves to control water temp, cleaned	OR MENTIONED UNIT MAY BE D DRAIN ACCORDING TO VERIFY IF UNIT IS MXSG OR
FOREMAN'S NOTES TO CRAFTSMEN	__ Safet ordination Required __ Diggi red _E al Coordination Required		__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DET S — **WT 11812847**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — **WT 11812847**

ASSET DETAILS — **WT 11812847**

WARRANTY DETAILS — **WT 11812847**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11812847**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11812847**

Primary Maintenance Reason Code **WT 11812847**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11812847**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11812847**

Additional Notes: **WT 11812847**

PROCEDURE STEP DETAILS **WT 11812847**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

12079293

PRIMARY WORK LOCATION	TINKER AFB SITE 1-3001
RESPONSIBLE PERSON	
PRINTED DATE	Mar 6, 2023, 5:00 PM
PLANNED END	10/28/2022 09:55:08

D WOMEN BATHROOMS TOILETS OVERFLOWING - DAVID

OVERFLOWING ONTO THE FLOOR.

E ONSITE
UNGED AND UNCLOGGED FLUSHED TOILETS
Y VAC AND CLEANED UP MESS

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Pre quired __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging P d __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAIL **WT 12079293**

REQUEST ID	EATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS **WT 12079293**

ASSET DETAILS **WT 12079293**

WARRANTY DETAILS **WT 12079293**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 12079293**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ **WT 12079293**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Primary Maintenance Reason Code **WT 12079293**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12079293**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12079293**

Additional Notes: **WT 12079293**

PROCEDURE STEP DETAILS **WT 12079293**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11732869

WORK TASK D					
TASK PRIORITY		**STATUS**	Closed	**PRIMARY WORK LOCATION**	TE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	VAC SHOP - C - BOS-			**RESPONSIBLE PERSON**	(NU)
CUSTOMER ORG	6 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	M 3 PM
EST HOURS		**PLANNED START**	08/11/2022 14:40:41	**PLANNED END**	0 1
TASK NAME	2W81 - WT - HVACC - CONDENSATION LINE IS LEAKING ALL C AISLE - REPAIR - E 736-5776				
TASK DESCRIPTION					

FOREMAN'S NOTES TO CRAFTSMEN

utions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS — WT 11732869

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — WT 11732869

ASSET DETAILS — WT 11732869

WARRANTY DETAILS — WT 11732869

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11732869

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11732869**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11732869**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11732869**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11732869**

Additional Notes: **WT 11732869**

PROCEDURE STEP DETAILS **WT 11732869**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 1 9498

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**Y WORK**	
		TRACKING STATUS		**N**	
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**SIBLE**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**DATE**	
EST HOURS	0	**PLANNED START**	09/19/2022 07:53:04	**D D**	
TASK NAME	3C - 3001 POST 2W83 - WT - INT PLUMB - 1ST TOILET I			BAG	- 736-5776
TASK DESCRIPTION	mens 1st stool is clogged and bagged post 2W83				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coo __Environmental		quired ce Required

SERVICE REQUEST DETAILS

99498

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3138226	09/19/2022 07:51:25	(405) 736-5776

FACILITY PROJECT DETAILS

WT 11899498

ASSET DETAILS

WT 11899498

WARRANTY DETAILS

WT 11899498

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11899498

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11899498

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11899498**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11899498**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11899498**

Additional Notes: **WT 11899498**

PROCEDURE STEP DETAILS **WT 11899498**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK		**1**	**38**
WORK TASK DE			
TASK PRIORITY	**STATUS** Closed		Y
	TRACKING STATUS		N
RESPONSIBLE ORG	SHOP - C - BOS-		
CUSTOMER ORG	XW (CSAG-M) - 63G		
TASK TYPE	**REQUEST CLASS** Leaks		
EST HOURS	**PLANNED START** 09/29/2022 01:00:00		
TASK NAME	69 - WT - HVACC - VAV5 NOT INSUL - 622-7855		
TASK DESCRIPTION	aking at the duct, leaking on ceiling ti 82-4590 Cell (405)625-3001		
FOREMAN'S NOTES TO CRAFTSMEN	s Required __Multi-Shop Co equired __Environmental		av

[redacted]

ILING TILES -

XSG/MXDEI Bldg 3001

COMM/_____
ation Required
Clearance Required

SERVICE REQUEST DETAILS — **WT 11966388**

REQUEST ID	CREATED DATE/TIME		WORK PHONE
3156827	09/28/2022 13:05:07	LER	(405) 622-7855

FACILITY PROJECT DETAILS — **WT 11966388**

ASSET DETAILS — **WT 11966388**

WARRANTY DETAILS — **WT 11966388**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11966388**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ **WT 11966388**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11966388**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11966388**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11966388**

Additional Notes: **WT 11966388**

PROCEDURE STEP DETAILS **WT 11966388**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11613548

WORK TASK DE

TASK PRIORITY	n	**STATUS** Closed **TRACKING STATUS**	**PRIMARY WORK LOCATION** TINKER AFB SITE 1-3001
RESPONSIBLE ORG	PEC MX TM - SUB - BOS-BMC		**RESPONSIBLE PERSON**
CUSTOMER ORG	6 MXW (CSAG-M) - 63G		
TASK TYPE		**REQUEST CLASS** Building Services	N E Mar 3, 2023, 8:40 PM
EST HOURS		**PLANNED START** 07/11/2022 11:23:38	07/11/2022 11:23:38
TASK NAME	3S-69 - WT - MOLD - INSPECT AREA FOR 582-4340 - MOLD		AKING CHILLED WATER LINE - REPAIR
TASK DESCRIPTION	e is dripping on ceiling tiles the length of this l e complaining of respiratory issues. They suspe W uld o have the area inspected for mold, the pipe in		post: 3S-69). tiles have been damp for an extended other remedy and replace the ceiling tiles.
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required	__Multi-Shop Coord __Environmental Co	__ FD/SFS/COMM/_____ Coordination Required red __ Travel/Access Clearance Required

SERVICE REQUEST DETAILS WT 11613548

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3017871	07/11/2022 11:18:24	(405)582-4340

FACILITY PROJECT DETAILS WT 11613548

ASSET DETAILS WT 11613548

WARRANTY DETAILS WT 11613548

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11613548

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11613548

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11613548**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11613548**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11613548**

Additional Notes: **WT 11613548**

PROCEDURE STEP DETAILS **WT 11613548**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11949993

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**PRINTED DATE**	
EST HOURS	0	**PLANNED START**	09/27/2022 01:00:00	**PLANNED END**	
TASK NAME	3C - 3001 POST 3S-69 MENS RR - WT - INT PLUMB - CLOGGED URINAL, BAG				- 622-7855
TASK DESCRIPTION	Post 3S-69 Men Restroom has a clogged urinal, urinal bagged.				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Required __Environmental Coordination Required		es uired e Required

SERVICE REQUEST DETAILS 9993

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE
3151822	09/26/2022 12:36:48	MICHAEL KESSLER	(405) 622-7855

FACILITY PROJECT DETAILS WT 11949993

ASSET DETAILS WT 11949993

WARRANTY DETAILS WT 11949993

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11949993

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11949993

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11949993**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11949993**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11949993**

Additional Notes: **WT 11949993**

PROCEDURE STEP DETAILS **WT 11949993**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11708819

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	T TE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Building Services	**PRINTED DATE**	M 4 PM
EST HOURS		**PLANNED START**	08/08/2022 04:19:32	**PLANNED END**	0 0
TASK NAME	3B - Building 3001, post A-59 - WT - Sprink - Fire suppression line is leaking - repair				736-5776
TASK DESCRIPTION	The fire suppression line is leaking Bldg 3001 post A59.				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required __ F S/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11708819

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11708819

ASSET DETAILS

WT 11708819

WARRANTY DETAILS

WT 11708819

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11708819

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11708819

Primary Maintenance Reason Code

WT 11708819

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

NOTES TO R&O ON ASSETS & LOCATION **WT 11708819**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11708819**

Additional Notes: **WT 11708819**

PROCEDURE STEP DETAILS **WT 11708819**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

	W	K	11806338		
WORK TASK DETAILS					
TASK PRIORITY	3B - Medium Sustain	**US** Closed **NG** **US**	**PRIMARY WORK LOCATION**		3001
RESPONSIBLE ORG	TINKER AFB - HVA BMC	S-	**RESPONSIBLE PERSON**		
CUSTOMER ORG	TINKER AFB - 76 M	63G			
TASK TYPE		**SS** HVAC Service	**PRINTED DATE**	M	
EST HOURS	504	**T** 08/30/2022 12:12:01	**PLANNED END**		
TASK NAME	3B - 3001 POST A5	- F/U 11708819 WATER MAKE UP LINE LEA			- 736-5776
TASK DESCRIPTION	11708819 WAS CLO WATER LINE. REQ CONTAMINATE EQ 30AUG22 NOTIFIE	ITH NOTES THAT IT WAS NOT A FIRE SUP D TO CHECK ON STATUS & STATED WHATE OF ISSUE			UT A MAKE UP AS STARTED TO
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautio __ Digging Permit R	__Multi-Shop Coordination Required __Environmental Coordination Required			MM/_____ Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS — **WT 11806338**

REQUEST ID	TE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — **WT 11806338**

ASSET DETAILS — **WT 11806338**

WARRANTY DETAILS — **WT 11806338**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11806338**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11806338**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11806338**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11806338**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11806338**

Additional Notes: **WT 11806338**

PROCEDURE STEP DETAILS **WT 11806338**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	P	AFB SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC				
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs		023, 4:01 PM
EST HOURS	0	**PLANNED START**	08/30/2022 01:00:00		022 0
TASK NAME	3C - 3001 AHU-7 UPPER - WT - INT PLUMB - UNCLOG FLO				734-2753
TASK DESCRIPTION	UNCLOG FLOOR DRAIN AHU 7 UPPER				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordi __Environmental Co		FD/SFS/COMM/_____ Coordination Required el/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11799327

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3105065	08/29/2022 12:58:34	(405) 734-2753

FACILITY PROJECT DETAILS

WT 11799327

ASSET DETAILS

WT 11799327

WARRANTY DETAILS

WT 11799327

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11799327

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11799327

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11799327**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11799327**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11799327**

Additional Notes: **WT 11799327**

PROCEDURE STEP DETAILS **WT 11799327**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

K 11851890

WORK TASK DETAILS

TASK PRIORITY	3A - High Su	**PRIMARY WORK LOCATION**	TIN
RESPONSIBLE ORG	TINKER AFB SYSTEM MX	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB		
TASK TYPE		**PRINTED DATE**	M
EST HOURS		**PLANNED END**	09 07
TASK NAME	3A - 3001 AH 7286	OR DRAIN CLOGGED -	- 801-971-
TASK DESCRIPTION	AHU 9L CON 09SEP22 072 09SEP22 073 09SEP22 074 09SEP22 075 09SEP22 081 09SEP22 1018 DRAIN DRAINI	OWING ONTO FLOOR. , NEED TO TRANSFER ONSITE IMES, CLEANED UP WA K. 2 HOURS LABOR	OOM GE .2 HR SS, ISSUE RESOLVED,
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Preca __ Digging Perm	rdination Required Coordination Required __	/SFS/COMM/_____ oordination Required ccess Clearance Required

SERVICE REQUEST DETAILS

WT 11851890

REQUEST ID	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11851890

ASSET DETAILS

WT 11851890

WARRANTY DETAILS

WT 11851890

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11851890

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11851890**

Primary Maintenance Reason Code **WT 11851890**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11851890**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11851890**

Additional Notes: **WT 11851890**

PROCEDURE STEP DETAILS **WT 11851890**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

TASK	11496692		
WORK TASK DETAILS			
TASK PRIORITY	3A - High Sus	**STATUS** Closed	**PRIMARY WORK LOCATION** SITE 1-3001
		RACKING STATUS	
RESPONSIBLE ORG	TINKER AFB BMC	- C - BOS-	**RESPONSIBLE PERSON** (NU)
CUSTOMER ORG	TINKER AFB	G-M) - 63G	
TASK TYPE		**T CLASS** Building Services	**PRINTED DATE** 5:02 PM
EST HOURS		**D START** 06/14/2022 07:01:34	**PLANNED END**
TASK NAME	3A - 3001 Pos	ACC - room is being flooded by condensate from H	air - Sean Blake - 736-5776
TASK DESCRIPTION	HVAC unit is le 14JUN2022 7: 14JUN2022 10 SYSTEM WAS GOT LADDERS THE BACK OF REQUESTOR, IT IS MAD'S UNIT AND THAT IT HAS A STOPPED UP DRAIN. O CLOSE WORK TASK. CHARGE TIME 3 HRS	ate into work area SITE VAS ABLE TO LOCATE UNIT AFTER TALKING WIT TROL OFFICE IN A WHITE BLDG IN PRODUCTION CCESS, COULD NOT FIND UID. IT APPEARED TO OT ACCESSIBLE, WENT ON LANDING, FOUND IT	R. GED PRIMARY DRAIN, G. CALLED
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required	__Multi-Shop Coordination Require __Environmental Coordination Required	FS/COMM/_____ rdination Required ess Clearance Required

SERVICE REQUEST DETAILS — **WT 11496692**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — **WT 11496692**

ASSET DETAILS — **WT 11496692**

WARRANTY DETAILS — **WT 11496692**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11496692**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11496692**

Primary Maintenance Reason Code **WT 11496692**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11496692**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11496692**

Additional Notes: **WT 11496692**

PROCEDURE STEP DETAILS **WT 11496692**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

11700194

WORK TASK DE			
TASK PRIORITY	Closed	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3001
RESPONSIBLE ORG		**RESPONSIBLE PERSON**	
CUSTOMER ORG			
TASK TYPE	Building Services	**PRINTED DATE**	Mar 6, 2023, 5:04 PM
EST HOURS	08/05/2022 13:43:23	**PLANNED END**	08/05/2022 13:43:23
TASK NAME	INT PLUMB - FLOOR DRAIN PLUGGED & FLOODING AREA - REPAIR		
TASK DESCRIPTION	ONSITE DRAIN IS CLOGGED. TRANSFER TO PLUMBING SHOP TO CLEAR. . NO MATERIALS USED.		

FOREMAN'S NOTES TO CRAFTSMEN __ S __ D

__Multi-Shop Coordination Required

__ FD/SFS/COMM/_____ Coordination Required

__Environmental Coordination Required __Travel/Access Clearance Re

SERVICE REQUEST **WT 11700194**

REQUEST I	TE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT D **WT 11700194**

ASSET DETAILS **WT 11700194**

WARRANTY DETAILS **WT 11700194**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11700194**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ **WT 11700194**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11700194**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11700194**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11700194**

Additional Notes: **WT 11700194**

PROCEDURE STEP DETAILS **WT 11700194**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TAS			11418173		
WORK TASK DETAILS					
TASK PRIORITY	3C - Low Sustain	**STATU**	**PRIMARY WORK LOCATION**		SITE 1-3001
		TRACKIN STATU			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BM		**RESPONSIBLE PERSON**		(NU)
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) -				
TASK TYPE		**REQUEST CLA**	rvices	**PRINTED DATE**	3:09 PM
EST HOURS		**PLANNED STAR**		**PLANNED END**	
TASK NAME	3C - 3001 POST B79 - WT - INTPLUM		LOGGED - REPAIR - T2498		- 739-4975 - -
TASK DESCRIPTION	THE WEST HEAT TREAT PIT DRAIN WATER AROUND THE DRAIN POC		AT POST B79, NEEDS TO 739-4975 SENT VIA EMAIL		UT. HAS STANDING
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		op Coordination Require mental Coordination Require		SFS/COMM/_____ ordination Required a cess Clearance Required

SERVICE REQUEST DETAILS			WT 11418173
REQUEST ID	**CREATED DATE/TIME**	**FULL NAME**	**WORK PHONE**

FACILITY PROJECT DETAILS	WT 11418173

ASSET DETAILS	WT 11418173

WARRANTY DETAILS			WT 11418173
ID	**REAL PROPERTY WARRANTY NAME**	**ID**	**BUILDING EQUIPMENT WARRANTY NAME**

CRAFTSMAN NOTES SECTION					WT 11418173
ASSIGNED CRAFTSMAN NAME(S)	**DATE (MM/DD/YYYY)**	**TOTAL LABOR HOURS**	**OVERTIME HRS**	**TRAVEL TIME HRS**	

Resolution Description / Notes:	__ Outage	Outage Event ID# __ __ __ __ __	WT 11418173

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Primary Maintenance Reason Code **WT 11418173**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11418173**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11418173**

Additional Notes: **WT 11418173**

PROCEDURE STEP DETAILS **WT 11418173**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

8089

WORK TASK DETAILS

TASK PRIORITY	3A - High Susta	Completed	**RY WORK TION** TINKER AFB SITE 1-3001
RESPONSIBLE ORG	TINKER AFB - SYSTEM MX -		**NSIBLE N**
CUSTOMER ORG	TINKER AFB -		
TASK TYPE		Building Servic	**ED DATE** Mar 6, 2023, 4:41 PM
EST HOURS		06/28/2022 07:10:01	**NED END** 06/28/2022 07:10:01
TASK NAME	3A - 3001 Pos	inal Overflowing	- 405-589-0500
TASK DESCRIPTION	3001. Post loc 28JUN2022 7: 28JUN2022 7: 28JUN2022 9:	has a urinal sta N SITE URINAL, CLOSE	flowing when flushed SK, CHARGE 1.5 HRS
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Prec __ Digging Per	ed __Multi-Shop Co __Environmental Coordination Required	Required __ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS WT 11558089

REQUEST ID	EATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS WT 11558089

ASSET DETAILS WT 11558089

WARRANTY DETAILS WT 11558089

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11558089

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11558089

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11558089**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11558089**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11558089**

Additional Notes: **WT 11558089**

PROCEDURE STEP DETAILS **WT 11558089**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11567069

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TIN 001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Mar
EST HOURS		**PLANNED START**	06/29/2022 14:51:42	**PLANNED END**	06/2 14:5
TASK NAME	3B - 3001 MEN'S RR POST B95 - WT - INT PLUMB - URINAL CLOGGED - REPAIR -				736-5776
TASK DESCRIPTION	URINAL IN MEN'S RR AT POST B95 IS CLOGGED - SENT VIA EMAIL				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Required __Environmental Coordination Required		M/_____ Required __Tra rance Required

SERVICE REQUEST DETAILS 11567069

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS WT 11567069

ASSET DETAILS WT 11567069

WARRANTY DETAILS WT 11567069

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11567069

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11567069**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11567069**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11567069**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11567069**

Additional Notes: **WT 11567069**

PROCEDURE STEP DETAILS **WT 11567069**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

1813

WORK TASK DETAILS

TASK PRIORITY	3A - High Susta	**PRIMA LOCAT**	R AFB SITE 1-3001
RESPONSIBLE ORG	TINKER AFB - W SYSTEM MX -	**RESPO PERSO**	
CUSTOMER ORG	TINKER AFB - 7		
TASK TYPE		**PRINT**	2023, 4:54 PM
EST HOURS		**PLAN**	2022 01
TASK NAME	3A - 3001 MRR	FLOWING	36-5776
TASK DESCRIPTION	URINAL OVERF 31AUG2022 121 31AUG2022 124 31AUG2022 134 REPLACED URI	ON SITE AL; RAN SN GE 1HR AN	UG T AIN LINE; CLEARED CLOG;
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precau __ Digging Permi	Coordination __Environmental Coordinat	q d __ FD/SFS/COMM/_____ Coordination Required Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS — **WT 11813816**

REQUEST ID	D DATE/TIME	FULL ME	WORK PHONE

FACILITY PROJECT DETAILS — **WT 11813816**

ASSET DETAILS — **WT 11813816**

WARRANTY DETAILS — **WT 11813816**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11813816**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11813816**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

Primary Maintenance Reason Code **WT 11813816**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11813816**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11813816**

Additional Notes: **WT 11813816**

PROCEDURE STEP DETAILS **WT 11813816**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11759759

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	(NU)
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Clogs	**PRINTED DATE**	3:55 PM
EST HOURS		**PLANNED START**	08/18/2022 14:42:24	**PLANNED END**	
TASK NAME	3C - 3001 POST B95 WOMEN'S RR - WT - INT PLUMB - TOILET IS CLOGGED				E - 736-5776
TASK DESCRIPTION	SENT BY EMAIL				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Required __Environmental Coordination Required		SFS/COMM/_____ ordination Required _ cess Clearance Required

SERVICE REQUEST DETAILS

WT 11759759

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11759759

ASSET DETAILS

WT 11759759

WARRANTY DETAILS

WT 11759759

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11759759

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11759759

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11759759**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11759759**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11759759**

Additional Notes: **WT 11759759**

PROCEDURE STEP DETAILS **WT 11759759**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRI** / **LOC**	SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RES** / **PER**	(NU)
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks	**I**	:35 PM
EST HOURS	0	**PLANNED START**	05/14/20 01:00:00		
TASK NAME	3C - 3001 - WT - INT PLUMB - Back flow leaking				# 2925627 - UID: 3001-BFRP-PD100
TASK DESCRIPTION	BACK FLOW LEAKING; UID: 3001-BFRP-PD100			3 FER IM 280	
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi		n Required	__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required	__Envir		ation Required	__Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11363032

REQUEST ID	CREATED DATE/TIME	L NAME	WORK PHONE
2925627	05/13/2022 13:02:3	K HASHA	(405) 734-2753

FACILITY PROJECT DETAILS

WT 11363032

ASSET DETAILS

WT 11363032

WARRANTY DETAILS

WT 11363032

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11363032

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11363032

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11363032**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11363032**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11363032**

Additional Notes: **WT 11363032**

PROCEDURE STEP DETAILS **WT 11363032**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11564567

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	TINKER A
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 72 FSS RESTAURANT - 97				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Mar 6, 2
EST HOURS		**PLANNED START**	06/29/2022 09:32:38	**PLANNED END**	06/29/20 09:32:38
TASK NAME	3B - 3001 MAIN CAFE KITCHEN AJ64A - WT - INT PLUMB - DRAIN CLOGGED - Repair 5143354				
TASK DESCRIPTION	OFFICE NUMBER 7343161 ACROSS FROM MOP SINK, FLOOR DRAIN IN CHEMICAL ROOM STANDING WATER				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Required		_
	__ Digging Permit Required		__Environmental Coordination Required		__Travel ed

[redacted]

SERVICE REQUEST DETAILS

REQUEST ID	CREATED DATE/TIME	FULL NAME

FACILITY PROJECT DETAILS

ASSET DETAILS

WARRANTY DETAILS

WT 11564567

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11564567

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11564567

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11564567**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11564567**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11564567**

Additional Notes: **WT 11564567**

PROCEDURE STEP DETAILS **WT 11564567**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11695552

WORK TASK D					
TASK PRIORITY		**STATUS**	Completed	**PRIMARY WORK LOCATION**	E 1
		TRACKING STATUS			
RESPONSIBLE ORG	- WATER AND FUELS - PLUMB INT - BOS-			**RESPONSIBLE PERSON**	(N
CUSTOMER ORG	- 72 FSS RESTAURANT - 97				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	PM
EST HOURS		**PLANNED START**	08/02/2022 18:27:32	**PLANNED END**	
TASK NAME	IN CAFE KITCHEN - WT - INT PLUMB - DISHWASHER LINE LEAK 734-3161				AIR
TASK DESCRIPTION	R LINE LEAKING AT A T; HAS BEEN LEAKING FOR SEVERAL WE				MER

FOREMAN'S NOTES TO CRAFTSMEN

recautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/__ Coordination Req

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearanc uired

SERVICE REQUEST DETAILS WT 1169

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHO

FACILITY PROJECT DETAILS WT 11695

ASSET DETAILS WT 11695552

WARRANTY DETAILS WT 11695552

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11695552

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ WT 11695552

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11695552**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11695552**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11695552**

Additional Notes: **WT 11695552**

PROCEDURE STEP DETAILS **WT 11695552**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11773725

WORK TASK DE			
TASK PRIORITY	ain	**STATUS** Completed **TRACKING STATUS** Maintenance Complete	**PRIMARY WORK LOCATION**
RESPONSIBLE ORG	- HVAC SHOP - C - BOS-		**RESPONSIBLE PERSON**
CUSTOMER ORG	- 72 FSS RESTAURANT - 97		
TASK TYPE		**REQUEST CLASS** HVAC Service	
EST HOURS		**PLANNED START** 08/23/2022 09:31:50	
TASK NAME	IN CAFE KITCHEN - WT - HVACC - LEAK CH 734-3161		R C
TASK DESCRIPTION	IN CAFE KITCHEN - WT - HVACC - LEAK CH 734-3161 T# 11748687		R C
FOREMAN'S NOTES TO CRAFTSMEN	cautions Required ermit Required	__Multi-Shop Coor __Environmental C	S in ss quired ce Required

SERVICE REQUEST DETAILS — WT 11773725

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3093668	08/23/2022 09:26:03	405-734-5815

FACILITY PROJECT DETAILS — WT 11773725

ASSET DETAILS — WT 11773725

WARRANTY DETAILS — WT 11773725

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11773725

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11773725**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11773725**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11773725**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11773725**

Additional Notes: **WT 11773725**

PROCEDURE STEP DETAILS **WT 11773725**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WOR			12075647	
WORK TASK DETAILS				
TASK PRIORITY	3A - High Sustain	ed ance In s	**PRIMARY WORK LOCATION**	IN E SITE 1-3001
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP BMC		**RESPONSIBLE PERSON**	(NU)
CUSTOMER ORG	TINKER AFB - 72 FSS RES			
TASK TYPE	**REQUE**	Services	**PRINTED DATE**	2:28 PM
EST HOURS	**PLANN**	22	**PLANNED END**	
TASK NAME	3A - 3001 88710H - WT - HV	CEILING NEAR ELEC PANEL	R	ESHA - 734-3161
TASK DESCRIPTION	LEAK FROM CEILING NEAR 28OCT22 0739 HVACC TEC 28OCT22 0753 NOTES: THI SINKS, THERE IS A PINHOL PLUMBER. 28OCT22 .4HR LABOR 28OCT22 0813 CREATED A	TCHEN OF 3001 POST 88710 ON SITE A PLUMBING PROBLEM, LEA E. HVACC TECH HAS TILES R INT PLUMB WT 12078575		E WATER LINE THAT FEEDS D LADDER SET UP FOR
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required	__Multi-Shop Coordination Required __Environmental Coordination Required		__ FD/SFS/COMM/_____ Coordination Required avel/Access Clearance Required

SERVICE REQUEST DETAILS **WT 12075647**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS **WT 12075647**

ASSET DETAILS **WT 12075647**

WARRANTY DETAILS **WT 12075647**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 12075647**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 12075647**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12075647**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12075647**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12075647**

Additional Notes: **WT 12075647**

PROCEDURE STEP DETAILS **WT 12075647**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12078575

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustai	**PRIMARY WORK LOCATION**	TINKER AFB S
RESPONSIBLE ORG	TINKER AFB - W SYSTEM MX -	**ESPONSIBLE ERSON**	
CUSTOMER ORG	TINKER AFB - 7		
TASK TYPE		**RINTED DATE**	Mar 6, 2023, 2:
EST HOURS		**LANNED END**	10/28/2022 08:04:14
TASK NAME	3A - 3001 8871 734-3161		ROM CEILING NEAR ELEC PANE
TASK DESCRIPTION	LEAK FROM C 28OCT22 0739 28OCT22 0753 SINKS, THERE F/U 12075647 H 28OCT22 0757 28OCT22 0810 28OCT22 1030 MITAGATED LE PICKED UP PA		001 POST 88710H PROBLEM, LEAK IS DUE TO WAT CH HAS TILES REMOVED AND L TE OLATE FOR FURTHER REPAIR. PICKUP P TER LUNCH WT TO GO BACK AFTER LUNCH
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Preca __ Digging Perm		ation Required __ FD/SFS/COMM/_ Coordination Rec ordination Required __ Travel/Access Clearanc

SERVICE REQUEST DETAILS

WT 1207

REQUEST ID	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 12078575

ASSET DETAILS

WT 12078575

WARRANTY DETAILS

WT 12078575

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12078575

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 12078575**

Primary Maintenance Reason Code **WT 12078575**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12078575**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12078575**

Additional Notes: **WT 12078575**

PROCEDURE STEP DETAILS **WT 12078575**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1413073

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	[redacted] ITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	02 PM
EST HOURS		**PLANNED START**	05/25/2022 18:41:25	**PLANNED END**	
TASK NAME	3C - 3001 D100 - WT - INTPLUMB - LEAKING BACKFLOW - REPAIR - T0280				- 734-7148 - - BFRP-PD100
TASK DESCRIPTION	BACK FLOW LEAKING; UID: 3001-BFRP-PD100				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11413073

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11413073

ASSET DETAILS

WT 11413073

WARRANTY DETAILS

WT 11413073

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11413073

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11413073

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11413073**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11413073**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11413073**

Additional Notes: **WT 11413073**

PROCEDURE STEP DETAILS **WT 11413073**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11441188

WORK TASK D

TASK PRIORITY	**STATUS** Completed	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3001
	TRACKING STATUS		
RESPONSIBLE ORG	B - WATER AND FUELS X - PLUMB INT - BOS-	**RESPONSIBLE PERSON**	
CUSTOMER ORG	B - OC ALC FM		
TASK TYPE	**REQUEST CLASS** Building Services	**PRINTED DATE**	Mar 2, 2023, 7:31 PM
EST HOURS	**PLANNED START** 06/02/2022 11:13:26	**PLANNED END**	06/02/2022 11:13:26
TASK NAME	EN'S RR ENTRY OF DOOR E - WT - INT PLUMB - LEAKING AND CLOGGED TOILET - REPAIR 17-2893		
TASK DESCRIPTION	EAKING AND ANOTHER STOPPED UP; DOOR TO STALL IS LOCKED		

FOREMAN'S NOTES TO CRAFTSMEN

recautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/____ Coordination Requir

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance

[redacted]

SERVICE REQUEST DETAILS

WT 114411

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11441188

ASSET DETAILS

WT 11441188

WARRANTY DETAILS

WT 11441188

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11441188

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11441188

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11441188**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11441188**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11441188**

Additional Notes: **WT 11441188**

PROCEDURE STEP DETAILS **WT 11441188**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

2027193

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**IMARY WORK CATION**	SITE 1-3001
RESPONSIBLE ORG	TINKER AFB - W SYSTEM MX - P	**SPONSIBLE RSON**	
CUSTOMER ORG	TINKER AFB - 7		
TASK TYPE		**INTED DATE**	:18 PM
EST HOURS		**LANNED END**	
TASK NAME	3A - 3001 POST	W PREVENTER	- 736-5776
TASK DESCRIPTION	REQUESTER S T STOPPAGE. PO 12OCT2022 085 12OCT2022 090 O 12OCT2022 100 N EAKING AND TUR AND ANOTHER ON. MET WITH REQ AT B T G ON. THEY TURN CKUP. THERE IS ANOTHER OPE E CAN CLOSE BECAUSE THERE IS NO LONGER A WORK STOPPAGE. 1HR LABOR. NO PARTS NEEDE	DI SHOP SAID T	RGENCY. WORK

FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Preca ired	__Multi-Shop Coordination Required	__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Perm	__Environmental Coordination Required	__Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 12027193

REQUEST ID	C	ATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 12027193

ASSET DETAILS

WT 12027193

WARRANTY DETAILS

WT 12027193

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12027193

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 12027193**

Primary Maintenance Reason Code **WT 12027193**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12027193**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12027193**

Additional Notes: **WT 12027193**

PROCEDURE STEP DETAILS **WT 12027193**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 1

WORK TASK DETA

TASK PRIORITY	3C	**STATUS**	Closed	K	-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TI BO	C SHOP - PM -			
CUSTOMER ORG	TI	XW (CSAG-M) - 63G			
TASK TYPE	Co	**REQUEST CLASS**	General Repa		
EST HOURS	0	**PLANNED START**	09/27/2022 01:00:00		
TASK NAME	3C	W and P19E - WT - HVAC PM - Vac			582-9513
TASK DESCRIPTION	3C PO	W and P19E - WT - HVAC PM - Vac		S	582-9513
FOREMAN'S NOTES TO CRAFTSMEN	__ __ D	ons Required Required	__Multi-Shop __Environmen	/	MM/_____ on Required earance Required

SERVICE REQUEST — **T 11951238**

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3152026	09/26/2022 13:38:07	405-734-3117

FACILITY PROJECT DETAILS — **WT 11951238**

ASSET DETAILS — **WT 11951238**

WARRANTY DETAILS — **WT 11951238**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11951238**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11951238**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11951238**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11951238**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11951238**

Additional Notes: **WT 11951238**

PROCEDURE STEP DETAILS **WT 11951238**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK [redacted]9

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed
		TRACKING STATUS	
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC		
CUSTOMER ORG	TINKER AFB - 72 CES		
TASK TYPE	Corrective	**REQUEST CLASS**	General R
EST HOURS	0	**PLANNED START**	09/16/202 01:00:00
TASK NAME	3C - 3001 G40 - WT - PIPE - CHILL WATER LEAK		
TASK DESCRIPTION	3C- 3001 G40- WT- TAC PIPEFITTING- CHILL WA		
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi-S	
	__ Digging Permit Required	_Enviro	

TINKER AFB SITE 1-3001

[redacted]

ar 6, 2023, 1:50 PM

9/16/2022 1:00:00

582-4496

__ FD/SFS/COMM/_____ Coordination Required

_Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11889092

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3135033	09/15/2022 13:55:4	405-582-4496

FACILITY PROJECT DETAILS

WT 11889092

ASSET DETAILS

WT 11889092

WARRANTY DETAILS

WT 11889092

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11889092

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11889092

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11889092**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11889092**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11889092**

Additional Notes: **WT 11889092**

PROCEDURE STEP DETAILS **WT 11889092**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted] 12 8

WORK TASK DETAILS

TASK PRIORITY	3A - High Su leted ng duling	**PRIM LOC**	**OR** KER AFB SITE 1-3001
RESPONSIBLE ORG	TINKER AFB SH BMC	**RES PER**	LE
CUSTOMER ORG	TINKER AFB		
TASK TYPE	EC ng Services	**PRIN**	T 6, 2023, 5:06 PM
EST HOURS	LA /2022 :24	**PLA**	28/2022 58:24
TASK NAME	3A - 3001 PO W ENTS FLOODING -		N - 405-736-8772
TASK DESCRIPTION	ENVIROMEN IN D VENTS ARE FLO , SE IN CEILING HAS BUSTED FLOODING T TH STOPPAGE. 28OCT22 14 FIE 28OCT22 141 EL 28OCT22 144 S: ISSUE, A TEMP HOS R M THE CEILING TO DRAIN ROOF, THE CONNEC AS ED THE LAB TO FLO OPENED F/U R R NO PARTS USED .5HR LABOR		
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __Multi-Shop Coordination e __ FD/SFS/COMM/_____ Coordination Required __ Digging Permit Required __Environmental Coordinat qu ravel/Access Clearance Required		

SERVICE REQUEST DETAILS **WT 12080508**

REQUEST ID	CREATED DATE/TIME	FULL	WORK PHONE

FACILITY PROJECT DETAILS **WT 12080508**

ASSET DETAILS **WT 12080508**

WARRANTY DETAILS **WT 12080508**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 12080508**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 12080508**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12080508**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12080508**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12080508**

Additional Notes: **WT 12080508**

PROCEDURE STEP DETAILS **WT 12080508**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11848305

WORK TASK DETAILS

TASK PRIORITY	3A - High Sus	**PRIMARY WORK LOCATION**	TINKE 1-3001
RESPONSIBLE ORG	TINKER AFB BMC	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB		
TASK TYPE		**PRINTED DATE**	Mar 3 PM
EST HOURS		**PLANNED END**	09/08 13:54
TASK NAME	3A - 3001 POS		R LEAK FROM 3 DIFF AREAS - - 736-5776
TASK DESCRIPTION	HAVE GALLO 08SEP22 135 08SEP22 140 08SEP22 1443 USED. CLOSE	LL W	ENT CC ON SITE. E, SWITCH TO PIPE FITTERS. 1849316 OR. NO PARTS
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Prec __ Digging Permit Required	_ __Env	Coordination Required MM/_____ ntal Coordination Required __Tra on Required earance Required

SERVICE REQUEST DETAILS

T 11848305

REQUEST ID	CREATED DATE/TIME	FULL NAME	K PHONE

FACILITY PROJECT DETAILS

T 11848305

ASSET DETAILS

T 11848305

WARRANTY DETAILS

WT 11848305

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11848305

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11848305

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11848305**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11848305**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11848305**

Additional Notes: **WT 11848305**

PROCEDURE STEP DETAILS **WT 11848305**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11849316

WORK TASK DE					
TASK PRIORITY	edium	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	R AFB - WATER AND FUELS M MX - PIPE FITTING - BOS-			**RESPONSIBLE PERSON**	
CUSTOMER ORG	R AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Mar 3, 2023, 10:22 PM
EST HOURS		**PLANNED START**	09/08/2022 14:41:23	**PLANNED END**	09/08/2022 14:41:23
TASK NAME	E 3B - 3001 POST G87 - WT - PIPE - (09/22/2022 COM) CHILLED WATER LEAK FROM 3 DIFF AREAS - 736-5776				
TASK DESCRIPTION	ED WATER MAIN PIPE LEAKING, THIS IS A PLANT MAINT ISSUE NOT HVAC.				
FOREMAN'S NOTES TO CRAFTSMEN	fety Precautions Required	__Multi-Shop Coordination Required		__ FD/SFS/COMM/_____ Coordination Require	
	__ Digging Permit Required	__Environmental Coordination Required		__Travel/Access Clearance Re	

SERVICE REQUEST DETAILS — **WT 1184931**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — **WT 11849316**

ASSET DETAILS — **WT 11849316**

WARRANTY DETAILS — **WT 11849316**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11849316**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11849316**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11849316**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11849316**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11849316**

Additional Notes: **WT 11849316**

PROCEDURE STEP DETAILS **WT 11849316**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11761512

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**ARY WORK ATION**	TINKER 01
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**PONSIBLE SON**	
CUSTOMER ORG	TINKER AFB - OC ALC FM				
TASK TYPE	Corrective	**REQUEST CLASS**	Other Interior Need	**TED DATE**	Mar 3, 2
EST HOURS	0	**PLANNED START**	08/19/2022 08:35:24	**D**	08/19/20 08:35:24
TASK NAME	3C - 3001 Post G97 - WT - INT PLUMB - FU 11413819 DRA			E	ING - T5798 - 736-5776
TASK DESCRIPTION	3C - 3001 Post G97 - RS33- WT - PLUMBERS - DRAIN LIN				Repair - T579 - 736-5776
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coor __Environmental C		_ F /_____ Required red __Travel/ ance Required

SERVICE REQUEST DETAILS 1761512

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3087959	08/19/2022 08:32:13	405 734 7083

FACILITY PROJECT DETAILS WT 11761512

ASSET DETAILS WT 11761512

WARRANTY DETAILS WT 11761512

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11761512

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11761512

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11761512**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11761512**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11761512**

Additional Notes: **WT 11761512**

PROCEDURE STEP DETAILS **WT 11761512**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K TASK 11511863

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	ITE 1-3001
		RACKING STATUS			
RESPONSIBLE ORG	TINKER AFB BMC		- C - BOS-	**RESPONSIBLE PERSON**	U)
CUSTOMER ORG	TINKER AFB				
TASK TYPE	Corrective	**SS**	HVAC Service	M	:08 PM
EST HOURS	168	**RT**	06/16/2022 09:55:07	0 2 0 0	
TASK NAME	3B - 3001 - WT PIPE - REPAIR		3588 INSULATORS 734-2765	X F	EAK ON COPPER
TASK DESCRIPTION	WT11483588 - LEAK ON COP		OMPLETE WITH TH	D H Z	C TO FIX OVERFLOW
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Preca		__Multi-Shop Co		__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Require		__Environmenta	d	__Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11511863

REQUEST ID	REA	E/TIME	WORK PHONE
2981450	6/16	:52:19	405-734-2765

FACILITY PROJECT DETAILS

WT 11511863

ASSET DETAILS

WT 11511863

WARRANTY DETAILS

WT 11511863

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11511863

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11511863

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11511863**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11511863**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11511863**

Additional Notes: **WT 11511863**

PROCEDURE STEP DETAILS **WT 11511863**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

W TASK 11431640

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**TATUS** **CKING TATUS** sed	**PRIMARY WORK LOCATION** TINKER AFB
RESPONSIBLE ORG	TINKER AFB - HVA BMC	- BOS	**RESPONSIBLE PERSON**
CUSTOMER ORG	TINKER AF 6 M	63	
TASK TYPE		**S** ding Services	**PRINTED DATE** Mar 2, 2023, 7
EST HOURS		**T** 1/2022 6:17	**PLANNED END** 05/31/2022 19:26:17
TASK NAME	3A - 3001 7 405-582-4	a aking clogged floor drains in the fan deck - Repair -	
TASK DESCRIPTION	Water leak sib	ns on the fan deck. POC: Frank Lopez 405-734-402	
	31May202 l 31May202 e 31May202 ha was floode a up. Cleane n out, but it pp was high. op 1JUN2022 RE	y e l n WT @ K67-FD24 drains. t estor advised that there is water dripping at post K67. Checked area and it g Fan Deck 24, North and South. Checked unit and the drain pan was clogged ater out, cleaned with a water hose and plunged it. Got most of it cleaned t unit down. Also closed the supply and return water to the coil 1-2-3 and 4 o ladder couldn't reach to the top. Close After HVAC; Carryover to HVACC THROUGH WT# 11432159; CLOSE THIS WT	
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety on	ulti-Shop Coordination Required	__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Re	__ Environmental Coordination Required	__ Travel/Access Clearance Required

SERVICE REQUEST DETA — WT 11431640

REQUEST ID	CREATED /TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETA — WT 11431640

ASSET DETAILS — WT 11431640

WARRANTY DETAILS — WT 11431640

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11431640

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11431640**

Primary Maintenance Reason Code **WT 11431640**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11431640**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11431640**

Additional Notes: **WT 11431640**

PROCEDURE STEP DETAILS **WT 11431640**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

		TAS		66	

WORK TASK DETAILS

TASK PRIORITY	3C - Low S	**STATUS**	Active	**WORK**	SITE 1-3001
		ACKING STATUS	Materiel R		
RESPONSIBLE ORG	TINKER AF BMC		C - BOS-	**BLE**	(NU)
CUSTOMER ORG	TINKER AF				
TASK TYPE	Corrective	**T CLASS**	Other Inter	**E**	10:07 PM
EST HOURS	504	**START**	08/25/2022 10:24:15	**D**	
TASK NAME	3C - 3001 P MICHAEL B		- HVACC - 11475927 AK00006-JBPC ADD	**NSI**	IT BY THE FILTERS-
TASK DESCRIPTION	PR 3009 12 3C - 3001 P - REPAIR - 22AUG2022		013 12/9/22 PO'S A - WT - HVACC - LEAK 736-5776 FU 1147592	30/22 E HV 083	THE FILTERS. ADD HVAC
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Pr __ Digging P		ed __Multi-Sho red __Environmental	ired	__ /SFS/COMM/_____ oordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAIL — **WT 11784666**

REQUEST ID	EATED DATE/TIME	WORK PHONE
3099376	8/25/2022 10:22:13	405 734 7083

FACILITY PROJECT DETAIL — **WT 11784666**

ASSET DETAILS — **WT 11784666**

WARRANTY DETAILS — **WT 11784666**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11784666**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11784666**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11784666**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11784666**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11784666**

Additional Notes: **WT 11784666**

PROCEDURE STEP DETAILS **WT 11784666**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11696638

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	E
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE**	(N
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs		
EST HOURS	0	**PLANNED START**	08/03/2022 07:00:00		0 0
TASK NAME	3B - 3001 Post L-63 -WT - Intplumb - Malevolent Act, sea 622-7855 - SR3057193				g - n
TASK DESCRIPTION	Post L-63 Men's Restroom.. Someone pooped and filled cannot be flushed.				a p
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop C		CO / ati Re
	__ Digging Permit Required		__Environment	r	Cle ran

SERVICE REQUEST DETAILS

WT 1169

REQUEST ID	CREATED DATE/TIME	WORK PH
3057193	08/03/2022 06:42:53	(405) 622-

FACILITY PROJECT DETAILS

WT 1169

ASSET DETAILS

WT 1169 38

WARRANTY DETAILS

WT 1169 38

ID	REAL PROPERTY WARRANTY NAME	D	BUILDING EQUIPMENT NAME	ARRANTY

CRAFTSMAN NOTES SECTION

WT 11696638

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ WT 11696638

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11696638**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11696638**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11696638**

Additional Notes: **WT 11696638**

PROCEDURE STEP DETAILS **WT 11696638**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11663022

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks	**ATE**	Mar 3, 2023, 8:50 PM
EST HOURS	0	**PLANNED START**	07/25/2022 07:09:05	**END**	07/25/2022 07:09:05
TASK NAME	3B - 3001 POST M31 - WT - INTPLUMB - WATER LEAKIN - 5030023				LOW PREVENTER - REPAIR -
TASK DESCRIPTION	3B - 3001 POST M31 - WT - INTPLUMB - WATER LEAKIN LOCATION: AIR COMPRESSOR RM SW CORNER				LOW PREVENTER - REPAIR -
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Co		ired __ FD/SFS/COMM Coordination
	__ Digging Permit Required		__Environmental		equired __Travel/Access Clea

SERVICE REQUEST DETAILS

WT 1

REQUEST ID	CREATED DATE/TIME	E	WORK
3042151	07/25/2022 07:06:26	(NU)	

FACILITY PROJECT DETAILS

WT 1

ASSET DETAILS

WT 1

WARRANTY DETAILS

WT 11663022

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11663022

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11663022

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11663022**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11663022**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11663022**

Additional Notes: **WT 11663022**

PROCEDURE STEP DETAILS **WT 11663022**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11779750

WORK TASK DE			
TASK PRIORITY	m	**STATUS** Closed **TRACKING STATUS**	**PRIMARY WORK LOCATION** TINKER AFB SITE 1-3001
RESPONSIBLE ORG	B - WATER AND FUELS X - PIPE FITTING - BOS-		**RESPONSIBLE PERSON**
CUSTOMER ORG	MXW (CSAG-M) - 63G		
TASK TYPE		**REQUEST CLASS** Leaks	**ED DATE** Mar 3, 2023, 9:59 PM
EST HOURS		**PLANNED START** 08/24/202 10:33:30	**ED END** 08/24/2022 10:33:30
TASK NAME	31 - WT - PIPE - F/U 11757522 8		THE OUTLET SIDE OF BACKFLOW -
TASK DESCRIPTION	31 - WT - MACH MAINT - F/U 1 TER GOING TO EQUIPMENT - 246-8579		EAK ON THE OUTLET SIDE OF BACK OR - 405-734-7098
FOREMAN'S NOTES TO CRAFTSMEN	_ __	ns Required __Multi-S equired __Environ	equired __ FD/SFS/COMM/_ Coordination Req n Required __Travel/Access Clearanc ed

SERVICE REQUEST — **WT 1177**

REQUEST I	CREATED DATE/TIME	AME	WORK PHO
309676	08/24/2022 10:25:5	AYNES	(405) 739-5

FACILITY PROJECT — **WT 1177**

ASSET DETAILS — **WT 1177**

WARRANTY DETAIL — **WT 11779 0**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11779750**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11779750**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11779750**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11779750**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11779750**

Additional Notes: **WT 11779750**

PROCEDURE STEP DETAILS **WT 11779750**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 12069957

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	1-3001
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	NU)
CUSTOMER ORG	TINKER AFB - 72 ABW				
TASK TYPE	Corrective	**REQUEST CLASS**	Other Plumbing Need		PM
EST HOURS	0	**PLANNED START**	10/27/2022 07:00:00		
TASK NAME	3B - 3001 Post M-47 Inside Tank & Cooler - WT - Intplumb Taylor - 736-2085 - SR 3196155				Repai
TASK DESCRIPTION	Handicap toilet in Mens restroom will not flush and piping le the Tank & Cooler shop.				post M4
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coo		__ FD/SFS/COMM/ Coordination Re
	__ Digging Permit Required		__Environmental		__Travel/Access Clearan

SERVICE REQUEST DETAILS

WT 120

REQUEST ID	CREATED DATE/TIME	WORK PH
3196155	10/27/2022 06:51:43	(405)736-

FACILITY PROJECT DETAILS

WT 120 7

ASSET DETAILS

WT 120 7

WARRANTY DETAILS

WT 1206 57

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12069957

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12069957

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12069957**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12069957**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12069957**

Additional Notes: **WT 12069957**

PROCEDURE STEP DETAILS **WT 12069957**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

2

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustai
RESPONSIBLE ORG	TINKER AFB - W SYSTEM MX - F
CUSTOMER ORG	TINKER AFB - 7
TASK TYPE	Services
EST HOURS	022
TASK NAME	3A - 3001 M-49 ng - Repair - - 736
TASK DESCRIPTION	Toilet overflowin antly running ing 01JUN2022 070 01JUN2022 07: 01JUN2022 07: S SEEN OVE THER ER IN MIDDLE OF BATHROOM TH ROPER WOR OF SE WORK TASK CHARGE .50
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Preca __Multi-Shop Coordina e OMM/_____ __ Digging Perm __Environmental Coord quired ion Required learance Required

ORK E 1-3001

LE NU)

TE PM

D

SERVICE REQUEST DETAILS T 11432532

REQUEST ID	D DATE/TIME	FU	RK PHONE

FACILITY PROJECT DETAILS T 11432532

ASSET DETAILS WT 11432532

WARRANTY DETAILS WT 11432532

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11432532

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11432532

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11432532**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11432532**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11432532**

Additional Notes: **WT 11432532**

PROCEDURE STEP DETAILS **WT 11432532**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K TASK 11451984

WORK TASK DE

TASK PRIORITY	n	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3001
		RACKING STATUS			
RESPONSIBLE ORG	W PL	FUELS BOS-		**RESPONSIBLE PERSON**	
CUSTOMER ORG		G-M			
TASK TYPE		T C	vices	**PRINTED DATE**	Mar 2, 2023, 7:35 PM
EST HOURS		D S		**PLANNED END**	06/06/2022 06:01:25
TASK NAME		om		umb - Water on flr, leaking through wall into admin area - repair -	
TASK DESCRIPTION		king		min area	
	6 CHARGE 2H	AN NO CO		ON SITE. HROUGH TOILET TO UNSTOP TOILET; CLEANED UP WATER;	
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety P	d		Coordination Required	__ FD/SFS/COMM/_____ Coordination Required
	__ Digging P			ntal Coordination Required	__ Travel/Access Clearance Required

SERVICE REQUEST DETA — **WT 11451984**

REQUEST I	C	ED D	FULL NAME	WORK PHONE

FACILITY PROJECT DETAI — **WT 11451984**

ASSET DETAILS — **WT 11451984**

WARRANTY DETAILS — **WT 11451984**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11451984**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11451984**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11451984**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11451984**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11451984**

Additional Notes: **WT 11451984**

PROCEDURE STEP DETAILS **WT 11451984**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

TASK 11469473

WORK TASK D

TASK PRIORITY	in	**ATUS** Closed **KING** **ATUS**	**PR ARY WORK LO ATION**	TINKER AFB SITE 1-3001	
RESPONSIBLE ORG	W P	LS	**R PONSIBLE P SON**		
CUSTOMER ORG	7	) -			
TASK TYPE		**A** lding Services	**P T**	r 3, 2023, 8:04 PM	
EST HOURS		**A** 8/2022 2:19	**P N**	08/2022 2:19	
TASK NAME	M 7	T - Intplumb - Wa		gh wall into admin area - repair -	
TASK DESCRIPTION	9 S 29 08JUN2022 8:00 08JUN2022 15:2 CLEANED UP ME	FORE BEGINNING FIRST TIME. PO X R AP IN THE WALL HARGE TIME 6.5		R STATED THAT THE ROOT 736-2085 ATER INBETWEEN WALLS,	
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precau __ Digging Permi	ulti-Shop Coordina nvironmental Coord		__ FD/SFS/COMM/_____ Coordination Required avel/Access Clearance Required	

SERVICE REQUEST DETAILS — **WT 11469473**

REQUEST ID	CREATED DA	FUL	WORK PHONE

FACILITY PROJECT DETAILS — **WT 11469473**

ASSET DETAILS — **WT 11469473**

WARRANTY DETAILS — **WT 11469473**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11469473**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ **Outage** **Outage Event ID#** __ __ __ __ __ — **WT 11469473**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11469473**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11469473**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11469473**

Additional Notes: **WT 11469473**

PROCEDURE STEP DETAILS **WT 11469473**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K 142708 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain [redacted] Closed	**PRIMARY W LOCATION**	SITE 1-3001
RESPONSIBLE ORG	TINKER AFB - HV BMC	**RESPONSIE PERSON**	
CUSTOMER ORG	TINKER AFB - 76		
TASK TYPE		**PRINTED D**	7:14 PM
EST HOURS		**PLANNED E**	
TASK NAME	3A - 3001 POST M LEAKING - REPAIR -		- 736-2085
TASK DESCRIPTION	UNION ON SECO DRIPPING HOT STEA Y BENEATH 31MAY2022 0747 Y ON SITE 31MAY2022 0750 AKING UNION AND HAD TO TAKE APART THE STEAM LINE TO 31MAY2022 0950 ND IT IS NO LONGER LEAKING; CHARGE 2HRS LABOR AND REPLACE; TIGHT CLOSE WT		
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precaut op Coordination Required __ FD/SFS/COMM/_____ Coordination Required __ Digging Permit ental Coordination Required __Travel/Access Clearance Required		

SERVICE REQUEST DETAILS

WT 11427089

REQUEST ID	T	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11427089

ASSET DETAILS

WT 11427089

WARRANTY DETAILS

WT 11427089

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11427089

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _

WT 11427089

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11427089**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11427089**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11427089**

Additional Notes: **WT 11427089**

PROCEDURE STEP DETAILS **WT 11427089**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1 8498

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**RY WORK 'ON**	1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**SIBLE**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**D DATE**	PM
EST HOURS	0	**PLANNED START**	09/13/2022 07:38:17	**D**	
TASK NAME	3B - 3001 MENS RR - WT - INT PLUMB - 3 TOILETS CLO			B ED	- 736-5776
TASK DESCRIPTION	men's rest room has 3ea toilets clogged and bagged				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Co		OMM/_____
	__ Digging Permit Required		__Environmenta	ed	tion Required e Clearance Required

SERVICE REQUEST DETAILS

T 11868498

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3128420	09/13/2022 07:33:23	(405) 736-5776

FACILITY PROJECT DETAILS

WT 11868498

ASSET DETAILS

WT 11868498

WARRANTY DETAILS

WT 11868498

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11868498

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11868498

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11868498**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11868498**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11868498**

Additional Notes: **WT 11868498**

PROCEDURE STEP DETAILS **WT 11868498**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	SK	12028793	
WORK TASK DE			
TASK PRIORITY	n Sustai	**TUS** Closed **ING TUS**	**PRIMARY WORK LOCATION** TINKER AFB SITE
RESPONSIBLE ORG	AFB - W MX - P	S BMC	**RESPONSIBLE PERSON**
CUSTOMER ORG	AFB - 7	- 63G	
TASK TYPE		**ASS** Building Services	**PRINTED DATE** Mar 6, 2023, 4:59 P
EST HOURS		**ART** 10/12/2022 12:14:31	**PLANNED END** 10/12/2022 12:14:31
TASK NAME	1 POST - 736-2	UMB - MULTIPLE TOILETS OVERFLOWING ONTO THE FLOOR	
TASK DESCRIPTION	LE TOIL 022 124 022 142 LLED NO	NG ONTO THE FLOOR, FLOOR DRAIN IS ALSO CLOGGED ONSITE S: RAN SEWER MACHINE DOWN FLOOR DRAIN; RAN 4 LINKS T E LEANED UP WATER. NO PARTS CLOSED. 1.8 HRS LABOR. CLO	
FOREMAN'S NOTES TO CRAFTSMEN	ty Precau __ Digging Permit Required	__Multi-Shop Coordination Required __Environmental Coordination Required	__ FD/SFS/CO Coordinatio _ __Travel/Access Clearanc ired

SERVICE REQUEST DETAILS **WT 1202**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHO

FACILITY PROJECT DETAILS **WT 1202**

ASSET DETAILS **WT 1202**

WARRANTY DETAILS **WT 12028**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 12028793**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 12028793**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12028793**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12028793**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12028793**

Additional Notes: **WT 12028793**

PROCEDURE STEP DETAILS **WT 12028793**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	12023988
WORK TASK DE	
TASK PRIORITY	**PRIMARY WORK LOCATION** SITE 1-3001
RESPONSIBLE ORG	**RESPONSIBLE PERSON**
CUSTOMER ORG	
TASK TYPE	ws **PRINTED DATE** :57 PM
EST HOURS	022 0 **PLANNED END**
TASK NAME	PLUMB - TOILET OVERFLOWING T TO HALLWAY -
TASK DESCRIPTION	WITH INT PLUMB, onsite 1540 with or drains were clogged with paper and drains have been nd put one carpet dryer in place, nc dryers were available.

FOREMAN'S NOTES TO CRAFTSMEN Re _ lti-Shop Coordination Required FS/COMM/_____ rdination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS **WT 12023988**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS **WT 12023988**

ASSET DETAILS **WT 12023988**

WARRANTY DETAILS **WT 12023988**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 12023988**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 12023988**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12023988**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12023988**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12023988**

Additional Notes: **WT 12023988**

PROCEDURE STEP DETAILS **WT 12023988**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11605700

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER A
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks	**E**	Mar 3, 202
EST HOURS	0	**PLANNED START**	07/09/2022 01:00:00	**D**	07/09/2022 01:00:00
TASK NAME	3B - 3001 POST N49 WRR - WT - INT PLUMB - TOILET LE [redacted] ASE - REPAIR [redacted] 582-4340 - SR# 3015430				
TASK DESCRIPTION	Toilet in Women's RR is leaking at the base Post: N-49				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coor [redacted]		__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required		__Environmental C [redacted] ired		__Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11605700

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3015430	07/08/2022 12:53:21	(405)582-4340

FACILITY PROJECT DETAILS

WT 11605700

ASSET DETAILS

WT 11605700

WARRANTY DETAILS

WT 11605700

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11605700

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11605700

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11605700**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11605700**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11605700**

Additional Notes: **WT 11605700**

PROCEDURE STEP DETAILS **WT 11605700**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

	K TASK	**11748889**	
WORK TASK DE			
TASK PRIORITY	**STATUS** Closed **TRACKING STATUS**	**PRIMARY WORK LOCATION**	SITE 1-3001
RESPONSIBLE ORG	P - C - BOS-	**RESPONSIBLE PERSON**	(NU)
CUSTOMER ORG	SAG-M) - 63G		
TASK TYPE	**EST CLASS** HVAC Service		9:19 PM
EST HOURS	**NED START** 08/15/2022 07:00:00		
TASK NAME	TING SH - WT - HVACC - FF/PC 582-9513 - FLT-PN6	ON	AKING - REPAIR - T5392 -
TASK DESCRIPTION	TING SH - WT - HVACC - FF/PC - 582-9513 - FLT-PN6	RO	EAKING - REPAIR - T5392
FOREMAN'S NOTES TO CRAFTSMEN	quired ed	__Multi-Shop Co __Environmental	SFS/COMM/_____ ordination Required ed cess Clearance Required

SERVICE REQUEST DETAILS — **WT 11748889**

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3081107	08/16/2022 12:57:27	405-734-5815

FACILITY PROJECT DETAILS — **WT 11748889**

ASSET DETAILS — **WT 11748889**

WARRANTY DETAILS — **WT 11748889**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11748889**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11748889**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11748889**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11748889**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11748889**

Additional Notes: **WT 11748889**

PROCEDURE STEP DETAILS **WT 11748889**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11368107

WORK TASK D					
TASK PRIORITY	dium	**STATUS**	Closed	**PRIMARY WORK LOCATION**	E 1
		TRACKING STATUS			
RESPONSIBLE ORG	AFB - SPEC MX TM - TOR - BOS-BMC			**RESPONSIBLE PERSON**	(N
CUSTOMER ORG	AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Leaks	**PRINTED DATE**	M PM
EST HOURS		**PLANNED START**	05/16/2022 09:14:19	**PLANNED END**	0 0
TASK NAME	1 POST O-47; KITTING CAGE - WT - INSULATOR - CONDENSATION LE - 736-2085 - 0 - AHU P210				306
TASK DESCRIPTION	-47; KITTING CAGE - CONDENSATION DRIPPING FROM AIR DUCTS; O TERIALS FOUND				LEM
FOREMAN'S NOTES TO CRAFTSMEN	ety Precautions Required	__Multi-Shop Coordination Required		__ FD/SFS/COMM/___ Coordination Requ	
	__ Digging Permit Required	__Environmental Coordination Required		__Travel/Access Clearance	ired

SERVICE REQUEST DETAILS — WT 11368

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHON

FACILITY PROJECT DETAILS — WT 113681

ASSET DETAILS — WT 11368107

WARRANTY DETAILS — WT 11368107

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11368107

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11368107**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11368107**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11368107**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11368107**

Additional Notes: **WT 11368107**

PROCEDURE STEP DETAILS **WT 11368107**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

	W TASK	11368137	
WORK TASK DE			
TASK PRIORITY	TATUS Closed CKING TATUS	PRIMARY WORK LOCATION	
RESPONSIBLE ORG	WATE ELS PLUM S-	RESPONSIBLE PERSON	
CUSTOMER ORG	76 MX G		
TASK TYPE	R Leaks	TED DATE	
EST HOURS	P 05/16/20 09:20:42	INED END	
TASK NAME	T O-6 I - 0 - F - CHILL	S LEAKING - R	
TASK DESCRIPTION	VC LA ION PO R LINE 39-4246	- POSSIBLE CL 736-5085	
	M ASSOC		
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precaution __Multi- Required __ Digging Permit Re __Enviro tion Required	__ FD/SFS/COMM/___ Coordination Requ __ Travel/Access Clearance quired	

SERVICE REQUEST DETAILS WT 11368

REQUEST ID	ME	NAME	WORK PHON

FACILITY PROJECT DETAILS WT 11368 7

ASSET DETAILS WT 11368137

WARRANTY DETAILS WT 11368137

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11368137

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ WT 11368137

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11368137**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11368137**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11368137**

Additional Notes: **WT 11368137**

PROCEDURE STEP DETAILS **WT 11368137**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

TASK 11602560

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINK 3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - W SYSTEM MX - P BMC		UELS DS-	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB		-M) - 63G		
TASK TYPE		**CLASS**	Building Services	**PRINTED DATE**	Mar 3
EST HOURS		**START**	07/08/2022 07:18:19	**PLANNED END**	07/08 07:18
TASK NAME	3A - 3001 PO		T PLUMB - WATER LEAKING FROM CEILING - Repair -		- 5824340
TASK DESCRIPTION	WATER LEAK REQUESTOR 8JUL2022 7:2 8JUL2022 7:4 8JUL2022 08		NG BELIEVE TO BE RELATED TO CHILL WATER PIPE AUSING A MAJOR SAFETY RISK AS THE AISLE IS BEIN WITH INT PLUMB K ON SITE ER LINE LEAKING, CLOSEWORK TASK OPEN NEW FOR PIPE FITTERS.		M APRIL 18, IN WATER.
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Pre __ Digging Pe		__Multi-Shop Coordination Required __Environmental Coordination Required	__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required	

SERVICE REQUEST DETAIL

WT 11602560

REQUEST ID	C	D DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAIL

WT 11602560

ASSET DETAILS

WT 11602560

WARRANTY DETAILS

WT 11602560

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11602560

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11602560

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11602560**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11602560**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11602560**

Additional Notes: **WT 11602560**

PROCEDURE STEP DETAILS **WT 11602560**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

W SK 11603539

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**TUS 'NG TUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AFB
RESPONSIBLE ORG	TINKER AFB - WATE SYSTEM MX - PIPE BMC	S -		**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB MX	- 63G			
TASK TYPE		**SS**	Building Services	**PRINTED DATE**	Mar 3, 2023, 8
EST HOURS		**RT**	07/08/2022 09:09:03	**PLANNED END**	07/08/2022 09:09:03
TASK NAME	3A - 3001 P 5 5824340	WATER LEAKING FROM CHILLED WATER LINE - Repair -			
TASK DESCRIPTION	WATER LE 8JUL22 949 E 8JUL22 103 E TO BE COM D	WATER PIPE. N SITE UNDER LEAK AND CAN BE CONTAINED. CLOSE WORK TASK. WOR EEDS GE. 1 HOUR LABOR.			
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety P n __ Digging e	__Multi-Shop Coordination Required __Environmental Coordination Required		__ FD/SFS/COMM/___ __ Coordination Requ d __Travel/Access Clearance equired	

SERVICE REQUEST DETA

WT 11603 39

REQUEST I	TE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETA

WT 11603539

ASSET DETAILS

WT 11603539

WARRANTY DETAILS

WT 11603539

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11603539

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11603539

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11603539**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11603539**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11603539**

Additional Notes: **WT 11603539**

PROCEDURE STEP DETAILS **WT 11603539**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

ASK **11611285**

WORK TASK DETAILS

TASK PRIORITY	3C - Low	**ATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3001
		KING ATUS			
RESPONSIBLE ORG	TINKER SYSTEM BMC	LS S-		**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER	) - 63G			
TASK TYPE		**LASS**	Building Services	**PRINTED DATE**	Mar 3, 2023, 8:39 PM
EST HOURS		**ART**	07/11/2022 07:18:53	**PLANNED END**	07/11/2022 07:18:53
TASK NAME	OUTAGE - Repair -	T - PIPE - F/U 11603539 WATER LEAKING FROM CHILLED WATER LINE IN FALL 0			
TASK DESCRIPTION	WATER L 8JUL22 9 8JUL22 1 TO BE CO POC MAR EMPTY T	D WATER PIPE. ON SITE N UNDER LEAK AND CAN BE CONTAINED. CLOSE WORK TASK. WORK NEEDS AGE. 1 HOUR LABOR L OUTTAGE CAN BE SET UP AND PIPE PEMANANTLY REPAIRED			
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety __ Diggin	__Multi-Shop Coordination Required __Environmental Coordination Required		__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required	

SERVICE REQUEST DET

WT 11611285

REQUEST I	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DET

WT 11611285

ASSET DETAILS

WT 11611285

WARRANTY DETAILS

WT 11611285

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11611285

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11611285**

Primary Maintenance Reason Code **WT 11611285**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11611285**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11611285**

Additional Notes: **WT 11611285**

PROCEDURE STEP DETAILS **WT 11611285**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

TASK 11631467

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sust	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3001
		ACKING STATUS			
RESPONSIBLE ORG	TINKER AFB BOS-BMC		PM -	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB				
TASK TYPE	Corrective	**SS**	General Repairs		Mar 3, 2023, 8:45 PM
EST HOURS	0	**RT**	07/15/2022 01:00:00		07/15/2022 01:00:00
TASK NAME	3C-3001 POST LEAK - REPAIR		11611285 EMPTY C -582-4496		RS CLOSET FROM CHILL WATER LINE
TASK DESCRIPTION	3C-3001 POST LEAK - REPAIR		11611285 EMPTY C -582-4496		RS CLOSET FROM CHILL WATER LINE
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Preca __ Digging Perm		__Multi-Shop C __Environmenta		__ FD/SFS/COMM/_____ Coordination Required ed __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11631467

REQUEST ID		TE/TIME	WORK PHONE
3025978	0	:23:52	405-582-4496

FACILITY PROJECT DETAILS

WT 11631467

ASSET DETAILS

WT 11631467

WARRANTY DETAILS

WT 11631467

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11631467

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11631467

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11631467**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11631467**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11631467**

Additional Notes: **WT 11631467**

PROCEDURE STEP DETAILS **WT 11631467**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

11661379

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain		Closed	**PRIMARY WORK LOCATION**	1
RESPONSIBLE ORG	TINKER AFB - HV BMC			**RESPONSIBLE PERSON**	U)
CUSTOMER ORG	TINKER AFB - 76 M		G		
TASK TYPE	Corrective		Building Services	**PRINTED DATE**	
EST HOURS	504		07/24/2022 01:05:26	**PLANNED END**	
TASK NAME	3B- 3001 Post O-65 736-2500		ater leaking from above, over filled trash ca		(MOC)-
TASK DESCRIPTION	24Jul2022 update: because it was caus		called & reported that he took the trash can ard.		pty it

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precaution __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11661379

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11661379

ASSET DETAILS

WT 11661379

WARRANTY DETAILS

WT 11661379

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11661379

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11661379

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11661379**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11661379**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11661379**

Additional Notes: **WT 11661379**

PROCEDURE STEP DETAILS **WT 11661379**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

11546000

WORK TASK DETAILS

TASK PRIORITY	3A - High Susta	**PRIMARY WORK LOCATION**	ITE 1-3001
RESPONSIBLE ORG	TINKER AFB - SYSTEM MX -	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB -		
TASK TYPE		**PRINTED DATE**	14 PM
EST HOURS		**PLANNED END**	
TASK NAME	3A - 3001 POS	K CLOGGED - REPAIR	620-2589
TASK DESCRIPTION	JANITOR'S SIN	AND CAUSING THEM A	GE; POST O83
	24JUN2022 14 24JUN2022 14 24JUN2022 15 MOP HEAD EN AND CLOSE	ON SITE LOOR DRAIN WITH DR IT; EVERYTHINKG DRA	ULLED A BUNCH OF NOW; CHARGE 1 HRS
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Preca __ Digging Perm	__Multi-Shop Coordination Require __Environmental Coordination Required	S/COMM/_____ nation Required s Clearance Required

SERVICE REQUEST DETAILS

WT 11546000

REQUEST ID	E/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11546000

ASSET DETAILS

WT 11546000

WARRANTY DETAILS

WT 11546000

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11546000

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11546000

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

Primary Maintenance Reason Code **WT 11546000**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11546000**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11546000**

Additional Notes: **WT 11546000**

PROCEDURE STEP DETAILS **WT 11546000**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11946442

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TE 1
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE**	[redacted] (N
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Overflows		P
EST HOURS	0	**PLANNED START**	09/26/2022 07:56:20		
TASK NAME	3C - 3001 POST 083 - WT - INT PLUMB - SECOND SINK - 736-5776			P	D
TASK DESCRIPTION	bldg. 3001 post O83 second sink from the door on OP ais				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Co		CO ati
	__ Digging Permit Required		__Environmenta	d	CI

SERVICE REQUEST DETAILS

WT

REQUEST ID	CREATED DATE/TIME
3150804	09/26/2022 07:54:24

OR 05)

FACILITY PROJECT DETAILS

WT

ASSET DETAILS

WT 11946442

WARRANTY DETAILS

WT 11946442

ID	REAL PROPERTY WARRANTY NAME	D	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11946442

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ WT 11946442

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11946442**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11946442**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11946442**

Additional Notes: **WT 11946442**

PROCEDURE STEP DETAILS **WT 11946442**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11588847

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	PM
EST HOURS		**PLANNED START**	07/05/2022 14:32:59	**PLANNED END**	
TASK NAME	3B - 3001 & POST O83 - WT - INT PLUMB - UNCLOG MENS TOILET - Repair - N				7365776
TASK DESCRIPTION	MENS TOILET NORTH END CLOGGED.				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Required __Environmental Coordination Required		OMM/_____ ation Required Clearance Required

SERVICE REQUEST DETAILS

WT 11588847

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11588847

ASSET DETAILS

WT 11588847

WARRANTY DETAILS

WT 11588847

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11588847

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11588847

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11588847**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11588847**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11588847**

Additional Notes: **WT 11588847**

PROCEDURE STEP DETAILS **WT 11588847**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 12045583

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	1-3001
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**PRINTED DATE**	PM
EST HOURS	0	**PLANNED START**	10/17/2022 08:22:44	**P**	**D**
TASK NAME	3B - 3001 POST 083 - WT - INT PLUMB - 5 TOILETS IN MEN			ED -	- 405-736-5776
TASK DESCRIPTION	Bldg 3001 post 083 5ea toilets are clogged in the mens restro				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coord	d	OMM/_____
	__ Digging Permit Required		__Environmental Co	ired Tr	ation Required Clearance Required

SERVICE REQUEST DETAILS

WT 12045583

REQUEST ID	CREATED DATE/TIME		WORK PHONE
3184938	10/17/2022 08:21:23	E	(405) 736-5776

FACILITY PROJECT DETAILS

WT 12045583

ASSET DETAILS

WT 12045583

WARRANTY DETAILS

WT 12045583

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12045583

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12045583

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12045583**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12045583**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12045583**

Additional Notes: **WT 12045583**

PROCEDURE STEP DETAILS **WT 12045583**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11868524

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	KER AFB SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs		
EST HOURS	0	**PLANNED START**	09/13/2022 07:43:11		
TASK NAME	3C - 3001 POST 083 - WT - INT PLUMB - URINAL CLOGGE				
TASK DESCRIPTION	mens rest room post O83 has a urinal clogged and bagged 22Sep22 Downey notes - Found no urinals bagged or clogged. I did fin				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coord		
	__ Digging Permit Required		__Environmental C		

SERVICE REQUEST DETAILS

WT 11868524

REQUEST ID	CREATED DATE/TIME
3128440	09/13/2022 07:39:40

FACILITY PROJECT DETAILS

WT 11868524

ASSET DETAILS

WT 11868524

WARRANTY DETAILS

WT 11868524

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11868524

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11868524

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11868524**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11868524**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11868524**

Additional Notes: **WT 11868524**

PROCEDURE STEP DETAILS **WT 11868524**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 20

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	R A	TINKER AFB SITE 1-3001
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC				
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs		Mar 6, 2023, 4:22 PM
EST HOURS	0	**PLANNED START**	10/17/2022 08:24:28		10/17/2022 08:24:28
TASK NAME	3B - 3001 POST 093 - WT - INT PLUMB - TOILET CLOGG				E - 405-736-5776
TASK DESCRIPTION	men's rest room Bldg 3001 postO93 has a toilet clogged				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Co		__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required		__Environmental		d __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 12045591

REQUEST ID	CREATED DATE/TIME		WORK PHONE
3184943	10/17/2022 08:23:00	E	(405) 736-5776

FACILITY PROJECT DETAILS

WT 12045591

ASSET DETAILS

WT 12045591

WARRANTY DETAILS

WT 12045591

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12045591

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12045591

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12045591**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12045591**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12045591**

Additional Notes: **WT 12045591**

PROCEDURE STEP DETAILS **WT 12045591**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 158889 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY W**	SITE 1-3001
		TRACKING STATUS		**LOCATION**	
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIB PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED D**	8:29 PM
EST HOURS		**PLANNED START**	07/05/2022 14:41:34	**PLANNED E**	
TASK NAME	3B - 3001 & POST O93 - WT - INT PLUMB - STOP URINAL LEAK - Repair				- 7365776
TASK DESCRIPTION	MENS URINAL AT POST O93 IS LEAKING				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required
__Multi-Shop Coordination Required
__ FD/SFS/COMM/_____ Coordination Required
__ Digging Permit Required
__Environmental Coordination Required
__Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11588892

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11588892

ASSET DETAILS

WT 11588892

WARRANTY DETAILS

WT 11588892

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11588892

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11588892

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11588892**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11588892**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11588892**

Additional Notes: **WT 11588892**

PROCEDURE STEP DETAILS **WT 11588892**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 2034 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMAR LOCATIO**	TE 1-3001
		TRACKING STATUS	Maintenance Complete		
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**RESPON PERSON**	NU)
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTE**	PM
EST HOURS	504	**PLANNED START**	10/13/2022 11:49:11	**PLANNE**	
TASK NAME	3B - 3001 POST O95 - WT - HVACC - ISOLATION VALVE LEAKING -				
TASK DESCRIPTION	STEAM TRAP AT POST O95 THAT IS COLD, VALVE TO ISOLATE TR				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Re		COMM/_____ ation Required
	__ Digging Permit Required		__Environmental Coordination		Clearance Required

SERVICE REQUEST DETAILS

WT 12034851

REQUEST ID	CREATED DATE/TIME	FULL NAME	ORK PHONE

FACILITY PROJECT DETAILS

WT 12034851

ASSET DETAILS

WT 12034851

WARRANTY DETAILS

WT 12034851

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12034851

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 12034851

Primary Maintenance Reason Code

WT 12034851

__ Abuse / Malevolent Act	__Accident/Event	__Corrosion	__Solid State	__Off-base Source	__Weather	__Tree/Vegetation
__ Cust Request/Directed	__Environmental	__Mechanical	__Structural	__Operator/Techn	__Wildlife	__Fire/Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

NOTES TO R&O ON ASSETS & LOCATION			WT 12034851
ASSET STATUS	**GEOSPATIAL LOCATION**		
__SMS Update Required (Record Comments in Asset Notes)	___ Point	___ Line	___ Area
__Asset Condition Changed __ Removed Asset	Primary Latitude: _____		Secondary Lat: _____
__Asset Replaced/Added	Primary Longitude: _____		Secondary Lon: _____
Asset Notes:			WT 12034851
Additional Notes:			WT 12034851
PROCEDURE STEP DETAILS			WT 12034851
STEP	**PROCEDURE TEXT**	**DURATION**	**PROCEDURE ID**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 2

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PR LOC**	TINKER AFB SITE 1-3001
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC			**RE ER**	
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE	Corrective	**REQUEST CLASS**	General Repairs		23, 2:24 PM
EST HOURS	0	**PLANNED START**	10/19/2022 09:21:44		2
TASK NAME	3B - 3001 POST O95 - WT - PIPE - ISOLATION VALVE LE			S	7
TASK DESCRIPTION	3B - 3001 POST O95 - WT - PIPE FITTING - ISOLATION V PREVIOUS WT# 12034851			W	- 734-9377
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coo		D/SFS/COMM/_____ oordination Required
	__ Digging Permit Required		__Environmental		Access Clearance Required

SERVICE REQUEST DETAILS

WT 12057441

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3190669	10/19/2022 09:19:26	405-734-5815

FACILITY PROJECT DETAILS

WT 12057441

ASSET DETAILS

WT 12057441

WARRANTY DETAILS

WT 12057441

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12057441

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12057441

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12057441**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12057441**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12057441**

Additional Notes: **WT 12057441**

PROCEDURE STEP DETAILS **WT 12057441**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PR**	NKER AFB SITE 1-3001
		TRACKING STATUS		**LO**	
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC			**RE**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs		ar 6, 2023, 4:23 PM
EST HOURS	0	**PLANNED START**	10/17/2022 08:25:31		/17/2022 :25:31
TASK NAME	3B - 3001 POST 0103 - WT - INT PLUMB - TOILET CLOG				405-736-5776
TASK DESCRIPTION	mens rest room post O103 has a clogged toilet				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Co		__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required		__Environmenta		ed __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 12045596

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3184949	10/17/2022 08:24:29	(405) 736-5776

FACILITY PROJECT DETAILS

WT 12045596

ASSET DETAILS

WT 12045596

WARRANTY DETAILS

WT 12045596

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 12045596

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 12045596

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12045596**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12045596**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12045596**

Additional Notes: **WT 12045596**

PROCEDURE STEP DETAILS **WT 12045596**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

ORK TASK	**1**	**6**	
WORK TASK DE			
TASK PRIORITY	**STATUS** Closed	**RK**	TINKER AFB SITE 1-3001
	TRACKING STATUS		
RESPONSIBLE ORG	AND FUELS INT - BOS-BMC	**E**	
CUSTOMER ORG	(CSAG-M) - 63G		
TASK TYPE	**QUEST CLASS** Overflows	**E**	Mar 6, 2023, 4:43 PM
EST HOURS	**ANNED START** 07/15/2022 07:53:54	**D**	07/15/2022 07:53:54
TASK NAME	MRR - WT - INT PLUMB - TOILET H # 3027428		ED AND IS NOW BAGGED - REPAIR
TASK DESCRIPTION	erflowing and is bagged 33-7034		
FOREMAN'S NOTES TO CRAFTSMEN	t Required __Multi-Shop Coord in uired __Environmental C	d uired	__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Requ

SERVICE REQUEST DETAILS **WT 11633926**

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3027428	07/15/2022 07:52:14	(405)582-4340

FACILITY PROJECT DETAILS **WT 11633926**

ASSET DETAILS **WT 11633926**

WARRANTY DETAILS **WT 11633926**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11633926**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11633926**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11633926**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11633926**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11633926**

Additional Notes: **WT 11633926**

PROCEDURE STEP DETAILS **WT 11633926**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11414033

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	[redacted]
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 AMXG				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	
EST HOURS		**PLANNED START**	05/26/2022 06:15:36	**PLANNED END**	
TASK NAME	3C - 3001 POST O103 - WT - INTPLUMB - URINAL CLOGGED & BAGGED - RE 4340 - -				- 582-
TASK DESCRIPTION	POST O103 - MENS RR - TOILET CLOGGED AND BAGGED				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Require		___ d
	__ Digging Permit Required		__Environmental Coordination Required		equired

SERVICE REQUEST DETAILS 3

REQUEST ID	CREATED DATE/TIME	FULL NAME	:

FACILITY PROJECT DETAILS 33

ASSET DETAILS 33

WARRANTY DETAILS WT 11414033

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11414033

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11414033**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11414033**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11414033**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11414033**

Additional Notes: **WT 11414033**

PROCEDURE STEP DETAILS **WT 11414033**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11418639

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER A
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Mar 6, 202
EST HOURS		**PLANNED START**	05/26/2022 19:44:17	**PLANNED END**	05/26/2022 19:44:17
TASK NAME	3C - 3001 POST O103 - WT - AFTER HRS PLUMB - TOILET CLOGGED - REPAIR - T3338 - [redacted] - 622-7846 - -				
TASK DESCRIPTION	POST O-103 WOMENS RR - TOILET CLOGGED/NOT FLUSHING; SENT VIA EMAIL 30Jun2022 Downey notes - 3rd stall from left needs new flush valve. Ordered new one. Carry over.				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi-Shop Coordination Required		__ FD/SFS/COMM/_____ Coordination Required	
	__ Digging Permit Required	__Environmental Coordination Required		__Travel/Access Clearance Required	

SERVICE REQUEST DETAILS

WT 11418639

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11418639

ASSET DETAILS

WT 11418639

WARRANTY DETAILS

WT 11418639

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11418639

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11418639

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11418639**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11418639**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11418639**

Additional Notes: **WT 11418639**

PROCEDURE STEP DETAILS **WT 11418639**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11418640

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	NU)
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	PM
EST HOURS		**PLANNED START**	05/26/2022 19:45:48	**PLANNED END**	
TASK NAME	3C - 3001 POST O103 - WT - INTPLUMB - TOILET CLOGGED - REPAIR - T3338				- 622-7846 - -
TASK DESCRIPTION	POST O-103 WOMENS RR - TOILET CLOGGED/NOT FLUSHING; SENT VIA EM				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Required		OMM/_____
	__ Digging Permit Required		__Environmental Coordination Required		ation Required Clearance Required

SERVICE REQUEST DETAILS

WT 11418640

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11418640

ASSET DETAILS

WT 11418640

WARRANTY DETAILS

WT 11418640

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11418640

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11418640

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11418640**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11418640**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11418640**

Additional Notes: **WT 11418640**

PROCEDURE STEP DETAILS **WT 11418640**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**P**	TE 1-3001
		TRACKING STATUS		**LO**	
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**R P**	(NU)
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE		**REQUEST CLASS**	Building Services	**PR**	3 PM
EST HOURS	504	**PLANNED START**	06/05/2022 17:14:13	**PL**	
TASK NAME	3B - 3001 Fan deck P24SFD - WT - HVACC - coil leaking - repai				
TASK DESCRIPTION	BAS - RWP found coil leaking pretty bad and valved it off and cle				r

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordinati d S/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11449649

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11449649

ASSET DETAILS

WT 11449649

WARRANTY DETAILS

WT 11449649

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11449649

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11449649

Primary Maintenance Reason Code

WT 11449649

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

NOTES TO R&O ON ASSETS & LOCATION **WT 11449649**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11449649**

Additional Notes: **WT 11449649**

PROCEDURE STEP DETAILS **WT 11449649**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11419092

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	-3001
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	
EST HOURS	960	**PLANNED START**	05/27/2022 06:33:49	**PLANNED END**	
TASK NAME	3C - 3001 POST P53 - WT - HVACC - CHILL WATER PIPE LEAK - REPAIR - T45				- 323-0319
TASK DESCRIPTION	POST P-53 - LEAK FROM CHILLED WATER PIPE; PROBABLY RELATED TO T4				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required MM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11419092

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11419092

ASSET DETAILS

WT 11419092

WARRANTY DETAILS

WT 11419092

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11419092

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11419092

Primary Maintenance Reason Code

WT 11419092

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

NOTES TO R&O ON ASSETS & LOCATION **WT 11419092**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11419092**

Additional Notes: **WT 11419092**

PROCEDURE STEP DETAILS **WT 11419092**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 13902 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY LOCATIO**	TE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**RESPON PERSON**	(NU)
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Leaks	**PRINTED**	2 PM
EST HOURS		**PLANNED START**	05/20/2022 09:41:50	**PLANNED**	
TASK NAME	3B - 3001 POST P57 - WT - HVACC - CONDENSATION LEAK - Repair				404
TASK DESCRIPTION	1 OF THE TARPS PUT IN PLACE IS OVERLY FULL AND SEEMS TO H OTHER TARPS ARE CONSTANTLY FULL AS WELL. PLEASE MEET W GETTING CLOSED WITHOUT WHAT HE CONSIDERS ACCEPTABLE R			Q T	T NEXT TO IT. THE WHY THIS KEEPS

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11390201

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11390201

ASSET DETAILS

WT 11390201

WARRANTY DETAILS

WT 11390201

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11390201

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11390201

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11390201**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11390201**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11390201**

Additional Notes: **WT 11390201**

PROCEDURE STEP DETAILS **WT 11390201**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K TASK 11403028

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WO LOCATION**	E 1-3001
		RACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - SPE INSULATOR - BOS		-	**RESPONSIB PERSON**	
CUSTOMER ORG	TINKER AFB		G-M) - 63G		
TASK TYPE	Corrective	**T CLASS**	Other Interior Need	**PRINTED DA**	PM
EST HOURS	0	**D START**	05/24/2022 09:54:36	**PLANNED E**	
TASK NAME	3B - 3001 PC		NSULATOR - CONDENSATION LEAK - REP		0-4404
TASK DESCRIPTION	3001 POST ONE OF TH TO BE RE-R HVACC POC SITUATION		LATOR - CONDENSATION LEAK - REPAIR - RLY FULL AND OTHER TARPS ARE CONS DOWNWARD INSTEAD OF UP AND DOWN (HE INVESTIGATED ON 5/23/2022 AND INF		04 P DRAINS NEED OF THE
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Pr __ Digging P	ed	__Multi-Shop Coordination Requir __Environmental Coordination Req		OMM/_____ ion Required learance Required

SERVICE REQUEST DETAI

T 11403028

REQUEST I	C	ED DATE/TIME	FULL NAME	RK PHONE
294218	0	/2022 09:42:14	TRACY CARTER	4 5-734-5815

FACILITY PROJECT DETAI

WT 11403028

ASSET DETAILS

WT 11403028

WARRANTY DETAILS

WT 11403028

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11403028

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11403028

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11403028**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11403028**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11403028**

Additional Notes: **WT 11403028**

PROCEDURE STEP DETAILS **WT 11403028**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 138 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMAR LOCAT**	R AFB SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - AFTER HRS - BOS-BMC			**RESPO PERSO**	
CUSTOMER ORG					
TASK TYPE		**CLASS**	Building Services	**PRINTE**	2023, 6:40 PM
EST HOURS	[redacted]	**START**	05/19/2022 19:39:06	**PLANN**	022 6
TASK NAME		R HVAC - Condensate leak - Repair –			- 801-971-7286

TASK DESCRIPTION

has been going on for awhile.
86

2155 onsite

went to post P-61 I found a condenst leak on one of the vats labeled chrome wax it has a
2 I am closeing the hvac shop turn this over to M.A.D.

im know that unit belongs to M.A.D.

FOREMAN'S NOTES TO CRAFTSMEN

__Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQU **WT 11387982**

REQUE	DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJE **WT 11387982**

ASSET DETAILS **WT 11387982**

WARRANTY DETAILS **WT 11387982**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11387982**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11387982**

Primary Maintenance Reason Code **WT 11387982**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11387982**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11387982**

Additional Notes: **WT 11387982**

PROCEDURE STEP DETAILS **WT 11387982**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11853578

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	[redacted]
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE P**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks		
EST HOURS	0	**PLANNED START**	09/09/2022 10:40:49		
TASK NAME	3B - 3001 POST P81 - WT - INT PLUMB - PIPE LEAKING/PO			RE	736-5776
TASK DESCRIPTION	pipe leaking possibly in the rest room post P81				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coord		_
	__ Digging Permit Required		__Environmental Co	ed	uired

SERVICE REQUEST DETAILS

REQUEST ID	CREATED DATE/TIME
3123996	09/09/2022 10:38:16

FACILITY PROJECT DETAILS

WT 11853578

ASSET DETAILS

WT 11853578

WARRANTY DETAILS

WT 11853578

ID	REAL PROPERTY WARRANTY NAME	D	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11853578

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ WT 11853578

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11853578**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11853578**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11853578**

Additional Notes: **WT 11853578**

PROCEDURE STEP DETAILS **WT 11853578**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

1 365

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**WO**	B SITE 1-3001
RESPONSIBLE ORG	TINKER AFB - WA SYSTEM MX - PL	B	
CUSTOMER ORG	TINKER AFB - 76		
TASK TYPE		A	4:49 PM
EST HOURS		E	
TASK NAME	3A - 3001 MRR P	G	736-5776
TASK DESCRIPTION	SINK IS OVERFL 25AUG2022 1212 25AUG2022 1227 25AUG2022 1425 CMAS AND GOT 2 HRS AND COM	A TU	TO FAUCET; WENT TO VERFLOWING; CHARGE
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precau __ Digging Permit	uir e	SFS/COMM/_____ rdination Required cess Clearance Required

SERVICE REQUEST DETAILS

WT 11785365

REQUEST ID	ME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11785365

ASSET DETAILS

WT 11785365

WARRANTY DETAILS

WT 11785365

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11785365

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11785365

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11785365**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11785365**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11785365**

Additional Notes: **WT 11785365**

PROCEDURE STEP DETAILS **WT 11785365**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11408548

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WO LOCATION**	ITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**RESPONSIBLE PERSON**	U)
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DAT**	:01 PM
EST HOURS		**PLANNED START**	05/25/2022 09:41:12	**PLANNED END**	
TASK NAME	3B - 3001 PATRIOT ROOM - WT - HVACC - CONDENSATE LEAK - REPAIR				73458956
TASK DESCRIPTION	REPAIR CONDENSDATE LEAK ON HVAC UNIT				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required _ FS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11408548

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11408548

ASSET DETAILS

WT 11408548

WARRANTY DETAILS

WT 11408548

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11408548

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11408548

Primary Maintenance Reason Code

WT 11408548

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

NOTES TO R&O ON ASSETS & LOCATION **WT 11408548**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11408548**

Additional Notes: **WT 11408548**

PROCEDURE STEP DETAILS **WT 11408548**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11755040

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMARY WORK LOCATION**	TINKER AFB SIT
		TRACKING STATUS	Awaiting Scheduling		
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Mar 3, 2023, 9:2
EST HOURS	504	**PLANNED START**	08/17/2022 13:15:30	**PLANNED END**	09/07/2022 13:15:30
TASK NAME	3B - 3001 PLANT POST 73A - WT - INT PLUMB - WATER LEAK FROM SEWAGE LINE - REPAIR				246-8579
TASK DESCRIPTION	WATER LEAK FROM SEWAGE LINE - SENT VIA EMAIL				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi-Shop Coordination Required		__ FD/SFS Coordin	
	__ Digging Permit Required	__Environmental Coordination Required		__Travel/Access	uired

[redacted]

SERVICE REQUEST DETAILS

REQUEST ID	CREATED DATE/TIME	FULL NAME	W

FACILITY PROJECT DETAILS

W

ASSET DETAILS

W

WARRANTY DETAILS

WT 11755040

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11755040

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11755040

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11755040**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11755040**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11755040**

Additional Notes: **WT 11755040**

PROCEDURE STEP DETAILS **WT 11755040**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK [redacted] 2 79

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed		SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC				(NU)
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	General Repa		:21 PM
EST HOURS	168	**PLANNED START**	07/14/2022 08:58:34		
TASK NAME	3B - 3001 Blr Plant - WT - HVACC - Clogged drain/back PCHW-BS05				2-9513 - UID 3001
TASK DESCRIPTION	3B - 3001 Blr Plant - WT - HVACC - Clogged drain/back PCHW-BS05 Under chiller #6, drain is clogged and is backing up - PC				2-9513 - UID 3001
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop __Environmen		S/COMM/_____ dination Required ss Clearance Required

SERVICE REQUEST DETAILS

WT 11629799

REQUEST ID	CREATED DATE/TIME	WORK PHONE
3025145	07/14/2022 08:50:41	405-734-3117

FACILITY PROJECT DETAILS

WT 11629799

ASSET DETAILS

WT 11629799

WARRANTY DETAILS

WT 11629799

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11629799

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11629799

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11629799**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11629799**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11629799**

Additional Notes: **WT 11629799**

PROCEDURE STEP DETAILS **WT 11629799**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 17350 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY LOCATION**	E 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**RESPONS PERSON**	NU)
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED D**	PM
EST HOURS	504	**PLANNED START**	08/12/2022 09:02:10	**PLANNED**	
TASK NAME	3B - 3001 POST Q40 - WT - HVACC – CHILLED WATER LEAK - REAPIR				18
TASK DESCRIPTION	COUPLE DROPS PER SECOND. DRIPPING ON CONCRETE. CONTAIN				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Requi d /COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11735039

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11735039

ASSET DETAILS

WT 11735039

WARRANTY DETAILS

WT 11735039

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11735039

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11735039

Primary Maintenance Reason Code

WT 11735039

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

NOTES TO R&O ON ASSETS & LOCATION			WT 11735039
ASSET STATUS	**GEOSPATIAL LOCATION**		
__SMS Update Required (Record Comments in Asset Notes)	___ Point	___ Line	___ Area
__Asset Condition Changed __ Removed Asset	Primary Latitude: _____		Secondary Lat: _____
__Asset Replaced/Added	Primary Longitude: _____		Secondary Lon: _____

Asset Notes:	WT 11735039

Additional Notes:	WT 11735039

PROCEDURE STEP DETAILS			WT 11735039
STEP	**PROCEDURE TEXT**	**DURATION**	**PROCEDURE ID**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11892228

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER A
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC			**RESPONSIBLE**	
CUSTOMER ORG	TINKER AFB - 72 CES				
TASK TYPE	Corrective	**REQUEST CLASS**	Other Interior Nee	**E**	Mar 6, 202
EST HOURS	0	**PLANNED START**	09/16/2022 09:59:04	**D**	09/16/2022 09:59:04
TASK NAME	3B - 3001 POST Q40 - WT - PIPE - F/U WT #11735039 & 1			**K FROM PIPE -**	- 736-4118
TASK DESCRIPTION	PREVIOUS W/T #11735039 TO 11778953 FOR INSULATO FROM PIPE.			NEW W/T FOR	TO FIX LEAK
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi-Shop Coo		__ FD/ Coordination Required	_____
	__ Digging Permit Required	__Environmental		ired __Travel/Access Clearance Required	

SERVICE REQUEST DETAILS

WT 11892228

REQUEST ID	CREATED DATE/TIME		WORK PHONE
3136425	09/16/2022 09:55:50	V	405-734-2765

FACILITY PROJECT DETAILS

WT 11892228

ASSET DETAILS

WT 11892228

WARRANTY DETAILS

WT 11892228

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11892228

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11892228

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11892228**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11892228**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11892228**

Additional Notes: **WT 11892228**

PROCEDURE STEP DETAILS **WT 11892228**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11396207

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINK -3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - PLANT OPS - INDUSTRIAL WASTEWATER TRMT - MAINT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 AMXG				
TASK TYPE		**REQUEST CLASS**	Leaks	**PRINTED DATE**	Mar 2
EST HOURS		**PLANNED START**	05/23/2022 08:40:39	**PLANNED END**	05/23 08:40
TASK NAME	3B - 3001 POST R49 - WT - IWTP - INDUSTRIAL WASTE PUMP IS LEAKING - Repair - [redacted] - 736-5776				
TASK DESCRIPTION	INDUSTRIAL WASTE PUMP IS LEAKING				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS WT 11396207

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS WT 11396207

ASSET DETAILS WT 11396207

WARRANTY DETAILS WT 11396207

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11396207

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11396207

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11396207**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11396207**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11396207**

Additional Notes: **WT 11396207**

PROCEDURE STEP DETAILS **WT 11396207**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11402685

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	[redacted] T
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**RESPONSIBLE PERSON**	[redacted] (N
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Leaks	**PRINTED DATE**	9
EST HOURS	504	**PLANNED START**	05/23/2022 09:26:00	**PLANNED END**	
TASK NAME	3B - 3001 POST R49 - WT - HVAC C - MONITOR SUMP PUMP DRAIN LEAKING 734-5856				61
TASK DESCRIPTION	MONITOR SUMP PUMP DRAIN LEAKING				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/___ Coordination Requ

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance [redacted] d

SERVICE REQUEST DETAILS

WT 11402

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHON

FACILITY PROJECT DETAILS

WT 11402685

ASSET DETAILS

WT 11402685

WARRANTY DETAILS

WT 11402685

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11402685

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11402685

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11402685**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11402685**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11402685**

Additional Notes: **WT 11402685**

PROCEDURE STEP DETAILS **WT 11402685**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK SK 962

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	Closed	SITE 1-3001
RESPONSIBLE ORG	TINKER AFB - WATER AND SYSTEM MX - PLUMB AFTE BOS-BMC		
CUSTOMER ORG	TINKER AFB - 76 MXW (CSA G		
TASK TYPE	**REQUE**	HVAC Se	7:17 PM
EST HOURS	**PLANNE**	05/31/202 15:52:20	
TASK NAME	3A - 3001 POST R61 - WT -	TEAM LIN	582-4340
TASK DESCRIPTION	STEAM LINE WATER LEAK	61; POC	
	31May2022 1615 Contacted equipment this is governmen	kcht. 163 d to call MA	t onsite. 1650 offsite this is not Alutiiq contacted @ 19:30
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Requir	__Multi-S	__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Require	__Enviro	d __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11430962

REQUEST ID	CREATE TIME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11430962

ASSET DETAILS

WT 11430962

WARRANTY DETAILS

WT 11430962

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11430962

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11430962

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11430962**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11430962**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11430962**

Additional Notes: **WT 11430962**

PROCEDURE STEP DETAILS **WT 11430962**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 757406

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**ARY WO ATION**	SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**PONSIB ON**	NU)
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**TED DA**	3:54 PM
EST HOURS	0	**PLANNED START**	08/18/2022 08:38:20	**N**	
TASK NAME	3B - 3001 POST S33 BREAKRM - WT - INT PLUMB - SINK			-	2-7387
TASK DESCRIPTION	Sink in breakroom at post S33 in building 3001 is clogged.				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coord		FS/COMM/_____ rdination Required
	__ Digging Permit Required		__Environmental C		cess Clearance Required

SERVICE REQUEST DETAILS

WT 11757406

REQUEST ID	CREATED DATE/TIME		WORK PHONE
3085457	08/18/2022 08:22:13	L	(405)622-7387

FACILITY PROJECT DETAILS

WT 11757406

ASSET DETAILS

WT 11757406

WARRANTY DETAILS

WT 11757406

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11757406

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11757406

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11757406**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11757406**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11757406**

Additional Notes: **WT 11757406**

PROCEDURE STEP DETAILS **WT 11757406**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

W SK 1

WORK TASK DETAILS

TASK PRIORITY 1-Emergency Closed K E 1-3001

RESPONSIBLE ORG TINKER AFB - HVAC S
BMC

CUSTOMER ORG T B - 76 M W

TASK TYPE PM

EST HOURS

TASK NAME T S35 ir - - 245-4051

TASK DESCRIPTION TER AL

0956
1003
10:35
TO G
1100
WIT
UND
TO C

ONSITE
PAIRED AGAIN. WILL TALK WITH

OKE WITH THE REQUESTER; CALLED
THAT THIS LINE IS CLOGGED
ER AGAIN TO INFORM THEM THAT

FOREMAN'S NOTES TO CRAFTSMEN cautio

ermit R u d r nm ired

__ FD/SFS/COMM/_____ Coordination Required

__ Travel/Access Clearance Required

SERVICE REQUE S WT 11378874

REQUES	REATED DATE/TI	FULL NAME	WORK PHONE

FACILITY PROJE LS WT 11378874

ASSET DETAILS WT 11378874

WARRANTY DETAILS WT 11378874

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11378874

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11378874**

Primary Maintenance Reason Code **WT 11378874**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11378874**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11378874**

Additional Notes: **WT 11378874**

PROCEDURE STEP DETAILS **WT 11378874**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**K**	E 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC				NU)
CUSTOMER ORG	TINKER AFB - 76 AMXG				
TASK TYPE		**REQUEST CLASS**	Climate Control	**P** **E**	PM
EST HOURS		**PLANNED START**	05/18/2022 15:34:58	**P**	
TASK NAME	3B - 3001 & S-55 - WT - HVACC - STOP THE LEAK - Repair -				- 622
TASK DESCRIPTION	AT POST POST S-55 THERE IS A LEAK DRIPPING FROM HV				CTS.

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordina d /COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11381718

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11381718

ASSET DETAILS

WT 11381718

WARRANTY DETAILS

WT 11381718

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11381718

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11381718

Primary Maintenance Reason Code

WT 11381718

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

NOTES TO R&O ON ASSETS & LOCATION **WT 11381718**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11381718**

Additional Notes: **WT 11381718**

PROCEDURE STEP DETAILS **WT 11381718**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	K T	E 1-30
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC				(NU)
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks		8 PM
EST HOURS	0	**PLANNED START**	08/29/2022 08:55:33		
TASK NAME	3C - 3001 - WT - INT PLUMB - LEAK POSSIBLY FROM 736-5776			OL	UGH -
TASK DESCRIPTION	there is water in an old coolant trough in the back off the the humidity in there and the tools keep rusting. sink connected to the coolant trough. coolant trough was			t to	ny they
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop C __Environmenta	ed	COMM/ _ ation Re Clearance

[redacted]

SERVICE REQUEST DETAILS

WT 11797

REQUEST ID	CREATED DATE/TIME
3103982	08/29/2022 08:52:05

ORK PHO
05) 736-5

FACILITY PROJECT DETAILS

WT 11797 7

ASSET DETAILS

WT 11797 7

WARRANTY DETAILS

WT 11797 17

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11797517

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11797517

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11797517**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11797517**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11797517**

Additional Notes: **WT 11797517**

PROCEDURE STEP DETAILS **WT 11797517**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 138 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMA LOCAT**	R AFB SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPO PERSO**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Leaks	**PRINT**	2023, 6:38 PM
EST HOURS		**PLANNED START**	05/19/2022 14:02:35	**PLANN**	022 5
TASK NAME	3B - 3001 POST T-65 - WT - INT PLUMB - DRAIN LEAKING - Repair [redacted] - 736-5776				
TASK DESCRIPTION	PER THE ROOFERS THAT RESPONDED TO WT 11363762, THE IS IS A DRAIN LEAKING FROM T-65 INTO T-65. SENT VIA EMAIL THE PLUMBING SHOP AS IT **A NEW WT WILL NEED TO BE OPENED TO REPLACE CEILING TILES ONCE LEAK IS REPAIRED**				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi-Shop Coordination Required		__ FD/SFS/COMM/_____ Coordination Required	
	__ Digging Permit Required	__Environmental Coordination Required		__Travel/Access Clearance Required	

SERVICE REQUEST DETAILS — WT 11386064

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — WT 11386064

ASSET DETAILS — WT 11386064

WARRANTY DETAILS — WT 11386064

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11386064

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ — WT 11386064

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11386064**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11386064**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11386064**

Additional Notes: **WT 11386064**

PROCEDURE STEP DETAILS **WT 11386064**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted] K [redacted]

WORK TASK DETAILS

TASK PRIORITY	3B - Mediu Sustain	ed	SITE 1-3001
RESPONSIBLE ORG	TINKER A BMC	P -	NU)
CUSTOMER ORG	TINKER A		
TASK TYPE	Corrective	r Interior N	0:05 PM
EST HOURS	168	5/2022 1:37	
TASK NAME	3B - 3001 P TRANSFE	62169 STO - 739-4975	NOT SURE WHERE
TASK DESCRIPTION	3B - 3001 P UNIT NOT 22AUG202	R - T5595 - VAC. FU 11	ING FROM INSIDE AC
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety P quire __ Digging P red	_ ulti-Shop Co _ Environmental	S/COMM/_____ dination Required ss Clearance Required

SERVICE REQUEST DETAILS **WT 11784636**

REQUEST ID	CREATED DATE/TIME	FULL N	WORK PHONE
3099360	08/25/2022 10:20:03	LISA HAG	405 734 7083

FACILITY PROJECT DETAILS **WT 11784636**

ASSET DETAILS **WT 11784636**

WARRANTY DETAILS **WT 11784636**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11784636**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11784636**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11784636**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11784636**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11784636**

Additional Notes: **WT 11784636**

PROCEDURE STEP DETAILS **WT 11784636**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

TASK 11407421

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	1-3001
		ACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - W SYSTEM MX - PL BMC		UELS OS-	**RESPONSIBLE PERSON**	NU)
CUSTOMER ORG	TINKER AFB -		M		
TASK TYPE	Corrective			**E**	PM
EST HOURS	0				
TASK NAME	3B - 3001 POS 734-5856 - SR		MP D	EPA	PULLINS -
TASK DESCRIPTION	3B - 3001 PO 734-5856 HVACC POC		SUM	AKIN	4161 - RON PULLINS
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Pre __ Digging Pe		o Co ental	ed	__ FD/SFS/COMM/_____ Coordination Required __ Travel/Access Clearance Required

SERVICE REQUEST DETAIL

WT 11407421

REQUEST ID	WORK PHONE
2944047	405-734-5815

FACILITY PROJECT DETAIL

WT 11407421

ASSET DETAILS

WT 11407421

WARRANTY DETAILS

WT 11407421

ID	AL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11407421

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11407421

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11407421**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11407421**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11407421**

Additional Notes: **WT 11407421**

PROCEDURE STEP DETAILS **WT 11407421**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11396106

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS TRACKING STATUS**	Closed	**PRIMARY WORK LOCATION**	TINK [redacted] 3001
RESPONSIBLE ORG	TINKER AFB - PLANT OPS - INDUSTRIAL WASTEWATER TRMT - MAINT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 AMXG				
TASK TYPE		**REQUEST CLASS**	Leaks	**PRINTED DATE**	Mar 2
EST HOURS		**PLANNED START**	05/23/2022 08:23:52	**PLANNED END**	05/23 08:23
TASK NAME	3B - 3001 POST U49 - WT - IWTP - INDUSTRIAL WASTE PUMP IS LEAKING - Repair - [redacted] - 736-5776				
TASK DESCRIPTION	INDUSTRIAL WASTE PUMP IS LEAKING ALL OVER THE FLOOR				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11396106

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11396106

ASSET DETAILS

WT 11396106

WARRANTY DETAILS

WT 11396106

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11396106

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11396106

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11396106**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11396106**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11396106**

Additional Notes: **WT 11396106**

PROCEDURE STEP DETAILS **WT 11396106**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K 1 07

WORK TASK DE

TASK PRIORITY	[redacted]	P LO	**WORK** TINKER AFB SITE 1-3001
RESPONSIBLE ORG		R P	IBLE
CUSTOMER ORG			
TASK TYPE		C R	**DATE** Mar 3, 2023, 8:12 PM
EST HOURS		L	**END** 06/24/2022 08:56:35
TASK NAME			- 6202589
TASK DESCRIPTION		T	CTRICAL EQUIPMENT AND CEILING TILES E N STAIRS, FOUND MAIN PRIMARY DRAIN WAS W FLOOR, CUT HOLE IN FLOOR TO ACCESS, NNING AND MONITORED, CLEANED UP MESS IN CREATE FOLLOW UP FOR STRUCTURES TO
FOREMAN'S NOTES TO CRAFTSMEN		ation Required rdination Required	__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required

SERVICE REQUE **WT 11544607**

REQUEST ID	CREATED DATE/TIME	ULL NAME	WORK PHONE

FACILITY PROJECT DETAILS **WT 11544607**

ASSET DETAILS **WT 11544607**

WARRANTY DETAILS **WT 11544607**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11544607**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ **WT 11544607**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11544607**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11544607**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11544607**

Additional Notes: **WT 11544607**

PROCEDURE STEP DETAILS **WT 11544607**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11363612

WORK TASK DE

TASK PRIORITY	ium	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-30
		TRACKING STATUS			
RESPONSIBLE ORG	AFB - HVAC SHOP - C - BOS-			**RESPONSIBLE PERSON**	
CUSTOMER ORG	AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	e	**REQUEST CLASS**	HVAC Service	**TE**	Mar 2, 2023, 4:46 PM
EST HOURS		**PLANNED START**	05/14/2022 01:00:00	**D**	05/14/2022 01:00:00
TASK NAME	POST W81 - WT - HVAC C - AIR CONDITION 36-5776 - SR#2925934				INTO AISLEWAY - REPAIR -
TASK DESCRIPTION	t W81 lab's A/C unit is leaking into the W-X aisl ASK 11367630 WAS TURNED IN ON MONDAY ETED ALREADY; CANCEL THIS WORK TASK NO MATERIAL REQUIRED				736-5776 - SENT VIA EMAIL A HIGH PRIORITY 3A AND HA
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required	__Multi-Shop C __Environment		ired	__ FD/SFS/COMM/__ Coordination Req __ Travel/Access Clearanc d

SERVICE REQUEST DETAILS WT 1136

REQUEST ID	CREATED DATE/TIME		WORK PHO
2925934	05/13/2022 14:52:40	D	405-734-311

FACILITY PROJECT DETAILS WT 11363612

ASSET DETAILS WT 11363612

WARRANTY DETAILS WT 11363612

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11363612

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11363612

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11363612**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11363612**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11363612**

Additional Notes: **WT 11363612**

PROCEDURE STEP DETAILS **WT 11363612**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1 0

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**STATUS**	Closed	**ORK**	TINKER AFB SITE
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**LE**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	HVAC Service	**TE**	Mar 2, 2023, 6:14 P
EST HOURS	0	**PLANNED START**	05/16/2022 07:04:59		05/16/2022 07:04:59
TASK NAME	3A - BLDG 3001 POST X81 - WT - HVAC C - WATER LE 736-4500 - SR#2926812				ATE LINE - REPAIR - D
TASK DESCRIPTION	WATER LEAK FROM CONDENSATE LINE AT POST X- 16MAY2022 DUPLICATE OF WORK TASK # 11367630 NO MATERIALS FOUND				6-4500
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop C __Environment		__ FD/SFS/COMM/__ Coordination Req d __Travel/Access Clearanc d

SERVICE REQUEST DETAILS

WT 11367

REQUEST ID	CREATED DATE/TIME	WORK PHON
2926812	05/16/2022 07:03:41	405-734-3117

FACILITY PROJECT DETAILS

WT 11367380

ASSET DETAILS

WT 11367380

WARRANTY DETAILS

WT 11367380

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11367380

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11367380

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11367380**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11367380**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11367380**

Additional Notes: **WT 11367380**

PROCEDURE STEP DETAILS **WT 11367380**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Open Work Tasks - CUI/SP-FNC

02/23/2023 13:09:11

Task ID	Task Priority	Task Name	Work Classification
11225086	3C - Low Sustain	TEST - 3C - 3001 POST O73 - WT - INT PLUMB - 2 TOILETS CLOGGED - REPAIR - HOOD - 18APR2022 - 2881304	Repair
11225087	3C - Low Sustain	DEFAULT - Work Task Template - Corrective Maintenance-Clogs	Repair
11225089	3C - Low Sustain	DEFAULT - Work Task Template - Corrective Maintenance-Clogs	Repair
11350207	3C - Low Sustain	3C - 3001 Post K67 - WT - Lock - Reset Cypher Lock Code - 11May2022 - SR# 2920190	Repair
11353607	3C - Low Sustain	3C - 3001 - WT - Structures - Door hitting door frame - Repair - [redacted] - SR2921283	Repair
11362333	1-Emergency	COMPLETE - 1 - 3001 Post 2Q74 - WT - HVACC - High humidity work stoppage - Repair - [redacted] 582-4340 - SR 2925261	Repair
11362949	3B - Medium Sustain	3B - 3001 Post 2W-48 - WT - Struc - Corner of door is hitting frame - Repair - [redacted] - 736-4118 - SR# 2925582	Repair
11363032	3C - Low Sustain	3C - 3001 - WT - INT PLUMB - Back flow leaking - Repair - T0280 - [redacted] - 734-2753 - SR# 2925627 - UID: 3001-BFRP-PD100	Repair
11363062	3B - Medium Sustain	3B - 3001 Post Y-62 - WT - SPRINK - Pressure Gauge Leaking from Knob - Repair - [redacted] - 736-9977 - SR# 2925649 - PSFS-P204	Repair
11363456	3B - Medium Sustain	3B - 3001 Post T105 - WT - HVACC - AC has stopped working at post T105 - Repair - [redacted] - 736-5776 - SR# 2925831	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11363612	3B - Medium Sustain	3B - 3001 POST W81 - WT - HVAC C - AIR CONDITIONING UNIT LEAKING INTO AISLEWAY - REPAIR - [redacted] 736-5776 - SR#2925934	Repair
11363762	3B - Medium Sustain	3B - 3001 Post T-65 - WT - Roof - Roof Leak - Repair - [redacted] - 736-5776 - SR# 2926011	Repair
11364008	3C - Low Sustain	3C - 3001 Y-80 - WT - Shop - ISWP - 25479-Install ADA door opener - Repair - [redacted] - 739-8921 - AFSC-748	Repair
11364782	3B - Medium Sustain	3B - 3001 POST 2B87 - WT - ROOF - ROOF LEAK - Repair - T5524 - [redacted] - 519-7894	Repair
11364816	3B - Medium Sustain	3B - 3001 POST P45 - WT - ROOF - ROOF LEAK - Repair - T5724 - [redacted] - 739-4975	Repair
11364818	3B - Medium Sustain	3B - 3001 POST T105 - WT - ROOF - ROOF LEAK - Repair - T5731 - [redacted] - 739-4975	Repair
11364820	3B - Medium Sustain	3B - 3001 POST 3S69 - WT - ROOF - ROOF LEAK - Repair - T5943 - [redacted] - 582-4590	Repair
11364821	3B - Medium Sustain	3B - 3001 POST P111 - WT - MACHINE MAINT - OH DOOR 4 ERROR - Repair - T5991 - [redacted] - 736-5776	Repair
11364894	3C - Low Sustain	3C - 3001 POST X71 - RS67 - WT - ROOF - ROOF LEAK - Repair - T5721 - [redacted] - 739-4975	Repair
11364895	3B - Medium Sustain	3B - 3001 POST X71 - WT - ROOF - ROOF LEAK - Repair - T5721 - [redacted] - 739-4975	Repair
11364896	3B - Medium Sustain	3B - 3001 POST X75 - WT - ROOF - ROOF LEAK - Repair - T5721 - [redacted] - 739-4975	Repair
11364897	3B - Medium Sustain	3B - 3001 POST X79 - WT - ROOF - ROOF LEAK - Repair - T5721 - [redacted] - 739-4975	Repair
11364898	3B - Medium Sustain	3B - 3001 POST X83 - WT - ROOF - ROOF LEAK - Repair - T5721 - [redacted] - 739-4975	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11364899	3B - Medium Sustain	3B - 3001 POST X89 - WT - ROOF - ROOF LEAK - Repair - T5721 - [redacted] - 739-4975	Repair
11364901	3B - Medium Sustain	3B - 3001 POST X95 - WT - ROOF - ROOF LEAK - Repair - T5721 - [redacted] - 739-4975	Repair
11364902	3B - Medium Sustain	3B - 3001 POSTS G70 & G105 - WT - ROOF - ROOF LEAKS - Repair - T5728 - [redacted] - 739-4975	Repair
11364903	3B - Medium Sustain	3B - 3001 POST U103 - WT - ROOF - ROOF LEAK - Repair - T5733 - [redacted] - 739-4975	Repair
11364904	3B - Medium Sustain	3B - 3001 POST U95 - WT - ROOF - ROOF LEAK - Repair - T5733 - [redacted] - 739-4975	Repair
11364905	3B - Medium Sustain	3B - 3001 POST E105 - WT - ROOF - ROOF LEAK - Repair - T5734 - [redacted] - 739-4975	Repair
11364906	3B - Medium Sustain	3B - 3001 POST E107 - WT - ROOF - ROOF LEAK - Repair - T5734 - [redacted] - 739-4975	Repair
11364949	3B - Medium Sustain	3B - 3001 POST 1AF72A - WT - HVACC - AC BLOWING WARM - Repair - T6204 - [redacted] - 417-2893 - 0 - AHU 2 LOWER	Repair
11364952	3B - Medium Sustain	3B - 3001 PLANT MAINT. - WT - HVACC - PATRIOT CONFERENCE ROOM IS HOT - Repair - T6434 - [redacted] - 417-2893 - 0 - PKG B1	Repair
11364967	3B - Medium Sustain	3B - 3001 PLATING SHOP ALARM - WT - ALARM - NETWORK SYSTEM ERROR - Repair - S6731 - [redacted] - 734-7964	Repair
11364970	3B - Medium Sustain	3B - 3001 POST 1AH1 103C - WT - HVACC - POST 1AH1 103C IS VERY HUMID AND HOT - Repair - T6220 - [redacted] - 628-3214 - 0 - AHU 12 LOWER	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11364973	3B - Medium Sustain	3B - 3001 POST 1AC1 106C - WT - BAS - HOT & HUMID T6211 - [redacted] - 410-3152 AHU 9L, 10L NEW PR 4768 2/22/23	Repair
11364981	3B - Medium Sustain	3B - 3001 Y67 - WT - TAC PIPEFITTING- VERIFY PRV OPERATION ON MAKEUP WATER MANIFOLD. - Repair - T4459 - [redacted] - 801-971-7286	Repair
11364996	3B - Medium Sustain	3B - 3001 POST X/Y-56 - WT - BAS - HVAC DIFFUSERS BLOWING DEBRIS ONTO ENGINE PARTS - Repair - T5227 - [redacted] - 736-4118 - 0 - FD 6	Repair
11365349	3B - Medium Sustain	3B - 3001 POST 2AE66A - WT - ROOF - ROOF LEAK - Repair - T5483 - [redacted] - 408-1339 - WEATHER - FAST	Repair
11366258	3B - Medium Sustain	3B - 3001 POST L111 - WT - INTELEC - EXTERIOR LIGHT IS OUT - Repair - T2484 - [redacted] - 622-7846	Repair
11366259	3B - Medium Sustain	3B - 3001 POST 2X2 - WT - STRUC - LATCH MECHANISM IS INOP - Repair - T2723 - [redacted] - 405-417-8194	Repair
11367380	3A - High Sustain	3A - BLDG 3001 POST X81 - WT - HVAC C - WATER LEAK FROM CONDENSATE LINE - REPAIR - [redacted] 736-4500 - SR#2926812	Repair
11367428	3A - High Sustain	3A - 3001 POST S35 - WT - PIPE - PIPE HAS WATER HAMMER BROKEN AT FLANGE - REPAIR - [redacted] 432-7097 - SR#2926834	Repair
11367621	3A - High Sustain	3A - 3001 POST S35 - WT - IWTP - PIPE HAS WATER HAMMER BROKEN AT FLANGE - REPAIR - [redacted] 432-7097 - SR#2926949	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11367630	3A - High Sustain	3A - 3001 X81 - WT - HVACC - WATER LEAK FROM CONDENSATE DRAIN - Repair - [redacted] - 736-4500 - SR#2926954	Repair
11367922	3B - Medium Sustain	3B - 3001 POST 2AH1 90B - WT - SYSTEMS - CONTROLS - AIRFLOW NEEDS ADJUSTED - REPAIR - [redacted] 736-1882 - SR#2927187	Repair
11368094	3B - Medium Sustain	3B - 3001 POST M-55 - WT - HVACC - STEAM LINE ABOVE BEARING SHOP NEEDS REPAIR - Repair - T6284 - [redacted] - 736-2085 - 0 - 0	Repair
11368107	3B - Medium Sustain	3B - 3001 POST O-47; KITTING CAGE - WT - INSULATOR - CONDENSATION LEAK - Repair - T6306 - [redacted] - 736-2085 - 0 - AHU P210	Repair
11368137	3B - Medium Sustain	3B - 3001 POST O-65 - WT - INTPLUMB - CHILLED WATER LINES LEAKING - Repair - T6345 - BRIAN WELSH - [redacted] - 0 - FAST FD 24N	Repair
11368147	3B - Medium Sustain	3B - 3001 POST 1AD831 - WT - HVACC - ROOM TOO COLD - Repair - [redacted] - 464-3381 - SR#2927355	Repair
11369110	3B - Medium Sustain	3B - 3001 POST Y56 - WT - STRUC - ADJUST CLOSERS ON NEW EXTERIOR DOORS - Repair - [redacted] - 736-9977	Repair
11369224	3B - Medium Sustain	3B - 3001G MEN'S RR - WT - PLUMB INT - TOILET CONTINUOUSLY FLUSHING - REPAIR - [redacted] 492-2496 - SR#2927980	Repair
11369461	3B - Medium Sustain	3B - 3001 Central Plant - OP - Replace Isolation valves - ENG FLIGHT - 25544 - [redacted] - 405-622-7846	Repair
11369669	3C - Low Sustain	3C - 3001 Central Plant - OP - Chilled water distribution study - 25360 - [redacted] - 622-7846	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11369763	3B - Medium Sustain	3B - 3001 EBI - WT - HONEYWELL - PKG B1 B2 B3 NOT COMMUNICATING TO EBI - REPAIR - [redacted] 582-5009 - SR#2928352	Repair
11369808	3B - Medium Sustain	3B - 3001 ANNEX G, RM 107 - WT - STRUC - ROOF LEAK - Repair - T5910 - [redacted] - 492-2496 - 0 - 0	Repair
11370030	3B - Medium Sustain	3B - 3001 ANNEX G, RM 104 - WT - HVACC - CRAC UNIT INOP - Repair - T6213 - [redacted] - 405-409-5733 - 0 - CRAC 2	Repair
11370201	3C - Low Sustain	3C - 3001 - OP - Replace N. 210 [redacted] in Horseshoe - 25833 - [redacted] - 736-4730	Repair
11372458	3C - Low Sustain	3C - 3001 TANK & COOLER - WT - STRUC - CORRECT NFPA-80 FIRE DOOR DEFICIENCIES - Repair - S1274 - [redacted] - 736-2085	Repair
11372500	3C - Low Sustain	3C - 3001 TANK & COOLER - WT - PAINT - CORRECT NFPA-80 FIRE DOOR DEFICIENCIES - Repair - S1274 - [redacted] - 736-2085	Repair
11372613	3B - Medium Sustain	3B - 3001 POST Y77 - WT - ALARM - SUPERVISORY ALARM ISSUE - FD WAS DISPATCHED - Repair - T6125 - [redacted] - 734-7964 - 0 - FA-P10999	Repair
11373485	3B - Medium Sustain	3B - 3001 POST O47-X57 - WT - STRUC - RELOCATE AND HANG FIRE EXTINGUISHERS - REPAIR - [redacted] 736-4118	Repair
11373575	3C - Low Sustain	3B - 3001G ROOM 104 DATACENTER - WT - ROOF - ROOF LEAK - REPAIR - J[redacted] [redacted] 409-5733	Repair
11373598	3B - Medium Sustain	3B - 3001 ANNEX 4 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 409-5733	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11374273	3B - Medium Sustain	3B - 3001 POST T105 - WT - HVACC - AIR CONDITIONER INOP - REPAIR - [redacted] 736-5776	Repair
11374357	3B - Medium Sustain	3B - 3001 PLASMA SHOP - WT - SPRINK - PUT SPRINKLER SYSTEM BACK TOGETHER - REPAIR - [redacted] 736-5776 - PSFS-P244	Repair
11375743	3B - Medium Sustain	3B - 3001 & 2AC4-89D- WT - STRUCTURES - REPLACE 3 STAINED CEILING TILES - Repair - IWIMS# - [redacted] - 405-736-1882	Repair
11375866	3B - Medium Sustain	3b - 3001 & 2AC4-89D - WT - ROOF - FIX ROOF LEAK - Repair - [redacted] - 405-736-1882	Repair
11375924	3B - Medium Sustain	3B - 3001 POST 1A1 75A - WT - DOORELEC - INSTALL MAG-LOCK RELEASE BUTTON - Repair - T5315 - [redacted] - 405-417-2893	Repair
11375975	3A - High Sustain	3A - 3001 POST 2X107 - WT - MOLD - MOLD INSPECTION - Repair - T6440 - [redacted] - MOLD	Repair
11377211	3A - High Sustain	3A - 3001 POST 1AJ78A - WT - ELEC DOOR - HANDICAP DOOR INOP - Repair - [redacted] - 739-8921	Repair
11377286	3B - Medium Sustain	3B - 3001 POST X/Y-56 - WT - SHEET METAL - RELOCATE DIFFUSER - Repair - [redacted] - 405-642-8309 - SR# 2931891	Repair
11378045	3B - Medium Sustain	3B - 3001 POST I63 - WT - BAS - TEMP AND HUMIDITY TOO HIGH - REPAIR - [redacted] 736-7752	Repair
11378069	3B - Medium Sustain	3B - 3001 POST 1A187A - WT - STRUC - REPLACE WOOD MECH RM DOOR - T6388 - [redacted] - 736-5230	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11378084	3B - Medium Sustain	3B - 3001 POST XR111 BREAKROOM - WT - PLUMB INT - BREAKROOM SINK CLOGGED - Repair - [redacted] - 7365716	Repair
11378128	3B - Medium Sustain	3B - 3001 - WT - BAS - AC IS RUNNING AND WONT SHUT OFF - Repair - [redacted] - 5824340	Repair
11378195	3B - Medium Sustain	3B - 3001 POST 104 - WT - PLUMB INT - 2 INOP URINALS - Repair - [redacted] - 4178194	Repair
11378259	3B - Medium Sustain	3B - 3001 POST O47 - WT - ROOF - ROOF LEAK CHECK - REPAIR - [redacted] 734-2765	Repair
11378650	3B - Medium Sustain	3B - 3001 POST 1AH71 - WT - STRUC - HAND RAIL IS LOOSE ON STAIRS - REPAIR - [redacted] 370-1490	Repair
11378870	3B - Medium Sustain	3B - 3001 POST 2E82 - WT - STRUC - ROOF LEAK CAUSING WET CEILING TILES - REPAIR - [redacted] 855-3012	Repair
11378874	1-Emergency	1 - 3001 POST S35 - WT - HVACC - CHILLED WATER LINE LEAKING - Repair - [redacted] - 245-4051	Repair
11379103	1-Emergency	1 - 3001 POST S35 - WT - PLUMB INT - SNAKE LINE FOR HVAC - REPAIR - [redacted] 245-4051	Repair
11379387	4A - High Enhance	4A - 3001 Post 1AH81A - INT ELEC - ISWP - 25885 - Install 3 electrical outlets - [redacted] - 734-8604 - CI-510	Repair
11380004	3B - Medium Sustain	3B - 3001 & POST P-39 - WT - Shop - MOVE PULL STATION TO P-39 - Repair - [redacted] - 582-4878	Repair
11380067	4B - Low Enhance	4B - 3001 -WT - LOCK ESTIMATE - 25884 - perform site survey for cypher lock Post1AG81 - [redacted] 734-8604	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11380218	3B - Medium Sustain	3B - 3001 POST H67 - WT - HVACC - HUMIDITY HIGH - REPAIR - [redacted] 739-4246	Repair
11380608	3B - Medium Sustain	3B - 3001 POST Y97 - WT - LOCK - CYPHER LOCK COMBO CHANGE - REPAIR - [redacted] 736-5776	Repair
11381095	3C - Low Sustain	3C - 3001 post 2G77 - WT - SPRINK - ISWP - 25227-RELOCATE ONE SPRINKLER HEAD - Repair - [redacted] 735-5871 CI-496	Repair
11381718	3B - Medium Sustain	3B - 3001 & S-55 - WT - HVACC - STOP THE LEAK - Repair - [redacted] - 622-7549	Repair
11383838	3C - Low Sustain	DEFAULT - Work Task Template - Corrective Maintenance-General Repairs	Repair
11384796	3B - Medium Sustain	3B - 3001 GRID P57 - WT - HONEYWELL - BAS: CHILL WATER VALVE WON'T CLOSE - REPAIR - [redacted] - 582-5009	Repair
11385102	3B - Medium Sustain	3B - 3001 POST H-61 PLATING SHOP - WT - HONEYWELL - AHU-P227 HAS LARGE SWINGS IN SUPPLY AIR TEMP - Repair - [redacted] - 582-5009	Repair
11385195	4A - High Enhance	EVAL COMPLETE - 4A - 3001 Post G77 - 25900 - Reassess alternate tornado shelter location - [redacted] - 736-5871	Repair
11385381	3B - Medium Sustain	3B - 3001 G DOOR G15 - WT - INT PLUMB - WATER LEAK - Repair - [redacted] - 4922496	Repair
11385451	3B - Medium Sustain	3B - 3001 TOAP LAB - WT - HONEYWELL - ROOM TEMP AND HUMIDITY CALIBRATED - Repair - [redacted] - 5825009 - AHU-PH62	Repair
11386064	3B - Medium Sustain	3B - 3001 POST T-65 - WT - INT PLUMB - DRAIN LEAKING - Repair - [redacted] - 736-5776	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11386295	3B - Medium Sustain	3B - 3001 POST L67 - WT - BAS - BAS: CHECK SPACE TEMP W/CALIBRATED TEMP SENSOR - Repair - [redacted] - 582-5009	Repair
11386420	3B - Medium Sustain	3B - 3001 1AI75A - WT - INT ELEC - DOOR LOCK REPAIR - Repair - [redacted] - 4172893	Repair
11387982	3B - Medium Sustain	3B - 3001 Post P61 - WT - AFTER HVAC - Condensate leak - Repair - [redacted] - 801-971-7286	Repair
11389596	3B - Medium Sustain	3B - 3001 POST 1AG/82A - WT - INT ELEC - EMER LIGHT REPAIR - REPAIR - T4003 - [redacted] - 7348604	Repair
11390201	3B - Medium Sustain	3B - 3001 POST P57 - WT - HVACC - CONDENSATION LEAK - Repair - [redacted] - 420-4404	Repair
11390457	3B - Medium Sustain	3B - 3001 - POST 2E82 - INSULATOR - F/U 11378870 DUCT WORK IS LEAKING AND NEEDS INSULATED - REPAIR - [redacted] - 734-7083	Repair
11391348	4A - High Enhance	4A - 3001 Post M-79 - OP - Demo existing white house 13'x50' - [redacted] - 736-4118 wesley programming	Repair
11392448	4A - High Enhance	4A - 3001 Post 2Q74 - WT - INT ELEC - ISWP - 25629-Move light switch to inside of office space - Repair - [redacted] 622-7846 CSAG-251 FT	Repair
11392511	3B - Medium Sustain	3B - 3001 AHU-A6L POST AE84A - WT - HONEYWELL - SEQUENCE DOESNT APPEAR TO WORK - Repair - [redacted] - 582-5009	Repair
11393174	3C - Low Sustain	3C - 3001 POST Y9 - WT - STRUC - PANIC DEVICE WILL NOT LATCH - Repair - [redacted] - 801-971-7286	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11393175	3C - Low Sustain	3C - 3001 POST Y15 - WT - STRUC - PANIC DEVICE GUTS MISSING - Repair - [redacted] - 801-971-7286	Repair
11393176	3C - Low Sustain	3C - 3001 POST Y15 - WT - INT ELEC - PANIC DEVICE ALARM INOP - Repair - [redacted] - 801-971-7286	Repair
11393177	3C - Low Sustain	3C - 3001 POST 2Y32 - WT - STRUC - SERVICE DOOR & FRAME - Repair - [redacted] - 801-971-7286	Repair
11393178	3B - Medium Sustain	3C - 3001 POST B11 - WT - STRUC - DOOR DOESNT CLOSE CORRECTLY - Repair - [redacted] - 801-971-7286	Repair
11393179	3C - Low Sustain	3C - 3001 POST B13 - WT - STRUC - MULTIPLE ISSUES WITH DOOR FRAME - Repair - [redacted] - 801-971-7286	Repair
11393180	3C - Low Sustain	3C - 3001 POST B12 - WT - STRUC - DOOR HINGE LOOSE/DOESNT CLOSE PROPERLY - Repair - [redacted] - 801-971-7286	Repair
11393181	3C - Low Sustain	3C - 3001 POST Y11 - WT - STRUC - PANIC DEVICE LATCH BROKEN - Repair - [redacted] - 801-971-7286	Repair
11393182	3C - Low Sustain	3C - 3001 POST Y35 - WT - STRUC - DOOR CLOSER NOT WORKING PROPERLY - Repair - [redacted] - 801-971-7286	Repair
11393194	3C - Low Sustain	3C - 3001 POST AB04 - WT - STRUC - DOOR PUSH BAR NOT RELEASING - Repair - [redacted] - 801-971-7286	Repair
11393896	3B - Medium Sustain	3B - 3001 Post X111 door 2A - WT - LOCKS - Panic bar is not latching correctly - repair - [redacted] 801-971-7286	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11393897	3B - Medium Sustain	3B - 3001 post B70 door 14 - WT - STRUCTURES - door is not mechanically closing - repair - [redacted] 801-971-7286	Repair
11396106	3B - Medium Sustain	3B - 3001 POST U49 - WT - IWTP - INDUSTRIAL WASTE PUMP IS LEAKING - Repair - [redacted] - 736-5776	Repair
11396207	3B - Medium Sustain	3B - 3001 POST R49 - WT - IWTP - INDUSTRIAL WASTE PUMP IS LEAKING - Repair - [redacted] - 736-5776	Repair
11396815	3B - Medium Sustain	3B - 3001 Post I-102 - WT - Sheet Metal - ISWP - 24954-Install metal safety railing for roof access hatch - [redacted] 622-7846 CSAG-208	Repair
11396832	3B - Medium Sustain	3B - 3001 Post I-102 - WT - ROOF - ISWP - 24954-Install metal safety railing for roof access hatch - [redacted] 622-7846 CSAG-208	Repair
11396840	3B - Medium Sustain	3B - 3001 POST Y19 - WT - LOCK - CYPHER LOCK NOT WORKING - REPAIR - [redacted] 417-8194 - SR#2939596	Repair
11396841	3B - Medium Sustain	3B - 3001 Post I-102 - WT - WELD - ISWP - 24954-Install metal safety railing for roof access hatch - [redacted] 622-7846 CSAG-208	Repair
11398723	3B - Medium Sustain	3B - 3001G MECH ROOM 117 - WT - HVACC - CHILLER PUMP 2 IN ALARM - [redacted] - 582-5009	Repair
11399702	3B - Medium Sustain	3B - 3001 Fan deck 1 and 2 - WT - AFTER - remove debris - repair - [redacted] 819-8135	Repair
11400348	3B - Medium Sustain	3B - 3001 Room 26 Post 2U77 - WT - INT ELEC - DISCONNECT POWER TO LIGHTS NEAR ROOF LEAK - repair - [redacted] 823-8833	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11401805	3B - Medium Sustain	3B - 3001 POST Y49 - WT - ALARM - ALARM GOING OFF - REPAIR - [redacted] 417-8194 - 3001-FA-P10154	Repair
11401809	3B - Medium Sustain	3B - 3001 POST 2AH73A - WT - ROOF - HEAVY LEAK - REPAIR - [redacted] - 408-1339 - STORM	Repair
11401860	3B - Medium Sustain	3B - 3001 POST 2FH73A - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 408-1339 - STORM	Repair
11401900	3B - Medium Sustain	3B - 3001 Room 26 Post 2U77 - WT - ROOF - F/U 11400348 Roof leak - repair - [redacted] 823-8833 - STORM	Repair
11401961	3C - Low Sustain	3B - 3001 Post 1AI75A - WT - LOCK - ORDER & REPLACE 6 (EA.) OILED BRONZE LEVER - Repair - T1287 - [redacted] - 417-2893	Repair
11402079	3B - Medium Sustain	3B - 3001 POST Y97 - WT - ELEC INT - EXIT SIGN INOP - REPAIR - [redacted] 734-5043	Repair
11402685	3B - Medium Sustain	3B - 3001 POST R49 - WT - HVAC C - MONITOR SUMP PUMP DRAIN LEAKING - REPAIR - T4161 - [redacted] 734-5856	Repair
11403028	3B - Medium Sustain	3B - 3001 POST P57 - WT - INSULATOR - CONDENSATION LEAK - REPAIR - [redacted] - 420-4404	Repair
11403742	3B - Medium Sustain	3B- 3001 POST 1AD831 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 4643381 - STORM	Repair
11404539	3B - Medium Sustain	3B- 3001 POST 2AF68A - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 3701490 - STORM	Repair
11404634	3C - Low Sustain	3C - 3001 POST 2X7 - RS37 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 4178194 - STORM	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11404804	3B - Medium Sustain	3B - 3001- WT - LOCK- MAKE 3 COPIES OF KEY - Repair - [redacted] - 628-3214	Repair
11404842	3B - Medium Sustain	3B - 3001 & CHILLER PLANT- WT - HONEYWELL- FIX JACE - Repair - [redacted] -5825009	Repair
11404940	3A - High Sustain	3A - 3001 POST W91 - WT - MOLD - DRTC - POSSIBLE MOLD IN VENT - Repair - [redacted] - 736-5776 - MOLD	Services
11405713	3B - Medium Sustain	3B - 3001 POST A55.1 - - WT - ROOF - ROOF LEAK - Repair - [redacted] - 736-5776 - STORM	Repair
11405812	3B - Medium Sustain	3B - 3001 Fan deck 3 and 4 - WT - AFTER - remove of debris - repair - [redacted] 819-8135	Repair
11406718	3B - Medium Sustain	3B - 3001 P75 to FD21 - WT - HONEYWELL - Inadequate lighting - repair - [redacted] 819-8135	Repair
11406722	3B - Medium Sustain	3B - 3001 Fan deck 3 - WT - HONEYWELL - Lights are out above FD3 - repair - [redacted] 819-8135	Repair
11407173	3A - High Sustain	3A - 3001 - post 3S69 - WT - Roof - Roof leak - repair - [redacted] - 582-4590	Repair
11407421	3B - Medium Sustain	3B - 3001 POST R49 - WT - PLUMB INT - SUMP PUMP DRAIN LEAKING - REPAIR - T4161 - [redacted] - 734-5856 - SR#2944047	Repair
11407518	3B - Medium Sustain	3B- 3001 & POST AD-70- WT - HONEYWELL - FIX LIGHTING ISSUES - Repair - [redacted] - 801-971-7286	Repair
11407740	3B - Medium Sustain	3B - 3001 POST 3S69 - WT - ELEC INT - ASSIST ROOFERS - REPAIR - [redacted] 582-4590	Repair
11407927	3B - Medium Sustain	3B - 3001 - post 3S69 - RS74 - WT - Roof - F/U 11407173 Roof leak - repair - [redacted] - 582-4590 - STORM	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11408517	3C - Low Sustain	3C - 3001 Post 1AG 76 - CBR - Refurbish AFSC/LG Area - [redacted] - 739-8921	Services
11408548	3B - Medium Sustain	3B - 3001 PATRIOT ROOM - WT - HVACC - CONDENSATE LEAK - REPAIR - [redacted] - 73458956	Repair
11408644	3B - Medium Sustain	3B - 3001 POST O-47 - WT - LOCK - CIPHER LOCK DEVICE REMOVED - REPAIR - [redacted] - 7362085	Repair
11408706	3B - Medium Sustain	3B - 3001 DOOR Y35 - WT - STRUC - REMOVE DOOR HARDWARE - Repair - [redacted] - 5824340	Repair
11411006	3B - Medium Sustain	3B - 3001G - WT - HVACC - NEED TO START REDUNDANT CHILLER - REPAIR - [redacted] 734-5856	Repair
11412221	3B - Medium Sustain	3B - 3001 POST F75 - RS67 - WT - ROOF - ROOF LEAK - Repair - [redacted] - 736-5776 - STORM	Repair
11412595	3C - Low Sustain	3C - 3001 ANNEX G - 1ST FLR MENS RR - WT - HVACC - REPAIR EXHAUST FAN - REPAIR - T3318 - [redacted] - 492-2496 - -	Repair
11412796	3B - Medium Sustain	3B - 3001 All Fan Decks - WT - AFTER - removal of debris - REPAIR - [redacted] 819-8135	Repair
11412848	3C - Low Sustain	3C - 3001 POST O93 ELEC VAULT - WT - INTELEC - FF/MISSING PANEL SCREWS ON TRANSFORMER - REPAIR - T3544 - [redacted] - 734-5043 - - 3001XFMRP202	Repair
11412851	3C - Low Sustain	3C - 3001 POST M63 ELEC VAULT5 - WT - INTELEC - FF/MISSING PANEL SCREWS ON SWITCHGEAR - REPAIR - T3545 - [redacted] - 734-5043 - - 3001SWGP1086	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11412856	3C - Low Sustain	3C - 3001 FD-H68 - WT - STRUC - CORRECT NFPA -80 FIRE DOOR DEFICIENCIES 3001-FD-H68 - REPAIR - S1079 - [redacted] - 622-7846 - -	Repair
11412861	3C - Low Sustain	3C - 3001 FD-M53-7 - WT - STRUC - CORRECT NFPA -80 FIRE DOOR DEFICIENCIES 3001-FD-M53-7 - REPAIR - S1275 - [redacted] - 736-2085 - -	Repair
11412864	3C - Low Sustain	3C - 3001 POST K69 - WT - INTELEC - FF/MISSING PANEL SCREWS - REPAIR - T3646 - [redacted] - 734-5043 - - 3001PNL10171	Repair
11412866	3C - Low Sustain	3C - 3001 PLANT - WT - HVACC - CHW PUMP MOTOR #2 HAS BAD BEARINGS - REPAIR - S2449 - [redacted] - 734-5856 - -	Repair
11412886	3C - Low Sustain	3C - 3001 POST O65 - WT - STRUC - REPAIR DAMAGED EXTERIOR WALL - REPAIR - T3698 - [redacted] - 736-7752 - -	Repair
11412988	3C - Low Sustain	3C - 3001 AHU-FD17S & MAU-P17S - WT - HVACC - AHU AND MAU FAIL TO START - REPAIR - S7906 - [redacted] - 323-0319 - - AHU 17S	Repair
11413073	3C - Low Sustain	3C - 3001 D100 - WT - INTPLUMB - LEAKING BACKFLOW - REPAIR - T0280 - [redacted] - 734-7148 - - BFRP-PD100	Repair
11413088	3C - Low Sustain	3C - 3001 POST Y-3 - WT - ROOF - FF/INVESTIGATE LEAK - T0677 - [redacted] - 734-5815 - RS-121	Repair
11413089	3C - Low Sustain	3C - 3001 PRODUCTION COL O54 - WT - BAS - FF/SEVERAL POINTS OVERRIDDEN AT PROGRAMMING LEVEL - REPAIR - T4083 - [redacted] - 818-1590 - - CNTR-P212	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11413093	3C - Low Sustain	3C - 3001 PRODUCTION COL O54 - WT - BAS - FF/SPACE IS LOW ON DUCT STATIC (1.12/2.5) WITH FAN AT 100% - REPAIR - T4092 - [redacted] - 818-1590 - - C	Repair
11413095	3C - Low Sustain	3C - 3001 POST Z31 - WT - STRUC - DOUBLE EXTERIOR DOORS TO HIGH VOLTAGE MECH ROOM NEED NEW WEATHERSTRIPPING - REPAIR - T1075 - [redacted] - 622-7846	Repair
11413100	3C - Low Sustain	3C - 3001 POST X79 - WT - INTELEC - F/U T1115 ROOF DRAIN LEAK - REPAIR - T1116 - [redacted] - 556-1954	Repair
11413104	3C - Low Sustain	3C - 3001 B3001G POST G-17 - WT - STRUC - DMAGED CEILING TILES - REPAIR - T1137 - [redacted] - 405-492-2496 - -	Repair
11413437	3C - Low Sustain	3C - 3001 POST J-73 - WT - IWTP MAINT - TROUBLESHOOT LIFT STATION - REPAIR - T2334 - [redacted] - 734-3114 - -	Repair
11413455	3C - Low Sustain	3C - 3001 AOP CONF RM - WT - INTELEC - LIGHT SWITCH LABELED CONFERENCE IN SESSION LIGHT IS CRACKED - REPAIR - T4272 - [redacted] - 736-9977 - -	Repair
11413461	3C - Low Sustain	3C - 3001 POST 2Y55 PROD OFC - WT - INTELEC - CHK PLUGS ON MODULAR - REPAIR - T4276 - [redacted] - 739-9977 - -	Repair
11413480	3C - Low Sustain	3C - 3001 POST 2G-77 - RS68 - LEAN TO - WT - ROOF - ROOF LEAK - REPAIR - T2743 - [redacted] - 582-6991 - -	Repair
11413481	3C - Low Sustain	3C - 3001 FAN DECK 17 S - WT - HVACC - SUPPLY AIR FAIL TO START ALARM - REPAIR - T2761 - [redacted] - 622-7846 - -	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11413484	3C - Low Sustain	3C - 3001 POST 2C76 - WT - HVACC - AC IS NOT WORKING - REPAIR - T2780 - [redacted] - 739-4975	Repair
11413506	3C - Low Sustain	3C - 3001 POST U102 - WT - STRUC - STORAGE/HAZMAT RM DOOR NOT HANGING STRAIGHT - REPAIR - T4405 - [redacted] - 736-4118 - -	Repair
11413507	3C - Low Sustain	3C - 3001 POST 2W83 - WT - INTELEC - ELECTRICAL OUTLET INOP - REPAIR - T3142 - [redacted] - 736-5776 - -	Repair
11413510	3C - Low Sustain	3C - 3907 RM 220 - WT - HVACC - ADJUST BELTS AND PULLEY ON EF-205 - REPAIR - T3203 - [redacted] - 582-9513 - - MAU-V205	Repair
11413514	3C - Low Sustain	3C - 3001 ANNEX G, RM 125, NW - WT - HVACC - FF/LEAKING DISCHARGE VALVE - REPAIR - T3210 - [redacted] - 582-9513 - - PCHW-GL118-1	Repair
11413516	3C - Low Sustain	3C - 3001 ANNEX G, RM 125, NW - WT - HVACC - FF/LEAKING DISCHARGE VALVE - REPAIR - T3211 - [redacted] - 582-9513 - - PCHW-GL118-2	Repair
11413518	3C - Low Sustain	3C - 3907 RM 120B - WT - HVACC - FF/LEAKING PIGTAIL ON PRESSURE GAUGE - REPAIR - T3212 - [redacted] - 582-9513 - HUM-H201	Repair
11413523	3B - Medium Sustain	3B - 63001 grey box on the infield between taxiway golf and delta - WT - EXTELEC - obstruction light out - REPAIR - [redacted] 734-2191	Repair
11413530	3C - Low Sustain	3C - 3001 ANNEX G - WT - HVACC - BRING CHILLER ONLINE - REPAIR - T4442 - [redacted] - 734-6589 - -	Repair
11413546	3C - Low Sustain	3C - 3001 POST O53 BEARING BA - WT - HVACC - CLEAN VAV LA1S - REPAIR - T3264 - [redacted] - 734-5856 - -	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11413564	3C - Low Sustain	3C - 3001 POST 2AF-75A CONF RM - WT - STRUC - REPLACE CEILING TILES - REPAIR - T4641 - [redacted] - 205-6973 - -	Repair
11413566	3C - Low Sustain	3C - 3001 POST O53; AHU PN55 - WT - BAS - CLEAN ROOM HUMIDITY OUT OF TOLERANCE - REPAIR - T4650 - [redacted] - 736-2085 - -	Repair
11413567	3C - Low Sustain	3C - 3001 POST Y90 - WT - STRUC - REPALCE CEILING TILES - REPAIR - T4664 - [redacted] 736-5776 -	Repair
11413575	3C - Low Sustain	3C - 3001 POST 2W22 - WT - STRUC - DOOR WON'T OPEN FROM OUTSIDE - REPAIR - T4682 - [redacted] - 622-7846 - -	Repair
11413661	3C - Low Sustain	3C - 3001 POST O65 - WT - MACHINE MAINT - CHECK OH DOOR OPENER FOR WATER DAMAGE - REPAIR - T4990 - [redacted] - 582-6991 - -	Repair
11413668	3C - Low Sustain	3C - 3001 POST X5 - WT - STRUC - CEILING TILES HAVE MOISTURE & NEED TO BE REPLACED - REPAIR - T5087 - [redacted] - 417-8194 - -	Repair
11413689	3C - Low Sustain	3C - 3001 EXT NEAR DOOR 7A - WT - STRUC - EXTERIOR LADDER MISSING A BOLT - REPAIR - T5153 - [redacted] - 736-5776	Repair
11413775	3C - Low Sustain	3C - 3001 1AH 101A - WT - Intplumb - Broken water fountain - repair - T5772 - [redacted] - 739-8921	Repair
11413799	3C - Low Sustain	3C - 3001 POST N61 PLATING SH - WT - STRUCT - FF/POST N-61 - REPLACE BROKEN CEILING TILE - REPAIR - T5392 - [redacted] - 582-9513 - FLT-PN6	Repair
11413811	3C - Low Sustain	3C - 3001 Post 899 - WT - Roof - Roof leak - Repair - T5797 - [redacted] - 736-5776	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11413819	3C - Low Sustain	3C - 3001 Post G97 - RS33- WT - Roof - Roof leak - Repair - T5798 - [redacted] - 736-5776	Repair
11413836	3C - Low Sustain	3C - 3001 POST 2Y61 - WT - INTPLUMB - REPLACE WATER FOUNTAIN FILTER - REPAIR - T5419 - [redacted] - 736-9977 - -	Repair
11413848	3C - Low Sustain	3C - 3001 POST Y55 - RS87 - WT - ROOF - ROOF LEAK IN STAIRWELL - REPAIR - T5516 - [redacted] - 736-9977 - STORM -	Repair
11413859	3C - Low Sustain	3C - 3001 POST 2Y55 - RS87 - WT - ROOF - ROOF LEAK IN CONF RM - REPAIR - T5517 - [redacted] - 734-3981 - -	Repair
11413905	3C - Low Sustain	3C - 3001 WHOLE BUILDING - WT - SPRINK - CHANGE PRESSURE GAUGES - REPAIR - T6094 - [redacted] - 734-5806 - - ALL	Repair
11413963	3C - Low Sustain	3C - 3001 POST X22 MECH RM - WT - STRUC - MECH ROOM DOOR VENTS NOT VENTING PROPERLY - REPAIR - T6260 - [redacted] - 417-8194 - -	Repair
11413967	3C - Low Sustain	3C - 3001 POST Y34 - WT - STRUC - EXT PERSONNEL DOOR MISSING HARDWARE - REPAIR - T6299 - [redacted] - 417-8194 - -	Repair
11413982	3C - Low Sustain	3C - 3001 POST L63 - WT - INTPLUMB - URINAL NOT FLUSHING, SENSOR NOT WORKING - REPAIR - T6329 - [redacted] - 582-4340 - -	Repair
11414001	3C - Low Sustain	3C - 3001 POST B93 - WT - INTPLUMB - TOILET WONT FLUSH & IS BAGGED - REPAIR - T6349 - [redacted] - 582-4340 - -	Repair
11414027	3C - Low Sustain	3C - 3001 POST Y90 - WT - INTPLUMB - URINAL CLOGGED & BAGGED - REPAIR - T6350 - [redacted]	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11414033	3C - Low Sustain	3C - 3001 POST O103 - WT - INTPLUMB - URINAL CLOGGED & BAGGED - REPAIR - T6352 - [redacted] - 582-4340 - -	Repair
11414037	3C - Low Sustain	3C - 3001 POST 2U79 - WT - HVACC - CHK HVAC UNITS IN CENTER MEZZANINE TO CONFIRM THEYRE WORKING - REPAIR - T6353 - [redacted] - 736-4118 -	Repair
11414127	3B - Medium Sustain	3B - 3001G MECH ROOM 117 - WT - BAS - F/U 11398723 CHILLER PUMP 2 IN ALARM - Repair - [redacted] - 582-5009 - SR# 2946258	Repair
11414133	3C - Low Sustain	3C - 3001 POST 2M41 - RS135 - WT - ROOF - ROOF LEAK - REPAIR - T5596 - [redacted] - 823-8883 - STORM -	Repair
11414170	3C - Low Sustain	3C - 3001 POST B70 - WT - MACHINE MAINT - OH DOOR OPENING & CLOSING RANDOMLY - REPAIR - T5653 - [redacted] - 736-5776 - -	Repair
11414516	3B - Medium Sustain	3B - 3001 POST 2G77 - WT - ELEC INT - EXIT SIGN INOP - REPAIR - [redacted] 736-5871	Repair
11414526	3C - Low Sustain	3B - 3001 POST 2T79 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 7365776 - STORM	Repair
11414589	3B - Medium Sustain	3B - 3001 POST 2G77 - WT - ELEC INT - EMERGENCY LIGHT INOP - REPAIR - [redacted] 736-5871	Repair
11414624	3B - Medium Sustain	3B - 3001 POST 2G77 - RS68 - WT - ROOF - ROOF LEAKS IN LAB - REPAIR - [redacted] 736-5871	Repair
11414635	3B - Medium Sustain	3B - 3001 DOOR 10 POST A95 - WT - STRUC - STAIR REPAIR - REPAIR - [redacted] - 7365776	Repair
11414840	3C - Low Sustain	3C - 3001 POST Y10.5 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11414841	3C - Low Sustain	3B - 3001 POST Y37 - RS102 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair
11414862	3C - Low Sustain	3B - 3001 POST X3 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair
11414863	3C - Low Sustain	3B - 3001 POST Y3 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair
11414890	3C - Low Sustain	3B - 3001 POST 2X5 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair
11414891	3C - Low Sustain	3B - 3001 POST X9 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair
11414909	3B - Medium Sustain	3B - 1060/FUEL TANK - WT - FUELS - PERFORM THE 3 YEAR OVERFILL AND SPILL BUCKET TESTS/ FF - Repair - [redacted] - 734-9385- SP#2946516 - 1060-TNK-1	Repair
11414913	3C - Low Sustain	3C - 3001 POST X16 - RS117 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair
11414914	3C - Low Sustain	3B - 3001 POST X21 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair
11414930	3C - Low Sustain	3B - 3001 POST X36 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair
11414932	3B - Medium Sustain	3B - 3001 POST M49 - RS92 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair
11415274	3B - Medium Sustain	3B - 3001 ANNEX G ROOM 104 - WT - HVACC - BATHROOM VENT FAN INOP - Repair - [redacted] - 7364730	Repair
11415325	3B - Medium Sustain	3B - 3001 POST Y78 - WT - HVACC - BATHROOM VENT FAN INOP - Repair - [redacted] - 7364730	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11415404	3B - Medium Sustain	3B - 3001 KITCHEN AND ROOM 1AI-75A - WT - PEST - ANTS IN KITCHEN AND ROOM 1AI-75A - Repair - [redacted] - 736-8707	Repair
11416366	4A - High Enhance	4A - 3001 N of Bldg - CBR - 22509 - to add 2 new plasma booths & their support dust collectors & chillers - [redacted] - 405 455 2020	Repair
11416572	3B - Medium Sustain	3B - 3001 POST 2AF73 MEN'S RR - WT - PLUMB INT - TOILET CLOGGED AND BAGGED - REPAIR - [redacted] 736-8536	Repair
11416591	4A - High Enhance	4A - 3001 Post Y76 - WT - INT ELEC - 25854 - Install electrical service for security office - [redacted] - 336-8536	Repair
11416667	4A - High Enhance	3C - 3001 Post 2AH67A - SVC FLOORING - Need old carpet removed and new installed - [redacted] - 370-1490	Services
11417511	3C - Low Sustain	3C - 3001 Staff Drive parking Lot E - CBM Complete - Paint the handrail at the S end parking lot yellow - [redacted] - 582-9077	Repair
11417774	3C - Low Sustain	3C - 3001 POST 1AF72A MENS RR - WT - BAS - VENTILATION NOT WORKING - REPAIR - T1349 - [redacted] - 417-2893	Repair
11417857	3C - Low Sustain	3C - 3001 PRODUCTION COL N-53 - WT - BAS - FF/TROUBLE SHOOT HOT WATER VALVE - REPAIR - T4094 - [redacted] - 818-1590 - - CNTR-P212	Repair
11417861	3C - Low Sustain	3C - 3001 POST I-95 - WT - BAS - HIGH HUMIDITY - REPAIR - T4704 - [redacted] - 736-5776 - - AHU PI95	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11417873	3C - Low Sustain	3C - 3001 POST Y70 - WT - BAS - CHILLED WATER EXPANSION TANK #3 NOT FILLING CORRECTLY - REPAIR - T4891 - [redacted] - 734-9377	Repair
11417979	3C - Low Sustain	3C - 3001 N END 3001 - WT - INTELEC - DAMAGED CROSSWALK BUTTON IN BOLLARDS - REPAIR - R7179 - [redacted] - 739-4975 - -	Repair
11418006	3C - Low Sustain	3C - 3001 POST Y56 - WT - PAINT - EXT FIRE DOUBLE DOOR DAMAGED - REPAIR - S2473 - [redacted] - 622-7846 - PAINT - EGD-Z56	Repair
11418011	3C - Low Sustain	3C - 3001W - WT - INT ELEC - ISWP - 23731-Install loadbank camlock box - Repair - [redacted] 734-5058 CSAG-217	Repair
11418034	3C - Low Sustain	3C - 3001 PLANT - WT - HVACC - FF/REPAIR PRIMARY CHILL WATER PUMP #6 - REPAIR - S4519 - [redacted] - 734-5856 - PCWP-6	Repair
11418073	3C - Low Sustain	3C - 3001 POST J69/K69 - WT - STRUCTURE SHOP - PATCH & REPAINT WALL - REPAIR - S7252 - [redacted] - 582-6991 - -	Repair
11418134	3C - Low Sustain	3C - 3001 RM 106 - WT - PM HVAC - ORDER REPLACEMENT FILTERS - REPAIR - T2199 - [redacted] - 582-9513 - -	Repair
11418139	3C - Low Sustain	3C - 3001 RM 200 - WT - PM HVAC - ORDER REPLACEMENT FILTERS - REPAIR - T2200 - [redacted] - 582-9513 - -	Repair
11418158	3C - Low Sustain	3C - 3001 ANNEX G - WT - HVACC - LOW HUMIDITY ALERT - REPAIR - S8951 - [redacted] - 492-2496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11418160	3C - Low Sustain	3C - 3001 OLD HORSESHOE - WT - HVACC - LEAKING PUMP ON REDUNDANT CHILLER - REPAIR - T2385 - [redacted] - 734-5856 - -	Repair
11418173	3C - Low Sustain	3C - 3001 POST B79 - WT - INTPLUMB - DRAIN CLOGGED - REPAIR - T2498 - [redacted] - 739-4975 - -	Repair
11418191	3C - Low Sustain	3C - 3001 POST V-53 - WT - INTELEC - MASSIVE STORM DRAIN - REPAIR - T2624 - [redacted] - 405-420-4404 - STORM -	Repair
11418296	3C - Low Sustain	3C - 3001 POST 2AH1-96H- RS43 - WT - ROOF - WATER LEAK IN CEILING - REPAIR - T2865 - [redacted] - 736-3537 - - RFS-37	Repair
11418304	3C - Low Sustain	3C - 3001 - WT - HVACC - FF/TROUBLE SHOOT SAMSUNG CHILLER - REPAIR - T0373 - [redacted] - 886-5386 - - CH - A1	Repair
11418581	3C - Low Sustain	3C - 3001 POST X110 - WT - SHEET METAL - REPLACE FRESH AIR LOUVERS - REPAIR - T0636 - [redacted] - 622-7846 - -	Repair
11418585	3C - Low Sustain	3C - 3001 POST X110 - WT - SHEET - REPLACE FRESH AIR LOUVERS - REPAIR - T0636 - [redacted] - 622-7846 - -	Repair
11418592	3C - Low Sustain	3C - 3001 POST Y-55 - WT - INTPLUMB - FLUSH SENSOR INOP & HANGING - REPAIR - T0673 - [redacted] - 622-7846 - -	Repair
11418604	3C - Low Sustain	3C - 3001 POST Y55 - WT - HVACC - EXHAUST FAN NOISY - REPAIR - T0923 - [redacted] - 734-5856 - EF-LT-Y55	Repair
11418639	3C - Low Sustain	3C - 3001 POST O103 - WT - AFTER HRS PLUMB - TOILET CLOGGED - REPAIR - T3338 - [redacted] - 622-7846 - -	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11418640	3C - Low Sustain	3C - 3001 POST O103 - WT - INTPLUMB - TOILET CLOGGED - REPAIR - T3338 - [redacted] - 622-7846 - -	Repair
11418662	3C - Low Sustain	3C - 3001 POST M112 EXT DOOR - WT - STRUC - INSTALL TRACTION TAPE ON METAL STAIRS - REPAIR - T1614 - [redacted] - 45-622-7846 - -	Repair
11418671	3C - Low Sustain	3C - 3001 POST M112 EXT DOOR - WT - STRUC - INSTALL TRACTION TAPE ON METAL STAIRS - REPAIR - T1614 - [redacted] - 45-622-7846 - -	Repair
11418682	3C - Low Sustain	3C - 3001 POST 1AB-98A - WT - PM HVAC - ORDER REPLACEMENT FILTERS - REPAIR - T1708 - [redacted] - 582-9513 - -	Repair
11418683	3C - Low Sustain	3C - 3001 POST Y-3 - WT - ROOF - WATER DRAIN LEAK - REPAIR - T3682 - [redacted] - 405-410-7686 - - RFS-121	Repair
11418931	3C - Low Sustain	3C - 3001 POST Y55 - WT - INTPLUMB - URINAL WONT FLUSH - REPAIR - T3729 - [redacted] - 622-7846 - -	Repair
11418934	3C - Low Sustain	3C - 3001 POST Y61 - WT - ROOF - ROOF LEAK - REPAIR - T3732 - [redacted] - 622-7846 - - RFS-82	Repair
11418946	3C - Low Sustain	3C - 3001 DOOR 2Y63 - WT - STRUC - STAIRWELL TREADS MISSING SLIP RESISTANCE - REPAIR - T3850 - [redacted] - 736-9977 - -	Repair
11418975	3C - Low Sustain	3C - 3001 POST O-103 - WT - INTPLUMB - BAGGED TOILET IN WOMENS RR - REPAIR - T4066 - [redacted] - 405-622-7846 - -	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11419041	3C - Low Sustain	3C - 3001 POST R111 - WT - INTPLUMB - TOILET WONT FLUSH - REPAIR - T4339 - [redacted] - 582-4590 - -	Repair
11419069	3C - Low Sustain	3C - 3001 POST P111 - WT - AIR - REPLACE AUTO DRAIN IN MECH ROOM - REPAIR - T4382 - [redacted] - 503-0023 - -	Repair
11419088	3C - Low Sustain	3C - 3001 POST Z-67.5 - WT - HVACC - BLOW DOWN SOLENOID VALVE NOT PURGING EXP TANK - REPAIR - T4539 - [redacted] - 801-971-7286 - -	Repair
11419092	3C - Low Sustain	3C - 3001 POST P53 - WT - HVACC - CHILL WATER PIPE LEAK - REPAIR - T4574 - [redacted] - 323-0319	Repair
11419123	3C - Low Sustain	3C - 3001 POST I-95 - WT - HVACC - HIGH HUMIDITY - REPAIR - T4704 - [redacted] - 736-5776 - - AHU PI95	Repair
11419201	3B - Medium Sustain	3B - 3001 POST 2Q81 - WT - INT PLUMB - TOILETS INOP - Repair - [redacted] - 9216452	Repair
11419293	3C - Low Sustain	3C - 3001 POST 1AJ75 - WT - INTPLUMB - TOILET LEAKING IN MENS RR - REPAIR - T5423 - [redacted] - 405-417-2893	Repair
11419437	3C - Low Sustain	3C - 3001 ANNEX 4 - WT - HVACC - REPLACE LOW LIMIT SWITCH - REPAIR - T5284 - [redacted] - 734-6589 - - PKG-A2	Repair
11419469	3C - Low Sustain	3C - 3001 POST O-53 - WT - BAS - HUMIDITY IS 55% IN BEARING BAY - REPAIR - T5440 - [redacted] - 736-2085 - - AHU P212	Repair
11419474	3C - Low Sustain	3C - 3001 FD-27 - WT - SSI - REPLACE DAMAGED BEARINGS - REPAIR - T5444 - [redacted] - 405-734-4321	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11419481	3C - Low Sustain	3C - 3001 POST AH151.1 - WT - SHEET - ROOF LEAK ONTO TEST STANDS - REPAIR - T5507 - [redacted] - 405-736-2085 - WEATHER - RFS-88	Repair
11419545	3C - Low Sustain	3C - 3001 - WT - INTPLUMB - R/R DEFECTIVE BACKFLOW - REPAIR - T5745 - [redacted] - 734-2753 - - BFRP-100	Repair
11419625	3C - Low Sustain	3C - 3001 POST X43 - WT - INTELEC - NEED CIRCUT CHECK, DOCK BOX 9 - REPAIR - T6249 - [redacted] - 417-8194 - -	Repair
11420163	3B - Medium Sustain	3B - 3001 - WT - PEST - DEAD POSUM BEHIND FRIDGE - Repair - APRIL WALKER - 2197894	Repair
11420251	3C - Low Sustain	3C - 3001 MAIN CAFE WAREHOUSE - WT - INTPLUMB - WATER COMING UP OUT OF CONCRETE FLOOR - REPAIR - T5484 - [redacted] - 734-3161 - -	Repair
11420444	3C - Low Sustain	3C - 3001 MAIN CAFE KITCHEN - WT - SPRINK - KITCHEN HOOD FIRE INSPECTION PARTS - REPAIR - T6066 - [redacted] - 734-4202 - -	Repair
11420785	3B - Medium Sustain	3B - 3001 POST 2B83 - RS51 - WT - ROOF - ROOF LEAK - Repair - [redacted] - 2197894 - STORM	Repair
11420836	3B - Medium Sustain	3B - 3001G ROOM 104 - WT - HVACC - CHILLED WATER TEMP TOO HIGH - Repair - [redacted] - 405-409-5733	Repair
11421192	3C - Low Sustain	3C - 3001 POST Y70 - WT - BAS - CHILLED WATER EXPANSION TANK #4 NOT FILLING CORRECTLY - REPAIR - T4892 - [redacted] - 734-9377 - - TANK 4	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11421421	3B - Medium Sustain	3B - 3001G ROOM 104 - WT - BAS - CHILLED WATER TEMP TOO HIGH - Repair - [redacted] - 405-409-5733 - HVAC 11420836	Repair
11427070	3B - Medium Sustain	3B - 3001 POST L67 - WT - HONEYWELL - BAS: CHECK SPACE TEMP W/CALIBRATED TEMP SENSOR - Repair - [redacted] - 582-5009 - REF-11386295	Repair
11427089	3A - High Sustain	3A - 3001 POST M54 - WT - HVACC - STEAM PIPE LEAKING - REPAIR - [redacted] - 736-2085	Repair
11427093	3B - Medium Sustain	3B - 3001 PRODUCTION COL O54 - WT - HONEYWELL - FF/SEVERAL POINTS OVERRIDDEN AT PROGRAMMING LEVEL - REPAIR - T4083 - [redacted] - 818-1590 - - CNTR	Repair
11427257	3B - Medium Sustain	3B - 3001 POST Q51 - WT - ROOF - ROOF LEAK - Repair - [redacted] - 736-5776 - STORM	Repair
11427555	3C - Low Sustain	3C - 3001 2AF73A WOMENS RR - WT - INT PLUMB - 2ND SINK FROM RIGHT INOP - [redacted] - 7368536	Repair
11427763	3B - Medium Sustain	3B - 3001 PLATING SHOP - WT - SPRINK - WATER FLOW ALARM - [redacted] - 734-7964	Repair
11428205	3B - Medium Sustain	3B - 3001 POST 2AH1-90B - WT - LOCK - NEED KEYS MADE - [redacted] - 7361882	Repair
11428330	3B - Medium Sustain	3B - 3001 POST 065 - WT - PAINT - FU 11412886 PAINT SHOP TO TAPE/BED/TEXTURE/PAINT PATCH SHEETROCK - REPAIR - [redacted] 734-7083 - SR# 2950095	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11429135	3A - High Sustain	3A - 3001 POST G70 - WT - MACHINE MAINT - ROLL UP DOOR (#16A) STUCK OPEN - REPAIR - [redacted] - 582-4340	Repair
11429788	3B - Medium Sustain	3B - 3001 O53 - WT - HVACC - HIGH HUMIDITY - REPAIR - [redacted] - 7362085	Repair
11429962	3B - Medium Sustain	3B - 3001 AHU 14 AND 15 - WT - HVACC - HOT TEMPS IN ROOM - REPAIR - [redacted] - 6283214	Repair
11430111	3B - Medium Sustain	3B - 3001 POST 1AB1-96H - WT - INT PLUMB - SINKS INOP/TOILET LEAK - REPAIR - [redacted] - 6283214	Repair
11430544	3B - Medium Sustain	3B - 3001 POST 1AH1 96H WOMEN'S RR - WT - INT PLUMB - TOILET NOT FLUSHING - REPAIR - [redacted] 628-3214	Repair
11430962	3A - High Sustain	3A - 3001 POST R61 - WT - AFTER - STEAM LINE WATER LEAK - REPAIR - [redacted] 582-4340	Repair
11430979	3B - Medium Sustain	3B - 3001 POST 1AD83A - RS56 - WT - STRUC - WALL LEAKING - REPAIR - [redacted] 734-9868	Repair
11431640	3A - High Sustain	3A - 3001 Post K67 - WT - AFTER - Water Leaking clogged floor drains in the fan deck - Repair - [redacted] 405-582-4340	Repair
11432159	3A - High Sustain	3A - 3001 Post K67 - WT - HVACC - Drain pan drain AHU 24 N & S is dripping 11431640 Carryover - repair - [redacted] - 582-7340	Repair
11432532	3A - High Sustain	3A - 3001 M-49 - WT - Intplumb - Toilet overflowing - Repair - [redacted] - 736-2085	Repair
11432775	3B - Medium Sustain	3B - 3001 POST 2U79 - WT - HVACC - CHECK HVAC UNITS FOR PROPER SERVICE - REPAIR - [redacted] 736-5776	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11433278	3B - Medium Sustain	3B - 3001 Post K67 - WT - ROOF - F/U 11432159/11431640 Drain pan drain AHU 24 N & S is dripping 11431640 Carryover - repair - [redacted] - 582-7340	Repair
11433475	3A - High Sustain	3A - 3001 POST Y61 - WT - INT PLUMB - SEWER BACK UP - Repair - [redacted] - 7369977	Repair
11435194	3A - High Sustain	3A - 3001 POST 2O-83 - WT - SPRINK - SPRINKER LEAKING - REPAIR - [redacted] - 736-5776	Repair
11435943	3B - Medium Sustain	3B -3001 POST W41 - WT - ALARM - UNHOOK FIRE ALARM - Repair - [redacted] - 5824340 - FA - P11039	Repair
11436000	3B - Medium Sustain	3B - 3001 DOOR 4 - WT - STRUC - DOOR CLOSER NOT FUNCTIONING PROPERLY - REPAIR - [redacted] 736-5776	Repair
11436637	3B - Medium Sustain	3B - 3001 ANNEX G - WT - ALARM - DISABLE SMOKE ALARM - Repair - [redacted] - 7364730	Repair
11437141	3B - Medium Sustain	3B - 3001 & POST 1AD-83A - WT - SHEET METAL - COVER CRACK WITH SHEETMETAL - Repair - [redacted] - 7349868	Repair
11437523	3B - Medium Sustain	Copy of 3B - 3001 All Fan Decks - WT - AFTER - removal of debris - REPAIR - [redacted] 819-8135	Repair
11439157	3B - Medium Sustain	3B - 3001 SOUTH GAS YARD - WT - STRUC - LATCH ON GATE NEEDS ADJUSTED - REPAIR - [redacted] 736-5776	Repair
11439212	3B - Medium Sustain	3B - 3001 POST 1AD2/92A - WT - STRUC - CEILING TILES/GRIDS NEED REPAIR - REPAIR - [redacted] 734-9028	Repair
11439304	3B - Medium Sustain	3B - 3001 POST 2U79 - WT - LOCK - KEYS MADE - Repair - [redacted] - 7365776	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11440332	3A - High Sustain	3A - 3001 POST 2C82 - WT - HVACC - 6 INCH WET SPOT ON CEILING - REPAIR - [redacted] - 219-7894	Repair
11440650	3B - Medium Sustain	3B - 3001 - WT - STRUC - FU 11401900 CEILING TILES - REPAIR - [redacted] 734-7083	Repair
11441079	3B - Medium Sustain	3B - 3001 1AB1/106C - WT - STRUC - DOOR HANDLE TO BATHROOM IS ABOUT TO FALL OFF - REPAIR - [redacted] 417-2893	Repair
11441188	3B - Medium Sustain	3B - 3001 MEN'S RR ENTRY OF DOOR E - WT - INT PLUMB - LEAKING AND CLOGGED TOILET - REPAIR - [redacted] 417-2893	Repair
11441212	3B - Medium Sustain	3B - 3001 POST 2AB1/109 MEN'S RR - WT - INT PLUMB - URINAL CLOGGED - REPAIR - [redacted] 417-2893	Repair
11441426	3B - Medium Sustain	3B - 3001 POST 2AA1103C - WT - INTELEC - LABEL BREAKERS IN ELEC PANEL - REPAIR - [redacted] - 582-4590	Repair
11441934	3B - Medium Sustain	3B- 3001 & POST 2A97 - WT - INT ELEC - REPAIR OUTLET - Repair - [redacted] - 580-821-1694	Repair
11442343	3B - Medium Sustain	3B - 3001 POST 2J66 - WT - LOCK - TEMP CORE REPLACEMENT- REPAIR - [redacted] - 7364730	Repair
11442429	3B - Medium Sustain	3B - 3001 POST Y15 - WT - STRUC - NEED APPROX 6 CEILING TILES CHANGED - REPAIR - [redacted] 417-8194	Repair
11442436	3B - Medium Sustain	3B - 3001 POST Y15 - WT - HVAC C - CHANGE A/C FILTERS - REPAIR - STEVE GONZALES 417-8194	Repair
11442878	3A - High Sustain	3A- 3001 & Y62 - WT - INT PLUMB - CLEAR FLOOR DRAIN - Repair - [redacted] - 7369977	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11443210	3B - Medium Sustain	3B- 3001 POST 1AB1106C - WT - STRUC - DOOR HANDLE REPAIR - Repair - [redacted] - 7363246	Repair
11444982	3C - Low Sustain	3C - 3001 P37-T37 - WT - INSULATE - ISWP - 23564- Insulate condensating air duct - Repair - [redacted] 582-4820 CSAG-201	Repair
11445225	3B - Medium Sustain	3B- 3001 POST P35 - WT - LOCK - PROGRAMMING/KEYS - Repair - [redacted] - 2004344	Repair
11445678	3B - Medium Sustain	3B- 3001 & CASHROOM - WT - LOCK - FIX LOCK - Repair - IWIMS# - [redacted] - 7343161	Repair
11446137	3B - Medium Sustain	3B - 3001 POST L67 - WT - HONEYWELL - CHECK SPACE TEMP W/CALIBRATED TEMP SENSOR - Repair - [redacted] 739-4246	Repair
11446968	3A - High Sustain	3A - 3001 & MAIN ENTRANCE BY FLAGPOLE - WT - PAVE - FIX HOLE - Repair - [redacted] - 7367736	Repair
11447648	3C - Low Sustain	3C - 3001 ANNEX G NW CORNER - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 4092888	Repair
11449649	3B - Medium Sustain	3B - 3001 Fan deck P24SFD - WT - HVACC - coil leaking - repair - [redacted] 582-5009	Repair
11451984	3A - High Sustain	3A - 3001 post M-49 Men's / Women's R/R - WT - Intplumb - Water on flr, leaking through wall into admin area - repair - [redacted] - 736-2085	Repair
11451987	3B - Medium Sustain	3B - 3001 POST 2U79 - WT - BAS - VERIFY EQUIPMENT BELONGS TO HONEYWELL - PKG P5, 6, 7 ,8A - REPAIR - [redacted] 736-5776	Repair
11452340	3B - Medium Sustain	3B - 3001 post L67 Lab temp - WT - Honeywell - Humidit / temp out of tolerance - [redacted] - 736-7752	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11452553	3B - Medium Sustain	3B - 3001 ANNEX G ROOM 100 - WT - LOCK - CORE REPLACED - [redacted] 4922496	Repair
11453008	3C - Low Sustain	3C - B3001 Post 1AG76A - WT - SPEC STRUC - ISWP - 25219-Replace ceiling tile grid system and lighting - [redacted] - 417-2893 - AFSC-749	Repair
11453077	3C - Low Sustain	3C - B3001 Post 1AG76A - WT - INT ELEC - ISWP - 25219-Replace ceiling tile grid system and lighting - [redacted] - 417-2893 - AFSC-749	Repair
11453122	3C - Low Sustain	3C - B3001 Post 1AG76A - WT - SHEET METAL - ISWP - 25219-Replace ceiling tile grid system and lighting - [redacted] - 417-2893 - AFSC-749	Repair
11453266	3B - Medium Sustain	3B - 1060 FUEL TANK - WT - FUELS - TANK HAS A PROBE ERROR ON AUTOMATIC TANK GAUGE MONITOR - Repair - [redacted] 734-9385 - 1060-TNK-1	Repair
11453280	3B - Medium Sustain	3B - 3001 POST 1AD81A/1AD83A - WT - PAINT - PAINT METAL STRIPS ON EXTERIOR WALL ON ROOF TOP - REPAIR - [redacted] 734-9868	Repair
11453577	3B - Medium Sustain	3B - 3001 ANNEX G & ROOM 104 - WT - HVACC - STOP LEAK - Repair - [redacted] - 4095733	Repair
11453657	3B - Medium Sustain	3B - 3001 POST 2AH73A - WT - INT ELEC - LIGHT FIXTURE ON WALL IS LOOSE - REPAIR - [redacted] - 3701490	Repair
11454011	3C - Low Sustain	3C - 3001 - Post Y56.5-Y61.5 - IDIQ - Prep surface and paint aisle floor a light gray - 25905 - [redacted] - 582-1385	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11454394	3C - Low Sustain	3C - 3001 Post Y-99 - SVC IDIQ - Remove paint from metal ceiling 1st floor white house - 25906 - [redacted] - 736-4118	Services
11454395	3B - Medium Sustain	3B - 3001G ROOM 104 - WT - HVACC - CHILLED WATER TEMP IS 54 DEG - Repair - [redacted] - 405-409-5733	Repair
11456830	3A - High Sustain	3A - 3001 Post 1AF77A - WT - AFTER PLUMB - urinal broke and water went everywhere - repair - [redacted] 205-0852	Repair
11459826	3A - High Sustain	3A - 3001 POST Y30 - WT - ROOF - ROOF LEAKING ONTO ATM - REPAIR - [redacted] 417-8194	Repair
11460090	3B - Medium Sustain	3B - 3001 POST Y30 - WT - INT PLUMB - ROOF DRAIN LEAKING ONTO ATM - REPAIR - [redacted] 417-8194	Repair
11460396	3B - Medium Sustain	3B - 3001 POST 1AF77A - WT - INT PLUMB - JANITOR CLOSET LEAKING FAUCET - REPAIR - [redacted] - 4172893	Repair
11460438	3B - Medium Sustain	3B - 3001 POST Y26 - WT - HVACC - HVAC UNIT COMPRESSOR NOT RUNNING PROPERLY - REPAIR - [redacted] 417-8194	Repair
11460441	3B - Medium Sustain	3B - 3001 POST 1AF77A - WT - INT PLUMB - HOT WATER TANK INOP - REPAIR - [redacted] - 4172893	Repair
11461898	3B - Medium Sustain	3B - 3001 POST 2AF81A - WT - HVACC - SERVER ROOM IS TOO HOT - Repair - REF T2895 - [redacted] - 580-583-7778	Repair
11462169	3C - Low Sustain	3C - 3001 POST T87 - RS47 - WT - ROOF - REPAIR - T5595 - [redacted] - 7394975 - STORM	Repair
11462360	3B - Medium Sustain	3B - 3001 POST Y55 MEN'S RR - WT - INT PLUMB - URINAL SPILLING WATER - REPAIR - [redacted] 734-2638	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11462532	3B - Medium Sustain	3B - 3001 POST A105 DOOR 8 - WT - DOOR ELEC - DOOR SENSOR TRIPPED AND NEEDS REALIGNMENT - REPAIR - [redacted] 739-4975	Repair
11462690	3A - High Sustain	3A - 3001 POST O65 - WT - HVACC - QVC LAB IS OUT OF TOLERANCE - REPAIR - [redacted] 739-4246	Repair
11469473	3A - High Sustain	3A - 3001 post M-49 Men's / Women's R/R - WT - Intplumb - Water on flr, leaking through wall into admin area - repair - [redacted] - 736-2085	Repair
11470424	3B - Medium Sustain	3B - 3001 POST V53 - WT - INT PLUMB - PVC ELBOW OF ROOF DRAIN IS LEAKING - Repair - [redacted] - 736-5776	Repair
11470429	3B - Medium Sustain	3B - 3001 FAN DECK 28 SOUTH - WT - HVACC - REPLACE BEARINGS ON BLOWER - REPAIR - [redacted] - 734-5856	Repair
11471111	3B - Medium Sustain	3B - 3001 POST 1AH71A - RS71 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 2050852 - STORM	Repair
11471316	3B - Medium Sustain	3B - 3001 FAN DECK 28 NORTH - WT - HVACC - REPLACE BEARINGS ON 28 NORTH - REPAIR - [redacted] - 734-5856	Repair
11471496	3C - Low Sustain	3C - 3001 1AI77A to 1AI-83A - SVC PAINT - Repair any damage and paint the hallway - [redacted] - 736-8707	Services
11471520	3B - Medium Sustain	3B - 3001 POST EXT DOOR BY FLAG POLE - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 7365776	Repair
11471696	3B - Medium Sustain	3B - 3001 POST 1AH1105 - WT - LOCK - RELOCATE LOCK - REPAIR - [redacted] - 5805837778	Repair
11471743	3B - Medium Sustain	3B - 3001 POST T35 - WT - BAS - THERMOSTAT INOP - REPAIR - [redacted] - 6227387	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11472479	3B - Medium Sustain	3B - 3001 EXHAUST FAN A20 - WT - HVACC - EXHAUST FAN NOISE - REPAIR - [redacted] - 2056973	Repair
11473018	3B - Medium Sustain	3B - 3001 ANNEX G CRACK UNIT 10 ROOM 104 - WT - HVACC - CRACK UNIT 10 INOP - REPAIR - [redacted] - 4095733	Repair
11473266	3B - Medium Sustain	3B - 3001 RM 26 POST 2U77 - WT - STRUC - FU 11401900 REPLACE CARPET AND CEILING TILE FROM ROOF LEAK DAMAGE - REPAIR - [redacted] 734-9868	Repair
11473273	3B - Medium Sustain	3B - 3001 RM 26 POST 2U77 - WT - INT ELEC - FU 11401900 LIGHT FIXTURES NEED REPAIR FROM ROOF LEAK - REPAIR - [redacted] 734-9868	Repair
11475542	3B - Medium Sustain	3B - 3001G MECH RM 117 - WT - HVACC - TRIPLE DUTY VALVE IS INOP (F/U BAS #11414127) - REPAIR - [redacted] - 405-818-1590	Repair
11475927	3B - Medium Sustain	3B - 3001 POST K107 - RS22 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 736-5776	Repair
11475937	3B - Medium Sustain	3B - 3001 POST D106 - RS27 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 736-5776	Repair
11476101	3B - Medium Sustain	3B - 3001 - POST B81 - RS51 - WT - ROOF - ROOF LEAK ON PANEL - Repair - [redacted] - 7365776 - STORM	Repair
11477244	3A - High Sustain	3A - 3001 & POST Y 53 - WT - INT PLUMB - ADDRESS TOILETS - Repair - [redacted] - 8161188	Repair
11477813	3C - Low Sustain	3C - 3001 STAFF DRIVE & MAIN PARKING - WT - PAVE - SEAL PAVEMENT CRACKS - REPAIR - [redacted] 417-2893	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11477935	3B - Medium Sustain	3B - 3001 POST Y64 BREEZEWAY - WT - PEST - SPIDER CONTROL NEEDED - REPAIR - [redacted] [redacted] 736-5200	Repair
11478962	3B - Medium Sustain	3B - 3001 Annex G Computer Room - WT - HVAC PM - Order 18 X 24 X 4 Pleated Filters - Repair - [redacted] - 582-9517	Repair
11478998	3B - Medium Sustain	3B - 3001 & Y 53- WT - INT PLUMB - REPAIR HALF FLUSH VALVES - Repair - F/U 11477244 - [redacted] - 8161188	Repair
11479028	3C - Low Sustain	3C - 3001 West Drive - WT - PAVE - SIGN - ISWP - Post "No POV Parking" signs on exterior of building - [redacted] - 622-7846 - CSAG-262	Repair
11479244	3C - Low Sustain	3C - 3001 mech room Column R-67 - WT - Sheet Metal - Fix channel for filters on AHU - Repair - [redacted] - 582-9517	Repair
11481497	3A - High Sustain	3A - 3001 POST 2O33 - WT - ROOF - ROOF LEAK RUNNING DOWN STAIRWELL - REPAIR - [redacted] [redacted] 4081339	Repair
11481909	2A - Preventive Maintenance	D30454101950 - A - Centrifugal, over 1 HP - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11481911	2A - Preventive Maintenance	D30454101950 - A - Centrifugal, over 1 HP - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11482277	3B - Medium Sustain	3B - 3001 POST 2O33 - WT - STRUC - ASSIST ROOF - 11481497 - REPAIR - [redacted] - 4081339	Repair
11482378	3B - Medium Sustain	3B - 3001 POST 2O33 - WT - INT PLUMB - FIX FLOOR DRAIN - REPAIR - [redacted] 4081339	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11483588	3B - Medium Sustain	3b - 3001 PRODUCTION - WT - INSULATOR - MOLDED INSULATION, NEEDS REPLACED - REPAIR - [redacted] 582-9517 - UID 3001-AHU-PM103	Repair
11483747	2A - Preventive Maintenance	D5095210295001 - BE - Diesel Generator, >500 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 39	Maintenance
11484176	4A - High Enhance	4A - 3001G DOOR 15 - WT - FAC PROJ - ISWP -23772-INSTALL A DUTCH DOOR - Repair - [redacted] 736-4731 ABW-5058	Repair
11484200	4A - High Enhance	4A - 3001 POST V37 - WT - FAC PROJ - ISWP - 25376-CUT (2) 1' DIA X 5' DEEP HOLES INTO THE CONCRETE - Repair - [redacted] 736-4118 CSAG-235	Repair
11486436	2A - Preventive Maintenance	D5015234195001 - A - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486439	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486440	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486441	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486450	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11486451	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486452	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486453	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486463	2A - Preventive Maintenance	D5015234195001 - A - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 31	Maintenance
11486466	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 31	Maintenance
11486467	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 31	Maintenance
11486468	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 31	Maintenance
11486477	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 31	Maintenance
11486478	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 31	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11486479	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 31	Maintenance
11486490	2A - Preventive Maintenance	D5015234195001 - A - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486493	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486494	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486495	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486504	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486505	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486506	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486507	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11486517	2A - Preventive Maintenance	D5015234195001 - A - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486518	2A - Preventive Maintenance	D5015234195001 - A - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486519	2A - Preventive Maintenance	D5015234195001 - A - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486526	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486527	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486528	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486529	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486530	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486531	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11486532	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486533	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486534	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486559	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486560	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486561	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486562	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486563	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486564	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11486565	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486566	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486567	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486568	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486569	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486570	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11486599	2A - Preventive Maintenance	D5015234195001 - A - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486602	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486603	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 30	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11486604	2A - Preventive Maintenance	D5015234195001 - M - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486613	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486614	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11486615	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11490741	3B - Medium Sustain	3B - 3001 - WT - INSULATERS - INSULATE AIR DUCTS, 8INCH X 4-5FT - Repair - [redacted] - 8553012	Repair
11491194	3B - Medium Sustain	3B - 3001 POST S65 AND Q65 - WT - STRUC - CEILING TILES NEED RELPACED - REPAIR - [redacted] 736-5776	Repair
11491271	3B - Medium Sustain	3B - 3001 R&D LAB POST K69/J69 - WT - HONEYWELL - REPLACE/REPAIR LIGHT FIXTURES - REPAIR - [redacted] 736-7132	Repair
11491464	3B - Medium Sustain	3B - 3001 POST 2AX73A COMPLEX CMD - WT - STRUC - REPLACE CEILING TILES - Repair - [redacted] - 4081339	Repair
11491595	3B - Medium Sustain	3B - 3001 POST 2AI68-2AI71A - WT - PEST - FLIES IN ADMIN AREA - Repair - [redacted] - 7368536	Repair
11492737	3B - Medium Sustain	3B - 3001 POST 2U79 - WT - LOCK - NEED KEYS MADE - Repair - [redacted] - 7365776	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11493674	3B - Medium Sustain	3B - 9001 X40 - WT - TAC HVAC - HVAC LEAK ONTO FLOOR - Repair - [redacted] - 5829038	Repair
11494614	3B - Medium Sustain	3B - 3001 ANNEX G ROM 107 - WT - LOCK - DOOR HANDLE GETTING STUCK - Repair - [redacted] - 7364730	Repair
11496509	1-Emergency	1A - 3001, Post O-53 - WT - HVACC - AHU PHU 55 is off - repair - [redacted] - 736-2085	Repair
11496692	3A - High Sustain	3A - 3001 Post P94 - WT - HVACC - room is being flooded by condensate from HVAC unit - repair - [redacted] - 736-5776	Repair
11497746	3B - Medium Sustain	3B - 4300 TO 214 - WT - PAVE - MOVE 120FT LIFT - REPAIR - [redacted] 734-2765	Repair
11498108	3B - Medium Sustain	3B - 3001 POST Y78 - WT - HVACC - A/C INOP AND LEAKING - REPAIR - [redacted] - 4922496	Repair
11498368	3B - Medium Sustain	3B - 3001 POST R67 - WT - LOCK - REKEY MECH ROOM DOOR - REPAIR - [redacted] 734-3255	Repair
11500164	3B - Medium Sustain	3B- 3001 & ROOM 107 D - WT - HVACC - ADDRESS AC - Repair - [redacted] - 4922496	Repair
11500868	3B - Medium Sustain	3B - 3001 POST 2C81 - WT - HVACC - DUCTS FULL OF WATER - REPAIR - [redacted] - 734-2765	Repair
11500887	3B - Medium Sustain	3B - 3001 & 2AG71 - WT - BAS - CHECK REHEAT VALVE - Repair - [redacted] - 7368536	Repair
11503458	3B - Medium Sustain	3B - 3001 - WT - HVACC - REF 11490741 NEED TO CLEAR BLOCKED DRAIN - REPAIR - [redacted] 734-2765	Repair
11503832	3B - Medium Sustain	3B - 3001 POST K103 - WT - STUCTURES - GAURD RAIL LOOSE - Repair - [redacted] - 5824340	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11504498	3B - Medium Sustain	3B - 3001 WEST SIDE BY RUNWAY - WT - PAVE - CHAIN LINK FENCE LAID DOWN - REPAIR - [redacted] 739-9964	Repair
11504537	3B - Medium Sustain	3B - 3001 POST 2W67 - WT - HVACC - A/C FOR CONFERENCE ROOM NOT WORKING - REPAIR - [redacted] 582-4764	Repair
11504973	3B - Medium Sustain	3B - 3001 DOOR Y23 - WT - STRUC - FIXED PANEL NOT SECURE; RUBS ON MULLION; CLOSER DEFICIENT - REPAIR - [redacted] 622-7855	Repair
11504974	3B - Medium Sustain	3B - 3001 POST W6 - WT - STRUC - PANIC BAR NEEDS ADJUSTMENT - REPAIR - [redacted] 622-7855	Repair
11505318	3B - Medium Sustain	3B - 3001 DOOR 19 - WT - STRUC - ALIGNMENT CORRECTION NEEDED - REPAIR - [redacted] 622-7855	Repair
11505319	3B - Medium Sustain	3B - 3001 POST W2 DOOR - WT - STRUC - DEFECTIVE CRASH BAR, INCONSISTENT RELEASE - REPAIR - [redacted] 622-7855	Repair
11505401	3B - Medium Sustain	3B - 3001 POST L67 - WT - HVACC - SIGNIFICANT CONDENSATION ON CHILL WATER LINES - REPAIR - [redacted] 739-4246	Repair
11505435	3A - High Sustain	3A - 3001 & POST S35- WT - INT ELEC - FIX POWER - Repair - [redacted] - 4058080827	Repair
11505552	3B - Medium Sustain	3B - 3001 POST W73 - WT - STRUC - TILE REPLACEMENT - Repair - [redacted] - 7398921	Repair
11505745	3B - Medium Sustain	3B - 3001 POST W21 - WT - STRUC - CRASH BAR NEEDS ADJUSTED - REPAIR - [redacted] 622-7855	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11507101	3B - Medium Sustain	3B - 3001 mech room Column R-67 - WT - STRUC - F/U 11479244 Fix channel for filters on AHU - Repair - [redacted] - 582-9517	Repair
11507282	2A - Preventive Maintenance	G30653101950 - A - Fuel oil storage tank, above ground - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 29	Maintenance
11507843	2A - Preventive Maintenance	D5095210295004 - BE - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 31	Maintenance
11507919	3A - High Sustain	3A - 3001 POST G69-H69 - WT - MOLD - DRTC- Structure Shop - MOLD IN LAB - Repair - [redacted] - 5824340	Services
11507948	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 31	Maintenance
11507949	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 31	Maintenance
11507951	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 31	Maintenance
11507976	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 31	Maintenance
11507977	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 31	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11507978	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 31	Maintenance
11508061	3B - Medium Sustain	3B - 3001 ANNEX G RM 131 - WT - ROOF LEAK - [redacted] - 492-2496	Repair
11508251	3C - Low Sustain	3B - 3001 POST 2O33 - WT - HVACC - THINKS CHILLER IS OUT - REPAIR - [redacted] - 7368536	Repair
11508269	3C - Low Sustain	3C - 3001 - WT - FUELS - ISWP - 24794-Move tank at 9301 generator and install at 3001-E generator - [redacted] 734-5058 CI-378 FT	Repair
11510097	3B - Medium Sustain	3B - 3001 POST 1AB1/86A - WT - INT PLUMB - NO HOT WATER FOR SINK - REPAIR - [redacted] 734-9028	Repair
11510986	3B - Medium Sustain	3B - 3001 POST N65 - WT - STRUC - REPAIR/REPLACE SHEETROCK OUTSIDE WALL OF QVC LAB - REPAIR - [redacted] 739-4246	Repair
11511047	3B - Medium Sustain	3B - 3001 LEAN TO 7.5 NORTH END - WT - SHEET METAL - SHEET METAL NEEDS REPAIR ON OUTSIDE OF FOLD UP DOOR - REPAIR - [redacted] 736-5776	Repair
11511863	3B - Medium Sustain	3B - 3001 - WT - HVACC - REF 11483588 INSULATORS COMPLETE; HVAC FIX OVERFLOW LEAK ON COPPER PIPE - REPAIR - [redacted] 734-2765	Repair
11512638	3B - Medium Sustain	3B - 3001 POST Y2 THRU Y6 SOUTH LEAN AND PMEL - WT - HVACC - NO A/C - REPAIR - [redacted] 734-2638	Repair
11512665	3B - Medium Sustain	3B - 3001 2AF76A MEN'S RR - WT - INT PLUMB - URINAL CONTINUOUSLY FLUSHING; NOT OVERFLOWING - REPAIR - [redacted]	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11512729	3A - High Sustain	3A - 3001 & 2AF76A - WT - INT PLUMB - URINAL IS CONSTANTLY FLUSHING - Repair - [redacted] - 7399118	Repair
11513213	3B - Medium Sustain	3B - 3001 & L71 - WT - HVACC- VERIFY AIRFLOW - Repair - [redacted] - 5824340	Repair
11514083	3B - Medium Sustain	3B - 3001 POST Y1 - WT - STRUC - CRASH BAR NEEDS ADJUSTMENT - REPAIR - [redacted] 582-4340	Repair
11514084	3B - Medium Sustain	3B - 3001 POST Y27 - WT - STRUC - CRASH BAR NEEDS ADJUSTMENT - REPAIR - [redacted] 582-4340	Repair
11514505	3B - Medium Sustain	3B - 3001 POST 2M59 - WT - HVACC - CLEAR CONDENSATE DRAIN - REPAIR - [redacted] - 734-5856	Repair
11516770	3B - Medium Sustain	3B - 3001, post 2AF68a - WT - HVACC - Temp has been elevated - repair - [redacted] - 408-1339	Repair
11520202	3B - Medium Sustain	3B - 3001 POST W73 - WT - STRUC - DOOR NEEDS ADJUSTED; WON'T LATCH WHEN SHUT - REPAIR - [redacted] 736-5776	Repair
11520823	3B - Medium Sustain	3B - 3001 POST Y78 - WT - STRUC - DOOR NEEDS ALIGNMENT - REPAIR - [redacted] 736-4730	Repair
11520867	3B - Medium Sustain	3B - 3001G - WT - LOCK - KEY REQUEST - REPAIR - [redacted] 736-4730	Repair
11521502	3B - Medium Sustain	3B - 3001 POST X-44 - WT - HONEYWELL - ALL LIGHTS IN DOCKS 8 & 9 ARE OUT - REPAIR - [redacted] - 739-3355	Repair
11527068	1-Emergency	1A - 3001 Bearing bay post O-53 - WT - HVACC - Humidity is to high, at 53% - repair - [redacted] - 736-2085	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11527333	3B - Medium Sustain	3B - 3001 outside door10, west drive - WT - Pest - baby possum under box - repair - [redacted] - 736-5776	Repair
11527792	3B - Medium Sustain	3B - 3001 POST 1AI76 - WT - STRUC - BATHROOM DOOR NEEDS ADJUSTMENT - REPAIR - [redacted] 739-8921	Repair
11527804	3B - Medium Sustain	3B - 3001 POST 1AI76 - WT - STRUC - BASEBOARD TRIM NEEDS REATTACHED - REPAIR - [redacted] 739-8921	Repair
11528566	3C - Low Sustain	3C - 3001 POST O-53 - WT - HVACC - INSULATION RIPPED ON DUCTWORK - REPAIR - [redacted] - 734-3328	Repair
11528872	3B - Medium Sustain	3B - 3001 POST 2P43 ADMIN - WT - HVACC - A/C NOT WORKING PROPERLY - WT - [redacted] 219-7894	Repair
11529930	3C - Low Sustain	3C - 3001 P37-T37 - WT - SPRINK - ISWP - 23564-Insulate condensating air duct - Repair - [redacted] 582-4820 CSAG-201	Repair
11529938	3B - Medium Sustain	3B - 3001 POST P31 - WT - METAL - OVERHEAD DOOR ONLY COMES DOWN 2/3RD OF THE WAY - REPAIR - [redacted] 582-4340	Repair
11530090	3B - Medium Sustain	3B - 3001 POST P31 2ND DOOR - WT - METAL - OVERHEAD DOOR WILL NOT SHUT - REPAIR - [redacted] 582-4340	Repair
11533390	3B - Medium Sustain	3B - 3001 Post O-53 Bearing shop - WT - BAS - VAV CR3S air flow stpt 1980 CFM, Actual air flow 4389 CFM - repair - [redacted] - 583-5009	Repair
11533422	3B - Medium Sustain	3B - 3001 POST 2M59 - WT - BAS - CONTROL C.W. VALVE (OFF) WHEN NO CALL FOR FAN/COOLING - REPAIR - [redacted] - 734-5856	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11533525	3A - High Sustain	3A - 3001 post Y-26 - WT - HVACC - Water is leaking out of the A/C down the wall - repair - [redacted] - 734-1929	Repair
11533636	3B - Medium Sustain	3B - 3001 POST 1AH/71A - WT - HONEYWELL - LIGHT FIXTURES INOP - REPAIR - [redacted] 635-7051	Repair
11533642	3B - Medium Sustain	3B - 3001 POST J69/K69 - WT - PAINT - PAINT WALL REPAIRS REF 11418073 - REPAIR - [redacted] 734-9868	Repair
11533670	3B - Medium Sustain	3B- 3001 X-5 personel door - WT - Struc - South door won't open - repair - [redacted] - 417-8194	Repair
11533671	3B - Medium Sustain	3B - 3001 POST 1AH/71A - WT - SPRINK - MISSING ESCUTION RING - REPAIR - [redacted] 635-7051	Repair
11533817	3B - Medium Sustain	3B - 3001 POST Y8 & Y24 CAGES DOCK BOX OFFICE - WT - LOCK - ID LOCKS AND MAKE KEYS - REPAIR - [redacted] 417-8194	Repair
11533890	3B - Medium Sustain	3B - 3001 & POST O-53 - WT - HONEY WELL - REFERENCE 11533390 - Repair - [redacted] - 582-5009	Repair
11533905	3B - Medium Sustain	3B - 3001 POST Q57 - WT - HONEYWELL - LIGHT NEEDS REPAIR - REPAIR - [redacted] 736-5776	Repair
11533924	3C - Low Sustain	3C - 3001 P37-T37 - WT - IN ELEC - ISWP - 23564-move light fixture/support - Repair - [redacted] 582-4820 CSAG-201	Repair
11533970	4A - High Enhance	4A - 3001G DOOR 15 - WT - LOCK - ISWP -23772-INSTALL A DUTCH DOOR/LOCK SHOP SUPPORT - Repair - [redacted] 736-4731 ABW-5058	Repair
11534175	3B - Medium Sustain	3B - 3001 POST 2Y45 - WT - HONEYWELL - 5 LIGHTS NEED REPLACED - REPAIR - [redacted] 417-8194	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11534332	3B - Medium Sustain	3B - 3001 POST 2Y31 - WT - PEST - SPRAY FOR ROACHES AND OTHER BUGS - REPAIR - [redacted] 417-8194	Repair
11534384	3B - Medium Sustain	3B - 3001 POST 2W49 - WT - HONEYWELL - LIGHT IN OFFICE IS FLASHING/STROBING - REPAIR - [redacted] 736-4118	Repair
11534385	3B - Medium Sustain	3B - 3001 POST T52 - WT - STRUC - REPAIR FLOOR CRACK - REPAIR - [redacted] 736-4118	Repair
11534470	3B - Medium Sustain	3B - 3001 Post O53 - WT - HVAC PM - Assist HVAC C with filters for AHU at Bearing Bay - Repair - [redacted] - 582-9513	Repair
11534476	3B - Medium Sustain	3B - 3001 DOOR 8 A105 - WT - MACH MAINT - DOOR NEEDS ADJUSTMENT - REPAIR - [redacted] 739-4975	Repair
11534958	3B - Medium Sustain	3B - 3001 & POST P73 X73 - WT - INT PLUMB - CAMERA STORM DRAIN - Repair - [redacted] A[redacted] - 7347223	Repair
11534965	3B - Medium Sustain	3B - 3001 N OF OVERHEAD DOOR 4 - WT - PEST - BEE HIVE/SWARM UNDER STAIRS - REPAIR - [redacted] 734-9868	Repair
11536144	3A - High Sustain	3A- 3001 & POST 2P57/2Q67- WT - structures - CHECK FOR MOLD - Repair - [redacted] - 4081339 - mold	Repair
11536817	3B - Medium Sustain	3B - 3001 POST 2G77 - WT - STRUC - CEILING TILES NEED REPLACED - REPAIR - [redacted] 736-5871	Repair
11536818	3C - Low Sustain	3C - 3001 POST 2G77 - WT - STRUC - HOLE IN CEILING FROM REMOVED SPRINKLER HEAD - REPAIR - [redacted] 736-5871	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11536841	3B - Medium Sustain	3B - 3001 POST M91 - WT - INT ELEC - LIGHT SWITCH NOT FUNCTIONING - REPAIR - [redacted] 739-4975	Repair
11536862	3B - Medium Sustain	3B - 3001 WOMEN'S RR POST 2P82 - WT - INT PLUMB - TOILET CONSTANTLY FLUSHING - REPAIR - [redacted] 739-4975	Repair
11537107	3B - Medium Sustain	3B - 3001 POST 2M59 - WT - STRUC - REF 11514505 REPLACE CEILING TILES - REPAIR - [redacted] 734-5856	Repair
11537137	3B - Medium Sustain	3B - 3001 BREAKROOM NEAR COLUMN M103 - WT - STRUC - REPLACE CEILNG TILES - REPAIR - [redacted] 582-9510	Repair
11538930	3B - Medium Sustain	3B - 3001 POST 2C81 - WT - INSULATE - INSULATE 2 SPOTS STILL DRIPPING - REPAIR - [redacted] - 734-2765	Repair
11539232	3B - Medium Sustain	3B - 3001 POST 1AI 77 - WT - INT ELEC - EXIT SIGN INOP - REPAIR - [redacted] 417-2893	Repair
11539393	3B - Medium Sustain	3B - 3001 POST W73 IG OFFICE - WT - STRUC - DOOR NEEDS ADJUSTED; WON'T LATCH; DRAGGING - REPAIR - [redacted] 736-5776	Repair
11539429	3C - Low Sustain	3C - 3001 POST W73 IG OFFICE - WT - STRUC - REPLACE 5 CEILING TILES - REPAIR - [redacted] 736-5776	Repair
11539548	3B - Medium Sustain	3B - 3001 Annex G Mech Room - WT - HVAC PM - Clean mech Room - Repair - [redacted] - 582-9513	Repair
11539870	3B - Medium Sustain	3B - 3001G ROOM 100 - WT - HVACC - A/C NOT WORKING - REPAIR - [redacted] - 736-4730	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11540609	3B - Medium Sustain	3B - 3001 Admin Roof (Orig Annex) - WT - HVAC PM - Extensive Cleaning Needed on CU-A2 - Repair - [redacted] - 582-9513 - UID 3001-CU-A2	Repair
11540708	3B - Medium Sustain	3B - 3001 Admin Roof - WT - HVACC - Possible refrigerant leak at bypass solenoid - Repair - [redacted] 582-9513 - UID 3001-CU-A1	Repair
11541351	4A - High Enhance	4A - 3001 COOLING TOWER - OP - 41696 - RENT & INSTALL TEMP COOLING TOWERS - [redacted] - 405 622 7839	Repair
11541471	3B - Medium Sustain	3B - 3001 POST 2AH198C - WT - HVACC - AC IS NOT WORKING PROPERLY - Repair - [redacted] - 736-2374	Repair
11541486	3A - High Sustain	3A - 3001 & POST Y45- WT - HVACC - ADDRESS AC ISSUES - Repair - [redacted] - 4055494485	Repair
11541504	3B - Medium Sustain	3B - 3001 & POST Y45- WT - PEST - ADDRESS BUGS AND MICE - Repair - [redacted] - 4055494485	Repair
11541855	4A - High Enhance	4A - Bldg 3001, Post 2AA76 - 2AD87A - CBR - Request the B-1 Division bay be remodeled - Repair - [redacted] 736-3537	Repair
11542084	3B - Medium Sustain	3B - 3001 VARIOUS LOCATIONS - OP - INSTALL FIRE SUPP & ALARM INTO NEW DOCK BOXES - [redacted] - 405 736 4118	Repair
11542092	4A - High Enhance	4A - 3001 POST L-81 - CBM - 25912-Install concrete isolation pad for cylindrical grinder - Repair - [redacted] 736-4118 MAD22-154	Repair
11542258	3C - Low Sustain	3C - 3001 - WT - SVC PAINT - 25909 PAINT CONFINED SPACE MARKINGS - Repair - [redacted] 734-0408 MAD22-150	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11543798	3B - Medium Sustain	3B - 3001 - WT - BAS - MOLD ISSUES FOR SSI & INSPECTOR GENERAL - REPAIR - [redacted] - 405-886-5386	Repair
11543912	3C - Low Sustain	3C - 3001 - WT - STRUC - REPLACE CEILING TILES REF 11490741 - REPAIR - [redacted] 734-2765	Repair
11544250	3B - Medium Sustain	3B - 3001 & X46 - WT - LOCK - ADJUST DOOR LOCKS - Repair - [redacted] - 7343161	Repair
11544455	3C - Low Sustain	3C - 3001 DOOR 6 - WT - MACH MAINT - PHOTO EYE SENSOR ERROR - REPAIR - T5114 - [redacted] - 736-5776 - 3001-OD-M118	Repair
11544607	3A - High Sustain	3A - 3001 & W67 - WT - HVACC - STOP LEAK - Repair - [redacted] - 6202589	Repair
11544991	3B - Medium Sustain	3B - 3001 POST 1AH1/103C - WT - HVACC - EXPERIENCING HIGH TEMPS IN ADMIN OFFICE - REPAIR - [redacted] 734-9028	Repair
11545002	3B - Medium Sustain	3B - 3001 POST 2W83 - WT - INT ELEC - ELECTRICAL OUTLET NOT WORKING - REPAIR - [redacted] 736-5776	Repair
11545027	3B - Medium Sustain	3B - 3001 POST Y29 - WT - BAS - ADJUST TEMP TO 72 IN MGMT OFFICE - REPAIR - [redacted] - 417-8194	Repair
11545077	3B - Medium Sustain	3B - 3001 POST X59 - WT - PEST - OPOSSUM SIGHTING - REPAIR - [redacted] 420-4404	Repair
11545891	3B - Medium Sustain	3B - 3001 & W67 - WT - STRUC - REPLACE CEILING TILES- Repair - F/U 11544607 - [redacted] - 6202589	Repair
11546000	3A - High Sustain	3A - 3001 POST O83 - WT - INT PLUMB - JANITOR SINK CLOGGED - REPAIR - [redacted] 620-2589	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11546592	3B - Medium Sustain	3B - 3001 Annex G Data Center room 104 - WT - INT PLUMB - Need to troubleshoot on back flow preventer - Repair - [redacted] 405-409-5733	Repair
11550165	3B - Medium Sustain	3B - 3001 POST A87 MEN'S RR - WT - INT PLUMB - TOILET BROKEN - REPAIR - [redacted] 739-4975	Repair
11550182	3B - Medium Sustain	3001 Annex G room 104 - WT - INT PLUMB - REF WT#11546592 Need to troubleshoot on back flow preventer - Repair - [redacted] 405-409-5733	Repair
11551145	3B - Medium Sustain	3b - 3001 - wt - ssi - to order parts - repair - [redacted] 734-4321	Repair
11551182	3B - Medium Sustain	3B - 3001 POST X-18 - WT - HVACC - STEAM PIPE HIT BY A TUGGER - Repair - [redacted] - 417-8194	Repair
11551331	3B - Medium Sustain	3B - 3001 STEAM PLANT - WT - STRUC - Railing is splintering and loose causing potential fall hazard - Repair - [redacted] - 734-3301	Repair
11551361	3B - Medium Sustain	3B - 3001 STEAM PLANT - WT - STRUC - STAIRS TO FAN ROOM ARE RICKETY - Repair - [redacted] - 734-3301	Repair
11551646	3B - Medium Sustain	3B - 3001 & MAIN HALLWAY ANNEX G - WT - ALARM - RESET ALERT - Repair - [redacted] - 7364730	Repair
11553006	3A - High Sustain	3A - 3001 & 1AF71 - WT - STRUC - FIX DOOR - Repair - [redacted] - 4056357051	Repair
11553309	3B - Medium Sustain	3B - 3001 POST X-18 - WT - PIPE FITTERS - REF 11551182 STEAM PIPE HIT BY A TUGGER - Repair - [redacted] - 417-8194	Repair
11553356	3B - Medium Sustain	3B - 3001 POST X-18 - WT - WELDERS - REF 11551182 HANDRAIL NEEDS TO BE RE-WELDED - Repair - [redacted] - 417-8194	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11553581	3B - Medium Sustain	3B - 3001 DOOR 4 - WT - PEST - SPRAY POISON IVY GROWNING - REPAIR - [redacted] 736-5776	Repair
11554134	3B - Medium Sustain	3B - 3001 P75 to FD21 - WT - INT ELEC - Inadequate lighting SENT FROM HONEYWELL 11406718 - repair - [redacted] 819-8135	Repair
11554402	3B - Medium Sustain	3B - 3001 & POST 2AH187A - WT - INT PLUMB - ADDRESS WATER FOUNTAIN - Repair - [redacted] - 4172893	Repair
11555336	3B - Medium Sustain	3B - 3001 POST 1AG72A - WT - HVACC - SEWER SMELL COMING FROM THE HVAC VENTS - Repair - [redacted] - 635-7051	Repair
11555959	3B - Medium Sustain	3B - 3001 ROOF - WT - HVACC - PICK UP EXTRA SHEETMETAL ON ROOF LEFT FROM CONTRACTOR - REPAIR - [redacted] - 405-734-5856	Repair
11555986	3B - Medium Sustain	3B - 3001 - WT - LOCK - 2 OFFICES NEED LOCKS CHANGED - REPAIR - [redacted] - 409-2888	Repair
11557849	3B - Medium Sustain	3B - 3001 & L71 - WT - BAS - VERIFY AIRFLOW - Repair - [redacted] - 5824340	Repair
11558089	3A - High Sustain	3A - 3001 Post B94 - WT - Intplumb - Urinal Overflowing - [redacted] - 405-589-0500	Repair
11558861	3B - Medium Sustain	3B - 3001 & POST 1AC79A - WT - INT ELEC - FIX BALLIST - Repair - [redacted] - 4172893	Repair
11558869	3B - Medium Sustain	3B - 3001 POST R49-O51 - WT - INT ELEC - LIGHTS OFF IN SHOP AREA - Repair - [redacted] - 4204404	Repair
11559170	3B - Medium Sustain	3B - 3001 POST 1AF71A - WT - REPAIR - WATER FOUNTAIN CLOGGED - REPAIR - [redacted] 323-0319	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11559680	3C - Low Sustain	3C - 3001 multi - WT - SVC PAINT - Repair/paint the select hallways on the first floor in Building 3001 betw Door A - Repair - [redacted] [redacted] 736-8707	Repair
11560520	3B - Medium Sustain	3B - 3001 FAN DECKS - WT - HVACC - WALK WITH FM [redacted] [redacted] TO IDENTIFY DAMAGED FAN DECKS - REPAIR - [redacted] - 734-5856	Repair
11560521	3B - Medium Sustain	3B - 3001 & DOOR 8 - WT - INT ELEC - REATAACH DOOR ARM - Repair - [redacted] - 6283214	Repair
11561167	3B - Medium Sustain	3B - 3001 & ROOM 2G99 - WT - INT ELEC - FIX LIGHTS - Repair - [redacted] - 2197894	Repair
11563651	3B - Medium Sustain	3B - 3001 & POST 2B87 - WT - STRUC- REPLACE CEILING TILES - Repair - F/U 11490741 - [redacted] [redacted] - 8553012	Repair
11563915	3B - Medium Sustain	3B - 3001 Lean-To Y-15 - WT - HVACC - Check bearings on motor - Repair - [redacted] [redacted] 582-9513 - UID 3001-EF-LT-Y-15	Repair
11564406	3B - Medium Sustain	3B - 3001 POST Y27 - WT - STRUC - F/U 11514084 CRASH BAR NEEDS ADJUSTMENT - REPAIR - [redacted] - 582-4340	Repair
11564567	3B - Medium Sustain	3B - 3001 MAIN CAFE KITCHEN AJ64A - WT - INT PLUMB - DRAIN CLOGGED - Repair - [redacted] [redacted] - 5143354	Repair
11564667	3B - Medium Sustain	3B - 3001 POST X55 MECH ROOM - WT - ALARM - TROUBLE SHOOT MONACO - Repair - [redacted] - 734-5806 - P10831	Repair
11564902	3B - Medium Sustain	3B - 3001 Annex G room 104 - WT - HVACC - REF WT#11546592/11550182 DRAIN PANS ARE OVER FILLING ON CRACK UNITS - Repair - [redacted] [redacted] - 405-734-7098	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11566679	2A - Preventive Maintenance	D5035710195002 - AF4 - FACP 101 to 300 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 39	Maintenance
11566754	3C - Low Sustain	3C - 3001 POST 2AF69A - 25919 - SVC PAINT - REMOVE WALPAPER & TEXTURE & PAINT WALLS - [redacted] - 405 626 6013	Repair
11567069	3B - Medium Sustain	3B - 3001 MEN'S RR POST B95 - WT - INT PLUMB - URINAL CLOGGED - REPAIR - [redacted] 736-5776	Repair
11567091	3B - Medium Sustain	3B - 3001 POST 2U79 - WT - LOCK - KEY REQUEST - REPAIR - [redacted] 736-5776	Repair
11569506	3B - Medium Sustain	3B - 3001 Post 2Y-55 - WT - Metal - Need welding on door jamb - [redacted] - 582-4340	Repair
11569714	4A - High Enhance	4A - 3001 POST G69-O69 - WT - CBR - RENOVATE MXSG QVC WALLS - [redacted] - 405 736 4315	Repair
11569805	2A - Preventive Maintenance	D50357101950 - A - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 39	Maintenance
11570041	4A - High Enhance	4A - 3001 POST L111 - WT - SVC FLOORING - INSTALL TILE CARPET - [redacted] - 405 622 7751	Repair
11570169	2A - Preventive Maintenance	D50357101950 - A - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11570283	3A - High Sustain	3A - 3001 & 2Y55 - WT - STRUC - FIX DOOR - Repair - [redacted] - 7369977	Repair
11570420	3B - Medium Sustain	3B - 3001 POST X-19 - WT - INT PLUMB - F/U 11551182 REPAIR LEAKING EYE WASH STATION - Repair - [redacted] - 417-8194	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11570482	2A - Preventive Maintenance	D50357101950 - A - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11570721	3B - Medium Sustain	3B - 3001 Chiller Plant - WT - Tac Pipefitting - Assist Zonce C with Plant install of Chilled Water Pump - Repair - [redacted] - 582-4496	Repair
11571093	3C - Low Sustain	3C - 3001 POST 1AG 77A - WT - FAC PROJ - ISWP - 25252-REPLACE 2X4 CEILING TILES WITH 2X2 TILES - Repair - [redacted] 405-417-2893 AFSC-751	Repair
11571167	3C - Low Sustain	3C - 3001 POST 1AG 77A - WT - INT ELEC - ISWP - 25252-REPLACE 2X4 CEILING TILES WITH 2X2 TILES - Repair - [redacted] 405-417-2893 AFSC-751	Repair
11571233	3C - Low Sustain	3C - 3001 POST 1AG 77A - WT - SHEET METAL - ISWP - 25252-REPLACE 2X4 CEILING TILES WITH 2X2 TILES - Repair - [redacted] 405-417-2893 AFSC-751	Repair
11571808	3B - Medium Sustain	3B - 3001 POST T66 - WT - ALARM - TROUBLE SHOOT MONACO - Repair - [redacted] - 734-5806	Repair
11572404	3B - Medium Sustain	3B - 3001 PLANT - WT - INT ELEC - CONNECT #2 SECONDARY PUMP MOTOR UP AND CHECK ROTATION - REPAIR - [redacted] - 734-5856	Repair
11575123	3C - Low Sustain	3C - 3001 POST J91 WHITEHOUSE - WT - STRUC - REPLACE CEILING TILES - REPAIR - [redacted] 420-4404	Repair
11575417	3C - Low Sustain	3C - 3001 1AH1/109B - WT - LOCK - KEY REQUEST - REPAIR - [redacted] 734-9028	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11575592	3C - Low Sustain	3C - 3001 POST P47 - WT - STRUC - DOOR KNOBS NEED REPLACED - REPAIR - [redacted] 736-2085	Repair
11575622	3A - High Sustain	3A - 3001 POST O107 - WT - STRUC - ENSURE MEZZANINE IS SAFE TO BE ON/UNDER - REPAIR - [redacted] 739-4975	Repair
11575701	3B - Medium Sustain	3B - 3001 POST Y90 - WT - INT PLUMB - TOILET CONSTANTLY FLUSHING - REPAIR - [redacted] 736-4118	Repair
11577523	2A - Preventive Maintenance	D10151101950 - Q - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 14	Maintenance
11577526	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 14	Maintenance
11577539	2A - Preventive Maintenance	D10151101950 - Q - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 14	Maintenance
11577540	2A - Preventive Maintenance	D10151101950 - Q - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 14	Maintenance
11577546	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 14	Maintenance
11577547	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 14	Maintenance
11578060	2A - Preventive Maintenance	D10151101950 - Q - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 14	Maintenance
11578061	2A - Preventive Maintenance	D10151101950 - Q - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 14	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11578062	2A - Preventive Maintenance	D10151101950 - Q - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 14	Maintenance
11578069	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 14	Maintenance
11578070	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 14	Maintenance
11578071	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 14	Maintenance
11578680	3B - Medium Sustain	3B - 3001 POST X15 - WT - SPRINK - SMALL LEAK FROM SPRINK PIPE - REPAIR - [redacted] - 620-2589	Repair
11578681	3B - Medium Sustain	3B - 3001 POST X12 - WT - SPRINK - SMALL LEAK FROM SPRINK PIPE - REPAIR - [redacted] - 620-2589	Repair
11578690	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 49	Maintenance
11578730	2A - Preventive Maintenance	D10153101950 - S - Wheelchair lift - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 14	Maintenance
11578731	2A - Preventive Maintenance	D10153101950 - S - Wheelchair lift - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 14	Maintenance
11578732	2A - Preventive Maintenance	D10153101950 - S - Wheelchair lift - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 14	Maintenance
11579048	2A - Preventive Maintenance	D5095210295001 - M - Diesel Generator, >500 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 39	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11579049	2A - Preventive Maintenance	D5095210295001 - M - Diesel Generator, >500 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 39	Maintenance
11579050	2A - Preventive Maintenance	D5095210295001 - M - Diesel Generator, >500 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 39	Maintenance
11579059	2A - Preventive Maintenance	D5095210295001 - J - Diesel Generator, >500 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 39	Maintenance
11579060	2A - Preventive Maintenance	D5095210295001 - J - Diesel Generator, >500 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 39	Maintenance
11579061	2A - Preventive Maintenance	D5095210295001 - J - Diesel Generator, >500 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 39	Maintenance
11579062	2A - Preventive Maintenance	D5095210295001 - J - Diesel Generator, >500 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 39	Maintenance
11579154	2A - Preventive Maintenance	D5015234195001 - J - Automatic Transfer Switch (ATS) - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 30	Maintenance
11583196	2A - Preventive Maintenance	D30452501950 - A - Hood and blower - TINKER AFB - 3001 - KITCHEN_HOODS - ANNUALWEEK 32	Maintenance
11583197	2A - Preventive Maintenance	D30452501950 - A - Hood and blower - TINKER AFB - 3001 - KITCHEN_HOODS - ANNUALWEEK 32	Maintenance
11584094	2A - Preventive Maintenance	D5095210295004 - S - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 15	Maintenance
11584096	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 15	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11584097	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 15	Maintenance
11584098	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 15	Maintenance
11584108	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 15	Maintenance
11584109	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 15	Maintenance
11584110	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 15	Maintenance
11584111	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 15	Maintenance
11584150	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 19	Maintenance
11584151	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 19	Maintenance
11584152	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 19	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11584153	2A - Preventive Maintenance	D5095210295004 - M - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 19	Maintenance
11584161	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 19	Maintenance
11584162	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 19	Maintenance
11584163	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 19	Maintenance
11584164	2A - Preventive Maintenance	D5095210295004 - J - Diesel Generator, 26 - 249 KW - TINKER AFB - 3001 - POWER_PRO - ANNUALWEEK 19	Maintenance
11585813	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 51	Maintenance
11585814	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 51	Maintenance
11585816	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 51	Maintenance
11585817	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 51	Maintenance
11585818	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 51	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11585850	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 51	Maintenance
11585851	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 51	Maintenance
11585852	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 51	Maintenance
11585853	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 51	Maintenance
11585854	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 51	Maintenance
11585855	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 51	Maintenance
11585856	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 51	Maintenance
11585857	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 51	Maintenance
11585860	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 51	Maintenance
11585861	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 51	Maintenance
11586214	2A - Preventive Maintenance	D50357101950 - S - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11586269	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11586270	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11586862	2A - Preventive Maintenance	D50357101950 - A - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 38	Maintenance
11587016	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 38	Maintenance
11587018	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 38	Maintenance
11587090	3C - Low Sustain	3C - 3001 POST Z31 - WT - LOCK - CHANGE CORE ON DOUBLE EXTERIOR DOORS - REPAIR - [redacted] - 734-7083	Repair
11587118	3C - Low Sustain	3C - 3001 POST Z31 - PAINT - PAINT DOOR/JAMB DOUBLE EXTERIOR DOORS - [redacted] - 734-7083	Repair
11588218	3B - Medium Sustain	3B - 3001 ROOFTOP - WT - HVACC - CLEAN CHILLER ON ROOF COILS VERY DIRTY - REPAIR - [redacted] - 734-5856	Repair
11588525	3C - Low Sustain	3C - 3001 & POST G59 - WT - STRUC - FIX DOOR - Repair - [redacted] - 7365776	Repair
11588583	3C - Low Sustain	3C - 3001 POST 2C/82 - WT - INT ELEC - FU 11490741/11543912 ASSIST REPLACING CEILING TILE - REPAIR - [redacted] 734-9868	Repair
11588652	3B - Medium Sustain	3B - 3001 POST 2P65 - WT - HVACC - AHU HAS SMALL LEAK - REPAIR - [redacted] - 5824340 -AHUPR65	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11588847	3B - Medium Sustain	3B - 3001 & POST O83 - WT - INT PLUMB - UNCLOG MENS TOILET - Repair - [redacted] - 7365776	Repair
11588892	3B - Medium Sustain	3B - 3001 & POST O93 - WT - INT PLUMB - STOP URINAL LEAK - Repair - [redacted] - 7365776	Repair
11592779	3B - Medium Sustain	3B - 3001 POST 2AF68A - WT - HVACC - AC NOT BLOWING - REPAIR - [redacted] - 408-1339	Repair
11596853	1-Emergency	1 - 3001 POST X-81 - WT - PEST - POSSUM IN TRASH CAN - REPAIR - [redacted] - 739-4975	Repair
11596889	3C - Low Sustain	3C - 3001 POST 2P65 - WT - STRUCTURE - REPLACE STAINED CEILING TILES - REPAIR - [redacted] - 5824340 -AHUPR65	Repair
11596903	3C - Low Sustain	3C - 3001 POST A105 DOOR 8 - WT - METAL - OH DOOR WILL NOT GO DOWN IN AUTO - REPAIR - [redacted] 736-5776	Repair
11597714	3C - Low Sustain	3C - 3001 POST 2D97 - WT - LOCK - NEED CORE BUILT AND INSTALLED/NEED KEYS - REPAIR - [redacted] 736-5776	Repair
11597839	3B - Medium Sustain	3B - 3001 2I63 METAL ID LAB - WT - INT PLUMB - EYE WASH STATION OVER SPRAYING - REPAIR - [redacted] 739-4246	Repair
11597963	3C - Low Sustain	3C - B3001 Post X106 - WT - SVC FLOORING - Replace carpet with tile - Repair - [redacted] 734-0408 MAD22-181	Repair
11598674	3B - Medium Sustain	3B - 3001 & 2AH/73A - WT - HVACC - UNIT IS LEAKING - Repair - [redacted] - 4059906861	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11602353	3B - Medium Sustain	3B - 3001 POST 2M59 - WT - HONEYWELL - FIX SOFTWARE TO CLOSE CHW VALVE WHEN FAN IS OFF - REPAIR - [redacted] - 405-550-3781 - REF 11533422	Repair
11602560	3A - High Sustain	3A - 3001 POST O65 - WT - INT PLUMB - WATER LEAKING FROM CEILING - Repair - [redacted] - 5824340	Repair
11602854	3C - Low Sustain	3C - 3001 POST 1AH1/102D WOMEN'S RR - WT - INT PLUMB - TOILET NOT FLUSHING WITH AUTO SENSOR - REPAIR - [redacted] 734-9028	Repair
11602904	3A - High Sustain	3A - 3001 POST R81 - WT - HVACC - PARTS FALLING OFF - Repair - [redacted] - 4204404	Repair
11603068	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11603069	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11603070	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11603071	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11603221	3B - Medium Sustain	3B - 3001 POST Y27 - WT - STRUC - F/U 11514084/11564406 CRASH BAR NEEDS ADJUSTMENT - REPAIR - [redacted] - 582-4340	Repair
11603245	3A - High Sustain	3A - 3001G ROOM 104 - WT - HVACC - CRAC UNITS IN ALARM AND 1 IS READING 77 DEGREES - REPAIR - [redacted] 492-2496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11603305	3C - Low Sustain	3C - 3001 POST Y64 DOOR 45 - WT - STRUC - CLOSER NEEDS ADJUSTED - REPAIR - [redacted] - 582-4340	Repair
11603310	3C - Low Sustain	3C - 3001 POST Y86/87 DOOR 150 - WT - STRUC -CRASH BAR NEEDS ADJUSTMENT - REPAIR - [redacted] - 582-4340	Repair
11603539	3A - High Sustain	3A - 3001 POST O65 - WT - PIPE - WATER LEAKING FROM CHILLED WATER LINE - Repair - [redacted] - 5824340	Repair
11603568	2A - Preventive Maintenance	D50357101950 - S - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603570	2A - Preventive Maintenance	D50357101950 - S - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603572	2A - Preventive Maintenance	D50357101950 - S - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603574	2A - Preventive Maintenance	D50357101950 - S - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603577	2A - Preventive Maintenance	D50357101950 - S - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603578	2A - Preventive Maintenance	D50357101950 - S - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603579	2A - Preventive Maintenance	D50357101950 - S - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603580	2A - Preventive Maintenance	D50357101950 - S - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11603582	2A - Preventive Maintenance	D50357101950 - S - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603583	2A - Preventive Maintenance	D50357101950 - S - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603584	2A - Preventive Maintenance	D50357101950 - S - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603585	2A - Preventive Maintenance	D50357101950 - S - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603631	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603633	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603635	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603637	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603640	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603643	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603645	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11603648	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603651	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603654	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603659	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603662	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603664	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603665	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603666	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603667	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603668	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603669	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11603670	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603671	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603672	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603673	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603674	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603675	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 11	Maintenance
11603870	3B - Medium Sustain	3B - 3001 Y 104 - WT - INT PLUMB - UNCLOG URINAL - Repair - [redacted] - 5824340	Repair
11603892	3B - Medium Sustain	3B - 3001 POST H69 THERMAL SPRAY LAB - WT - HONEYWELL - TEMPS TOO HIGH FOR LAB - REPAIR - [redacted] 736-7752	Repair
11604091	3C - Low Sustain	3C - 3001 1AC4/93A OFFICE BAY - WT - PEST - REQUESTING STICKY TRAPS FOR MICE - REPAIR - [redacted] 734-9028	Services
11604743	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 22	Maintenance
11604751	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 22	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11604752	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 22	Maintenance
11605255	3B - Medium Sustain	3B - 3001 POST M106 - WT - HVACC - A/C UNIT CONDENSATING HEAVILY; DECOMMISSIONED OC# 21450 - REPAIR - [redacted] 736-5776	Repair
11605543	3C - Low Sustain	3C - 3001 POST Y90 MEN'S RR - WT - INT PLUMB - URINAL WILL NOT FLUSH; BAGGED - REPAIR - [redacted] 582-4340 - SR# 3015363	Repair
11605575	3B - Medium Sustain	3B - 3001 MEN'S RR POST X22 - WT - INT PLUMB - HANDICAP TOILET SEAT NEEDS REPLACED - REPAIR - [redacted] 582-4340 - SR# 3015382	Repair
11605606	3C - Low Sustain	3C - 3001 POST U111 #2 SHOWER AREA - WT - HONEYWELL - LIGHT IN SHOWER INOP - REPAIR - [redacted] 582-4340 - SR# 3015396	Repair
11605635	3C - Low Sustain	3C - 3001 POST X7 MRR - WT - INT PLUMB - SINK WILL NOT TURN ON - REPAIR - [redacted] 582-4340 - SR# 3015403	Repair
11605651	3B - Medium Sustain	3B - 3001 X7 MRR - WT - INT PLUMB - URINAL CONTINUOUSLY FLUSHING - REPAIR - [redacted] 582-4340 - SR# 3015411	Repair
11605700	3B - Medium Sustain	3B - 3001 POST N49 WRR - WT - INT PLUMB - TOILET LEAKING AT THE BASE - REPAIR - [redacted] 582-4340 - SR# 3015430	Repair
11605742	3B - Medium Sustain	3B - 3001 POST X22 MRR - WT - INT PLUMB - TOILET KEEPS FLUSHING - REPAIR - [redacted] 582-4340 - SR# 3015439	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11605889	3B - Medium Sustain	3B - 3001 POST X6 ELEVATOR - WT - SUB ELEVATOR - LIGHTS OUT IN ELEVATOR - REPAIR - [redacted] 582-4340 - SR# 3015479	Repair
11605909	3C - Low Sustain	3C - 3001 MRR POST X22 - WT - INT PLUMB - BAGGED SINK NEEDS REPAIR - REPAIR - [redacted] 582-4340 - SR# 3015484	Repair
11605948	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 49	Maintenance
11605953	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 49	Maintenance
11605954	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 49	Maintenance
11605981	3C - Low Sustain	DEFAULT - Work Task Template - Corrective Maintenance-Other Exterior Need	Repair
11606067	3A - High Sustain	3A- 3001 POST G89 - WT - INT PLUMB - GAS SMELL PRESENT INSIDE - REPAIR - [redacted] - 7347964	Repair
11606096	3C - Low Sustain	3C - 3001 POST P83 - WT - STRUC - NEED DOOR CLOSER REPLACED - REPAIR - [redacted] 736-5776	Repair
11606310	3C - Low Sustain	3C - 3001 Y46 exterior - WT - PAVE - ISWP - 22538-Repair sidewalk so it drains properly - Repair - [redacted] 734-0761 ABW-5039 MAD-19-227	Repair
11606313	3C - Low Sustain	3C - 3001 MRR POST M40 - WT - INT PLUMB - TOILET WILL NOT FLUSH/NEEDS KICKPLATE SENSOR - REPAIR - [redacted] 582-4340 - SR# 3015601	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11606449	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 39	Maintenance
11606450	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 39	Maintenance
11606491	2A - Preventive Maintenance	D50357101950 - A - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 43	Maintenance
11606515	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 43	Maintenance
11606517	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 43	Maintenance
11606560	2A - Preventive Maintenance	D50357101950 - Q - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 48	Maintenance
11606571	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 48	Maintenance
11606573	2A - Preventive Maintenance	D50357101950 - M - Fire alarm annunciator system - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 48	Maintenance
11606824	3A - High Sustain	C/O 3A - 3001 POST H81 - WT - HVACC - F/U 11606067 GAS SMELL STILL PRESENT INSIDE - REPAIR - [redacted] - 7347964	Repair
11606873	3B - Medium Sustain	3B - 3001G ROOM 104 - WT - HVACC - F/U 11603245 CRAC UNITS IN ALARM AND 1 IS READING 77 DEGREES - REPAIR - [redacted] 492-2496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11611285	3C - Low Sustain	OUTAGE 3C - 3001 POST O65 - WT - PIPE - F/U 11603539 WATER LEAKING FROM CHILLED WATER LINE IN FALL - Repair - [redacted] - 5824340	Repair
11612307	3B - Medium Sustain	3B - 3001 ROOM 104 - WT - HVACC - AC FROZE UP - Repair - [redacted] - 4922496	Repair
11612416	3C - Low Sustain	3C - 3001 POST 1AG 77A - WT - ALARM - ISWP - 25252-ALARM ASSIST-REPLACE 2X4 CEILING TILES - Repair - [redacted] 405-417-2893 AFSC-751	Repair
11612472	3C - Low Sustain	3C - 3001 POST 1AG 77A - WT - SPRINK - 25252-SPRINKLER ASSIST-REPLACE 2X4 CEILING TILES - Repair - [redacted] 405-417-2893 AFSC-751	Repair
11612750	3B - Medium Sustain	3B - 3001 FAN DECK 25N - WT - HVACC - BEARINGS GOING OUT ON FAN DECK - REPAIR - [redacted] - 734-5856	Repair
11612786	3B - Medium Sustain	3B - 3001G SERVER ROOM - WT - HVACC - CRAC UNIT NOT OPERATING PROPERLY - REPAIR - [redacted] - 734-5856	Repair
11612962	3C - Low Sustain	3C - 3001 POST Z31 - WT - PAINT - PAINT DOUBLE OUTSIDE DOOR ENTRANCE TO ELECTRICAL ROOM - REPAIR - [redacted] 734-2765 - PAINT	Repair
11613548	3A - High Sustain	3A - 3001 POST 3S-69 - WT - MOLD - INSPECT AREA FOR MOLD FROM LEAKING CHILLED WATER LINE - REPAIR - [redacted] 582-4340 - MOLD	Repair
11613585	3B - Medium Sustain	3B - 3001 MRR O73 - WT - INT PLUMB - URINAL WILL NOT STOP RUNNING - REPAIR - [redacted] 582-4340	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11613660	3C - Low Sustain	3C - 3001 POST W78 - WT - STRUC - FLOOR NEEDS PATCHED AGAIN; TRIP HAZARD - REPAIR - [redacted] 736-5776	Repair
11613849	3C - Low Sustain	3C - 3001 Mech rm F74 roof - WT - WELD - ISWP - 25415-Fabricate safety railing around roof access - Repair - [redacted] 622-7846 CSAG-237	Repair
11615296	3C - Low Sustain	3C - 3001 POST Y36/37 - WT - INT ELEC - INVESTIGATE ELECTRICAL OUTLETS AND DISCONNECT BOXES - REPAIR - [redacted] 734-0408 - SR# 3018836	Repair
11617736	3B - Medium Sustain	3B - 3001 POST 2P65 - WT - HVACC - HVAC WATER LEAK - REPAIR - [redacted] - 5824340	Repair
11618096	3B - Medium Sustain	3B - 3001 & ROOM 107 D - WT - INSULATOR - F/U 11500164 INSULATE LINES (UID: FCU 4) - Repair - [redacted] - 4922496	Repair
11618609	3C - Low Sustain	DEFAULT - Work Task Template - Corrective Maintenance-Landscaping	Repair
11619567	3B - Medium Sustain	3B - 3001 POST 2AH62A - WT - STRUC - TRASH CHUTE GLOGGED - Repair - [redacted] - 4081339	Repair
11619960	3C - Low Sustain	3C - 3001G RM 131 - WT - INT ELEC -ISWP - 25870 REMOVE ABANDONED UPS CONTROL BOX - Repair - [redacted] 736-4731	Repair
11620354	3B - Medium Sustain	3B - 3001 POSTS H70/L69 - WT - INT ELEC - 2 EXIT SIGNS NEED BATTERIES/REPAIR/REPLACE - REPAIR - [redacted] 582-4340 - SR# 3020966	Repair
11620964	3B - Medium Sustain	3B - 3001 POST O63 - WT - HVACC - LOUD NOISE FROM DUCT; INVESTIGATE - REPAIR - [redacted] 582-4340	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11621200	3C - Low Sustain	3B - 3001 POST 3S-69 - WT - STRUC - FU 11613548 REPLACE CEILING TILES/INSTALL DRIP PAN - REPAIR - [redacted] 582-4340	Repair
11621279	3B - Medium Sustain	3B - 3001 POST 3S-68.5 - WT - INT ELEC - EXIT SIGN HAS BURNT OUT BULBS - REPAIR - [redacted] 582-4340 - SR# 3021408	Repair
11621329	3C - Low Sustain	3C - 3001 POST 3S-69 WEST WALL - WT - STRUC - SINK CABINET PLASTIC CONNECTION POINTS ARE LOOSE - REPAIR - [redacted] 582-4340 - SR# 3021431	Repair
11621346	2A - Preventive Maintenance	D5035710195003 - AF4 - FACP 50 or Less Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 35	Maintenance
11622094	3B - Medium Sustain	3B - 3001 A74 - WT - FAC PROJ - ISWP - 23155-Install safety railing on roof line - Repair - [redacted] 622-7845 MAD20-093	Repair
11625204	3B - Medium Sustain	3B - 3001 NW ANNEX - WT - ALARM CONT - FULL COMM FAILURE - REPAIR - [redacted] 736-3129	Repair
11626376	3B - Medium Sustain	3B - 3001 Annex G N Comm RM - WT - HVACC - AHU trips on high pressure - Repair - [redacted] - 582-9513 - UID 3001-AHU-GC2V118	Repair
11626551	3C - Low Sustain	3C - 3001 - WT - STRUC - REF 11539393 ADJUST DOUBLE DOOR - REPAIR - [redacted] 734-9868 - ?	Repair
11627227	3B - Medium Sustain	3B - 3001 ROOM 103C - WT - HVACC - VERY HUMID AND HOT - Repair - [redacted] - 6283214	Repair
11627498	3C - Low Sustain	3C - 3001 CENTRAL PLANT POST AE67-69 - WT - HVAC C - TROUBLESHOOT NOISE - Repair - [redacted] - 7343328	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11629250	3B - Medium Sustain	3B - 3001 POST 2W83 NE CORNER CENTER MEZZ - WT - HVACC - CHECK HVAC; HIGH HUMIDITY - REPAIR - [redacted] 736-5776	Repair
11629275	3B - Medium Sustain	3B - 3001 POST HA 51.1 - WT - INT ELEC - APPROX 15/20 BULBS NEED REPLACED IN TANK&COOLER SHOP FLUSH ROOM - REPAIR - [redacted] 736-2085	Repair
11629290	3B - Medium Sustain	3B - 3001 POST 2R82 - WT - INT ELEC - SEVERAL OUTLETS IN CUBICLE ARE NOT WORKING/CORRECT CONTACT - REPAIR - [redacted] 734-3414	Repair
11629349	3A - High Sustain	3A - 3001 POST B80 HEAT TREAT ANNEX - WT - INT PLUMB - RAW SEWAGE DRIPPING FROM BRASS CAPS ALL DOWN AISLE - [redacted] 736-5776	Repair
11629460	3C - Low Sustain	3C - 3001 POST F111 - WT - PEST - LOTS OF ROACHES IN OFFICES - REPAIR - [redacted] - 370-1490	Services
11629799	3B - Medium Sustain	3B - 3001 Blr Plant - WT - HVACC - Clogged drain/backing up - Repair - [redacted] - 582-9513 - UID 3001 PCHW-BS05	Repair
11629824	3C - Low Sustain	3C - 3001 POST 2Y49 - WT - LOCK - REQUESTING 6 KEYS 330D50 - REPAIR - [redacted] 549-4485 - SR# 3025158	Repair
11630173	3B - Medium Sustain	3B - 3001 POST 1AI77 - WT - INT ELEC - EXIT SIGN INOP - REPAIR - [redacted] 417-2893	Repair
11630218	3C - Low Sustain	3C - 3001 POST 1AG76A - WT - STRUC - NEED TO PATCH SMALL HOLES IN AFSC LG DIRECTOR'S SUITE - REPAIR - [redacted] 417-2893	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11630922	3C - Low Sustain	3C - 3001 POST G44 - WT - PAVE - LARGE CRACK IN ROADWAY ON W SIDE OF BLDG APPROX POST G44-49 - REPAIR - [redacted] 734-0408 - SR# 3025664	Repair
11631467	3C - Low Sustain	3C-3001 POST O65 - WT - PM - F/U 11611285 EMPTY CANS FROM JANITORS CLOSET FROM CHILL WATER LINE LEAK - REPAIR- [redacted] -582-4496	Repair
11631499	3B - Medium Sustain	3B - 3001 POST Y27 - WT - STRUC - REINSTALL THE MORTISE IN THE DOOR - Repair - [redacted] - 622-7839	Repair
11631640	3B - Medium Sustain	3B - 3001 EXT DOOR 16 G70 - WT - ELEC DOOR - DOOR NOT LATCHING WHEN CLOSED - REPAIR - [redacted] 622-7839 - SR# 3026104	Repair
11632078	2A - Preventive Maintenance	D5035710195002 - AF4 - FACP 101 to 300 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 36	Maintenance
11632079	2A - Preventive Maintenance	D5035710195002 - AF4 - FACP 101 to 300 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 36	Maintenance
11633712	3C - Low Sustain	3C - 3001 POSTS W39 Q43 T41 - WT - ALARM - REMOVE FIRE ALARM&SPRINK COMPONENTS SO OFFICES CAN BE SCRAPPED - REPAIR - [redacted] 582-4340 - SR#3027304	Repair
11633723	3B - Medium Sustain	3B - 3001 2J67 - WT - INT ELEC - EXIT LIGHT NEEDS REPAIR/REPLACE - REPAIR - [redacted] 582-4340 - SR# 3027312	Repair
11633869	3C - Low Sustain	3C - 3001 POST B86 MRR - WT - INT PLUMB - TOILET HAS NO WATER AND IS BAGGED; SENSOR MAY NEED BATTERIES - REPAIR - [redacted] 582-4340 - SR# 3027392	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11633919	3C - Low Sustain	3C - 3001 POST Y55 - WT - INT PLUMB - 2 URINALS DRAINING SLOWLY AND BAGGED - REPAIR - [redacted] 582-4340 - SR# 3027421	Repair
11633926	3B - Medium Sustain	3B - 3001 POST O103 MRR - WT - INT PLUMB - TOILET HAS OVERFLOWED AND IS NOW BAGGED - REPAIR - [redacted] 582-4340 - SR# 3027428	Repair
11634421	3B - Medium Sustain	3B - 3001 2Y49 - WT - BAS - ADJUST AIRFLOW - Repair - [redacted] - 5825009	Repair
11634741	3B - Medium Sustain	3B - 3001 POST 1AG1104A - WT - LOCK - REPAIR CIPHER LOCK - REPAIR - [redacted] 4103152	Repair
11634766	3C - Low Sustain	3C - 3001 POST AH70H - WT - INT PLUMB - REPLACE BROKEN SINK - REPAIR - [redacted] - 7343161	Repair
11635367	3B - Medium Sustain	3B - 3001 POST G70 DOOR 16 - WT - STRUC - DOOR NEEDS ADJUSTED - REPAIR - [redacted] - 6227839	Repair
11635449	3B - Medium Sustain	3B - 3001 OH DOOR G59A - WT - METAL - NOT SHUTTING ON THE S SIDE; PREVENTING SECURITY ENVELOPE FROM READING CONTACTS - REPAIR - [redacted] 622-7839	Repair
11635510	3B - Medium Sustain	3B - 3001 POST Y64 EXT DOOR 38 - WT - STRUC - REMOVE DOOR STOPS - REPAIR - [redacted] 622-7839 - SR# 3028417	Repair
11637555	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 35	Maintenance
11637556	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 35	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11637557	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 35	Maintenance
11637558	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 35	Maintenance
11637559	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 35	Maintenance
11637560	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 35	Maintenance
11637562	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 35	Maintenance
11637563	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 35	Maintenance
11637564	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 35	Maintenance
11639178	3B - Medium Sustain	3b - 3001 X55 - WT - Honeywell - Lights won't come on - [redacted] - 850-4064	Repair
11639659	3B - Medium Sustain	3B - 3001 POST 2U79 - WT - LOCK -NEED KEYS MADE - REPAIR - [redacted] - 7365776	Repair
11639806	3B - Medium Sustain	3B - 3001 PKG-P8A - WT - BAS - HUMIDITY ISSUES VERIFY BELONGS TO HONEYWELL - REPAIR - [redacted]	Repair
11640132	3B - Medium Sustain	3B - 3001G RM 104 - WT - HVACC - Repair side panel of CRAC unit #3 - REPAIR - [redacted] 736-4731 - SR# 3030047	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11640457	3C - Low Sustain	3C - 3001 POST X30 C02 FIRE EXTINGUISHER STORAGE - WT - STRUC - MISSING ACCESS ENTRY POINT DOOR - REPAIR - [redacted] 582-4340 - SR# 3030229	Repair
11640737	3B - Medium Sustain	3B - 3001 POST 2AF81 - WT - HONEYWELL - LIGHT SENSOR NEEDS ADJUSTMENT - REPAIR - [redacted] 622-7839 - SR# 3030387	Repair
11641544	3C - Low Sustain	3C - 3001 2J111 - WT - INT PLUMB - BREAKROOM SINK LEAK - REPAIR - [redacted] 205-6973	Repair
11641672	3B - Medium Sustain	3B - 3001 POST D109 BREAKROOM - WT - LOCK - HANDLE/LOCK IS BROKEN AND REMOVED; NEEDS REPLACED - REPAIR - CO[redacted] 736-4118	Repair
11641732	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11641749	3C - Low Sustain	3C - 3001 WRR 1AF78A - WT - INT PLUMB - SINK SENSOR INOP - REPAIR - [redacted] 417-2893	Repair
11641897	3C - Low Sustain	3C - 3001G ROOM 104 - WT - INT PLUMB - SEWER SMELL - REPAIR - [redacted] - 7364731	Repair
11642097	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11642128	3C - Low Sustain	3C - 3001 ANNEX G RM 143 - WT - HVACC - UNIT NOT RUNNING RM 107 - REPAIR - [redacted] - 405-642-8309	Repair
11642156	3B - Medium Sustain	3B - 3001 POST 2AF 81A - WT - HONEYWELL - PRE-HEAT SUPPLY TEMP GRAPHICS - REPAIR - [redacted] - 642-8309 - CNTR-A10	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11642177	3B - Medium Sustain	3B - 3001 POST 2AE 85A - WT - HONEYWELL - PRE-HEAT SUPPLY TEMP GRAPHICS - REPAIR - [redacted] - 642-8309 - CNTR-A5U	Repair
11642212	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11642271	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 42	Maintenance
11642914	3B - Medium Sustain	3B - 3001 RM 2G99 - WT - HONEYWELL - F/U 11561167 FIX RELAY - Repair - [redacted] - 219-7894	Repair
11642936	3C - Low Sustain	3C - 3001 NW CORNER OF BLDG - WT - LOCK - (Short Work Descrip/COO or FF) - Repair - [redacted] - 4204404	Repair
11647309	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 39	Maintenance
11647319	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 39	Maintenance
11647331	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 39	Maintenance
11647335	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 39	Maintenance
11647337	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 39	Maintenance
11647741	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 43	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11647745	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 43	Maintenance
11647749	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 43	Maintenance
11647752	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 43	Maintenance
11647758	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 43	Maintenance
11647763	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 43	Maintenance
11647770	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 43	Maintenance
11647775	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 43	Maintenance
11647787	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 43	Maintenance
11647795	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 43	Maintenance
11647801	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 43	Maintenance
11648862	3A - High Sustain	3A - 3001 POST G70 - WT - METAL - OH DOOR ONLY SHUTTING PARTIALLY - REPAIR - [redacted] 739-4246	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11648892	4A - High Enhance	4A - 3001 POST P37-T37 - WT - CBR - REQUEST PERMISSION FOR MXSG TO DISCONNECT FIRE SUPPRESSION FROM DLA - REPAIR - [redacted] - 734-5079	Repair
11649047	3A - High Sustain	3A - 3001 POST K67 - WT - INT ELEC - LIGHT FIXTURE LOOSE AND SWAYING - REPAIR - [redacted] 739-4246	Repair
11649138	3B - Medium Sustain	3B - 3001 P37 - T37 - OP - RELOCATE FIRE ALARM PANEL AND PULLS TO SOUTHSIDE OF BUILDING - REPAIR - [redacted] - 734-5079	Repair
11649170	3A - High Sustain	3A - 3001 POST B80 MRR - WT - INT PLUMB - SEWAGE COMING FROM TOILETS AND FLOOR DRAIN - [redacted] 830-9822	Repair
11650687	4A - High Enhance	4A - 3001 POST 1AH1-103C - WT - OPS PLAN ISWP ON HOLD - 25747 - INSTALL (4) OUTLET CIRCUIT 20 AMP POWER POLE - [redacted] - 734-9028	Repair
11651289	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11651295	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11651300	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11651305	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11651312	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11651318	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11651324	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11651331	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11651338	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 41	Maintenance
11651386	3B - Medium Sustain	3B - 3001 POST 1AH1116 MENS/WOMENS RR - WT - INT ELEC - EMERGENCY LIGHT OUT - Repair - [redacted] - 7398921	Repair
11651411	3B - Medium Sustain	3B - 3001 POST AH70H - WT - STRUC - INSTALL NEW DOOR SWEEPS - Repair - [redacted] - 7343161	Repair
11651497	3B - Medium Sustain	3B - 3001 POST 2F79 - WT - INT ELEC - NEED 3 ELECTRICAL OUTLET COVERS REPAIRED/REPLACED - REPAIR - MICHAEL BLAKE 736-5776	Repair
11651515	3C - Low Sustain	3C - 3001 POST 2AH1102H MENS RR - WT - INT PLUMB - 1 TOILET IS CLOGGED - Repair - [redacted] - 7398921	Repair
11651519	3B - Medium Sustain	3B - 3001 POST A111 OH DOOR 8 - WT - METAL - OH DOOR KEEPS GETTING STUCK OPEN - REPAIR - [redacted] 736-5776	Repair
11651608	3C - Low Sustain	3C - 3001 POST Y102 - WT - STRUC - REPAIR HOLE IN THE WALL - REPAIR - [redacted] 734-3161	Repair
11651866	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 38	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11651954	2A - Preventive Maintenance	D5035710195004 - AF4 - FACP 51 to 100 Heat Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 42	Maintenance
11651960	3C - Low Sustain	3C - 3001 Rm 102 - WT - STRUC - Replace door knob - repair - [redacted] 549-4485	Repair
11652442	3C - Low Sustain	3C - 3001 POST A85/B85 ELEVATOR - WT - SUB ELEVATOR - LOCKED OUT; TURNED OFF; NO LIGHTS - REPAIR - [redacted] 200-4344	Repair
11652762	3B - Medium Sustain	3B - 3001 POST Y64 - WT - HONEY - 2 ROWS OF LIGHTS INOP - Repair - [redacted] - 7364589	Repair
11653536	3B - Medium Sustain	3B - 3001 POST Y111 - WT - STRUC - DOOR HANDLE MISSING PARTS - Repair - [redacted] - 5494485	Repair
11653570	3C - Low Sustain	3C - 3001 POSTS W39 Q43 T41 - WT - SPRINKLER - ASSIST ALARM SHOP TO REMOVE FIRE COMPONENTS SO OFFICES CAN BE SCRAPPED - REPAIR - [redacted] 582-4340	Repair
11653572	3B - Medium Sustain	3B - 3001 POST H81 - WT - HONEYWELL - F/U 11606067 GAS SMELL STILL PRESENT INSIDE - REPAIR - [redacted] - 7347964 - HONEYWELL	Repair
11653598	3B - Medium Sustain	3B - 3001 POST 2AG-66A - WT - HVACC - AREA TOO HOT - Repair - [redacted] - 3701490	Repair
11653669	3C - Low Sustain	3C - 3001G ROOM 108 - WT - STRUC - FIX STICKY DOOR - REPAIR - [redacted] - 6790006	Repair
11654252	3A - High Sustain	3A - 3001 Post X73 - WT - AFTER ELEC - The outlets are dead inside the switch cabinet - Repair - [redacted] 405-394-2069	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11655425	3C - Low Sustain	3C - 3001 Post W73 - WT - INT ELEC - assist in changing ceiling tiles that have an outlet - repair - [redacted] 734-9868	Repair
11655460	3C - Low Sustain	3C - 3001 Post W73 - WT - ALARM - F/U WT 11505552 assist in changing ceiling tiles w/audio visual alarm in tile - Repair - [redacted] 405-734-9868	Repair
11655779	3B - Medium Sustain	3B - 3001 POST 2AF-67/68 - WT - HVACC - AREA TOO HOT - REPAIR - [redacted] - 736-8536	Repair
11655904	3C - Low Sustain	3C - 3001 POST 1AJ-87E - WT - STRUC - DOOR NOT WORKING PROPERLY - REPAIR - [redacted] - 5824340	Repair
11655964	3B - Medium Sustain	3B - 3001 Entrance E (1AJ-87E) - WT - INTPLUMB - Exterior faucet leaking/dripping, valve is closed by hand - Repair - [redacted] 405-582-4340	Repair
11656102	3C - Low Sustain	3C - 3001 Post 1AE-87A - WT - STRUC - replace 3 small missing tiles - repair - [redacted] 582-4340	Repair
11656381	3C - Low Sustain	3C - 3001 Post Y55 - WT - INTPLUM - Men's bathroom urinals 1 & 5 will not flush properly - Repair - [redacted] 405-549-4485	Repair
11656388	3C - Low Sustain	3C - 3001 post Q105 southeast to post T95 - WT - HONEYWELL - Several lights not working - Repair - [redacted] 405-734-0408	Repair
11656717	3C - Low Sustain	3C - 3001 Post O69-G69 shop areas southward - WT - HONEYWELL - Lights not working - Repair - [redacted] 405-582-4340	Repair
11657211	3C - Low Sustain	3C -3001 Mens RR Post X22 - WT - INT PLUMB - far west sink is not running water - repair - [redacted] 582-4340	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11657267	3A - High Sustain	3A - 3001 POST Q103 - WT - INT ELEC - EMERGENCY LIGHT - REPAIR - [redacted] - 4178194	Repair
11658687	3B - Medium Sustain	3B - 3001 - WT - AIR - ASSIST HONEYWELL AT BLR PLANT - REPAIR - [redacted] - 405-734-3328	Repair
11658785	3C - Low Sustain	3C - 3001 POST 2U79 - WT - LOCK - REQUEST 2 KEYS# 716B34 - REPAIR - [redacted] 582-5776	Repair
11658852	3C - Low Sustain	3C - 3001 - WT - LOCK - REQUEST 6 KEYS# 802D57 - REPAIR - [redacted]	Repair
11658925	3A - High Sustain	3A - 3001 POST 2G77 - WT - HVAC C - HVAC INOP - REPAIR - [redacted] - 7363871	Repair
11659023	3C - Low Sustain	3C - 3001 POST 1AE-87A - WT - INT ELEC - LIGHT ADJUSTMENTS/COVER REPLACEMENT - [redacted] - 582-4340	Repair
11659623	3B - Medium Sustain	3B - 3001 RM 2G99 - WT - INT ELEC - F/U 11561167/11642914 FIX RELAY - Repair - [redacted] - 219-7894	Repair
11659710	3A - High Sustain	3A - 3001 - WT - STRUC - REPLACE 9 PAVERS IN MAIN ENTRANCE - REPAIR - [redacted] 820-8404	Repair
11659732	3C - Low Sustain	3C - 3001 MENS RR 3RD FLR - WT - STRUC - MISSING PIECE OF TILE ON ENTRY WALL - REPAIR - [redacted] - 5824340	Repair
11660025	3B - Medium Sustain	3B - 3001 POST 1AE85 - WT - INT PLUMB - TOILET BACKING UP WHEN FLUSHED - REPAIR - [redacted] - 7398921	Repair
11660428	3B - Medium Sustain	3B - 3001 Lean-To Y-15 - WT - HVACC - F/U 11563915 Replace bearings on motor - Repair - [redacted] - 582-9513 - UID 3001 EF-LT-Y-15	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11661379	3B - Medium Sustain	3B- 3001 Post O-65 - WT - HVACC - Water leaking from above, over filled trash can - repair - [redacted] [redacted] (MOC)- 736-2500	Repair
11662767	3B - Medium Sustain	3B - 3001 POST 2W83 NE CORNER CENTER MEZZ - WT - HONEYWELL - CHECK HVAC; HIGH HUMIDITY - REPAIR - [redacted] 736-5776 - SR3042001	Repair
11662985	3C - Low Sustain	3C - 3001 POST M48 - WT - STRUC - DOOR CLOSER NEEDS ADJUSTMENT; SINGLE GRAY FIRE DOOR - REPAIR - [redacted] [redacted] 736-2085 - SR# 3042129	Repair
11663022	3B - Medium Sustain	3B - 3001 POST M31 - WT - INTPLUMB - WATER LEAKING ON BACK FLOW PREVENTER - REPAIR - [redacted] - 5030023	Repair
11663550	3B - Medium Sustain	3B - 3001 M69/O69 - WT - INT PLUMB - CAMERA LINE - REPAIR - [redacted] 820-8404	Repair
11663805	3C - Low Sustain	3C - 3001 POST 2AC/79A - WT - LOCK - REQUEST 4 KEYS - REPAIR - [redacted] 205-6973	Repair
11663902	2A - Preventive Maintenance	D5035710195007 - AF4 - FACP 51 to 100 Smoke Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 35	Maintenance
11664576	3B - Medium Sustain	3B - 3001 POST Y86/Y87 - WT - SPRINK - SPRINKLER LINE LEAKING IN HIGH BAY - REPAIR - [redacted] 736-5776	Repair
11664592	3B - Medium Sustain	3B - 3001 POST B80 WRR - WT - INT PLUMB - BATHROOM IS BACKED UP - REPAIR - [redacted] [redacted] 736-5776	Repair
11665369	3B - Medium Sustain	3B - 3001 AHU A2U - WT - HONEYWELL - BAS: RETURN AIR DAMPER ACTUATOR HAS COME LOOSE FROM IT'S MOUNT - REPAIR - [redacted] 582-5009	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11668438	3B - Medium Sustain	3B - 3001 Post 2AF-67/68 - WT - BAS - Verify actuator belongs to Honeywell - repair - [redacted] 736-8536 - SR 3045081-	Repair
11669244	3A - High Sustain	3A - 3001 1AH84A - WT - HVACC - WATER LEAK FROM AHU - REPAIR - [redacted] - 9906861	Repair
11669957	3C - Low Sustain	3C - 3001 Post X-65 & P-43 - WT - SVC FLOORING - 25378 Replace carpet - Repair - [redacted] 736-4118	Repair
11671263	3C - Low Sustain	3C - 3001B Room 107 - WT - LOCK - Needing one copy of key 702 C 3 made - Repair - [redacted] 405-409-5733	Repair
11672037	2A - Preventive Maintenance	D5035710195005 - S - Unmonitored FACP (Monthly) - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 10	Maintenance
11672038	2A - Preventive Maintenance	D5035710195005 - S - Unmonitored FACP (Monthly) - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 10	Maintenance
11672051	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 10	Maintenance
11672053	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 10	Maintenance
11672054	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 10	Maintenance
11672056	2A - Preventive Maintenance	D5035710195005 - A - Unmonitored FACP (Monthly) - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 10	Maintenance
11672076	2A - Preventive Maintenance	D5035710195005 - A - Unmonitored FACP (Monthly) - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 32	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11672089	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 32	Maintenance
11672090	2A - Preventive Maintenance	D5035710195005 - M - Unmonitored FACP (Monthly) - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 32	Maintenance
11672153	3B - Medium Sustain	3B - 3001 P35 - WT - INT ELEC - OUTLET INOP - REPAIR - [redacted] 200-4344	Repair
11672169	3C - Low Sustain	3B - 3001 1AH84A - WT - STRUC - RELACE RUINED TILES FROM WATER LEAK - REPAIR - [redacted] - 9906861	Repair
11672175	2A - Preventive Maintenance	D5035710195007 - AF4 - FACP 51 to 100 Smoke Devices - TINKER AFB - 3001 - ALARMS - ANNUALWEEK 33	Maintenance
11672224	3C - Low Sustain	3C - 3001 POST 2U79 - WT - LOCK - NEED CORES AND KEYS - REPAIR - [redacted] 736-5776	Repair
11672253	3C - Low Sustain	3C - 3001 1AH84A - WT - STRUC - F/U 11669244 TO REPLACE CEILING TILES - REPAIR - [redacted] 990-6861	Repair
11672320	3C - Low Sustain	3C - 3001 MAIN ENTRANCE DOOR B - WT - STRUC - REPOINT BRICKS - REPAIR - [redacted] 417-2893	Repair
11672331	3C - Low Sustain	3C - 3001 POST 2AG66A - WT - INT ELEC - REPLACE EXIT LIGHT BATTERIES - Repair - [redacted] - 6266013	Repair
11672375	3B - Medium Sustain	3B - 3001 POST 1AH87A - WT - HVACC - CONDENSATION DRIP PAN POSSIBLE OVERFLOW - REPAIR - [redacted] 628-3214	Repair
11672390	3B - Medium Sustain	3B - 3001G POWER PRO ROOM - WT - HVACC - TEMPS RISING IN POWER PRO ROOM - Repair - [redacted] - 4922496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11672674	3C - Low Sustain	3C - 3001 T91 - CBM - INSTALL 5TON MOVINCOOL SYSTEM - [redacted] - 405 582 4950	Repair
11673162	4A - High Enhance	4A - 3001 Post 1AF 77A - OP - Renovate both men's & women's restrooms - Repair - [redacted] III 739-5646	Minor Construction
11673182	3B - Medium Sustain	3B - 3001 POST V75-T69 - WT - STRUC - THICK PAINT CHIPPING UP - REPAIR - [redacted] - 8553012	Repair
11673213	4A - High Enhance	4A - 3001 Post 1AJ 77A - OP - Renovate both men's & women's restrooms - [redacted] 739-5646 AFSC/FM	Minor Construction
11673478	3B - Medium Sustain	3B - 3001 DOOR 60 NW ANNEX - WT - ALARM CONT - FULL COMM FAILURE - REPAIR - [redacted] - 845-3267	Repair
11674569	3C - Low Sustain	3C - 3001 1AI77A 82A - OP - REPLACE 9 EA 2'X4' OVERHEAD LIGHT FIXTURES - [redacted] - 405 739 8921	Repair
11674655	3C - Low Sustain	3C - 3001 BTWN POST W79/V75 - WT - STRUC - UNEVEN SPOTS IN CONCRETE CAUSING A TRIP HAZARD - REPAIR - [redacted] 734-9449	Repair
11674782	3B - Medium Sustain	3B - 3001 Post M31 - WT - HONEYWELL - FU 11663022 Supply make up water to air comp at meter is dripping - repair - [redacted] 734-7098 - SR3049073	Repair
11674978	3C - Low Sustain	3C - 3001 Post 1AI77A-83A - WT - STRUC - Replace old/stained ceiling tiles - Repair - [redacted] 405-417-2893	Repair
11675810	3C - Low Sustain	3C - 3001 ANNEX G EQUIP RM 106 NEAR CENTER ENT - WT - HVACC - REPLACE FILTERS - REPAIR - [redacted] - 405-818-1590 - PM-3001-CNTR-GS117-2 - SR3049589	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11676230	3C - Low Sustain	3C - 3001 Post Y12 dock box - WT - LOCK - need new cypher lock and handle replaced - repair - [redacted] 734-0408 - SR3049851	Repair
11678699	3C - Low Sustain	3C - 3001 Post 1AH79A - WT - HVACC - replace soft close damper on AFLCMC door - [redacted] 736-8707 - SR3051056	Repair
11679104	3A - High Sustain	3A - 3001 Post 1AD80A - WT - CONT ALARM - Full com fail on the entire room Northwest ANEX - Repair - [redacted] 405-734-3737	Repair
11680418	3B - Medium Sustain	3B - 3001 STC AREA - WT - LOCK - NEED CORE ON EXT DOOR - REPAIR - [redacted] - 7364118	Repair
11680675	3C - Low Sustain	3C - 3001 ANNEX G RM 106 - WT - BAS - FF-SPACE NOT COOLING, TROUBLE SHOOT CHWV FUNCTIONALITY - REPAIR - [redacted] - 405-818-1590 - UID CNTR-GF9R115	Repair
11680819	3C - Low Sustain	3B - 3001 POST 2T111 MECH ROOM - WT - ROOF - ROOF LEAK INTO TARP, NEED TARP ADJUSTED - Repair - [redacted] - 4922496	Repair
11681596	3B - Medium Sustain	3B - 3001 POST 1AH1/109B - WT - EXIT SIGN TEST BATTERY BACK UP INOP - REPAIR - [redacted] 734-9028	Repair
11681597	3B - Medium Sustain	3B - 3001 POST 1AC1/115 - WT - EXIT SIGN TEST BATTERY BACK UP INOP - REPAIR - [redacted] 734-9028	Repair
11681632	3B - Medium Sustain	3B - 3001 POST 1AA2/112B - WT - EXIT SIGN TEST BATTERY BACK UP INOP - REPAIR - [redacted] 734-9028	Repair
11681633	3B - Medium Sustain	3B - 3001 POST 1AH1/96H - WT - EXIT SIGN TEST BATTERY BACK UP INOP - REPAIR - [redacted] 734-9028	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11681648	3B - Medium Sustain	3B - 3001 POST 1AF1/95A - WT - EXIT SIGN TEST BATTERY BACK UP INOP - REPAIR - [redacted] 734-9028	Repair
11681650	3B - Medium Sustain	3B - 3001 POST 1AC1/92A - WT - EXIT SIGN TEST BATTERY BACK UP INOP - REPAIR - [redacted]	Repair
11682064	3C - Low Sustain	3C - 3001 G, LEANTO Y15 - WT - HVACC - LOUD EXHAUST FAN - [redacted] - 7346589	Repair
11682802	3B - Medium Sustain	3B - 3001 POST Q103 - WT - INT ELEC - F/U 11657267 EMERGENCY LIGHT - REPAIR - [redacted] - 4178194	Repair
11683421	3B - Medium Sustain	3B - 3001 POST 1AA2/112A NEAR DOOR P - WT - ROOF - LEAK FROM ROOF - Repair - [redacted] - 9906861 - STORM	Repair
11683995	3C - Low Sustain	3C - 3001 2F - WT - LOCK - CHANGE CORES TO TEMP CONSTRUCTION CORES - REPAIR - [redacted] 734-4111	Repair
11684031	3C - Low Sustain	3C - 3001 POST 2U79 - WT - LOCK - REQUEST 2 KEYS# 303B60 - REPAIR - [redacted] 736-5776	Repair
11684654	1-Emergency	1 - 3001 Post 1AD185 - WT - AFTER PLUMB - sink overflowing - repair - [redacted] 734-3737	Repair
11689075	1-Emergency	1 - 3001 Post O61 - WT - INT ELEC - Loss of power to 500 line - repair - [redacted] 269-8874	Repair
11689847	3A - High Sustain	3A - 3001 2y61 - WT - Roof - leak dripping on desk from area next to vent - repair - [redacted] - 736-9977	Repair
11689928	3B - Medium Sustain	3B - 3001 POST P45 -RS92 - WT - ROOF - ROOF LEAKING DURING RAIN - REPAIR - [redacted] 736-5776	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11689936	3B - Medium Sustain	3B - 3001 POST T105 - WT - ROOF - ROOF LEAKING DURING RAIN - REPAIR - [redacted] 736-5776	Repair
11690004	3C - Low Sustain	3C - 3001 1AH1/09B - WT - PEST - REQUESTER WOULD LIKE EXTRA STICKY TRAPS FOR MICE IN THE AREA - REPAIR - [redacted] 734-9028	Services
11690047	3B - Medium Sustain	3B - 3001 J-H/68 - WT - BAS - FAN FAIL TO START - Repair - [redacted] - 5825009	Repair
11691295	3B - Medium Sustain	3B - 3001 Post I-102 - WT - PAINT - ISWP - 24954-Install metal safety railing for roof access hatch - [redacted] 622-7846 CSAG-208	Repair
11691618	3B - Medium Sustain	3B - 3001 POST 2AF86A - WT - INT PLUMB - URINAL IS LEAKING AND WATER IS ALL OVER THE FLOOR - REPAIR - [redacted] - 409-2888	Repair
11691716	3B - Medium Sustain	3B - 3001 POST 2AF68A OFFICE - WT - INT ELEC - NO POWER TO FOUR-PLEX OUTLET - Repair - [redacted] - 370-1490	Repair
11691723	3A - High Sustain	3A - 3001 POST 2AF76A MENS RR - WT - INT PLUMB - WATER IS ALL OVER THE FLOOR AND REQ DOES NOT KNOW WHY - Repair - [redacted] - 370-1490	Repair
11691782	3C - Low Sustain	3C - 3001 POST 2O33 AND O-33 SHOP AREA - WT - STRUC - NEED CEILING TILES REPLACED - Repair - [redacted] - 408-1339	Repair
11692151	3B - Medium Sustain	3B - 3902 - WT - HVACC - CHILLER 2 IS ALARMED OUT - REPAIR - [redacted] 519-8389	Repair
11692204	3B - Medium Sustain	3B - 3001 POST AF77A - WT - INT PLUMB - CAMERA SEWER LINE - Repair - [redacted] - 820-8404	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11692217	3B - Medium Sustain	3B - 3001 POST O73 MRR - WT - INT PLUMB - URINAL CONTINUOUSLY FLUSHING - REPAIR - [redacted] 420-4404	Repair
11692445	3C - Low Sustain	3C - 3001 Mech rooms - WT - AFTER PLUMB - removal of debris - [redacted] 819-8135	Repair
11693819	3C - Low Sustain	3C - 3001 POST 2W83 - WT - AFTER HVAC - HIGH HUMIDITY NE SECTION CENTER MEZZ - REPAIR - [redacted] 736-5776	Repair
11694095	3C - Low Sustain	3C - 3001 POST 2W83 - WT - HVACC - 86% HUMIDITY - REPAIR - [redacted] 736-5776	Repair
11695208	3C - Low Sustain	3C - 3001 POST 2AH82A - WT - INT ELEC - LIGHTS FLICKERING ABOVE DESK - Repair - [redacted] - 739-9118	Repair
11695250	3C - Low Sustain	3C - 3001 POST 1AH1105A - WT - PEST - NEED MICE TRAPS LAID IN OFFICE AREA - Repair - [redacted] - 739-9118	Services
11695552	3B - Medium Sustain	3B - 3001 MAIN CAFE KITCHEN - WT - INT PLUMB - DISHWASHER LINE LEAKING AT A T - REPAIR - [redacted] 734-3161	Repair
11695565	3C - Low Sustain	3C - 3001 BOILER PLANT - WT - STRUC - SEAL PIPE FOR AIR COMPRESSOR - REPAIR - [redacted]	Repair
11696638	3B - Medium Sustain	3B - 3001 Post L-63 -WT - Intplumb - Malevolent Act, seat cover paper towels clogging toilet - repair - [redacted] - 622-7855 - SR3057193	Repair
11696739	3B - Medium Sustain	3B - 3001 Post 102H - WT - Metal - Door G, northeast door has a broken closer - repair - [redacted] - 622-7855 - SR3057223	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11696847	3C - Low Sustain	3C - 3001 Post Y-11 - WT - Lock - Need passage lock for dock box office - repair - [redacted] - 734-0408- SR3057272	Repair
11696941	3C - Low Sustain	3C - 3001 POST 1AG-77A - WT - STRUC - ADJUST DOOR/FRAME WILL NOT LOCK - REPAIR - [redacted] 417-28936	Repair
11697423	3C - Low Sustain	3C - 3001 ANNEX G ROOM 134 + 107 DOOR E - WT - INT ELEC - ALL LIGHTS ARE OUT - Repair - [redacted] 4922496	Repair
11697453	3C - Low Sustain	3C - 3001 AHU-20N - WT - HVACC - LEFT DAMPER SECTION NOT OPENING - REPAIR - [redacted] 734-4321	Repair
11697461	3C - Low Sustain	3C - 3001 FD-17S - WT - INT ELEC - LIGHTS FLICKERING REPLACE BULBS - REPAIR - [redacted] 734-4321	Repair
11697476	3C - Low Sustain	3C - 3001 AHU-25 South - WT - HONEYWELL - REPLACE DISPLAY KEYPAYD ON VFD - REPAIR - [redacted] 734-4321	Repair
11697854	3C - Low Sustain	3C - 3001 FD 22 SOUTH - WT - HVACC - REPLACE BAD BEARINGS ON DRIVER BALDER AND MASKA - REPAIR - [redacted] 734-4321	Repair
11697868	3C - Low Sustain	3C - 3001 27 SOUTH- WT - SHEET METAL - MAKE SPACER - REPAIR - [redacted] 734-4321	Repair
11697953	4A - High Enhance	4A - 3001 DOORS A & C - SVC FLOORING - Replace the carpeting with linoleum - [redacted] - 405 736 8707	Repair
11699307	3C - Low Sustain	3C - 3001G SERVER ROOM - WT - HVACC - REPAIR BACKFLOW PREVENTER ON 3/4 DRAIN LINE - REPAIR - [redacted] - 734-5856	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11699362	3C - Low Sustain	3C - 3001 G ANNEX SE SERVER ROOM - WT - HVACC - NEED TO REPLACE HIGH PRESSURE SWITCH ON AHU-GC2V118 - REPAIR - [redacted] 734-5856	Repair
11699409	3B - Medium Sustain	3B - 3001 POST N34 - WT - STRUC - DOOR NEEDS ADJUSTED - REPAIR - [redacted] 408-1339 - RE0020	Repair
11699429	3A - High Sustain	3A - 3001 1AB1 94A - WT - AFTER HVAC - WATER LEAKING FROM AIR HANDLER - REPAIR - [redacted] 734-9028 - RE0021	Repair
11699484	3B - Medium Sustain	3B - 3001 POST O-34 - WT - LOCK - NEED CYPHER LOCK CODES CHANGED AND 6 DOORS RE-KEYED - Repair - [redacted] 479-445-7642 - as0001	Repair
11700194	3A - High Sustain	3A - 3001 MECH RM 14 UPPER - WT - INT PLUMB - FLOOR DRAIN PLUGGED & FLOODING AREA - REPAIR - [redacted] - 246-8579 - KH080504	Repair
11701368	3B - Medium Sustain	3B - 3001 1AD80A N VAULT - WT - ALARM CONT - NORTH VAULT SECURITY SYSTEM ISSUE - REPAIR - [redacted] 635-7051	Repair
11701632	3C - Low Sustain	3C - 3001 1AB1 94A - WT - STRUC - F/U 11699429 REPLACE DAMAGED CEILING TILES FROM HVAC LEAK - REPAIR - [redacted] 734-9028	Repair
11701763	3A - High Sustain	3A - 3001 Post 2Q73 - WT - HVACC - Possible HVAC leak - repair - [redacted] 736-8536 - ACCESS	Repair
11701896	1-Emergency	1 - 3001 Post Y64 - WT - ALARM - Fire alarm, water flow alarm - [redacted] 734-7964	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11705738	3C - Low Sustain	3C - 3001 POST M71 - WT - LOCK - DOOR HANDLE WON'T LOCK OR UNLOCK - REPAIR - [redacted] - 736-5776	Repair
11708733	3C - Low Sustain	3C - 3001 Post V-78 - WT - Structure - Patch chipped out floor - repair - [redacted] - 736-5776	Repair
11708819	3B - Medium Sustain	3B - Building 3001, post A-59 - WT - Sprink - Fire suppression line is leaking - repair - [redacted] - 736-5776	Repair
11709401	3B - Medium Sustain	3B - 3001 POST A55.1 - WT - ROOF - HANG TARP FOR HOLE IN ROOF - REPAIR - [redacted] 736-5776	Repair
11709875	4A - High Enhance	4A - 3001 - WT - INT ELEC - ISWP - 25792 Install 120V electrical outlet for charging golf cart batteries - [redacted], 734-9277 CSAG-259	Repair
11710452	3C - Low Sustain	3C - 3001 - WT - STRUC - REF 11634766 REPLACE COUNTER TOP DUE TO WATER DAMAGE & SINK REPLACEMENT - REPAIR - [redacted] 734-2753	Repair
11710702	3B - Medium Sustain	3B - 3001 INV P20190 - WT - INT ELEC - D509002 LIGHT ELECTRICAL VAULT POST O83 TESTED& BATTERIES INSPECTED - REPAIR - [redacted] 622-7855	Repair
11710776	3B - Medium Sustain	3B - 3001 INT P20145 - WT - INT ELEC - D509002 LIGHT POST W31 TEST &INSPECT BATTERIES - REPAIR - [redacted] 622-7855	Repair
11711654	3B - Medium Sustain	3B - 3001 ROOFTOP - WT - HVACC - WATER PRESSURE ISSUE NEED TO ISOLATE AND DETERMINE ISSUE - REPAIR - [redacted] - 734-5856	Repair
11712208	3C - Low Sustain	3C - 3001G Mech Rms 1 and 2 - WT - HVAC PM - Clean Mech Rms - Repair - [redacted] - 582-9513	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11712511	3C - Low Sustain	3C - 3001 PLANT - WT - PIPE- CHECK MUFFLER ON AIR COMPRESSOR - Repair - [redacted] - 7343328	Repair
11713514	3A - High Sustain	3A - 3001 POST O 61 - WT - INT ELEC - WATER COMING OUT OF ELECTRICAL PANEL - Repair - [redacted] 7365776	Repair
11713581	3C - Low Sustain	3C - 3001 1AG76 - REMOVE & REPLACE CARPET - 25340 - SVC FLOORING - [redacted] - 405 417 2893	Repair
11713841	3A - High Sustain	3A - 3001 POST H 67 - WT - HVAC C - TEMP TOO LOW AND HUMIDITY TOO HIGH - Repair - [redacted] 5829613	Repair
11713990	3C - Low Sustain	3C - 510 TO 3001 - WT - PAVE - MOVE 45' BOOM LIFT L12 - REPAIR - [redacted] 734-3142	Repair
11714084	4A - High Enhance	4A - 3001 3S69 - REPLACE CARPET TILES - 25628 - SVC FLOORING - [redacted] - 405 622 7846	Repair
11714233	3C - Low Sustain	3C - 3001 Post 1AI77A-83A - OP - Replace old/stained ceiling tiles - Repair - [redacted] 405-417-2893	Repair
11714326	3B - Medium Sustain	3B - 3001 POST 2AH1 96H MRR - WT - INT ELEC - POSSIBLE ELECTRICAL SHORT - REPAIR - [redacted] 736-8536	Repair
11714749	3C - Low Sustain	3C - 3001 2 STORY WHITEHOUSE - 25458 - SVC CARPET - RENOVATE ADMIN 2 STORY WHITE HOUSE - [redacted] - 405 736 4118	Services
11714842	3B - Medium Sustain	3B - 3001 AD77A UCC CONTROL AREA - WT - INT PLUMB - TOILET NOT FLUSHING, CONTINUES TO RUN - REPAIR - [redacted] 205-0852	Repair
11715016	3C - Low Sustain	3C - 3001 Post 2Q73 - WT - HVACC - F/U 11701736 RECHECK HVAC UNIT - repair - [redacted] 736-8536	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11715144	3B - Medium Sustain	3B - 3001 POST Y11 - WT - STRUC - WINDOW NEEDS REPLACED - REPAIR - [redacted] 734-0408	Repair
11717342	3C - Low Sustain	3C - 3001 POST 197 - WT - LOCK - 2 CYPHER DOOR COMBOS CHANGED - REPAIR - [redacted] 736-5776	Repair
11717369	3B - Medium Sustain	3B - 61024 - WT - EXT PLUMB - FIRE HYDRANT LEAK EXT BLDG 3001 POST Y14 - REPAIR S[redacted]	Repair
11717548	3C - Low Sustain	3C - 3001 BLR PLANT N PKG UNIT - WT - HVACC - CONDENSER COOLING FINS ARE DIRTY - REPAIR - [redacted] - 405-642-8309 - CNTR-HP-2	Repair
11717556	3C - Low Sustain	3C - 3001 BLR PLANT S PKG UNIT - WT - HVACC - CONDENSER COOLING FINS ARE DIRTY - REPAIR - [redacted] - 405-642-8309 - CNTR-HP-1	Repair
11718059	3C - Low Sustain	3C - 3001 POST R35 - WT - ALARM - INSTALL AUDIO VISUAL ALARM - [redacted] - 405 739 3348	Repair
11718410	3C - Low Sustain	3C - 3001 POST 2R35 - CBM - MODIFY EXISTING SPACE - [redacted] - 405 739 3348	Repair
11719266	3A - High Sustain	3A - 3001 1AB1 94A - WT - INT PLUMB - FLOOR DRAIN BACKING UP AGAIN - REPAIR - [redacted] 734-9028	Repair
11720159	3C - Low Sustain	3C - 3001 Post 2AF-66A 2nd Fl Mech Rm - WT - HVAC PM - Clean mech room - Repair - [redacted] - 582-9513	Repair
11720370	3B - Medium Sustain	C/O - 3B - 3001 POST H61 - WT - HONEYWELL - HUMIDITY OUT OF TOLERANCE - Repair - [redacted] - 736-7752	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11722066	3A - High Sustain	3A - 3001 A71 - WT - AFTER ELEC - 480 volt main line went down - repair - [redacted] 736-5791	Repair
11723720	3B - Medium Sustain	3B - 3001 POST 2F79 - WT - INT ELEC - ELECTRICAL PANEL KEEPS TRIPPING - REPAIR - [redacted] 736-5776	Repair
11724387	3C - Low Sustain	3C - 3001 POST G70 - WT - MACH MAINT - BUTTON OUTSIDE OVERHEAD DOOR 16 NOT WORKING TO OPEN THE DOOR - REPAIR - [redacted] 736-5776	Repair
11725057	3C - Low Sustain	3C - 3001 POST 2-P82 - WT - INT PLUMB - F/U 11536862 REPLACE FLUSH VALVE, 3RD STALL WOMENS RR - REPAIR - [redacted] - 734-7098	Repair
11725082	3C - Low Sustain	3C - 3001 BOILER PLANT - WT - ROOF - ROOF LEAK ONTO BOILER 1 AND 2 - Repair - [redacted] 246-8579	Repair
11725269	3A - High Sustain	3A - 3001 2P67 - WT - MOLD - SVC - PLEASE CHECK OFFICE FOR MOLD - [redacted] 408-1339 - MOLD	Services
11726847	3C - Low Sustain	3C - 3001 POST M79 - WT - LOCK - 6 KEYS MADE 303B31 - REPAIR - [redacted] 736-5776	Repair
11726994	3C - Low Sustain	3C - 3001 DOOR B MAIN ENTRY - OP - REPLACE BRICK & MORTAR - [redacted] - 405 739 8921 wesley programming	Repair
11727087	3C - Low Sustain	3C - 3001 P37-T37 - WT - SHEET METAL - ISWP - 23564-Insulate condensating air duct - Repair - [redacted] 582-4820 CSAG-201	Repair
11727358	3B - Medium Sustain	3B - 3001 ROOM 104 - WT - HVACC - F/U 11546592 REPAIR FLOAT SYSTEM ON CRACK UNIT - REPAIR - [redacted] - 405-734-7098	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11727428	3C - Low Sustain	3C - 3001 POST Y80 - WT - LOCK - 5 KEYS #716D-61 & 2 KEYS #716D-61-64 - REPAIR - [redacted] 417-2893	Repair
11729172	3C - Low Sustain	3C - 3001 POST 450 - WT - LOCK - 3 KEYS # 303C48 & 2 KEYS # 303CSM - [redacted] 736-5776	Repair
11729651	3C - Low Sustain	3C - 3001 Post M-51 - WT - HVACC - EF not running - Repair - [redacted] 582-9513 - UID 3001-EF-PM51F	Repair
11730114	3C - Low Sustain	3C - 3001 Post 2Q73 - WT - STRUC - REPLACE CEILING TILES - repair - [redacted] 736-8536	Repair
11730259	3C - Low Sustain	3C - 3001 POST C120 - WT - SPRINK - FIRE SUPPRESSION INSPECTION TAGS OUT OF DATE - Repair - [redacted] 7364118	Repair
11731780	3B - Medium Sustain	3B - 3001 VAULT 10 - WT - ALARM - TROUBLE SHOOT MONACO - Repair - [redacted] 734-5806	Repair
11732826	3C - Low Sustain	3C - 3001 POST Y64 - WT - INT PLUMB - ELECTRIC CONTROL PIPE IS PULLED AWAY FROM URINAL & NOT WORKING PROPERLY - REPAIR - [redacted] 736-5776	Repair
11732869	3B - Medium Sustain	3B - 3001 POST 2W81 - WT - HVACC - CONDENSATION LINE IS LEAKING ALL OVER THE WX AISLE - REPAIR - [redacted] 736-5776	Repair
11735039	3B - Medium Sustain	3B - 3001 POST Q40 - WT - HVACC - CHILLED WATER LEAK - REAPIR - [redacted] 736-4118	Repair
11735226	3A - High Sustain	3A - 3001 POST 1AH87R - WT - INT PLUMB - 15 LOWER FLOOR DRAIN CLOGGED & FLOODING AREA - REPAIR - [redacted] - 405-246-8579	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11735317	3B - Medium Sustain	3B - 3001 POST AH6L - WT - INT PLUMB - 14 LOWER FLOOR DRAIN HAS SMALL LEAK ONTO CONCRETE - REPAIR - [redacted] - 405-246-8579	Repair
11735443	3B - Medium Sustain	3B - 3001 - WT - HVACC - TEMP INCREASE FROM 70 TO 72 DEGREES - REPAIR - [redacted] 549-4485	Repair
11735902	3A - High Sustain	3A - 3001 1AB1 94A - WT - INT PLUMB - FLOOR DRAIN IN UPSTAIRS MECH RM STILL LEAKING - REPAIR - [redacted] 628-3214	Repair
11736156	3C - Low Sustain	3C - 3001 1AH1/109B - WT - PEST - REQUIRE A BOX OF MOUSE GLUE TRAPS FOR 448 SCMW AREAS - REPAIR - [redacted] 734-9028	Services
11736663	3C - Low Sustain	3C - 3001 POST 1AH1/100B - WT - INT ELEC - LIGHTS ARE NOT WORKING PROPERLY - REPAIR - [redacted]	Repair
11736673	3C - Low Sustain	3C - 3001 POST 1AH1/99A - WT - INT ELEC - LIGHTS ARE NOT WORKING PROPERLY - REPAIR - [redacted]	Repair
11737354	3C - Low Sustain	3C - 3001 Posts M47 - WT - LOCK - Change harware cores to contractor cores - repair - [redacted] - 734-411 - SR3076162	Repair
11737758	2A - Preventive Maintenance	D10151101950 - A - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11737772	2A - Preventive Maintenance	D10151101950 - A - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11737773	2A - Preventive Maintenance	D10151101950 - A - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 44	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11737803	2A - Preventive Maintenance	D10151101950 - A - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11737804	2A - Preventive Maintenance	D10151101950 - A - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11737805	2A - Preventive Maintenance	D10151101950 - A - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11737856	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11737857	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11737858	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11737879	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11737882	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11737883	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11738388	2A - Preventive Maintenance	D10151101950 - A - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11738394	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 44	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11738403	2A - Preventive Maintenance	D10151101950 - M - Elevator, hydraulic, passenger / freight - TINKER AFB - 3001 - ELEVATORS - ANNUALWEEK 44	Maintenance
11741528	3B - Medium Sustain	3B - 3001 POST 2AF-67/68 - WT - HONEYWELL - REPAIR PROGRAM - REPAIR - [redacted] 736-8536	Repair
11742288	3B - Medium Sustain	3B - 3001 POST 2AH73A - WT - HVACC - NO AIR COMING OUT OF VENTS; VERY STUFFY - REPAIR - [redacted] 370-1490	Repair
11742326	3B - Medium Sustain	3B - 3001 ROOM 104 - WT - INT PLUMB - Investigate/Repair smell of like plugged drain/sewage - REPAIR - [redacted] 736-4731	Repair
11744124	3B - Medium Sustain	3B - 3001 POST 2AH1-103C - WT - HVACC - HIGH TEMPS IN ADMIN OFFICE - Repair - [redacted] 2056973	Repair
11744238	3C - Low Sustain	3C - 3001 POST 2G-77, LEAN TO - WT - STRUC - T2743 - ADD STRUCTURE SHOP TO REPLACE CEILING TILES - REPAIR - [redacted] 734-7083	Repair
11744316	3C - Low Sustain	3C - 3001 PLANT - WT - HVACC - INSTALL SECONDARY CHW #4 - REPAIR - [redacted] - 734-5856	Repair
11744340	3B - Medium Sustain	3B - 3001 POST 2G77 - WT - STRUC - F/U 11414624 REPLACE CEILING TILES IN LAB - REPAIR - [redacted] 734-7083	Repair
11746328	3C - Low Sustain	REJECT - SEE WORK DETAILS	Repair
11747228	3C - Low Sustain	3C - 3001 & 2AH/73A - WT - STRUC - REPLACE CEILING TILES - Repair - [redacted] - 990-6861	Repair
11748330	3C - Low Sustain	3C - 3001 AHU13 C - WT - HVACC - DOORS TO AHU13 NEED TO BE SECURED - REPAIR - [redacted] - 734-5856	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11748687	3B - Medium Sustain	3B - 3001 MAIN CAFE KITCHEN - WT - HVACC - DISHWASHER COILS SHORTING OUT - REPAIR - [redacted] 734-3161	Repair
11748889	3C - Low Sustain	3C - 3001 POST N61 PLATING SH - WT - HVACC - FF/POST N-61 PIPES FROM AC UNIT LEAKING - REPAIR - T5392 - [redacted] 582-9513 - FLT-PN6	Repair
11749367	3C - Low Sustain	3C - 3001 POST O-53 - WT - INSULATE - INSULATION RIPPED ON DUCTWORK - REPAIR - [redacted] - 734-3328	Repair
11752781	3C - Low Sustain	REJECT SEE WORK DETAILS	Repair
11752833	3A - High Sustain	3A - 3001 Y53 - WT - INT PLUMB - 3 TOILETS OVERFLOWING - Repair - [redacted] 7365776	Repair
11753351	3B - Medium Sustain	3B - 3001 1AC4-95A - INT ELEC - EXIT LIGHT NOT WORKING - REPAIR - [redacted] 628-3214	Repair
11753561	3C - Low Sustain	3C - 3001 FAN DECK 17 SOUTH - WT - HVACC - REPLACE FAN MOTOR ON 17 SOUTH - REPAIR - [redacted] 734-5856	Repair
11753604	3C - Low Sustain	3C - 3001 POST Y-6 ROOM 102 - WT - LOCK - F/U 11651960 SWAP CORE - REPAIR - [redacted] 734-9868	Repair
11753953	3C - Low Sustain	3C - 3001 POST 1AH1/102D - WT - STRUC - WOMEN'S RR DOOR HAS SCREWS MISSING/NEEDS TIGHTENING - [redacted] - 734-9028	Repair
11754059	3B - Medium Sustain	3B - 3001 2U79 - WT - LOCK - NEEDING TWO DOOR CORES CHANGED - Repair - [redacted] 7365776	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11754967	2A - Preventive Maintenance	D3035160295002 - Q - Boiler/Chilled Water loops, Chemical Treatment - TINKER AFB - 3001 - BOILERS - ANNUALWEEK 51	Maintenance
11754985	2A - Preventive Maintenance	D3035160295002 - M - Boiler/Chilled Water loops, Chemical Treatment - TINKER AFB - 3001 - BOILERS - ANNUALWEEK 51	Maintenance
11754999	3C - Low Sustain	3C - 3001 PLANT EXPANSION TANKS 1&4 - WT - BAS - TANK 1 CONTROLS READING INCHES INSTEAD OF %; NEEDS CALIBRATED - REPAIR - [redacted] 246-8579	Repair
11755011	3C - Low Sustain	3C - 3001 PLANT EXPANSION TANK 2 - WT - BAS - TANK 2 NEEDS CALIBRATED - REPAIR - [redacted] 246-8579	Repair
11755035	3C - Low Sustain	3C - 3001 PLANT - WT - HVACC - NEED ISOLATION VALVES ON CHILLED WATER LINES - REPAIR - [redacted] 246-8579	Repair
11755040	3B - Medium Sustain	3B - 3001 PLANT POST 73A - WT - INT PLUMB - WATER LEAK FROM SEWAGE LINE - REPAIR - [redacted] 246-8579	Repair
11756901	3C - Low Sustain	3C - 3001 POST N61 PLATING SH - WT - BAS - FF/POST N-61 REPLACE ACTUATOR AHU-PN61- REPAIR - [redacted] - 734-5856 - SR3085109	Repair
11756946	3B - Medium Sustain	3B - 3001 POST 2AH73A - WT - BAS - REPLACE THERMOSTAT - REPAIR - [redacted] 370-1490 - SR3085138	Repair
11756973	3C - Low Sustain	3C - 3001N - WT - POWER - REFUILING GENERATOR - [redacted] - 734-5806 - EG03001-N	Repair
11757033	3B - Medium Sustain	3B - 3001 POST Y90 - WT - HVACC - HVAC IS LEAKING ON THE FLOOR - [redacted] - 736-5776	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11757181	3C - Low Sustain	3C - 3001 POST W111 - WT - ALARM - [redacted] INDICATED FACP TROUBLE - [redacted] - 734-5806 - P100835	Repair
11757187	3C - Low Sustain	3C - 3001 - WT - PEST - WEST DRIVE BETWEEN OVERHEAD DOORS 8 & 9 THERE IS A BIG VINE OF POISON IVY GROWING ON BLDG - [redacted] - 736-5776	Services
11757266	4A - High Enhance	4A - 3001 - WT - INT ELEC - ISWP - Install lighting in Central Plant - FP# - [redacted] 622-7846 - CSAG-253 MAD22-089	Repair
11757406	3B - Medium Sustain	3B - 3001 POST S33 BREAKRM - WT - INT PLUMB - SINK IS CLOGGED - [redacted] 622-7387	Repair
11757522	3B - Medium Sustain	3B - 3001 POST M31 - WT - INT PLUMB - [redacted] - 246-8579	Repair
11757663	3B - Medium Sustain	3B - 3001 POST Y34 - WT - INT PLUMB - CENTER URINAL ON S WALL CONSTANTLY RUNNING/SYSTEM WILL NOT SHUT OFF - [redacted] - 734-0408	Repair
11757741	3C - Low Sustain	3C - 3001 - WT - ALARM - F/U 11543912 REPLACE CEILING TILES WITH SMOKE ALARMS IN AREA 2B87 - [redacted] - 734-7083	Repair
11757760	3B - Medium Sustain	3B - 3001 POST X7 - WT - INT PLUMB - INSPECT ALL URINALS FOR OVERFLOWING - [redacted] - 734-0408	Repair
11757954	3C - Low Sustain	3C - 3001 POST M34 LIFT STATION - WT - IWTP MAINT - INVESTIGATE WHY PUMP IS NOT RUNNING - [redacted] 582-272-4685	Repair
11758907	3C - Low Sustain	3C - 3001 POST M41 WOMENS RR - WT - INT PLUMB - SINK FAUCET IS BAGGED - [redacted] - 622-7855	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11759595	3C - Low Sustain	3C - 3001 DOOR G - WT - STRUC - DOOR G'S CLOSURE TOO TIGHT/NEEDS ADJUSTMENT - [redacted] - 622-7855	Repair
11759759	3C - Low Sustain	3C - 3001 POST B95 WOMEN'S RR - WT - INT PLUMB - TOILET IS CLOGGED - [redacted] - 736-5776	Repair
11761512	3C - Low Sustain	3C - 3001 Post G97 - WT - INT PLUMB - FU 11413819 DRAIN LINE IS LEAKING - T5798 - [redacted] - 736-5776	Repair
11761866	3C - Low Sustain	3C - 3001 - WT - PIPE - REPAIR LINE AT 107D/REF WT 11618096 - [redacted] - 492-2496	Repair
11762016	3B - Medium Sustain	3B - 3001 POST Y63 - WT - INT PLUMB - MENS RR HAS CLOGGED AND BAGGED URINAL - [redacted] - 622-7855	Repair
11762312	3C - Low Sustain	3C - 3001 POST 1AC80A - WT - INT ELEC - INSTALL AUTO LIGHT SENSOR - [redacted] - 405-205-0852	Repair
11762935	3C - Low Sustain	3C - 3001 POST 2U79 - WT - LOCK - NEED 2 KEYS MADE #710D9 - [redacted] - 736-5776	Repair
11763388	3C - Low Sustain	3C - 3001 POST Y34 MEN'S RR - WT - INT PLUMB - SINK HAS LOW WATER PRESSURE - [redacted] - 549-4485	Repair
11763586	3C - Low Sustain	3C - 3001 Post X73-T73 and T33-T63 - WT - OP - Repair/Replace storm water piping - [redacted] 405-820-8404	Services
11763594	3C - Low Sustain	3C - 3001 - WT - OP - Define scope and develop PAA based on storm water study - [redacted] 405-820-8404	Services
11767175	3C - Low Sustain	3C - 3001 PLANT - WT - HVACC - REPLACE GASKETS ON CHILLED WATER PUMP - [redacted] - 734-6589	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11767466	3C - Low Sustain	3C - 3001 HOLLYWOOD AND VINE - WT - INT ELEC - INSTALL/MOVE LIGHT SWITCH - [redacted] 7368536	Repair
11767482	3B - Medium Sustain	3B - 3001 POST 2V77 - WT - LOCK - CYPHER LOCK FOR SAFETY OFFICE DOOR AT ROOM 24 WILL NOT UNLOCK - [redacted] - 622-7855	Repair
11767612	3C - Low Sustain	3C - 3001 2Y45 - WT - INT ELEC - ELECTRICAL SOCKET IS LOOSE/GOES BACK INTO WALL WHEN SOMETHING IS PLUGGED IN - [redacted] - 823-8873	Repair
11768300	3A - High Sustain	3A - 3001 MECH ROOM 6 LOWER POST 1AD85A - WT - INT PLUMB - VERY LARGE WATER LEAK - [redacted] 4052487122	Repair
11768944	3C - Low Sustain	3C - 3001 PLANT - WT - INT ELEC - HOOK ELECTRICAL BACK TO SECONDARY PUMP #2 - [redacted] - 734-5856	Repair
11769026	3C - Low Sustain	3C - 3001 POST 1AC80A CSPO OFFICE - WT - STRUC - HANG WORLD CLOCK & SHIELD - [redacted] 417-2893	Repair
11769912	3B - Medium Sustain	3B - 3001 2 UPPER - WT - HVACC - 2 UPPER HAS A WATER LEAK - [redacted] - 734-5856	Repair
11770475	3B - Medium Sustain	3B - 3001 2Q73 - WT - HVACC - WATER LEAK REPEATEDLY SOAKING CEILING TILES - [redacted] 408-1339	Repair
11773601	3C - Low Sustain	3C - 3001 POST 2B87 - WT - INT ELEC - F/U 11757741 TILES TO BE REPLACED HAVE MOTION SENSORS FOR LIGHTING - [redacted] - 734 -5806	Repair
11773725	3C - Low Sustain	3C - 3001 MAIN CAFE KITCHEN - WT - HVACC - LEAK CHECK DISHWASHER COILS - REPAIR - [redacted] 734-3161	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11773768	3B - Medium Sustain	3B - 3001 2 LOWER - WT - BAS - 2 UPPER VFD TRIPPED OFF - [redacted] - 734-5856 PO 20HAL00272 ADD 5/22/23	Repair
11773826	4A - High Enhance	4A - 3001 2AF76A, 2AD85A,2AH190B - WT - INT PLUMB - Install 3 upgraded water fountains w/bottle fillers - [redacted] - 405 736 3537	Repair
11774186	3A - High Sustain	3A - 3001 MECH ROOM 6 LOWER - WT - INT PLUMB - 2" DRAIN LEAKING - [redacted] 7345856	Repair
11774656	3C - Low Sustain	REJECT DEFAULT - Work Task Template - Corrective Maintenance-Pest Control	Repair
11775704	3C - Low Sustain	3C - 3001 AHU P890 - WT - HVACC - CLEAR CONDENSATE DRAIN ON AIR HANDLER - [redacted] - 734-5856	Repair
11776155	3A - High Sustain	3A - 3001 HORSHOE - WT - SWEEP - SWEEP HORSHOE OF BLDG - [redacted] 7362500	Repair
11776764	3A - High Sustain	3A - 3001 Post 1AB194A Mech room 7 lower - WT - AFTER HVAC - Water leaking - [redacted] 990-6861	Repair
11777991	3C - Low Sustain	3C - 3001 PLANT - WT - SHEET METAL - FF/REPAIR COVER OVER HOUSING ON PUMP #6 - REPAIR - [redacted] - 734-5856 - SR3095859	Repair
11778523	3B - Medium Sustain	3B - 3001 Post 2AF 72A - WT - HVACC - Water leaking from air coil - [redacted] - 582-9513 - UID 3001-AHU-A2U	Repair
11778953	3B - Medium Sustain	3B - 3001 POST Q40 - WT - INSULATOR - INSULATE CHILLED WATER RETURN LINE REF WT# 11735039 - [redacted] - 736-4118	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11779157	3B - Medium Sustain	3B - 3001 POST 0-73 - WT - INT PLUMB - WOMENS RR SINK ON W SIDE IS INOP/OTHER FAUCET SPRAYS WATER EXTREMELY HARD - [redacted] - 622-7855	Repair
11779409	3B - Medium Sustain	3B - 3001 ADMIN - WT - BAS - ORDER BACK UP VFD'S - [redacted] - 734-6395	Repair
11779592	3C - Low Sustain	3C - 3001 ROOFTOP - WT - HVACC - REPLACE 1985 CONDENSER UNIT - [redacted] - 734-5856	Repair
11779750	3B - Medium Sustain	3B - 3001 POST M31 - WT - PIPE - F/U 11757522 METER LEAK ON THE OUTLET SIDE OF BACKFLOW - [redacted] - 734-7098	Repair
11780030	3A - High Sustain	3A - 3001 POST 1AH184A - WT - INT PLUMB - CLOGGED DRAIN COMING FROM MECH ROOM AU16UPPER - [redacted] - 990-6861	Repair
11781146	3B - Medium Sustain	3B - 3001 Y60 - WT - LOCK - REPLACE CORE IN ONE PADLOCK - [redacted] 7342420	Repair
11781498	3B - Medium Sustain	3B - 3001 POST 1AH184A - WT - STRUC - FLOOR DRAIN NEEDS TO BE RESEALED WITH CONCRETE - [redacted] 990-6861	Repair
11782946	3B - Medium Sustain	3B - 3001 POST 2AH73A - WT - HONEYWELL - REPLACE THERMOSTAT - REPAIR - [redacted] - 405-818-1590 - SR3098479	Repair
11783250	3B - Medium Sustain	3B - 3001 POST 2AHI-103C - WT - HONEYWELL - REVIEW/ADJUST PROGRAMMING FOR AHU-12U - REPAIR - [redacted] - 734-2328	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11783724	3C - Low Sustain	3C - 3001 POST 2V77 & W75 - WT - LOCK - ASSISTANCE DETERMINING NEED FOR PURCHASE/INSTALLATION OF CORRECT CYPHER LOCKS - [redacted] - 622-7855	Repair
11784199	3C - Low Sustain	3C - 3001 Post G97 - WT - ROOF - F/U 11761512 & 11413819 DRAIN LINE IS LEAKING - T5798 - [redacted] - 734-7098 - SR 3099169	Repair
11784604	3B - Medium Sustain	3B - 3001 POST 1AH71A - RS71 - WT - SPRINK - FU 11471111 FIRE SUPPERESSION LINE IS LEAKING - [redacted] - 205-0852 - STORM	Repair
11784636	3B - Medium Sustain	3B - 3001 POST T87 - WT - HVACC - FU 11462169 STORM LEAKING FROM INSIDE AC UNIT NOT SURE WHERE TRANSFER TO HVAC - T5595 - [redacted] - 739-4975	Repair
11784666	3C - Low Sustain	3C - 3001 P K107 - RS22 - WT - HVACC - 11475927 LEAK COMING FROM INSIDE HVAC UNIT BY THE FILTERS- [redacted] 736-5776 PR 3009. 3012, 3013 12/6-9	Repair
11785315	3A - High Sustain	3A - 3001 MAIN CAFE - WT - INT PLUMB - MOP SINK IN KITCHEN IS BACKING UP - [redacted] - 734-3161	Repair
11785365	3A - High Sustain	3A - 3001 MRR POST P103 - WT - INT PLUMB - SINK IS OVERFLOWING - [redacted] 736-5776	Repair
11785765	4A - High Enhance	4A - 3001 MAIN PARKING LOT S. - SVC CONT - RE-STRIPE PARKING LOT - [redacted] - 405 739 8921	Repair
11786441	3C - Low Sustain	3C - 3001 ALLEY - WT - HVACC - CLEAN IMPACTED COILS - [redacted] - 734-6589 - CH-2	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11787844	3B - Medium Sustain	3B - 3001 POST 2AH1-103C - WT - BAS - VERIFY EQUIP BELONGS TO HONEY - HONEY TO REVIEW AND ADJUST - REPAIR - [redacted] - 205-6973 - SR3101099	Repair
11788170	3B - Medium Sustain	3B - 3001 POST 1AH71A - WT - STRUC - F/U 11784604 PULL CEILING TILE TO ASSIST SPRINK - [redacted] - 734-5806	Repair
11788416	3C - Low Sustain	3C - 3001 AHU-20N - WT - BAS - LEFT DAMPER SECTION NOT OPENING, ACTUATOR IS BAD - [redacted] 734-4321	Repair
11788474	3C - Low Sustain	3C - 3001 POST 1AH79A - WT - STRUC - F/U 11678699 REPLACE SOFT CLOSE DAMPER ON AFLCMC DOOR - [redacted] - 736-8707	Repair
11788730	3A - High Sustain	3A - 3001 POST 2M41 - WT - HVACC - AC NOT BLOWING - [redacted] - 635-7051	Repair
11789038	1-Emergency	1 - 3001 - WT - HONEYWELL - BAS/ALL FAN DECKS OFF DUE TO EMERGENCY SHUT DOWN BUTTON - [redacted] - 582-5009	Repair
11790004	3B - Medium Sustain	3B - 3001G RM 104 - WT - HVACC - HIGH HUMIDITY ALERT - [redacted] - 409-5733- CRAC-5	Repair
11790340	3C - Low Sustain	3C - 3001 S HANGAR E PED DOOR - WT - STRUC - F&F/DOOR NOT LATCHING CORRECTLY - [redacted] - 734-1794	Repair
11797126	3C - Low Sustain	3C - 3001 POST R80 - WT - STRUC - REPAIR POTHOLE IN AISLE WAY - [redacted] - 736-5776	Repair
11797376	3C - Low Sustain	3C - 3001 - WT - LOCK - NEEDS COPIES OF KEYS MADE - [redacted] - 736-2085	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11797517	3C - Low Sustain	3C - 3001 - WT - INT PLUMB - LEAK POSSIBLY FROM SINK ATTACHED TO OLD COOLANT TROUGH - [redacted] - 736-5776	Repair
11797576	3B - Medium Sustain	3B - 3001 POST 2F79 HEAT TREAT OFFICES - WT - HVACC - HVAC NOT WORKING - [redacted] 736-5776	Repair
11797801	3C - Low Sustain	3C - 3001 STREAM PLANT POST Y64 - WT - ALARM - TROUBLESHOOT MONACO TRANSMITTER - [redacted] 734-4202	Repair
11799177	3B - Medium Sustain	3B - 3001 POST 2D82 - WT - HONEYWELL - LED LIGHT OUT IN OFFICE - [redacted] - 2197894	Repair
11799266	3C - Low Sustain	3C - 3001 AHU 16 UPPER - WT - INT PLUMB - F/U 11780030 REPLACE FLOOR DRAIN - [redacted] 990-6861	Repair
11799327	3C - Low Sustain	3C - 3001 AHU-7 UPPER - WT - INT PLUMB - UNCLOG FLOOR DRAIN - [redacted] 734-2753	Repair
11800805	3B - Medium Sustain	3B - 3001 POST 1AH1/116 - WT - STRUC - DOOR DOES NOT STAY SECURE, CAN BE PULLED OPEN EVEN WHEN LOCKED; SECURE ROOM - [redacted] 990-6861	Repair
11801145	3B - Medium Sustain	3B - 3001 OH DOOR 24 - WT - MACH MAINT - OH DOOR # 24 AT CORP BLDG WILL ONLY JOG DOWN ON CLOSING - [redacted] - 464-0929	Repair
11801209	3B - Medium Sustain	3B - 3001 POST 1AH1/116 - WT - STRUC - RAISED FLOOR TILE READY TO COLLAPSE - [redacted] - 734-9028	Repair
11801472	3A - High Sustain	3A - 3001 ANNEX 4 - WT - ROOF - ROOF LEAK ON S WALL OF ROOMS 110-115. REPAIR ROOF & REPLACE DAMAGED CEILING TILES - [redacted] - 736-4730	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11802919	3B - Medium Sustain	3B - 3001 POST Q40 - WT - HVACC - CHILLED WATER LINE DRIPPING - [redacted] - 736-5776	Repair
11803521	3A - High Sustain	3A - 3001 R97 - WT - LOCK - DOOR WILL NOT UNLOCK - [redacted] 414-5193	Repair
11804527	3C - Low Sustain	3C - 3001 POST 2Y55 CONFERENCE ROOM - WT - STRUC - CEILING TILES NEED REPLACED - [redacted] - 736-9977	Repair
11804759	3C - Low Sustain	3C - 3001 POST Y55 - WT - LOCK - REQUEST BOTH GLASS DOORS BE MADE TO LOCK/UNLOCK WITH A KEY - [redacted] - 736-9977	Repair
11804773	3C - Low Sustain	3C - 3001 POST Y61 - WT - LOCK - REQUEST BOTH GLASS DOORS BE MADE TO LOCK/UNLOCK WITH A KEY - [redacted] - 736-9977	Repair
11805123	2A - Preventive Maintenance	B20354101950 - S - Door, overhead, electric, roll up, to 24' high x 25' wide - TINKER AFB - 3001 - METALS - ANNUALWEEK 17	Maintenance
11805126	2A - Preventive Maintenance	B20354101950 - S - Door, overhead, electric, roll up, to 24' high x 25' wide - TINKER AFB - 3001 - METALS - ANNUALWEEK 17	Maintenance
11805219	2A - Preventive Maintenance	B20354101950 - S - Door, overhead, electric, roll up, to 24' high x 25' wide - TINKER AFB - 3001 - METALS - ANNUALWEEK 17	Maintenance
11805653	3C - Low Sustain	3C - 3001 POST Y35 - WT - STRUC - REPLACE DOUBLE EXTERIOR DOORS TO COMPLY WITH SECURITY ENVELOPE - [redacted] - 622-7839	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11805721	3B - Medium Sustain	3B - 3001 POST Y76 HOLLYWOOD&VINE DOOR - WT - INT ELEC - NEED ADA OPENER INSTALLED/OPENER NEED TO WORK WITH SECURITY ENVELOPE - [redacted] - 622-7839	Repair
11806338	3B - Medium Sustain	3B - 3001 POST A59 - WT - HVACC - F/U 11708819 WATER MAKE UP LINE LEAKING - [redacted] - 736-5776	Repair
11807112	3A - High Sustain	3A - 3001 1AF81A - WT - HVACC - WATER LEAKING FROM CEILING IN OFFICE - [redacted] 7348604	Repair
11807417	3C - Low Sustain	3C - 3001 - WT - PEST - APPLY RODENT BAIT BETWEEN DOOR C AND E - [redacted] - 734-9028	Services
11808105	3B - Medium Sustain	3B - 3001 1AF81A - WT - HVACC - F/U 11807112 ORDER NEW CONDENSATE PUMP - [redacted] 7348604	Repair
11808341	2A - Preventive Maintenance	B20354101950 - S - Door, overhead, electric, roll up, to 24' high x 25' wide - TINKER AFB - 3001 - METALS - ANNUALWEEK 16	Maintenance
11808343	2A - Preventive Maintenance	B20354101950 - S - Door, overhead, electric, roll up, to 24' high x 25' wide - TINKER AFB - 3001 - METALS - ANNUALWEEK 16	Maintenance
11808345	2A - Preventive Maintenance	B20354101950 - S - Door, overhead, electric, roll up, to 24' high x 25' wide - TINKER AFB - 3001 - METALS - ANNUALWEEK 16	Maintenance
11808346	2A - Preventive Maintenance	B20354101950 - S - Door, overhead, electric, roll up, to 24' high x 25' wide - TINKER AFB - 3001 - METALS - ANNUALWEEK 16	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11808347	2A - Preventive Maintenance	B20354101950 - S - Door, overhead, electric, roll up, to 24' high x 25' wide - TINKER AFB - 3001 - METALS - ANNUALWEEK 16	Maintenance
11808348	2A - Preventive Maintenance	B20354101950 - S - Door, overhead, electric, roll up, to 24' high x 25' wide - TINKER AFB - 3001 - METALS - ANNUALWEEK 16	Maintenance
11808435	3B - Medium Sustain	3B - 3001 POST 2AH1/84A AHU 16 UPPER - WT - INT PLUMB - EXISTING FLOOR DRAIN&ABANDONED PIPE NEED TO BE PERMANENTLY REPAIRED - [redacted] -	Repair
11809008	3B - Medium Sustain	3B - 3001G 2nd fl stairwell - WT - INT ELEC - repair/replace emergency light - [redacted] 492-2496 - SR3108613	Repair
11809063	3C - Low Sustain	3C - 3001G Room 107 - WT - STRUC - repair/replace broken raised floor vent - [redacted] 492-2496 - SR3108633	Repair
11809116	3C - Low Sustain	3C - 3001G Room 104 - WT - STRUC - 20 water stained ceiling tiles need replaced - [redacted] 409-5733 - SR3108658	Repair
11809131	3A - High Sustain	3A- 3001G Room 203 - WT - HVAC C - leak has collapsed ceiling tile above filing cabinet - repair - [redacted] - 405-409-5733 - SR3108667	Repair
11809133	3A - High Sustain	3A - 3001G Rooms 203 and 205 - MOLD REMD - Clean two 3x3 carpet areas suspected of mold - [redacted] 492-2496 - SR3108668 - MOLD	Services
11809161	3C - Low Sustain	3C - 3001 Annex 4 Rms 110-115 - WT - STRUC - replace 20 water stained ceiling tiles - [redacted] 409-5733 - SR3108683	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11809162	3C - Low Sustain	3C - 3001G Room 206 - WT - INT ELEC - replace missing outlet cover - [redacted] 492-2496 - SR3108684	Repair
11809171	3C - Low Sustain	3C - 3001G 2nd fl mech room - WT - INT ELEC - Junction box cover missing - [redacted] 409-5733 - SR3108686	Repair
11809203	3C - Low Sustain	3C - 3001G W Mech room - WT - INT ELEC - 5 junction boxes need covers & 2 wall penetrations need sealed - [redacted] 409-5733 - SR3108701	Repair
11810338	3B - Medium Sustain	3B - 3001 T35 tool crib - WT - Lock - combination dial spins freely - [redacted] - 736-7053	Repair
11811254	3C - Low Sustain	3C - 3001 ANNEX G 2ND FLOOR MECH ROOM - WT - ROOF - REPAIR OPENING IN CEILING FROM ANTENNA STAND PIPE - [redacted] - 736-4731	Repair
11811547	3C - Low Sustain	3C - 3001 POST Y34 - WT - INT PLUMB - 1 SINK IS NOT FUNCTIONING - [redacted] - 734-0408	Repair
11811557	3B - Medium Sustain	3B - 3001 POST Y34 MEN'S RR - WT - INT PLUMB - CENTER URINAL ON S WALL IS BAGGED - [redacted] - 734-0408	Repair
11811640	3C - Low Sustain	3C - 3001 POST A115 STC P&W AREA - WT - SPRINK - FIRE SUPPRESSION TAG/INSPECTION - [redacted] - 736-5776 - PSFS-W003	Repair
11811700	3B - Medium Sustain	3B - 3001 POST K97 - WT - STRUC - ROOF LEAK NEAR ELECTRICAL PLUG - [redacted] - 736-5776	Repair
11811852	3A - High Sustain	C/O 3A - 3001 ANNEX 4 COMPUTER ROOM - WT - HVACC - HIGH TEMP READINGS - [redacted] 409-5733 PO B200571-BCPC ADD 9/12/22	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11812083	3C - Low Sustain	3C - 3001G RM 203 - WT - STRUC - F/U 11809131 REPLACE DAMAGED CEILING TILE FROM LEAK - [redacted] - 736-4730	Repair
11812847	3A - High Sustain	C/O - 3A - 3001 POST 2Q73 - WT - HVACC - POSSIBLE HVAC LEAK - [redacted] - 736-8536	Repair
11813009	3C - Low Sustain	3C - 3001 POST 2AF68A - WT - HVACC - NO AIRFLOW COMING FROM VENTS IN OFFICE - [redacted] - 370-1490	Repair
11813048	3B - Medium Sustain	3B - 3001 Y76 - WT - INT ELEC - NON FUCTIONING ELECTRICAL OUTLET INSIDE OFFICE OF NEW OC/ALC "SECURITY OFFICE" - [redacted] - 370-1490	Repair
11813816	3A - High Sustain	3A - 3001 MRR B95 - WT - INT PLUMB - URINAL OVERFLOWING - [redacted] 736-5776	Repair
11816194	3C - Low Sustain	3C - 3001 Post 1AI-74A - WT - PEST - Extermination requested for roaches in the AFSC Command Suite - [redacted] - 736-8707	Services
11818270	3C - Low Sustain	3C - 3001 AHUS 8S,9S,&10S - OP - 59508 - RETROFIT BLOWERS W/FAN TYPE BLOWERS - [redacted] - 405 582 4820 alexis programming	Repair
11818647	3B - Medium Sustain	3B - 3001 2AH71A & 2AG66A - WT - LOCK - NEED 5 NEW CORES & 6 KEYS FOR 5 MR OFFICES - [redacted] - 370-1490	Repair
11820808	3B - Medium Sustain	3B- 3001 POST X 111 - WT - Structure - cypher lock door not latching after opening & closing - repair - [redacted] - 736-5717 - SR 3113051	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11824690	3B - Medium Sustain	C/O 3A - 3001 POST 2W77 - RS65 - WT - KH090102 ROOF LEAK ABOUT TO BURST CEILING TILE - [redacted] - 736-5776	Repair
11825542	3B - Medium Sustain	3B - 3001 POST M38 - WT - MACH MAINT - OH DOOR WON'T OPEN - [redacted] - 464-0929	Repair
11832792	4A - High Enhance	4A - 3001 Post 1AH-105 - CBR - Install a temporary wall - [redacted] - 405 736 8707	Repair
11833239	3B - Medium Sustain	3B - 3001 POST I-67 - WT - IWTP - HAZWASTE BUBBLING UP FROM DRAIN - [redacted] 5826991	Repair
11838359	3B - Medium Sustain	3B- 3001 ROOM 107D - WT - INSULATOR - INSULATE CHILL WATER LINES - [redacted] - 492-2496	Repair
11838374	3B - Medium Sustain	3B- 3001 ROOM 107D - WT - BAS - VALVE ACTUATOR DISCONNECTED - [redacted] - 492-2496	Repair
11838507	3C - Low Sustain	3C - 3001 ANNEX G RM 143 - WT - INSULATOR - UNIT RM 107 NEED TO INSULATE PIPES - [redacted] - 642-8309	Repair
11838518	3C - Low Sustain	3C - 3001 ANNEX G RM 143 - WT - BAS - UNIT NOT RUNNING RM 107, WIRE ACTUATOR - [redacted] - 642-8309	Repair
11838778	3B - Medium Sustain	3B - 3001 SW CORNER ANNEX G EXT - WT - HVACC - REPAIR/REPLACE DAMAGED VENT COVER - [redacted] - 492-2496	Repair
11839137	3C - Low Sustain	3C - 3001 POST 1AH184A - WT - INT PLUMB - F/U 11780030 & 11799266 REPLACE FLOOR DRAIN - [redacted] - 734-2753 - AHU-16	Repair
11839883	3A - High Sustain	3A - 3001 POST O65 QVC LAB - WT - INT ELEC - FRONT HALF OF CEILING LIGHTS WENT OUT - [redacted] - 408-0683	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11842638	3B - Medium Sustain	3B - 3001 POST 2AH1-103C - WT - HONEYWELL - HONEYWELL TO REVIEW AND ADJUST PROGRAMMING - REPAIR - [redacted] - 205-6973 - SR 3120742	Repair
11843106	4A - High Enhance	4A - 3001 POST X44 - WT - INT ELEC - INSTALL ELECTRICAL OUTLET - [redacted] - 405 549 4485	Repair
11843486	3A - High Sustain	3A - 3001 POST Y84 LEANTOO 13 - WT - HVACC - AC NOT WORKING/BLOWING HOT AIR - [redacted] - 417-8194	Repair
11844133	3C - Low Sustain	3C - 3001 ANNEX G DOOR G15 - WT - HVACC - REPAIR VENTILATION OPENING - [redacted] - 736-4731	Repair
11844191	3C - Low Sustain	3C - 3001 RTU 1 - WT - BAS - CHW PUMP INOP - [redacted] - 582-5009	Repair
11844201	3B - Medium Sustain	3B - 3001 2AH1-109B - WT - LOCK - UNLOCK DOOR TO ALLOW ACCESS - [redacted] - 405-6973	Repair
11844224	3C - Low Sustain	3C - 3001 ANNEX G ROOM 107B - WT - HONEYWELL - REPAIR NON WORKING LIGHT FIXURE - [redacted] - 736-4731	Repair
11844296	3C - Low Sustain	3C - 3001 ANNEX G 2ND FLR MEN'S RR - WT - INT PLUMB - REPAIR WATER CLOSET - [redacted] - 492-2496	Repair
11844607	3C - Low Sustain	3C - 3001 LEAN-TO 1 2ND FL RM 202 - WT - BAS - HUMIDITY SENSOR IS BAD - [redacted] - 818-1590	Repair
11844759	3A - High Sustain	3A - 3001 POST 2 X 56 - WT - HVAC C - FAN DECK LEAKING WATER - [redacted] - 4204404	Repair
11845372	3B - Medium Sustain	3B - 3001 CAFE LOADING DOCK DOOR - WT - STRUC - LOADING DOCK EXIT DOOR WON'T SECURE - [redacted] 734-3161	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11847332	3C - Low Sustain	3C - 3001 COL T95 - WT - PM - VACUUM WATER FROM FAN DECK - [redacted] - 582-9513 - FLT-P15W	Repair
11847385	3C - Low Sustain	3C - 3001 Col T-95 - WT - HVAC PM - Vacuum water from fan deck - [redacted] - 582-9513 - UID 3001-FLT-P15E	Repair
11848305	3A - High Sustain	3A - 3001 POST G87 - WT - HVACC - CHILLED WATER LEAK FROM 3 DIFF AREAS - [redacted] - 736-5776	Repair
11849132	3C - Low Sustain	3C - 3001 POST 2X56 - WT - HVACC - F/U 11844759 REPAIR CRACKS IN FAN DECK - [redacted] - 420-4404	Repair
11849316	3B - Medium Sustain	OUTAGE 3B - 3001 POST G87 - WT - PIPE - (09/22/2022 COM) CHILLED WATER LEAK FROM 3 DIFF AREAS - [redacted] - 736-5776	Repair
11849336	3B - Medium Sustain	3B - 3001 POST 2X56 - WT - INT ELEC - F/U 11844759 REPAIR DAMAGED WIRING/CONDUIT - [redacted] - 420-4404	Repair
11849790	3C - Low Sustain	3C - 3001 - WT - HVAC PM - ORDER 400 20X24X4 FILTERS - [redacted] - 582-9513	Repair
11849859	3C - Low Sustain	REJECTED - NEED MORE INFO	Repair
11849917	3B - Medium Sustain	3B - 3001 Annex G - WT - INT ELEC - Repair handicapped push button - [redacted] 492-2496 SR3122764	Repair
11849944	3C - Low Sustain	3C - 3001 S PARKING LOT - OP - Restriping Parking Lot - [redacted] - 405 734 4111 Alexis programming	Repair
11849957	3B - Medium Sustain	3B - 3001 POST 1AJ-71 DOOR A - WT - ALARM - FA PANEL SHOWING TROUBLE CALL & BEEPING - [redacted] - 408-1339	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11850242	3C - Low Sustain	3C - 3001 Post PY90 - WT - BAS - Check supply fan VFD - Keith Dotter 582-5009	Repair
11851890	3A - High Sustain	3A - 3001 AHU 9L - WT - INT PLUMB - CONDENSATE FLOOR DRAIN CLOGGED - [redacted] - 801-971-7286	Repair
11851891	3C - Low Sustain	3C - 3001 POST Y90 - WT - DUCT - NEED AIR DUCTS CLEANED - MICHAEL BLAKE - 736-5776	Repair
11852128	3B - Medium Sustain	3B - 3001 POST O65 QVC LAB - WT - INT ELEC - F/U 11839883 FRONT HALF OF CEILING LIGHTS WENT OUT - [redacted] - 408-0683	Repair
11852997	4A - High Enhance	REJECT - 3001 MAIN PARKING LOT - WT - Request ENG EVAL to repair numerous cracks/potholes - [redacted] - 405 739 8921	Repair
11853529	3C - Low Sustain	3C - 3001 POST C75 - WT - INT ELEC - BROKEN LIGHT SWITCH - [redacted] - 736-5776	Repair
11853578	3B - Medium Sustain	3B - 3001 POST P81 - WT - INT PLUMB - PIPE LEAKING/POSSIBLY IN THE REST ROOM - [redacted] - 736-5776	Repair
11853633	3C - Low Sustain	3C - 3001 POST K75 - WT - ROOF - ROOF LEAKS WHEN IT RAINS - [redacted] - 736-5776	Repair
11853680	3C - Low Sustain	3B - 3001 POST F 70 - WT - WELD - 2 METAL FLOOR COVERS MISSING - [redacted] - 7365776	Repair
11853697	3C - Low Sustain	3C - 3001 - WT - HVACC - SERVICE CHILLER - [redacted] - 492-2496	Repair
11853723	3B - Medium Sustain	3B - 3001 POST 2X56 - WT - INT PLUMB - PLUMBING LEAK IN THE CEILING - [redacted] - 736-5776	Repair
11853738	3C - Low Sustain	3C - 3001 - WT - STRUC - NEED CEILING TILES REPLACED - [redacted] - 736-5776	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11853932	3A - High Sustain	3A - 3001 CAFE LOADING DOCK DOOR - WT - STRUC - LOADING DOCK EXIT DOOR WON'T SECURE - [redacted] 734-3161	Repair
11854244	3C - Low Sustain	3C - 3001 - WT - ALARM - TROUBLE SHOOT FA PANEL IN THE AREA OF ANNEX 4 & MAKE REPAIR TO ANY ITEMS NOT WORKING CORRECTLY - [redacted] - 734-4202	Repair
11854263	3C - Low Sustain	3C - 3001 - WT - ALARM CONT - TROUBLE SHOOT FA PANEL IN THE AREA OF ANNEX 4 & MAKE REPAIR TO ANY ITEMS NOT WORKING CORRECTLY - [redacted] - 734-4202	Repair
11855028	3C - Low Sustain	3C - 3001 POST K77 - WT - INT ELEC - ELECTRICAL OUTLET NOT WORKING - [redacted] - 736-5776	Repair
11855212	3C - Low Sustain	REJECT - Requester is not a facility manager for 9001	Repair
11856361	3C - Low Sustain	3C - 3001 POST N-61 - WT - INSULATOR - FF/PIPES NEED INSULATED - [redacted] - 582-9513 - FLT-PN61	Repair
11861013	3C - Low Sustain	3C - 3001 BETWEEN Y59 & Y60 - WT - HONEYWELL - 3 LIGHT BULBS OUT ON TRACK LIGHTING - [redacted] - 736-9977	Repair
11861146	3C - Low Sustain	3C - 3001 POST 2Y55 TO 2Y63 HALLWAY - WT - STRUC - REPLACE 14 STAINED CEILING TILES - [redacted] - 736-9977	Repair
11861179	3C - Low Sustain	3C - 3001 POST Y 55 - WT - STRUC - 5 CEILING TILES NEEDING REPLACED - [redacted] - 7369977	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11861938	3C - Low Sustain	3C - 3001 POST 2Y61 - WT - LOCK - INSTALL LOCKS ON MENS AND WOMENS RR - [redacted] - 7369977	Repair
11863760	3C - Low Sustain	3C - 3001 P39 - OP - 24999 - Replace corroded ductwork - [redacted] - 405 582 4820 wesley programming	Repair
11863764	3A - High Sustain	3a - 3001 Post Q81 - WT - INTPLUMB - Sewage bubbling out of a pipe - [redacted] 830-9822	Repair
11865233	3B - Medium Sustain	3B - 3001G ROOM 105 - WT - STRUC - TREAD COVER ON STAIRS CAUSING TRIP HAZARD - [redacted] - 4922496	Repair
11865752	4A - High Enhance	4A - 3001 K69 - CBM - modify existing lab space - [redacted] - 405 582 4820	Repair
11867913	3B - Medium Sustain	3B - 3001 FAN DECK 3 - WT - INTELEC - NO POWER TO LIGHTS ABOVE FD3 - REPAIR - [redacted] - 819-8135 - SR 3128092	Repair
11868135	3B - Medium Sustain	C/O - 3B - 3001 G54 - WT - INT PLUMB - BACKFLOW PREVENTER LEADING TO RO UNITS IN PLATING SHOP WASTING WATER - [redacted] - 736-5776	Repair
11868373	3C - Low Sustain	3C - 3001 POST 073 WOMENS RR - WT - INT PLUMB - BROKEN TOILET SEAT - [redacted] - 732-6189	Repair
11868412	3B - Medium Sustain	3B - 3001 POST O83 MENS RR - WT - INT PLUMB - 1ST AND 3RD TOILETS WILL NOT FLUSH/3RD URINAL WILL NOT FLUSH - [redacted] - 732-6189	Repair
11868467	4A - High Enhance	4A - 3001 K69 - OP - INSTALL AUDIO VISUAL ALARM - [redacted] - 405 739 3348 Wesley programming	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11868472	3B - Medium Sustain	3B - 3001 ANNEX G DATA CENTER ROOM 104 - WT - HVACC - NEED TO TROUBLESHOOT ON BACK FLOW PREVENTER - REPAIR - [redacted] 405-409-5733	Repair
11868498	3B - Medium Sustain	3B - 3001 MENS RR - WT - INT PLUMB - 3 TOILETS CLOGGED AND BAGGED - [redacted] - 736-5776	Repair
11868524	3C - Low Sustain	3C - 3001 POST 083 - WT - INT PLUMB - URINAL CLOGGED AND BAGGED - [redacted] - 736-5776	Repair
11868553	3C - Low Sustain	REJECT - SEE WORK DETAILS	Repair
11869063	3B - Medium Sustain	3B - 3001 NEAR POST P70 - WT - LOCK - CYPHER LOCK IS NOT FUNCTIONING - [redacted] - 734-1959	Repair
11871273	3C - Low Sustain	3C - 3001 UPPER FAN DECK #9 - WT - INT ELEC - RUN CONDUIT TO NAC PANEL FOR HORN/STROBES - [redacted] - 734-4202	Repair
11872349	3A - High Sustain	3A - 3001 POST 2U77 - WT - INT ELEC - OUTLET TRIPPED BREAKER AND LOST POWER TO AREA - [redacted] - 823-8873	Repair
11872564	3A - High Sustain	3A - 3001 1AG1-95A - WT - INT ELEC - LOUD POPPING NOISE & LOSS OF POWER TO AREA - [redacted] - 990-6861	Repair
11872827	3C - Low Sustain	3C - 3001 ANEX G SERVER ROOM - WT - HVACC - HVAC UNIT IS NOT RUNNING IN ROOM 107D - [redacted] - 734-6589	Repair
11874044	3B - Medium Sustain	3B - 3001 1AG1-95A - WT - INT ELEC - F/U 11872564 REPLACE DAMAGED BALLASTS - [redacted] - 990-6861	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11878692	3A - High Sustain	3A - 3001 POST 1AI70 ANACONDA CONF RM - WT - SPRINK - ACTIVE WATER LEAK FROM CEILING - [redacted] - 417-2893	Repair
11879567	3B - Medium Sustain	3B - 3001 POST 1AI70 ANACONDA CONF RM - WT - ALARM - F/U 11878692 ACTIVE WATER LEAK FROM CEILING - [redacted] - 417-2893	Repair
11880478	3C - Low Sustain	3B - 3001 POST 1AF-71A - WT - STRUC - REPLACE 1 FT OF SHEET ROCK IN HALLWAY - [redacted] - 736-5232 - ?	Repair
11880537	3B - Medium Sustain	3B - 3001 POST AH70H - WT - STRUC - RIGHT ENTRANCE DOOR SLAMMING - [redacted] - 7343161	Repair
11880879	3A - High Sustain	3A - 3001 DOOR 24 - WT - INT ELEC - CIRCUIT BREAKER TO RIP SAW INOP - [redacted] - 508-0150	Repair
11881323	3A - High Sustain	3A - 3001 POST HA50.2 TANK & COOLER SHOP - WT - HVACC - TEST END ROOM TEMP OUT OF TOLERANCE, CURRENTLY 80 DEG - [redacted] - 736-2085	Repair
11882278	3C - Low Sustain	3C - 3001 DOOR A POST 1AJ71A - WT - STRUC - REPAIR/REPLACE SPLINTERING WOODEN HANDRAIL - [redacted] - 408-1339	Repair
11883457	3B - Medium Sustain	F/U 11880879 - 3B - 3001 DOOR 24 - WT - INT ELEC - REPLACE CIRCUIT BREAKER TO RIP SAW - [redacted] - 508-0150	Repair
11883523	3B - Medium Sustain	FU 11881323 - 3B - 3001 POST HA50.2 TANK & COOLER SHOP - WT - HVACC - REPLACE FILTERS - [redacted] 2487122	Repair
11883563	3C - Low Sustain	EVAL COMPLETE - 3C - 3001 1AF-71A - REQUEST ENG EVAL FOR STRUCTURAL BREAK - [redacted] - 405 734 9868	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11885637	3C - Low Sustain	3C - 3001 Post O-73 - WT - Intplumb - Women's R/R has broken toilet seat - repair - [redacted] - 736-5776 - SR 3133594	Repair
11885748	3B - Medium Sustain	3B - 3001 JOP LAB - WT - BAS - TROUBLE SHOOT HUMIDITY ISSUE - REPAIR - [redacted] - 405-886-5386 - SR 3133680	Repair
11885811	3C - Low Sustain	3C - 3001 POST 2W75 - WT - STRUC - MOUNT A FIRE EXTINGUISHER - [redacted] - 622-7855	Repair
11885823	4A - High Enhance	REJECTED - SEE WORK DETAILS	Repair
11885826	3C - Low Sustain	3C - 3001 - WT - LOCK - 2 KEYS 712 A 1-64 & 6 KEYS 712 A 11 - [redacted] - 734-0408	Repair
11885850	3C - Low Sustain	3C - 3001 POST 2M48 TO 2MN48 - WT - ALARM - OUTAGE SUPPORT # 22-398 - [redacted] - 734-5806	Repair
11885854	3C - Low Sustain	3C - 3001 POST 2M48 TO 2MN48 - WT - SPRINK - OUTAGE SUPPORT # 22-398 - [redacted] - 734-5806	Repair
11885861	3C - Low Sustain	3C - 3001 POST AA-106C TO AA116 TO AJ106C TO AJ116 - WT - ALARM - OUTAGE SUPPORT # 22-400 - [redacted] 734-5806	Repair
11885873	3C - Low Sustain	3C - 3001 POST AA-106C TO AA116 TO AJ106C TO AJ116 - WT - SPRINK - OUTAGE SUPPORT # 22-400 - [redacted] 734-5806	Repair
11885969	3B - Medium Sustain	3B - 3001 POST Y46 - WT - HVACC - 2 UNITS OF S SIDE OF OFFICE ARE EMITTING AN ODOR AND NEED TO BE WASHED OUT - [redacted] - 734-0408	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11886151	3B - Medium Sustain	3B - 3001 SW CORNER ANNEX G EXT - WT - SHEET - REPAIR/REPLACE DAMAGED VENT COVER - [redacted] - 492-2496	Repair
11886515	3B - Medium Sustain	3B - 3001 POST 1AB-76A - WT - PEST - TERMITE DAMAGE ON WALL TRIM ON S WALL - [redacted] - 739-8940	Services
11888026	3C - Low Sustain	3C - 3001 POST 2B83 - WT - STRUC - REPAIR/REPLACE CEILING TILE THAT HAS A WHITE NOISE SPEAKER IN IT THAT HAS WATER DAMAGE - [redacted] - 855-3012	Repair
11888029	3B - Medium Sustain	3B - 3001 Post 2T80 - WT - INT ELEC - ISWP - 25139-Install fire alarm indicator - [redacted] 739-4975 - CSAG-257 - FP#11970162	Repair
11888068	3B - Medium Sustain	3B - 3001 Post 2S76 - WT - ALARM - ISWP - 25140-Install fire alarm indicator - [redacted] 739-4975 - CSAG-258 -FP#1018944	Repair
11888767	3C - Low Sustain	3C - 3001 POST 1AB-76A - WT - STRUC - CORNER ROUND TRIM NEEDS REPLACED ON WALL TRIM - [redacted] - 739-8940	Repair
11889003	3C - Low Sustain	3C - 3001 1ST FLOOR WOMENS RR - WT - INT PLUMB - FAUCET FOR THE LEFT HAND SINK ISN'T WORKING - [redacted] - 736-4730	Repair
11889092	3C - Low Sustain	3C - 3001 G40 - WT - PIPE - CHILL WATER LEAK - [redacted] - 582-4496	Repair
11889115	3C - Low Sustain	3C - 3001 Y1 - WT - STRUC - DOOR ACTUATOR HAS COME DETACHED FROM DOOR - [redacted] - 734-0408	Repair
11889167	3C - Low Sustain	3C - 3001 1AH1-101A MENS RR - WT - INT PLUMB - SINK WATER IS COMING OUT HARD AND SPRAYING WIDE - [redacted] - 734-9028	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11889464	3C - Low Sustain	3C - 3001 1AB1-99A MENS RR - WT - INT PLUMB - SINK SENSOR NOT WORKING PROPERLY&URINAL CLOGGED/BOTH ARE BAGGED - [redacted] SHED - 734-9028	Repair
11889524	3B - Medium Sustain	3B - 3001 1AD-86A - WT - INT ELEC - EXIT TEST LIGHT INOP - [redacted] - 734-9028	Repair
11889556	3C - Low Sustain	3C - 3001 AHU #6 - WT - HVAC - AFTER HOURS - REPLACE VERY DIRTY FILTERS ON AHU #6 - [redacted] - 734-6856	Repair
11889576	3B - Medium Sustain	3B - 3001 1AD2-116A INSIDE VAULT - WT - INT ELEC - EXIT TEST LIGHT INOP ON FAR E WALL - [redacted] - 734-9028	Repair
11891449	3C - Low Sustain	3C - 3001 POST 663 - WT - INT PLUMB - 5TH FAUCET IS NOT WORKING - [redacted] - 736-5776	Repair
11891529	3C - Low Sustain	3C - 3001G - SERVER ROOM - WT - HVACC - REPLACE LOW PRESSURE SWITCH ON LIEBERT - [redacted] - 734-5856	Repair
11891713	3C - Low Sustain	3C - 3001 - WT - BAS - CHWV ACTUATOR NOT CLOSING OFF - [redacted] - 818-1590 MAT COMP 9/23/2022	Repair
11892172	3A - High Sustain	3A - 3001G ROOM 107 - WT - STRUC - DOOR NOT CLOSING ON ITS OWN - [redacted] - 4095733	Repair
11892217	3C - Low Sustain	3C - 3001 MAIN CAFE CANDY ROOM - WT - PEST - MICE PROBLEMS - [redacted] - 7343161	Services
11892228	3B - Medium Sustain	3B - 3001 POST Q40 - WT - PIPE - F/U WT #11735039 & 11778953 FIX LEAK FROM PIPE - [redacted] - 736-4118	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11892243	3C - Low Sustain	3C - 3001 - WT - HVACC - NEW W/T FOR HVAC - HVACC - FOR POSSIBLE BLOCKED PIPE - [redacted] - 734-2765	Repair
11892439	3B - Medium Sustain	3B - 3001 DOOR G17 (WEST) - WT - STRUC - REPAIR THE LOOSE DOOR ON THE CRASH BAR - [redacted] - 736-4730	Repair
11892577	3B - Medium Sustain	3B - 3001 DOOR G13 - WT - HVACC - THERMOSTATE IN AREA SHOW SET AT 68 DEGREES BUT ROOM TEMP IS 83 - [redacted] - 736-4730	Repair
11892763	3B - Medium Sustain	3B - 3001 2ND FL COL Q-74 - WT - HONEYWELL - CHECK COMMUNICATIONS NOT VISABLE ON EBI CNTR-P2Q74 - REPAIR - [redacted] 405-203-8933	Repair
11893365	3B - Medium Sustain	3B - 3001 POST X111 - WT - INT ELEC - ELECTRIC STRIKE PLATE MALFUNCTIONING - [redacted] - 736-5716	Repair
11893624	3B - Medium Sustain	3B - 3001 M105 - WT - INT ELEC - OUTLETS FOR SODA MACHINES HAVE NO POWER - [redacted] - 734-3106	Repair
11894021	3A - High Sustain	3A - 3001G DOOR G16 - WT - STRUC - EXTERIOR DOOR NOT CLOSING WITHOUT ASSISTANCE/THIS IS A SECURED AREA - [redacted] - 409-5733	Repair
11894062	3A - High Sustain	3A - 3001 POST 2AH196H - WT - INT PLUMB - LEAK IN MENS RESTROOM - [redacted] - 205-6973	Repair
11894103	3C - Low Sustain	3C - 3001G UPS ROOM - WT - INT PLUMB - remove an eyewash station and demo all water lines - [redacted] - 405 736 4730	Repair
11894145	3B - Medium Sustain	3B - 3001 1AB/99 - WT - INT PLUMB - HOT WATER TANK INOP - [redacted] - 734-9028 - AHU 8L	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11894168	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894169	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894170	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894171	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894172	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894173	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894174	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894175	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894176	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894177	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894178	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11894179	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894180	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894181	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894182	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894183	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894184	2A - Preventive Maintenance	B2035225195007 - TE - Ladders, Fixed - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 40	Maintenance
11894199	3C - Low Sustain	3C - 3001 POST W67 - WT - STRUC - REPAIR MOVABLE DIVIDER WALL - [redacted] - 734-1959	Repair
11894731	3C - Low Sustain	3C - 3001 5,6,7 upper and lower - WT - AFTER HVAC - Check for proper operations - [redacted] 405-819-8135	Repair
11898837	3C - Low Sustain	3C - 3001 POST 2V78 SE SIDE OF MEZZ - WT - HVACC - AREA TOO HOT - [redacted] - 736-5776	Repair
11899221	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899222	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11899223	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899224	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899225	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899227	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899228	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899230	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899232	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899233	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899235	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11899236	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899237	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899238	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899363	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899364	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899365	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899367	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899368	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899369	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11899370	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899371	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899373	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899375	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899376	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899377	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899378	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899477	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899481	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11899486	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899488	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899490	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899491	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899495	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899498	3C - Low Sustain	3C - 3001 POST 2W83 - WT - INT PLUMB - 1ST TOILET IS CLOGGED AND BAGGED - [redacted] - 736-5776	Repair
11899579	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899587	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899589	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11899590	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899940	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899942	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899944	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899946	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899949	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899951	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899954	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899957	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11899959	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899961	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899962	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899965	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899966	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899968	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899971	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899973	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899974	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11899975	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899977	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899979	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899981	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899982	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899983	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899985	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899986	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899987	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11899988	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899989	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899990	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899991	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899992	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899993	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899994	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899995	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899996	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11899998	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11899999	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900000	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900001	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900002	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900003	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900004	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900005	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900006	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11900007	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900008	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900011	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900012	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900013	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900015	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900017	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900019	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900020	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11900021	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900022	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900024	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900025	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900026	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900027	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900028	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900031	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900032	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11900033	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900034	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900035	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900036	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900038	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900039	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900040	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900041	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900043	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11900044	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900045	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900046	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900047	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900048	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900050	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900051	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900053	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900054	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11900056	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900059	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900062	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900064	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11900066	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11901048	3C - Low Sustain	3C - 3001 POST 1AH190B - WT - LOCK - NEED DUPLICATE KEY/KEY IS 211A56 - [redacted] - 734--6469	Repair
11901144	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11901145	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11901148	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11901149	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11901151	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11901153	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11901154	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11901246	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11901247	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11901249	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11901250	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11901252	2A - Preventive Maintenance	B20352251950 - Q - Door, emergency egress, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11901328	3C - Low Sustain	3C - 3001 WOMENS RR POST 1AF77A - WT - INT PLUMB - AUTOMATIC SINK SENSOR NOT WORKING - [redacted] - 739-8921	Repair
11901476	3C - Low Sustain	3C - 3001 WOMENS RR POST 1AH102D - WT - STRUC - REPAIR DOOR HINGE ON WOMENS RR DOOR - [redacted] - 739-8921	Repair
11901505	3C - Low Sustain	3C - 3001 WOMENS RR POST 2AB199A - WT - INT PLUMB - SINK AUTO SENSOR NOT WORKING - [redacted] - 739-8921	Repair
11901517	3C - Low Sustain	3C - 3001 MENS RR POST 2AB196H - WT - INT PLUMB - URINAL CLOGGED - [redacted] - 739-8921	Repair
11901539	3C - Low Sustain	3C - 3001 MENS RR POST 1AF71 - WT - INT PLUMB - URINAL CLOGGED - [redacted] - 739-8921	Repair
11901564	3B - Medium Sustain	3B - 3001 MENS RR POST 1AD86 - WT - INT PLUMB - HANDICAP TOILET CLOGGED - [redacted] - 739-8921	Repair
11901585	3C - Low Sustain	3C - 3001 WOMENS RR POST 1AB196H - WT - INT PLUMB - TOILET SEAT BROKEN - [redacted] - 739-8921	Repair
11901597	3C - Low Sustain	3C - 3001 MENS RR POST 1AF77A - WT - INT PLUMB - AUTO SENSOR ON SINK NOT WORKING - [redacted] - 739-8921	Repair
11901795	3B - Medium Sustain	3B - 3001 POST 1AF73A OFFICE DOOR- WT - STRUC - OFFICE DOOR NOT CLOSING CORRECTLY - [redacted] - 739-8921	Repair
11901952	3C - Low Sustain	3C - 3001 POST 2AF 72A WOMENS RR - WT - INT PLUMB - SINK AUTO FAUCET NOT WORKING - [redacted] - 739-8921	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11902120	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902121	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902123	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902125	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902127	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902128	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902473	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902476	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902478	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902480	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902484	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11902487	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902490	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902491	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902497	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902501	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902507	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902513	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902518	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902522	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902526	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902532	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11902535	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902542	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902544	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902546	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902547	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902548	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902551	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902553	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902635	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902638	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902641	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11902858	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902860	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902861	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902863	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902865	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902867	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902871	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902873	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902876	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902877	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902880	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11902882	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902884	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902886	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902889	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902891	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902892	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902893	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902895	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902896	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902898	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902899	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11902900	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902902	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902906	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902910	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902914	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902916	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902917	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902918	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902919	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902921	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902922	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11902923	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902924	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902925	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902927	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902929	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902933	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902937	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902939	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902942	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902948	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902950	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11902953	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902955	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902956	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902959	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902961	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902962	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902965	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902966	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902967	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902972	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11902976	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11902979	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11903095	3C - Low Sustain	3C - 3001 POST 1AH1-106C MENS RR - WT - INT PLUMB - 1ST STALL TOILET CLOGGED - [redacted] 734-9028	Repair
11903458	3B - Medium Sustain	3B - 3001 POST 2P83 - WT - HVACC - WATER LEAKING FROM HVAC UNIT - [redacted] - 7365776	Repair
11903568	3C - Low Sustain	3C - 3001 OVERHEAD DOOR 8 - WT - PEST - POISON IVY GROWING UP WALL - [redacted] - 7365776	Services
11903602	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11903603	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11903604	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11903605	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11903608	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11903611	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11903614	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11903616	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11903621	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11903625	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11903627	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11903629	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11903631	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11903634	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11903637	2A - Preventive Maintenance	C10251101950 - Q - Fire doors, swinging - TINKER AFB - 3001 - STRUCTURES - ANNUALWEEK 41	Maintenance
11904966	3C - Low Sustain	3B - 3001 POST 2A82 W MEZZ IN LARGE CONFERENCE ROOM - WT - INT ELEC - BALLAST INOP - [redacted] - 855-3012	Repair
11905083	3C - Low Sustain	3C - 3001 POST 2B85 W MEZZ - WT - HONEYWELL - LIGHTS INOP - [redacted] - 855-3012	Repair
11905154	3C - Low Sustain	3C - 3001 POST 2B85 W MEZZ - WT - HONEYWELL - LIGHTS INOP/RIGHT SIDE OF ROOM - [redacted] - 855-3012	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11905244	3C - Low Sustain	3C - 3001G EXT N SIDE - WT - INT ELEC - EXT LIGHTS ARE STAYING ON BECAUSE OF A BAD PHOTOCELL THAT IS HARDWIRED /REPAIR - [redacted] - 622-7855	Repair
11905580	3B - Medium Sustain	3B - 3001 POST 2AH77A - WT - HVACC - COMMAND SECTION ROOM TOO HOT/VENT IS MAKING LOUD HUMMING NOISE - [redacted] - 739-9118	Repair
11906316	3C - Low Sustain	3C - 3001 POST 1AH105 - WT - PEST - TREAT FOR MICE & COCKROACHES - [redacted]	Services
11906594	3B - Medium Sustain	3B - 3001 POST 2AD81A - WT - STRUC - REPAIR LOOSE HANDRAIL ON STAIRS - [redacted] - 739-9118	Repair
11907956	1-Emergency	1 - 3001 Post 2AE85A - WT - AFTER PLUMB - Men's restroom is flooding - [redacted] 409-2888	Repair
11909833	3B - Medium Sustain	3B - 3001 POST O67 - WT - SPRINK - REPLACE HANDLE ON FIRE VALVE - [redacted] - 622-7855	Repair
11910524	3C - Low Sustain	3C - 3001 FAN DECK 18 - WT - HVACC - REPAIR AND RESEAL DRAIN PAN ON FAN DECK C - [redacted] - 734-5856	Repair
11911456	3C - Low Sustain	REJECT - SEE WORK DETAILS	Repair
11911611	3C - Low Sustain	3C - 3001 POST 2AF71/2AF72 MENS&WOMENS RR - WT - INT PLUMB - BOTH RR'S HAVE FAUCETS THAT DON'T FUNCTION CORRECTLY - [redacted] - 370-1490	Repair
11911664	3C - Low Sustain	3C - 3001 - WT - POWER - MONTHLY TANK ASSESSMENT - CLEAR CORROSION AROUND LADDERS,PLATFORMS,HANDRAILS&STAIRS - [redacted] - 734-5806 - EG03001-W	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11912114	4A - High Enhance	3C - 3001 Post R43 - CBM - Reroute 120V/20A power circuit for fire alarm panel - [redacted] - 405 582 5996	Repair
11912154	4A - High Enhance	3C - 3001 near post K91 - CBM - Install a steam humidifier - [redacted] - 405 736 4315	Repair
11912367	3B - Medium Sustain	3B - 3001 MAIN CAFE OFFICE/CASHROOM - WT - LOCK - NEEDING SAFE COMBINATIONS CHANGED - [redacted] 7343161	Services
11913173	3C - Low Sustain	3C - 3001 ANNEX G RM 131 - WT - INSULATOR - FU#11508061 PIPE SWEATING - [redacted] - 734-7083	Repair
11913418	3C - Low Sustain	3C - 3001 POST X111 - WT - F/U 11893365 - STRUC - STRIKE PLATE MALFUNCTIONING - [redacted] - 736-5716	Repair
11914404	1-Emergency	1 - 3001 POST X55 - WT - PEST - CAT RUNNING AROUND IN BLDG - [redacted] - 519-5837	Services
11915144	3C - Low Sustain	3C - 3001 POST 2AH-11B - WT - INT PLUMB - RIGHT SINK SENSOR INOP - [redacted] - 7349028	Repair
11915814	3B - Medium Sustain	3B - 3001 POST X55 - WT - PEST - F/U 11914404 MONITOR LIVE TRAPS FOR CAT - [redacted] - 519-5837	Services
11916675	3C - Low Sustain	3C - 3001 POST I 63 - WT - PEST - COCKROACHES IN OFFICE - [redacted] - 7340098	Services
11916737	3B - Medium Sustain	3B - 3001 POST 1AJ-71 - WT - STRUC - HAND RAIL IS LOOSE IN STAIRWELL - [redacted] - 370-1490	Repair
11917172	3C - Low Sustain	3C - 3001 POST 2Y55 - WT - LOCK - REQUESTING 4 KEYS #H6170 - [redacted] - 736-9977	Services
11920018	3C - Low Sustain	3C - 3001 POST 2V78 SE SIDE OF MEZZ - WT - BAS - AREA TOO HOT - repair - [redacted] - 736-5776 - SR 3143486	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11920040	3B - Medium Sustain	3B - 3001 POST 2P83 - WT - BAS - WATER LEAKING FROM HVAC UNIT - REPAIR - [redacted] - 736-5776	Repair
11921457	3C - Low Sustain	3C - 3001 POST Y60 - WT - LOCK - REQUESTING 4 PADLOCKS BE PROCURED AND KEYED TO 701C64 - [redacted] - 736-9977	Repair
11922090	3C - Low Sustain	3C 3001 SCWP-2 - WT - HVACC - CLEAR CONDENSATE DRAIN ON SCWP-2 - [redacted] - 734-5856	Repair
11922201	3C - Low Sustain	3C - 3001 POST 2AH82A - WT - LOCK - NEED (6) KEYS MADE (722A61) - [redacted] - 739-9118	Repair
11922248	3C - Low Sustain	3C - 3001 G87 - WT - INSULATOR - INSULATE 6" CHILL WATER PIPE - [redacted] - 582-4496	Repair
11922302	3C - Low Sustain	3C - 3001 POST X46 - WT - PEST - ROACHES IN FACILITY - [redacted] - 734-3161	Services
11922463	3C - Low Sustain	3C - 3001 POST 2AH82A - WT - HONEYWELL - NEED LIGHT BULBS REPLACED IN OFFICE AREA - [redacted] - 739-9118	Repair
11923258	3C - Low Sustain	3C - 3001 POST 1AG77A SOUTH DOOR - WT - LOCK - CONVERT CYPHER LOCK TO TURN LATCH MECHANISM - [redacted] - 739-8940	Repair
11924407	4A - High Enhance	4A - 3001 DEPUTY COMM OFFICE - SVC CONT - updated texture and paint - [redacted] - 405 736 7978	Repair
11926131	3B - Medium Sustain	3B - 3001 Y78 SERVER ROOM AHU#7 - WT - HVACC - REPLACE SHEAVE ON AHU7 - [redacted] - 734-5856 - AHU#7	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11927124	3C - Low Sustain	3C - 3001 Post Y34 Men's RR - WT - INT PLUMB - Urinal bagged on east wall - [redacted] 405-734-0408	Repair
11929641	3C - Low Sustain	3C - 3001 MECH ROOM BREAKROOM 2ND FLOOR - WT - STRUC - REPLACE BAD CIELING TILES - [redacted] - 7342765	Repair
11929704	3C - Low Sustain	3C - 3001 POST 1AH190B - WT - LOCK - WANTS CYPHER LOCK INSTALLED/REVIEW DOOR TO SEE WHICH ONE WOULD BE BEST - [redacted] - 734-6469	Repair
11932287	3C - Low Sustain	3C - 3001 DOOR B - WT - OPS PLAN ISWP SIGN - REPLACE WEATHERED/FADING RIBBONS ABOVE DOOR B - [redacted] - 739-8921	Repair
11932954	3C - Low Sustain	3C - 3001 - WT - POWER - REFUELING GENERATOR - [redacted] - 734-5806 - EG03001-E	Repair
11932963	3C - Low Sustain	3C - 3001 - WT - POWER - REFUELING GENERATOR - [redacted] - 734-5806 - EG03001-W	Repair
11933391	3A - High Sustain	3A - 3001 POST Y90 - WT - INT PLUMB - URINAL OVERFLOWING ONTO THE FLOOR - [redacted] - 8245403	Repair
11934888	3A - High Sustain	3A - 3001 POST 2AF71A - WT - INT PLUMB - URINALS LEAKING FROM THE BACK - [redacted] - 4081339	Repair
11935003	4A - High Enhance	4A - 3001 Post 1AF75A - OPS PLAN (FAC PROJ) ISWP - Estimate to install wall and door - [redacted] - 405 739 8921 - FP#1019556 - MULTI SHOP	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11935042	3C - Low Sustain	3C - 3001 - WT - LOCK - HAVE BLANK CORE & KEY/WOULD LIKE THE DOOR KEYED TO MATCH KEY#906D8 & 5 KEYS MADE - [redacted] - 622-7839	Repair
11938432	3C - Low Sustain	3B - 3001 SW CORNER ANNEX G EXT - WT - SHEET - REPAIR/REPLACE DAMAGED VENT COVER - [redacted] - 492-2496	Repair
11938470	3C - Low Sustain	3C - 3001 POST 2A88 W MEZZ WOMENS RR - WT - INT PLUMB - 1 OF THE 2 SINKS ISN'T WORKING PROPERLY - [redacted] - 855-3012	Repair
11938685	3B - Medium Sustain	3B - 3001 POST POST R67, 2R67, 3R67 - WT - LOCK - CHANGE CYPHER LOCK CODE FOR ENTIRE CMXG COMMAND - [redacted] - 734-1959	Repair
11938741	3B - Medium Sustain	3B - 3001 Y104 MENS RR - WT - INT PLUMB - 2 URINALS ARE BAD - [redacted] - 549-4485	Repair
11941164	3C - Low Sustain	3C - 3001 POST X6.5 MENS RR - WT - INT PLUMB - TOILET CLOGGED - [redacted] - 549-4485	Repair
11941231	3C - Low Sustain	3C - 3001 POST X22 MENS RR - WT - INT PLUMB - 2 URINALS ARE BAGGED - [redacted] - 549-4485	Repair
11946429	3C - Low Sustain	REJECT - NEED MORE INFO AS TO WHAT THE ACTUAL ISSUE IS	Repair
11946442	3C - Low Sustain	3C - 3001 POST 083 - WT - INT PLUMB - SECOND SINK FROM DOOR ON OP AISLE IS CLOGGED - [redacted] - 736-5776	Repair
11946903	3B - Medium Sustain	3B - 3001 POST 2Y49 - WT - STRUC - NEEDING DOOR HANDLE REMOVE AND BLANK INSTALLED - [redacted] - 734-0408	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11947830	4A - High Enhance	4A - 3001 Post 2AC79A & 2AF75A - CBR - Install 5 glass whiteboards - [redacted] - 739-2061	Repair
11948144	3C - Low Sustain	3C - 3001 PLANT - WT - INSULATOR - INSULATE PCWP # 6 - RON PULLINS - 734-5856	Repair
11948179	3C - Low Sustain	3C - 3001 PLANT - WT - INSULATOR - INSULATE SCWP #4 - [redacted] - 734-5856	Repair
11948426	3A - High Sustain	3A - 3001 EXT N CROSSWALK - WT - PAVE - ASPHALT CAVED IN UNDER FORKLIFT WEIGHT - [redacted]	Repair
11949862	3C - Low Sustain	3C - 3001 POST 2AF-81 DOOR - WT - STRUC - DOOR KNOB STICKING - [redacted] - 739-2061	Repair
11949993	3C - Low Sustain	3C - 3001 POST 3S-69 MENS RR - WT - INT PLUMB - CLOGGED URINAL, BAGGED - [redacted] - 622-7855	Repair
11950203	3B - Medium Sustain	3B - 3001 POST P-61 - WT - HONEY - NO PRESSURE IN STEAM LINES TO WAX TANKS - [redacted] - 405-420-4404	Repair
11950684	3C - Low Sustain	3C - 3001 ANNEX G RM 136 - WT - HVACC - F&F/MOTOR LOCKED UP - [redacted] - 582-9513 - UH-GJ116	Repair
11950698	3C - Low Sustain	3C - 3001 Mech rm F74 roof - WT - SHEET METAL - ISWP - 25415- Fabricate safety railing around roof access - Repair - [redacted] 622-7846 CSAG-237	Repair
11951238	3C - Low Sustain	3C - 3001 FLT-P19W and P19E - WT - HVAC PM - Vacuum water from coil leak - [redacted] - 582-9513	Repair
11951615	3C - Low Sustain	3C - 3001 Door Y46 - WT - Cath - adjust/raise well site in sidewalk - [redacted] - 734-5053	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11951693	3C - Low Sustain	3C - 3001 Filters - WT - HVAC PM - Order 18X25X2 Filters - [redacted] - 582-9513	Repair
11951701	3C - Low Sustain	3C - 3001 Filters - WT - HVAC PM - Order 20X30X2 Filters - [redacted] - 582-9513	Repair
11953557	4A - High Enhance	4A - 3001 post P89 - WT - INT ELEC - Install 100amp electric bus switch - [redacted]n - 405 582 4878	Repair
11954020	3B - Medium Sustain	3B - 3001 ANNEX G SW CORNER EXT - WT - WELD - REPLACE/REPLACE DAMAGED VENT COVER - [redacted] - 492-2496	Repair
11954571	3C - Low Sustain	3C - 3001 - WT - HVAC PM - ORDER 20X20X4 FILTERS - [redacted] - 582-9513	Repair
11956418	3B - Medium Sustain	3B - 3001 ANNEX G N CROSSWALK - WT - PAVE - F/U 11948426 REPAIR CROSSWALK - [redacted] - 492-2496	Repair
11956927	3A - High Sustain	3A - 3001 POST 2AF72 WOMENS RR - WT - INT PLUMB - TOILET CLOGGED & VERY CLOSE TO OVERFLOWING - [redacted] - 370-1490	Repair
11957582	3C - Low Sustain	3C - 3001 ANNEX G - WT - LOCK - REQUESTING THREE 702 C3 KEYS - [redacted] - 736-4731	Repair
11958653	3B - Medium Sustain	3B - 3001G - WT - FCU-1&4 - WT - HVACC - FCU-1 SPACE TEMP IS 79 DEGREES/FCU-4 SPACE TEMPS IS 77 DEGREES - [redacted] - 582-5009	Repair
11958847	3B - Medium Sustain	3B - 3001 2AB1-107B - WT - INT PLUMB - TOILET COMING AWAY FROM WALL - [redacted] - 734-9028	Repair
11960926	3C - Low Sustain	3C - 3001 4,5 & 6 upper and lower - WT - AFTER HVAC - Clean drain lines and pans - Repair - [redacted] - 819-5534	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11961812	3B - Medium Sustain	3B - 3001 JOP LAB - WT - HONEYWELL - VERIFY SENSOR & LOCATION - REPAIR - [redacted] 3155465	Repair
11962210	3C - Low Sustain	REJECTED-NEED A POST LOCATION AS WELL AS PICTURES IF ALL POSSIBLE	Repair
11962546	3A - High Sustain	3A - 3001 POST 1AI-78A - WT - SPRINK - HEARING LEAKING IN CEILING, SUSPECTS ITS THE FIRE SUPPRESSION SYSTEM AGAIN - [redacted] - 736-8707	Repair
11962847	3B - Medium Sustain	3B - 3001 POST 2O33 - WT - STRUC - REPLACE DAMAGED CEILING TILES - [redacted] - 7368536	Repair
11962880	3B - Medium Sustain	C/O 3B - 3001 POST 1AI-78A - WT - INT PLUMB - HEARING LEAKING IN CEILING, SUSPECTS ITS THE FIRE SUPPRESSION SYSTEM AGAIN - [redacted] - 736-8707	Repair
11962941	3C - Low Sustain	3C - 3001 POST Y55 - WT - HVACC - TO CAPTURE PARTS FOR WT# 11418604 T0923 - [redacted] - 734-5856 - EF-LT-Y55	Repair
11964359	3C - Low Sustain	3C - 3001 ANNEX G SW CORNER OF BLDG - WT - SHEET - REPAIR/REPLACE DAMANGED VENT COVER - [redacted] - 736-4731	Repair
11964721	3B - Medium Sustain	3B - 3001 POST Y90 MENS RR - WT - INT PLUMB - MOP DRAIN IS CLOGGED - [redacted] - 736-5776	Repair
11965362	3C - Low Sustain	REJECT	Repair
11966388	3B - Medium Sustain	3B - 3001 POST 3S69 - WT - HVACC - VAV5 NOT INSULATED/LEAKING AT THE DUCT ONTO CEILING TILES - [redacted] - 622-7855	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11966479	3B - Medium Sustain	3B - 3001 POST T-72 - WT - INT ELEC - REPAIR LIGHTING FOR THE BREAKROOM - [redacted] - 622-7855	Repair
11969917	3B - Medium Sustain	3B - 3001 POST X23 - WT - INT PLUMB - WASH BASIN IS LEAKING ON FLOOR - [redacted] - 734-0408	Repair
11969927	3B - Medium Sustain	3B - 3001 POST X23 WOMENS RR - WT - INT PLUMB - HANDICAPPED STALL OUT OF ORDER/BAGGED - [redacted] - 734-0408	Repair
11970070	3B - Medium Sustain	3B - 3001 Post 2S76 - WT - INT ELEC - ISWP - 25140-Install fire alarm indicator - [redacted] 739-4975 - CSAG-258 - FP#1018944	Repair
11970162	3B - Medium Sustain	3B - 3001 Post 2T80 - WT - ALARM - ISWP - 25139-Install fire alarm indicator - [redacted] 739-4975 - CSAG-257 - FP#11970162	Repair
11971188	3C - Low Sustain	3C - 3001 CAFETERIA - WT - INT ELEC - HOOK UP GENERATOR TO SUPPORT FREEZERS FOR OUTAGE - [redacted] - 734-5043	Repair
11971580	3C - Low Sustain	3C - 3001 CAFETERIA - WT - POWER - TRANSPORT GENERATOR FOR FALL OUTAGE - [redacted] - 734-5043	Repair
11971897	3A - High Sustain	3A - 3001 POST 2K63 - WT - INT ELEC - METAL ID CHEMISTRY LAB HAS LOST POWER TO SEVERAL MACHINES - [redacted] - 739-4246	Repair
11972311	3C - Low Sustain	3C - 3001 POST T83 - WT - STRUC - DOOR STOPS NEED REPAIRED - [redacted] - 736-5776	Repair
11972368	3C - Low Sustain	REJECTED-DUPLICATE WT-SEE WT#11972311	Repair
11972691	3B - Medium Sustain	3B - 3001 POST 20-70 - WT - INT ELEC - EXIT LIGHT INOP - [redacted] - 622-7855	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11973343	3C - Low Sustain	3C - 3001 POST X22 MENS RR - WT - INT PLUMB - 2 SINKS ARE BAGGED/INOP - [redacted] [redacted] - 549-4485	Repair
11975053	3C - Low Sustain	3C - 3001 POST 2W83 - WT - STRUC - REPLACE 5 CEILING TILES - [redacted] - 736-5776	Repair
11975213	3C - Low Sustain	3C - 3001 ADMIN 3 UPPER - WT - HVACC - REPLACE UV LIGHTS IN 3 UPPER - [redacted] - 734-6589	Repair
11975369	3C - Low Sustain	3C - 3001 ADMIN - WT - HVACC - REPLACE UV LIGHTS ON 4 UPPER - [redacted] - 405-734-6589 PR 3011 12/8/22	Repair
11975382	3C - Low Sustain	3C - 3001 ADMIN - WT - HVACC - REPLACE UV LIGHTS ON 2 UPPER - [redacted] - 405-734-6589	Repair
11975389	3C - Low Sustain	3C- 3001 ADMIN - WT - HVACC - REPLACE UV LIGHTS ON 1 UPPER - [redacted] - 734-6589	Repair
11975399	3C - Low Sustain	3C - 3001 ADMIN - WT - HVACC - REPLACE UV LIGHTS ON 10 LOWER - [redacted] - 734-6589	Repair
11975427	3C - Low Sustain	3C - 3001 ADMIN - WT - HVACC - REPLACE UV LIGHTS ON 9 LOWER - [redacted] - 734-6589	Repair
11975440	3C - Low Sustain	3C- 3001 ADMIN - WT - HVACC - REPLACE UV LIGHTS ON 8 LOWER - [redacted] 734-6589	Repair
11975456	3C - Low Sustain	3C - 3001 ADMIN - WT - HVACC - REPLACE UV LIGHTS ON 7 LOWER - [redacted] - 734-6589	Repair
11975468	3C - Low Sustain	3C - 3001 ADMIN - WT - HVACC - REPLACE UV LIGHTS ON 6 LOWER - [redacted] - 734-6589	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11975485	3C - Low Sustain	3C - 3001 ADMIN - WT - HVACC - REPLACE UV LIGHTS ON 5 LOWER - [redacted] - 734-6589	Repair
11975505	3C - Low Sustain	3C - 3001 ADMIN - WT - HVACC - REPLACE UV LIGHTS ON 2 LOWER - [redacted] - 734-6589	Repair
11975519	3C - Low Sustain	3C - 3001 ADMIN - WT - HVACC - REPLACE UV LIGHTS ON 3 LOWER - [redacted] - 734-6589	Repair
11975527	3C - Low Sustain	3C - 3001 ADMIN - WT - HVACC - REPLACE UV LIGHTS ON 4 LOWER - [redacted] 734-6589	Repair
11975535	3C - Low Sustain	3C - 3001 ADMIN - WT - HVACC - REPLACE UV LIGHTS ON 16 LOWER - [redacted] - 734-6589	Repair
11975542	3C - Low Sustain	3C - 3001 ANNEX - WT - HVACC - REPLACE UV LIGHTS AT P220 - [redacted] - 734-6589	Repair
11975550	3C - Low Sustain	3C - 3001 ANNEX - WT - HVACC - REPLACE UV LIGHTS AT P225 - [redacted] - 734-6589	Repair
11975978	3C - Low Sustain	3C - 3001 POST 2N85 - WT - PEST - SPRAY FOR ROACHES - [redacted] - 736-5776	Services
11976032	3B - Medium Sustain	3B - 3001 POST 1AI-78A BACK DOOR - WT - INT ELEC - BACKUP BATTERY FOR EXIT SIGN IN SFSC COMMAND STAFF OFFICE DOESN'T WORK - [redacted] - 736-8707	Repair
11976857	3B - Medium Sustain	3B - 3001 POST 087 - WT - INT ELEC - EMERGENCY LIGHT ON POLE IS HANGING LIKE THE FIXTURE IS BROKEN - [redacted] - 736-5776	Repair
11977538	3C - Low Sustain	3C - POST 2AC-108B - WT - LOCK - NEED KEYS MADE - [redacted] - 734-9028	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11985832	3C - Low Sustain	3C - 3001 POST 2AH82A - WT - F/U 11695208 - HONEYWELL - LIGHTS FLICKERING ABOVE DESK - REP{AIR - [redacted] - 739-9118 - SR3161949	Repair
11987062	3C - Low Sustain	3C - 3001 PLANT - WT - HVACC - REBUILD SECONDARY CHILLED WATER PUMP # 2 - REPAIR - [redacted] 405-734-6589 PO A23-000342 12/23/22	Repair
11987782	3C - Low Sustain	3C - 3001 POST 2P-65 - WT - INT PLUMB - FAUCET IN BREAK ROOM/CONFERENCE ROOM WILL NOT FULLY TURN OFF - [redacted] - 622-7855	Repair
11988401	3C - Low Sustain	3C - 3001G - WT - LOCK - KEY COPIES NEEDED - [redacted] - 736-4731	Repair
11988446	3C - Low Sustain	3C - 3001 163 PLATING LAB - WT - HVACC - REPLACE 3 FILTERS IN CEILING - [redacted] - 405-739-4246	Repair
11989105	3C - Low Sustain	3C - 3001 2P-67 & 2S-76 - OPS PLAN SH METAL - ISWP - Install duct heater - [redacted] - 405 408 1339	Repair
11991543	3B - Medium Sustain	3B - 3001 Post J-71 - WT - Sprink - Want sprinklers - Repair - [redacted] - 736-5776 - SR3164705	Repair
11993896	3B - Medium Sustain	3B - 3001 POST X64 - WT - INT PLUMB - CLOGGED SINK IN BREAKROOM - [redacted] - 736-5776	Repair
11993959	3C - Low Sustain	3C - 3001 POST P-33 - WT - ALARM - CONNECT FIRE ALARM TO STACKER - [redacted] - 405-582-4820	Repair
11994442	3C - Low Sustain	3C- 3001 Plant AC-1 - INSULATE - Perform evaluation on air compressor for high pitched noise - [redacted] - 405 582 4820	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11994480	3C - Low Sustain	3C - 3001 1ST FLOOR - WT - LOCK - INSTALL 8 NEW CYPHER LOCKS/CYPHER LOCKS ARE AT THE DESK IN AFSC/FM - [redacted] - 622-7967	Repair
11994579	3B - Medium Sustain	3B - 3001 POST Y66 - WT - STRUC - REPAIR PERSONNEL DOOR & FIRE SAFETY DOOR - [redacted] - 734-0408	Repair
11996196	3C - Low Sustain	3C - 3001 - WT - LOCK - REQUESTING CYPHER LOCKS TO REPLACE KEY LOCKS ON 5 OFFICE DOORS AT THE LOCATIONS LISTED BELOW - [redacted] - 736-9118	Repair
12003235	3B - Medium Sustain	3B - 3001 POST X9 - WT - STRUC - NORTH PERSONNEL DOOR LATCH GUARD BROKEN - [redacted] - 405-734-0408	Repair
12003674	3B - Medium Sustain	3B - 3001 POST X7 MENS RR - WT - INT PLUMB - 2 SINKS OF THE S SIDE ARE INOP WITH BAGS - [redacted] - 734-0408	Repair
12004017	3C - Low Sustain	3C- 3001 Post 2M48 - WT - Sprink - Support Outage - Service - [redacted] - 734-4202 - SR 3169640	Services
12004043	3C - Low Sustain	3C - 3001 Post 2M53 - WT - Alarm - Outage Support - Service - [redacted] - 734-4202 - SR 3169662	Services
12006320	3C - Low Sustain	3C - 3001 G EXTERIOR - WT - HVACC - BRING CHILLER # 2 ONLINE FOR FALL OUTAGE - REPAIR - [redacted] - 405-734-6589	Repair
12007579	3B - Medium Sustain	3B - 3001 2ND FLR ABOVE CAFE - LOCK - [redacted] - 405-734-7812	Repair
12007625	3C - Low Sustain	3C - 3001 - WT - HONEYWELL - LED LIGHTS ARE INOP AT MULTIPLE LOCATIONS - [redacted] - 734-9028	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12008020	3B - Medium Sustain	3B - 3001 POST 2C105 - WT - STRUC - THE DOOR CLOSER IS FALLING OFF DOOR - [redacted] - 736-5776	Repair
12010094	3C - Low Sustain	3C - 3001G ROOM 107 - WT - LOCK - CHANGE COMBO ON 7 SAFES - [redacted] - 736-4730	Repair
12012318	3B - Medium Sustain	3B - 3001 POST M70 - WT - ALARM - LOW GAS LEVEL ALARM THAT CAN NOT BE SILENCED - [redacted] - 734-7964	Repair
12018131	3B - Medium Sustain	3B - 3001 AHU-A16N - WT - HONEYWELL - Supply fan is off in alarm - [redacted] 582-5009	Repair
12020088	3B - Medium Sustain	3B - 3001 POST 2AH1 90B - WT - HONEYWELL - TEMPS IN THE 80S - [redacted] - 203-3740	Repair
12020174	3B - Medium Sustain	3B - 3001 DOOR G47 - WT - ROOF - ROOF LEAKING ONTO ELECTRONICS - [redacted] - 410-7686	Repair
12020178	3C - Low Sustain	3C - 3001 POST 1AH184A - WT - INT ELEC - F/U 11839137 RECONNECT LIGHT AFTER CEILING GRID IS REINSTALLED - [redacted] - 734-2753	Repair
12020207	3B - Medium Sustain	3B - 3001 POST 1AH184A - WT - STRUC - F/U 11839137 REINSTALL CEILING GRID & TILES IN OFFICE - [redacted] - 734-2753	Repair
12020515	3B - Medium Sustain	3B - 3001 BETWEEN POST Y-109 & Y-110 - WT - HONEYWELL - LEAK RAINING ONTO ELECTRICAL EQUIPMENT - [redacted] - 417-8194	Repair
12022848	3B - Medium Sustain	3B - 3001 LEAN TO 1 - WT - HVACC - LOW AIR FLOW - [redacted] - 582-5009	Repair
12022961	3B - Medium Sustain	3B - 3001 POST Y-92 TFCU FIRE DOOR - WT - MACH MAINT - FIRE DOOR TRIPPED - [redacted] - 622-7855	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12023348	3B - Medium Sustain	3B - 3001 POST2AH19 - WT - ROOF - LEAK IN ROOF - [redacted] - 405-736-3537	Repair
12023356	4A - High Enhance	4A - 3001 Post O-59 - WT - METAL - FABRICATE HANGAR FOR SHOP SIGN - [redacted] - 405 736 2085	Repair
12023455	4A - High Enhance	4A - 3001 Post 2AH1 90B - WT - INT PLUMB - INSTALL BOTTLE FILLER - [redacted] - 405 736 3537	Repair
12023773	4A - High Enhance	4A - 3001 Post 2AB76A - WT - INT ELEC - INSTALL Electrical Power Pole - [redacted] - 405 736 3537	Repair
12023921	3B - Medium Sustain	3B - 3001 POST Y49 - WT - ALARM - ALARM NEEDS TO BE SILENCED - [redacted] - 734-0408	Repair
12023944	3C - Low Sustain	3B - 3001 POST 2AG63A - WT - SPRINK - MISSING ESCUTCHEON RING - [redacted] - 370-1490	Repair
12023954	3B - Medium Sustain	3B - 3001 posts X5 & 2X5 - WT - HVACC - Rooms are too warm - repair - [redacted] - 734-0408 - SR 3176555	Repair
12023969	3B - Medium Sustain	3B - 3001 Post Y-55 Men's R/R - WT - Intplumb - Bagged urinal overflows - [redacted] - 734-0408 - SR 3176566	Repair
12023988	3A - High Sustain	3A - 3001 POST N49 WOMEN'S RR - WT - INT PLUMB - TOILET OVERFLOWING, WATER OUT TO HALLWAY - [redacted] - 370-1490	Repair
12024341	3B - Medium Sustain	3B - 3001 2 keys - WT - Lock - Employee Office Key #725B43 needed- service - [redacted] - 739-9118 - SR3176775	Services
12026967	3C - Low Sustain	3C - 3001 POST N61 - WT - STRUC - REPLACE CEILING TILES - [redacted] - 405-734-5815	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12026985	3C - Low Sustain	3C - 3001 POST N61 - WT - BAS - REPLACE ACTUATOR PM - [redacted] - 405-734-5815	Repair
12027193	3A - High Sustain	3A - 3001 POST E-99 - WT - INT PLUMB - LEAKING BACKFLOW PREVENTER - [redacted] - 736-5776	Repair
12027288	3A - High Sustain	3A - 3001 POST L-81 - WT - INT PLUMB - CONTRACTOR HIT AN OLD PLUMBING LINE AND BLACK STUFF IS COMING OUT - [redacted] - 736-5776	Repair
12027529	3B - Medium Sustain	3B - 3001 Post 1AG1 104A (BETWEEN DOORS G and H) - WT - LOCK - CYPHER LOCK NOT WORKING PROPERLY - [redacted] - 405-736-3246	Repair
12027886	3C - Low Sustain	3C - 3001 POST E-99 - WT - INT PLUMB - THIS IS TO CHARGE LABOR FOR 12027193 - [redacted] - 736-5776	Repair
12028076	3C - Low Sustain	3C - 3001 1AD/86A - WT - STRUC - INSTALL 3 DOOR SWEEPS - [redacted] - 405-734-9028	Repair
12028186	3B - Medium Sustain	3B - 3001 POST A95 DRTC - WT - IN TPLUMB - ALL TOILETS CLOSSED IN BOTH M/W BATHROOMS - [redacted] - 405-736-5776	Repair
12028434	3B - Medium Sustain	3B - 3001 POST 1AB1 108B - WT - LOCK - TRICKY LOCK - [redacted] - 405-736-3246	Repair
12028510	3B - Medium Sustain	3B - 3001 1AC1 106C - WT - HONEYWELL - ADJUST OCCUPANCY HOURS - [redacted] - 405-736-3246	Repair
12028573	3C - Low Sustain	3C - 3001 1AJ/85A - WT - STRUC - INSTALL 6 DOOR SWEEPS - [redacted] - 405-734-9028	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12028793	3A - High Sustain	3A - 3001 POST N49 - WT - INT PLUMB - MULTIPLE TOILETS OVERFLOWING ONTO THE FLOOR - [redacted] - 736-2085	Repair
12029479	3A - High Sustain	C/O - 3A - 3001 POST 1AH72A - WT - SPRINK - [redacted] 405-417-2893	Repair
12030057	3B - Medium Sustain	3B - 3001POST 1AH72A - WT - STRUC - [redacted] - 405-417-2893	Repair
12030622	3B - Medium Sustain	3B - 3001 Post X111 cypher locked door - WT - Structure - Cypher door lock doesn't latch - [redacted] - 736-5716 - SR 3179101	Repair
12032738	3B - Medium Sustain	3B - 3001 P-77 - WT - Sub - Elevator is stuck on first floor - [redacted] - 405-659-6917	Repair
12032824	3C - Low Sustain	3C - 3001 - WT - HVACC - TO ADD PARTS FROM WT# 11853697 THAT WAS CLOSED IN ERROR - [redacted] - 492-2496	Repair
12033236	3C - Low Sustain	3C - 3001 POST W73 - WT - INT ELEC - REMOVE 2 CEILING TILE MOUNTED ELEC. RECEPTACLES - [redacted] - 405-739-8921	Repair
12033357	3C - Low Sustain	3C - 3001 - WT - INT PLUMB - REPLACE CHECK VALVE & REPAIR DRAIN TO BLACKFLOW DEVICE - [redacted] - 734-2753 - BRFP-PD100	Repair
12033513	3C - Low Sustain	3C - 3001 POST Y78 - WT - HVACC - TROUBLE SHOOT THE CASUE FOR FREON UNIT TO GO OFFLINE - [redacted] - 736-4731	Repair
12033551	3A - High Sustain	MOLD - 3A - 3001 POST 2B83 - WT - MOLD - INVESTIGATE MOLD ON CEILING TILES IN OFFICE - [redacted] - 200-4344	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12033570	3C - Low Sustain	3C - 3001 ADMIN AREA - WT - ALARM - ASSIST SPRINKLER OUTAGE POST 1AH72A - [redacted] - 734-5806	Repair
12034166	4A - High Enhance	4A - 3001 POST I67 - WT - ALARM ESTIMATE - INSTALL 2 ALARM PULL STATIONS - [redacted] - 622-7855	Repair
12034525	3C - Low Sustain	3C - 3001 POSTX103 - WT - INT ELEC - OUTLET PHASED WRONG FOR EQUIP. USAGE - [redacted] - 405-734-0408	Repair
12034677	1-Emergency	1 - 3001 ANNEX G SW CORNER EXT - WT - EXT PLUMB - GAS LEAK REPORTED BY FIRE DEPT - [redacted] - 734-7964	Repair
12034851	3B - Medium Sustain	3B - 3001 POST O95 - WT - HVACC - ISOLATION VALVE LEAKING - [redacted] - 734-9377	Repair
12035351	3C - Low Sustain	3C - 3001 2AH1/83A - WT - SHEET METAL - PIPE PLUG - [redacted] - 405-734-9028 - AHU 16U	Repair
12035448	3C - Low Sustain	3C - 3001 MULTI POSTS - ALARM ESTIMATE - Reposition Audio Visual Alarms - [redacted] - 405 736 4315	Repair
12035609	3B - Medium Sustain	3B - 3001 K-65-K67 - WT - HVACC - LIGHT COVER COMING OFF LIGHT - [redacted] - 405-736-7752	Repair
12037507	3C - Low Sustain	3C - 3001 POST 2B87 - WT - HONEYWELL - LED LIGHT IS OUT OVER DESK - [redacted] - 855-3012	Repair
12037951	3C - Low Sustain	3C - 3001 ANNEX G 1ST FLOOR MENS RR - WT - INT PLUMB - REPAIR INOP TOILET - [redacted] - 736-4731	Repair
12038136	3C - Low Sustain	3C - 3001 - WT - SPRINK - SUPPORT KITCHEN HOOD INSPECTIONS - [redacted] - 734-4202	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12038330	3C - Low Sustain	3B - 3001 POST 1AF-72A - WT - PEST - TREAT AREA FOR TERMITES - [redacted] - 736-8707	Services
12039453	3C - Low Sustain	3C - 3001 - WT - HVACC - KEEP EYE ON TEMPS - [redacted] - 405-734-9028 - AHU 7L	Repair
12039617	3C - Low Sustain	3C - 3001 - WT - WELD - NEED METAL SHOP TO WELD A SAFE DRAWER AFTER DRILLING OPEN BY THE LOCKSHOP ON WT#12007579 - [redacted] - 734-2350	Repair
12045583	3B - Medium Sustain	3B - 3001 POST 083 - WT - INT PLUMB - 5 TOILETS IN MENS RR CLOGGED - [redacted] - 405-736-5776	Repair
12045591	3B - Medium Sustain	3B - 3001 POST 093 - WT - INT PLUMB - TOILET CLOGGED - [redacted] - 405-736-5776	Repair
12045596	3B - Medium Sustain	3B - 3001 POST 0103 - WT - INT PLUMB - TOILET CLOGGED - [redacted] - 405-736-5776	Repair
12045607	3B - Medium Sustain	3B - 3001 POST 2M103 - WT - INT ELEC - LIGHT SWITCH HAS SHORT - [redacted] - 405-736-5776	Repair
12045615	3B - Medium Sustain	3B - 3001 M59 - WT - MACH MAINT - OVERHEAD DOOR INOP - [redacted] - 405-736-5776	Repair
12045731	4A - High Enhance	3C - 3001 COMMAND SECT HALLWAYS - WT - FAC PROJ - REMOVE/REPLACE WOOD BASEBOARD - [redacted] - 1 940 395 1927	Repair
12046312	3C - Low Sustain	3C - 3001 POST N61 PLATING SH - WT - BAS - POST N-61 AHU NEEDS ACTUATOR T5392 [redacted] 582-9513 PO A23-001005 ADD 2/28/23	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12046377	3C - Low Sustain	3C - 3001 POST N61 PLATING SH - WT - STRUC - POST N-61 REPLACE CEILING TILES - T5392 - [redacted] 582-9513 - FLT-PN6	Repair
12046599	3C - Low Sustain	3C - 3001 POST G73 - WT - ALARM - REPLACING SPRINKLER HEADS IN PLASMA AREA - [redacted] - 734-5806	Repair
12046731	3B - Medium Sustain	3B - 3001G - WT - ALARM - ALARM PANEL HAS AUDIBLE TROUBLE ALERT IN THE AM - [redacted] - 405-736-4730	Repair
12047388	3B - Medium Sustain	3B - 3001 J101 - WT - INT PLUMB - NEED LARGE DRAIN SNAKED OUT - [redacted] - 736-5776	Repair
12048313	3C - Low Sustain	3C - 3001 POST X64 - WT - PEST - NEED BREAKROOM SPRAYED FOR ROACHES - [redacted] - 736-5776	Services
12049250	3B - Medium Sustain	3B - 3001 POST 1AJ71 DOOR A - WT - STRUC - HAND RAIL NEEDS LONGER BOLTS - [redacted] - 405-370-1490	Repair
12050264	3B - Medium Sustain	3B - 3001 POST Y34 MEN RR - WT - INT PLUMB - URINAL RUNNING CONSTANTLY - [redacted] - 405-734-0408	Repair
12052333	3A - High Sustain	3A - 3001G ROOM 104 - WT - HVACC - LEAK COMING FROM CRAC UNITS - [redacted] - 492-2496	Repair
12053779	3A - High Sustain	3A - 3001 O/H DOOR 4 - WT - MACH MAINT - OVERHEAD DOOR OFF TRACKS - [redacted] - 414-5193	Repair
12053947	3A - High Sustain	3A - 3001 MAIN CAFETERIA - WT - INT PLUMB - FLOOR DRAIN IS BACKING UP - [redacted] - 734-3161	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12055256	3A - High Sustain	3A - 3001 Post I63 AH P-800 - WT - AFTER HVAC - FD responded with a natural gas smell - [redacted] 734-3368	Repair
12056533	3B - Medium Sustain	3B - 3001 POST A105 DOOR #8 - WT - MACH METAL - [redacted] - 405-736-5776	Repair
12056580	3C - Low Sustain	3C - 3001 POST P-73 - WT - INT ELEC - F/F PNL-P11066 HAS A MISSING PANEL SCREW - [redacted] - 734-5043	Repair
12056640	3A - High Sustain	3a - 3001 post 2v75 - WT - HVACC - training room is 59 deg. - [redacted] - 736-5776	Repair
12056794	3B - Medium Sustain	3B - 3001 POST Y60 MOC - WT - LOCK - CYPHER LOCK CODES - [redacted] - 736-2500	Repair
12056950	3B - Medium Sustain	3B - 3001 POST 2V75 - WT - HVACC - F/U TO 12056640 - [redacted] - 736-5776	Repair
12057061	3A - High Sustain	3A - 3001 POST I63 - WT - HVACC - UNIT P800/GAS LEAK ALARM WENT OFF BUT EVERYTHING WAS NORMAL - [redacted] - 734-7964	Repair
12057156	3B - Medium Sustain	3B - 3001 - WT - LOCK - NEED 2 KEYS MADE FOR SUPS. 341DP - [redacted] - 405-736-3246	Repair
12057387	4A - High Enhance	3C - 3001 Post 2V-83 - WT - INT ELEC - Install a light and light switch - [redacted] - 405 736 2018	Repair
12057441	3B - Medium Sustain	3B - 3001 POST O95 - WT - PIPE - ISOLATION VALVE LEAKING - [redacted] - 734-9377	Repair
12062865	4A - High Enhance	4A - 3001 POST I-50 - CBM - INSTALL ELECTRICAL POWER - [redacted] - 405 739 2584	Repair
12062914	3C - Low Sustain	3C - 3001 POST HA 49.4 - WT - INT ELEC - MAIN LIGHT SWITCH INOP - [redacted] - 736-2085	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12062981	3C - Low Sustain	3C - 3001 POST 1AH1/105A - WT - INT PLUMB - TOILET CLOGGED - [redacted] - 734-9028	Repair
12063006	3C - Low Sustain	3C - 3001 POST 1AB/106C - WT - INT PLUMB - TOILET IS CLOGGED - [redacted] - 734-9028	Repair
12063040	3C - Low Sustain	3C - 3001 POST 2AF/71 - WT - INT PLUMB - TOILET IS CLOGGED - [redacted] - 734-9028	Repair
12063085	3C - Low Sustain	3C - 3001 Post 2AG76A - WT - INTPLUMB - Sink inop in men's room - [redacted] 734-9028 - SR3191432	Repair
12063201	3C - Low Sustain	3C - 3001 Post 1AB1/109B - WT - STRUC - Ceiling molding has detached from wall and ceiling - [redacted] 734-9028 - SR3191528	Repair
12063287	3C - Low Sustain	3C - 3001 Post 1AC4/112A - WT - STRUC - replace ceiling tiles - [redacted] 734-9028 - SR3191606	Repair
12064119	3C - Low Sustain	3C - 3001 - WT - CATH - ANNUAL CATHODIC SURVEY - [redacted] - 405-734-4802	Repair
12064354	3C - Low Sustain	3C - 3001 - WT - SPRINK - ASSIST CONTRACTOR OUTAGE - [redacted] - 405-734-5806	Repair
12064496	3C - Low Sustain	3C - 3001 Post A113 - WT - Honeywell - Infrared heater vents let in water - repair - [redacted] - 855-3012	Repair
12065217	3C - Low Sustain	3C - 3001 Post 1AD85A - WT - INTPLUMB - handicap stall has clogged toilet - [redacted] 734-9028 - SR3193258	Repair
12065432	4A - High Enhance	4A - 3001 Post 2AG1-103C - CBR - EXTEND WALL BY 4 FEET - [redacted] - 405 734 9071	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12065467	3C - Low Sustain	3C - 3001 HORSESHOE - WT - HVACC - WINTERIZE CHILLERS IN HORSESHOE - [redacted] - 734-6589 - SR3193469	Repair
12067821	3A - High Sustain	3A - 3001 POST 12A88 - WT - SUB ELEVATOR - ELEVATOR INOP, SOMEONE HAD TO PRY THEIR WAY OUT - [redacted] - 200-4344	Repair
12069524	3C - Low Sustain	3C - 3001 LT56R - WT - BAS - TROUBLE SHOOT LT56R - REPAIR - [redacted] 405-818-1590 - SR 3195801	Repair
12069957	3B - Medium Sustain	3B - 3001 Post M-47 Inside Tank & Cooler - WT - Intplumb - Handicap toilet plugged up, pipes leak. - Repair - [redacted] - 736-2085 - SR 3196155	Repair
12072559	3B - Medium Sustain	3B - 3001 POST I67 - WT - SPRINK - REPLACE 12 SPRINKLER HEADS - [redacted] - 734-4202	Repair
12073484	3B - Medium Sustain	3B - 3001 X22 MENS BATHROOM - WT - INT PLUMB - [redacted] - 405-734-0408	Repair
12073511	3B - Medium Sustain	3B - 3001 X7 MEN RR - WT - INT PLUMB - 2/4 SINKS ON SOUTH SIDE & 1/4 URINALS BAGGED - [redacted] - 734-0408	Repair
12073542	3C - Low Sustain	3C - 3001 Y3 - WT - PEST - RATS NEST FOUND - [redacted] 734-0408	Services
12074383	3C - Low Sustain	3C - 3001POST 2P43 - WT - HVACC - OFFICE TO COLD - [redacted] - 405-855-3012	Repair
12075006	3C - Low Sustain	3C - 3001 POST 2Y55 - WT - HVACC - LOUD NOISE COMING FROM AC SYSTEM - [redacted] - 736-9977	Repair
12075647	3A - High Sustain	3A - 3001 88710H - WT - HVACC - LEAK FROM CEILING NEAR ELEC PANEL - [redacted] - 734-3161	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12075710	3A - High Sustain	3A - 3001 POST Y80 CSS OFFICE - WT - INT ELEC - DOOR TIMING OFF - [redacted] - 736-5131 - TW101922B	Repair
12075939	3C - Low Sustain	3C - 3001 2A88 - WT - SUB ELEVATOR - ELEVATOR DOORS WIL NOT STAY SHUT - [redacted] - 405-200-4344	Repair
12076173	3C - Low Sustain	3C - 3001 ANNEX G - WT - EXT PLUMB - GAS METER OUTSIDE MECH RM NEEDS ADJUSTED - [redacted] - 246-8579 - RS0003	Repair
12077641	3A - High Sustain	3A - 3001 NW Annex - WT - ROOF - Rain is leaking on Cardxe - [redacted] 622-2156 Temp WT RM102502	Repair
12077647	3B - Medium Sustain	3B - 3001 NW Annex - WT - INT ELEC - Follow up to RM102502/12077641 seal around conduit - [redacted] 622-2156	Repair
12078230	3C - Low Sustain	3B - 3001G FCU-4 - WT - BAS - TROUBLE SHOOT ACTUATOR REF WT 11872827 - REPAIR - [redacted]	Repair
12078440	3A - High Sustain	3A - 3001 ANNEX G DOOR 15 MEN'S RR - WT - INT PLUMB - FAUCET DRIPPING WATER ON FLOOR - [redacted] - 492-2496 - KS102001	Repair
12078575	3A - High Sustain	3A - 3001 88710H - WT - INT PLUMB - F/U 12075647 LEAK FROM CEILING NEAR ELEC PANEL - [redacted] - 734-3161	Repair
12078605	3C - Low Sustain	3C - 3001 POST Y104 MENS RR - WT - INT PLUMB - TOILET CONTINOUSLY RUNNING - [redacted] - 734-0408	Repair
12078631	3B - Medium Sustain	3B - 3001 POST 2Y55 THRU 2Y61 - WT - BAS - WHOLE FLR IS 80 DEG - [redacted] - 736-9977 - AK102405	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12078652	3B - Medium Sustain	3B - 3001 ANNEX G, 1ST FL - WT - ALARM - PANEL IN TROUBLE MODE PLEASE RESET - [redacted] - 405-496-4633	Repair
12079018	3C - Low Sustain	3C - 3001 POST 1AH-1-84A - WT - INT ELEC - LIGHTS OUT - [redacted] - 734-9868	Repair
12079056	3C - Low Sustain	3C - 3001 POST 1AH-1-84A - WT - ALARM - ENSURE ALARM WORKING PROPERLY - [redacted] - 734-9868	Repair
12079156	3C - Low Sustain	3C - 3001 COOLING TOWER - WT - PAVE - MOVE LIFT - [redacted] - 582-4265	Repair
12079293	3A - High Sustain	3A - 3001 POST 2Q81 - WT - INT PLUMB - BOTH MEN AND WOMEN BATHROOMS TOILETS OVERFLOWING - [redacted] - 734-0086	Repair
12079571	3B - Medium Sustain	3B - 3001 88710H - WT - INT PLUMB - F-U 12078575 TO FINISH REPAIRS - [redacted] - 734-3161	Repair
12080125	3B - Medium Sustain	3B - 3001 E PARKING LOT - WT - PAVE - 2" PIECE OF METAL, TRIP HAZARD - [redacted] - 736-7184 - AK102416	Repair
12080351	3B - Medium Sustain	3B - 3001 POST W55 MECH RM - WT - LOCK - NEED MECH RM UNLOCKED - [redacted] - 734-2885 - TW102005	Repair
12080508	3A - High Sustain	3A - 3001 POST Z77 - WT - HVACC - HOOD VENTS FLOODING - [redacted] - 405-736-8772	Repair
12080693	3A - High Sustain	3A - 3001 POST 2G77 - WT - ROOF - F/U 12080508 HOSE FROM CEILING IF FLOODING LAB - [redacted] - 405-736-8720	Repair
12080950	3B - Medium Sustain	3B - 3001 POST A1-11 BOILER RM - WT - INT ELEC - BREAKER BOX HAS MANY KNOCKOUTS EXPOSED - [redacted] - 246-8579 - KS102007	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12081020	3A - High Sustain	3A - 3001 ANNEX G BOILER RM - WT - INT PLUMB - DRAIN BEHIND BOILERS IS CLOGGED - [redacted] - 246-8579 - KS102008	Repair
12087688	3A - High Sustain	3A - 5947 RM 120 - WT - SMART PLUMB - TOILET CLOGGED, INOP - [redacted] - 734-4421 - TW102103	Repair
12087940	3A - High Sustain	3A - 3001 POST N 79 - WT - INT ELEC - SHAFT SHOP LIGHT OUT - [redacted] - 414-5193 - DK102107	Repair
12088165	3A - High Sustain	3A - 3001 POST Y 13 - WT - LOCK - KEY ASSEBLY LOOSE AND CAN'T SECURE DOOR - [redacted] - 410-7686 - DK102110	Repair
12088320	3C - Low Sustain	3C- 3001 POST X23 WOMENS RR - WT - INT PLUMB - 2 STALLS ARE BAGGED - [redacted] - 734-0408	Repair
12088326	3C - Low Sustain	3C - 3001 POST X23 WOMENS RR - WT - INT PLUMB - 2 SINKS ON THE N SIDE OF RR ARE INOP - [redacted] - 734-0408	Repair
12088587	3C - Low Sustain	3C - 3001 POST 2G81 - WT - STRUC - RECURRING LEAK IN CEILING - [redacted] - 855-3017	Repair
12088719	3B - Medium Sustain	3B - 3001 POST Y34 - WT - PAVE - SMALL SINKHOLE TRIP HAZARDS IN GRASS NEXT TO BLDG - [redacted] - 417-8194 - TW102101	Repair
12088744	3B - Medium Sustain	3B - 3001 POST N 79 - WT - HONEYWELL - SHAFT SHOP LIGHT OUT - [redacted] - 414-5193 - DK102108	Repair
12089041	3A - High Sustain	3A - 3001 POST B93 WOMENS RR - WT - INT PLUMB - FLOOR DRAIN BACKED UP - [redacted] - 405-314-2499	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12095640	3C - Low Sustain	3C - 3001 ROOFTOP - WT - HVACC - SEAL CRACKS ON ROOFTOP FOR FAN DECK-18 - [redacted] - 734-6589 PR 3008 12/6/22		Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Work Location	Responsible Organization	Planned Start(Respond Date)
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	04/18/2022 10:17:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	04/18/2022 10:17:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	04/18/2022 10:17:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	05/11/2022 08:29:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/12/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/13/2022 10:44:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	05/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/14/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 09:55:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 10:10:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 10:12:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 10:17:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	05/15/2022 10:18:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 13:46:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 13:48:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 13:51:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 13:54:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 13:58:59

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 14:01:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 14:03:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 14:05:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 14:06:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 14:08:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 14:10:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 14:12:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/15/2022 17:57:31
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/15/2022 18:03:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	05/15/2022 18:20:09
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/15/2022 18:21:37

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/15/2022 18:24:43
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	05/15/2022 18:29:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/15/2022 18:44:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 19:04:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/15/2022 19:43:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/15/2022 19:45:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/16/2022 07:04:59
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	05/16/2022 07:13:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PLANT OPS - INDUSTRIAL WASTEWATER TRMT - MAINT - BOS-BMC	05/16/2022 07:52:25

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/16/2022 07:53:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	05/16/2022 08:45:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/16/2022 09:12:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	05/16/2022 09:14:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/16/2022 09:20:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/16/2022 09:23:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/16/2022 11:43:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/17/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	05/17/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	05/17/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	05/17/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/16/2022 13:45:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/16/2022 14:20:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	05/17/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/17/2022 07:51:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PROTECTIVE COATING (PAINT) - BOS-BMC	05/17/2022 08:00:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	05/17/2022 08:23:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/17/2022 10:27:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/17/2022 10:39:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/17/2022 10:43:45

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/17/2022 12:14:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	05/17/2022 12:27:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/17/2022 15:10:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/17/2022 15:17:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/17/2022 15:29:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/17/2022 15:49:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/18/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	05/18/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/18/2022 07:56:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/18/2022 07:59:45

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/18/2022 08:04:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/18/2022 08:09:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/18/2022 08:31:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/18/2022 08:41:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/18/2022 09:30:59
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/18/2022 09:53:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/18/2022 09:42:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/18/2022 10:23:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/18/2022 11:07:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	05/18/2022 12:45:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	05/18/2022 12:52:54

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/18/2022 13:10:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	05/18/2022 13:46:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	05/18/2022 14:38:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/18/2022 15:34:58
\Locations\TINKER AFB SITE 1\3001 - 1211932		05/19/2022 08:01:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	05/19/2022 10:36:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	05/19/2022 11:31:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	05/19/2022 11:44:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/19/2022 12:06:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	05/19/2022 12:28:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/19/2022 14:02:35

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/19/2022 14:26:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/19/2022 15:01:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - AFTER HRS - BOS-BMC	05/19/2022 19:39:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/20/2022 07:21:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/20/2022 09:41:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	05/20/2022 10:17:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	05/20/2022 12:24:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/20/2022 15:25:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	05/20/2022 15:54:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/21/2022 12:34:40

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/21/2022 12:36:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/21/2022 12:38:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/21/2022 12:41:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/21/2022 12:43:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/21/2022 12:45:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/21/2022 12:46:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/21/2022 12:49:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/21/2022 12:51:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/21/2022 12:52:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/22/2022 11:11:45

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/22/2022 11:16:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PLANT OPS - INDUSTRIAL WASTEWATER TRMT - MAINT - BOS-BMC	05/23/2022 08:23:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PLANT OPS - INDUSTRIAL WASTEWATER TRMT - MAINT - BOS-BMC	05/23/2022 08:40:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	05/23/2022 09:57:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/23/2022 10:04:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	05/23/2022 10:07:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - WELDING - BOS-BMC	05/23/2022 10:06:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/23/2022 14:23:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	05/23/2022 16:56:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/23/2022 20:42:49

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	05/24/2022 08:02:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/24/2022 07:53:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/24/2022 08:09:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/24/2022 08:06:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	05/24/2022 08:18:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/24/2022 08:34:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/23/2022 09:26:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	05/24/2022 09:54:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/24/2022 10:55:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/24/2022 12:42:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/24/2022 12:52:42

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	05/24/2022 13:06:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	05/24/2022 13:10:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	05/24/2022 13:17:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/24/2022 15:30:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	05/24/2022 16:07:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	05/25/2022 00:14:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	05/25/2022 00:25:31
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/25/2022 06:51:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/25/2022 07:39:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	05/25/2022 07:53:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/25/2022 08:14:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/25/2022 08:34:12

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	05/25/2022 09:36:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 09:41:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	05/25/2022 09:50:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/25/2022 09:54:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 13:54:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/25/2022 15:23:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 16:23:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	05/25/2022 17:10:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SMART ELECTRIC - BOS-BMC	05/25/2022 17:21:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SMART ELECTRIC - BOS-BMC	05/25/2022 17:23:20

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/25/2022 17:24:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	05/25/2022 17:26:31
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/25/2022 17:27:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 17:28:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/25/2022 17:31:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 18:07:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/25/2022 18:41:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/25/2022 18:46:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/25/2022 18:47:19

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/25/2022 18:48:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/25/2022 18:50:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/25/2022 18:53:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/25/2022 18:55:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PLANT OPS - INDUSTRIAL WASTEWATER TRMT - MAINT - BOS-BMC	05/25/2022 19:48:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/25/2022 20:01:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/25/2022 20:03:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/25/2022 20:15:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 20:17:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 20:18:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/25/2022 20:35:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/25/2022 20:35:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 20:37:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 20:39:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 20:41:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 20:43:15
\Locations\TINKER AFB SITE 1\63001 - 1213396	TINKER AFB - ELECTRICAL SYSTEMS - EXTERIOR - BOS-BMC	05/25/2022 20:45:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 20:53:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 20:58:30

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/25/2022 21:12:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/25/2022 21:13:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/25/2022 21:15:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/25/2022 21:22:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	05/26/2022 00:29:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/26/2022 00:39:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/26/2022 00:54:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 01:59:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/26/2022 02:14:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 02:18:51

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 02:22:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 02:34:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 02:42:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 02:53:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	05/26/2022 04:03:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/26/2022 05:20:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/26/2022 05:26:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 05:40:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 05:55:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 06:13:05

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 06:15:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/26/2022 06:17:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 06:52:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	05/26/2022 07:08:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/26/2022 07:49:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 07:50:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/26/2022 07:53:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 07:59:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/26/2022 07:54:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:28:26

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:28:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:31:43
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:31:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:34:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:34:27
\Locations\TINKER AFB SITE 1\1060 - 1213001	TINKER AFB - WATER AND FUELS SYSTEM MX - FUELS - BOS-BMC	05/26/2022 08:37:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:36:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:36:43
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:38:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:38:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/26/2022 09:09:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/26/2022 09:09:40

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	05/26/2022 09:20:31
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	05/26/2022 11:02:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 12:06:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/26/2022 12:06:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	05/26/2022 12:34:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	05/26/2022 14:24:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/26/2022 15:12:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/26/2022 15:40:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/26/2022 15:42:50

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/26/2022 15:45:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/26/2022 16:32:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PROTECTIVE COATING (PAINT) - BOS-BMC	05/26/2022 16:42:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/26/2022 16:43:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/26/2022 16:52:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/26/2022 17:13:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	05/26/2022 17:34:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	05/26/2022 17:36:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	Air Force Materiel Command	05/26/2022 17:47:03

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/26/2022 17:47:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 17:53:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/26/2022 17:58:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 18:52:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/26/2022 18:59:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	05/26/2022 19:09:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	05/26/2022 19:11:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 19:15:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/26/2022 19:22:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	05/26/2022 19:44:17

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 19:45:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	05/26/2022 20:01:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/26/2022 20:04:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	05/26/2022 20:08:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 20:09:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	05/27/2022 04:07:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/27/2022 04:08:43
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/27/2022 04:15:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	05/27/2022 04:24:41

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/27/2022 06:15:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - AIR COMPRESSORS - BOS-BMC	05/27/2022 06:21:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/27/2022 06:31:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/27/2022 06:33:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/27/2022 06:47:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/27/2022 07:29:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/27/2022 08:14:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/27/2022 08:44:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/27/2022 08:46:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - RCM-PDM - BOS-BMC	05/27/2022 08:49:11

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/27/2022 08:53:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/27/2022 08:57:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/27/2022 09:12:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	05/27/2022 10:26:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/27/2022 10:51:31
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	05/27/2022 11:27:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/27/2022 12:43:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/27/2022 12:47:09
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/27/2022 13:39:14

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	05/27/2022 15:06:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	05/31/2022 07:21:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/31/2022 07:25:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	05/31/2022 07:28:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/31/2022 07:52:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/31/2022 08:31:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	05/31/2022 09:05:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	05/31/2022 09:47:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PROTECTIVE COATING (PAINT) - BOS-BMC	05/31/2022 10:10:07

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	05/31/2022 11:33:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/31/2022 12:52:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/31/2022 13:14:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/31/2022 13:26:09
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/31/2022 14:33:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	05/31/2022 15:52:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/31/2022 15:57:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/31/2022 19:26:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/01/2022 02:13:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/01/2022 06:31:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/01/2022 07:28:15

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/01/2022 08:27:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/01/2022 08:46:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	06/01/2022 11:19:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	06/01/2022 12:29:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/01/2022 13:07:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	06/01/2022 13:58:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	06/01/2022 15:04:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	05/25/2022 17:10:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/02/2022 07:08:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/02/2022 07:16:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	06/02/2022 07:26:21

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/02/2022 09:50:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/02/2022 10:22:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/02/2022 11:06:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/02/2022 11:13:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/02/2022 11:15:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/02/2022 11:31:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/02/2022 12:31:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	06/02/2022 13:18:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/02/2022 13:45:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/02/2022 13:48:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/02/2022 14:51:45

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/02/2022 15:10:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	06/03/2022 07:19:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	06/03/2022 08:08:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	06/03/2022 09:14:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	06/03/2022 10:13:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	06/03/2022 12:23:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/03/2022 13:34:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/05/2022 17:14:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/06/2022 06:01:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	06/06/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	06/06/2022 07:23:35

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	06/06/2022 07:49:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	06/06/2022 08:31:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/06/2022 08:37:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	06/06/2022 08:41:03
\Locations\TINKER AFB SITE 1\1060 - 1213001	TINKER AFB - WATER AND FUELS SYSTEM MX - FUELS - BOS-BMC	06/06/2022 08:56:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PROTECTIVE COATING (PAINT) - BOS-BMC	06/06/2022 08:57:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/06/2022 09:34:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/06/2022 09:42:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	06/06/2022 10:26:15

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	06/06/2022 11:10:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/06/2022 11:14:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	06/06/2022 16:22:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/07/2022 08:39:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/07/2022 09:07:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/07/2022 09:37:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/07/2022 09:40:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/07/2022 09:41:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/07/2022 11:27:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/07/2022 12:13:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/07/2022 12:36:15

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/07/2022 12:43:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/07/2022 13:12:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/08/2022 07:22:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/08/2022 09:21:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/08/2022 09:28:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/08/2022 09:57:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/08/2022 10:47:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	06/08/2022 10:59:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	06/08/2022 10:33:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	06/08/2022 11:09:31
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	06/08/2022 11:26:55

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/08/2022 12:57:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/08/2022 14:01:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/09/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/09/2022 07:11:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/09/2022 07:13:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/09/2022 07:44:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/09/2022 10:27:48
\Locations\TINKER AFB SITE 1\43001 - 1212451	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	06/09/2022 11:48:19

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	06/09/2022 12:05:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	06/10/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/09/2022 14:25:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	06/09/2022 14:15:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	06/10/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/10/2022 08:10:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/11/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/11/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/10/2022 10:16:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/10/2022 10:25:09

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	06/11/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/19/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	06/10/2022 15:10:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	06/10/2022 15:16:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/11/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/25/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/25/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/12/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/11/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/25/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/24/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/11/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/11/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/11/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/12/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/25/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/25/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/25/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/22/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/18/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/15/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/19/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/01/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/05/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	06/13/2022 08:37:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/13/2022 09:43:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	06/13/2022 09:46:21
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/13/2022 09:57:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	06/13/2022 10:11:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	06/13/2022 11:44:11

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	06/13/2022 13:32:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	06/13/2022 14:43:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/14/2022 05:35:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/14/2022 07:01:34
\Locations\TINKER AFB SITE 1\43001 - 1212451	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	06/14/2022 09:23:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/14/2022 09:34:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	06/14/2022 10:16:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/14/2022 12:21:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/15/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	06/14/2022 13:34:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/15/2022 07:28:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/15/2022 07:51:49

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	06/15/2022 09:11:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/15/2022 09:05:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/15/2022 09:49:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/15/2022 09:27:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/15/2022 10:16:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/15/2022 10:17:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/15/2022 10:23:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/15/2022 10:28:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/15/2022 10:44:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/15/2022 10:58:46

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/16/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/11/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/25/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/15/2022 14:28:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/01/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/05/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/15/2022 14:49:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/15/2022 15:21:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - FUELS - BOS-BMC	06/15/2022 15:25:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/16/2022 07:03:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/16/2022 08:31:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	06/16/2022 08:40:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/16/2022 09:55:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/16/2022 11:11:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/16/2022 11:15:08

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/16/2022 11:16:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/16/2022 11:55:59
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/16/2022 13:41:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/16/2022 13:41:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/17/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/17/2022 07:00:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/17/2022 13:23:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/17/2022 15:21:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	06/17/2022 15:29:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	06/18/2022 04:30:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/21/2022 05:22:54

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	06/21/2022 06:59:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/21/2022 08:29:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/21/2022 08:29:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/21/2022 09:54:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/21/2022 10:24:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	06/21/2022 12:27:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	06/21/2022 12:27:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	06/21/2022 12:33:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	06/22/2022 06:16:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	06/22/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/22/2022 07:04:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	06/22/2022 07:25:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PROTECTIVE COATING (PAINT) - BOS-BMC	06/22/2022 07:28:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/22/2022 07:28:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	06/22/2022 07:29:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	06/22/2022 07:49:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	06/22/2022 07:56:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	06/22/2022 08:00:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/22/2022 08:04:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	06/22/2022 08:13:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	06/22/2022 08:41:52

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	06/22/2022 09:05:09
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	06/22/2022 09:10:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/22/2022 09:10:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	06/22/2022 09:27:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	06/22/2022 09:27:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/22/2022 10:32:09
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	06/22/2022 10:34:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - MOLD REMED - BOS-BMC	06/22/2022 13:09:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/22/2022 14:24:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/22/2022 14:24:14

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/22/2022 14:29:43
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	06/22/2022 14:34:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/22/2022 15:03:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/22/2022 15:06:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	06/23/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/23/2022 07:26:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/23/2022 07:43:31
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/23/2022 07:48:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	06/23/2022 08:08:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/23/2022 08:53:10

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	06/23/2022 10:50:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/23/2022 11:03:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	06/23/2022 12:24:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/23/2022 12:51:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/23/2022 12:57:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	06/23/2022 13:01:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	06/23/2022 13:56:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	06/23/2022 14:20:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	06/23/2022 14:29:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	06/23/2022 14:58:37

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	06/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	06/24/2022 07:54:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	06/24/2022 08:31:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/24/2022 08:56:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/24/2022 10:08:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/24/2022 10:11:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	06/24/2022 10:15:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	06/24/2022 10:23:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/24/2022 13:27:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/24/2022 13:58:56

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/24/2022 16:57:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/27/2022 07:27:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/27/2022 07:33:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - RCM-PDM - BOS-BMC	06/27/2022 08:53:21
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/27/2022 08:52:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/27/2022 09:03:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/27/2022 09:05:59
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	06/27/2022 09:26:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/27/2022 10:35:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	06/27/2022 11:01:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - WELDING - BOS-BMC	06/27/2022 11:07:52

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	06/27/2022 11:39:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/28/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/27/2022 12:56:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/27/2022 14:04:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/27/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	06/27/2022 15:56:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	06/28/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/28/2022 07:10:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/28/2022 08:59:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/28/2022 08:56:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/28/2022 09:38:11

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	06/28/2022 10:24:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/29/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/28/2022 12:14:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/28/2022 13:49:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/29/2022 07:39:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/29/2022 08:22:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/29/2022 09:14:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/29/2022 09:32:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	06/29/2022 09:56:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/29/2022 10:27:12

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/19/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	06/29/2022 14:14:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/29/2022 14:51:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	06/29/2022 14:54:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - WELDING - BOS-BMC	06/30/2022 07:04:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	06/30/2022 07:50:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/19/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	06/30/2022 08:32:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/30/2022 09:16:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/30/2022 09:36:58

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	06/30/2022 10:26:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	06/30/2022 11:07:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/30/2022 11:20:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	06/30/2022 11:23:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	07/01/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/01/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/01/2022 11:01:43
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/01/2022 11:20:15

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/01/2022 12:00:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/01/2022 12:07:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/01/2022 12:25:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	07/04/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	07/04/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	07/04/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	07/04/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	07/04/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	07/04/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	07/03/2022 14:30:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	07/03/2022 14:33:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	07/25/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/18/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/15/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/04/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/01/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/05/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/04/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - KITCHEN HOODS - BOS-BMC	08/01/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - KITCHEN HOODS - BOS-BMC	08/01/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/11/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/25/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/11/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/12/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	07/25/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/05/2022 10:27:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PROTECTIVE COATING (PAINT) - BOS-BMC	07/05/2022 10:28:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/06/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/05/2022 13:38:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/06/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/05/2022 13:57:57

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/05/2022 14:32:59
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/05/2022 14:41:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/06/2022 12:26:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	07/07/2022 07:49:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/07/2022 07:54:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	07/07/2022 07:53:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/07/2022 09:46:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/07/2022 10:05:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	07/07/2022 10:23:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/07/2022 12:17:42

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	07/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/08/2022 07:18:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/08/2022 08:07:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/08/2022 08:14:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/01/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/01/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/05/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/05/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/08/2022 08:45:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/08/2022 08:47:34

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/08/2022 08:48:21
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/08/2022 08:49:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	07/08/2022 09:09:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/08/2022 09:27:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	07/08/2022 09:23:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	07/08/2022 09:39:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/26/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/08/2022 11:37:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	07/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	07/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/09/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	07/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	07/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/08/2022 13:26:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/08/2022 13:38:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	07/08/2022 14:01:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/09/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/15/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/15/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/19/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/15/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/19/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/08/2022 15:32:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/08/2022 15:48:52

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	07/11/2022 07:18:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/11/2022 08:54:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	07/11/2022 09:03:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	07/11/2022 09:11:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/11/2022 09:41:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/11/2022 09:44:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PROTECTIVE COATING (PAINT) - BOS-BMC	07/11/2022 10:05:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - MOLD REMED - BOS-BMC	07/11/2022 11:23:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/11/2022 11:30:27

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/11/2022 11:46:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - WELDING - BOS-BMC	07/11/2022 12:03:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/12/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	07/12/2022 07:45:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	07/12/2022 08:47:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/12/2022 10:21:21
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/12/2022 11:31:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/13/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/13/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/12/2022 14:20:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/13/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/13/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	07/12/2022 15:25:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - FACILITY CONTROLS - OTHER - BOS-BMC	07/13/2022 10:12:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/13/2022 14:07:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/13/2022 14:33:51

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/14/2022 07:46:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/14/2022 07:49:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/14/2022 07:52:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/14/2022 07:58:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	07/14/2022 08:12:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/14/2022 08:58:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/14/2022 09:00:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/14/2022 09:40:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PROTECTIVE COATING (PAINT) - BOS-BMC	07/14/2022 09:51:16

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	07/14/2022 11:00:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	07/15/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/15/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/15/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	07/15/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/15/2022 07:05:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/15/2022 07:42:03

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/15/2022 07:51:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/15/2022 07:53:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	07/15/2022 09:29:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/15/2022 10:36:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/15/2022 10:41:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/16/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	07/16/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/16/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/22/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	07/18/2022 06:29:59
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/18/2022 07:54:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	07/18/2022 08:15:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/18/2022 08:53:32

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/18/2022 09:31:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	07/18/2022 09:58:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/18/2022 11:21:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/18/2022 11:37:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/18/2022 11:47:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/19/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/19/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	07/19/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	07/19/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	07/19/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/18/2022 14:24:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/19/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/19/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/19/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/19/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/17/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	07/19/2022 14:47:34

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	07/19/2022 14:44:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/19/2022 15:13:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	07/19/2022 15:14:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/19/2022 15:30:09
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS PLANNING	07/20/2022 06:53:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/20/2022 08:58:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/20/2022 09:01:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/20/2022 09:13:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/20/2022 09:13:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	07/20/2022 09:15:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/20/2022 09:28:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/12/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/20/2022 10:19:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	07/20/2022 11:25:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	07/20/2022 12:22:21
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/21/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	07/21/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	07/20/2022 14:21:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/20/2022 14:19:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/20/2022 14:38:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - AFTER HRS - BOS-BMC	07/20/2022 17:29:37

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/21/2022 07:50:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	07/21/2022 08:00:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/21/2022 09:05:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/21/2022 09:35:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/21/2022 09:47:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/21/2022 10:11:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/21/2022 11:06:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	07/21/2022 11:07:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	07/22/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	07/22/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/21/2022 14:08:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - AIR COMPRESSORS - BOS-BMC	07/22/2022 07:42:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/22/2022 08:05:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/22/2022 08:28:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/22/2022 08:40:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/22/2022 09:20:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/22/2022 11:43:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/22/2022 12:12:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/23/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	07/22/2022 13:29:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/23/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/24/2022 01:05:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	07/25/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/25/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/25/2022 07:09:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/25/2022 08:52:09
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/25/2022 09:30:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	07/25/2022 11:48:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/25/2022 11:49:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	07/25/2022 13:55:44

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	07/26/2022 09:13:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/26/2022 11:24:21
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	07/26/2022 13:08:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/26/2022 21:26:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/05/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/05/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/01/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/01/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/01/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/05/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/27/2022 07:24:09
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/27/2022 07:27:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/27/2022 07:35:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/27/2022 07:41:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/27/2022 07:52:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/27/2022 07:53:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/27/2022 08:02:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/27/2022 08:03:01

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	07/27/2022 08:53:59
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	07/27/2022 10:25:43
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/27/2022 10:10:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	07/27/2022 10:34:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - FACILITY CONTROLS - OTHER - BOS-BMC	07/27/2022 11:30:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	07/27/2022 14:42:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/27/2022 15:11:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	07/28/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/27/2022 17:02:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/28/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/28/2022 08:22:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/29/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - FACILITY CONTROLS - OTHER - BOS-BMC	07/28/2022 17:15:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/29/2022 07:02:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	07/29/2022 07:55:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	07/29/2022 08:10:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/29/2022 09:39:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/29/2022 09:39:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/29/2022 09:44:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/29/2022 09:44:10

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/29/2022 09:47:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/29/2022 09:47:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/29/2022 10:50:31
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/29/2022 12:35:59
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	07/29/2022 13:39:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/29/2022 15:05:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	07/29/2022 15:07:43
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/29/2022 23:30:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	07/31/2022 21:39:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	08/01/2022 06:57:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	08/01/2022 07:31:35

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	08/01/2022 07:34:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	08/01/2022 07:53:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	08/01/2022 07:59:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PROTECTIVE COATING (PAINT) - BOS-BMC	08/01/2022 12:30:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	08/01/2022 13:27:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/01/2022 13:49:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/01/2022 13:54:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/01/2022 14:05:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/01/2022 15:00:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/01/2022 15:14:17

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	08/01/2022 15:18:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	08/01/2022 16:30:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - AFTER HRS - BOS-BMC	08/02/2022 08:01:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/02/2022 10:10:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/02/2022 15:25:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	08/02/2022 15:28:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/02/2022 18:27:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/02/2022 18:41:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	08/03/2022 07:19:50

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/03/2022 08:41:43
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/03/2022 09:37:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/03/2022 11:45:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/03/2022 11:56:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/03/2022 12:08:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	08/03/2022 12:17:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/03/2022 14:01:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	08/03/2022 14:12:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	08/03/2022 15:24:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/02/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/06/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/05/2022 12:27:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - AFTER HRS - BOS-BMC	08/05/2022 12:29:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/05/2022 12:32:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/05/2022 13:43:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - FACILITY CONTROLS - OTHER - BOS-BMC	08/03/2022 15:30:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/05/2022 16:09:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/05/2022 16:32:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/05/2022 16:48:57

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/07/2022 14:49:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/08/2022 03:44:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	08/08/2022 04:19:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/08/2022 07:05:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/08/2022 07:50:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/08/2022 08:30:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/08/2022 08:49:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/08/2022 08:53:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/08/2022 09:57:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	08/08/2022 10:34:40

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	08/08/2022 10:52:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/08/2022 12:34:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	08/08/2022 12:40:31
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/08/2022 13:04:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	08/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	08/08/2022 13:23:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	08/08/2022 13:41:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/08/2022 13:51:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	08/08/2022 14:36:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/08/2022 14:33:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/08/2022 15:17:07

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/09/2022 07:10:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB EXT - BOS-BMC	08/09/2022 07:18:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/09/2022 07:51:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/09/2022 07:53:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/09/2022 08:50:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	08/09/2022 09:30:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/09/2022 10:40:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	08/10/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	08/09/2022 12:58:37

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - AFTER HRS - BOS-BMC	08/09/2022 16:48:09
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/10/2022 07:21:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	08/10/2022 09:11:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/10/2022 10:41:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	08/10/2022 10:41:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	08/10/2022 11:09:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/10/2022 14:05:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	08/10/2022 14:18:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	08/10/2022 14:28:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/11/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/10/2022 15:10:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/11/2022 07:10:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/11/2022 08:16:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/11/2022 09:31:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	08/11/2022 09:44:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/12/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/11/2022 14:33:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/11/2022 14:40:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/12/2022 09:02:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/12/2022 09:22:15

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/12/2022 09:37:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/12/2022 09:57:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/12/2022 11:06:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	08/12/2022 12:00:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/12/2022 14:15:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/12/2022 14:23:59
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/15/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	10/24/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	09/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	09/26/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	08/15/2022 07:59:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/15/2022 10:07:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/15/2022 10:13:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/15/2022 14:50:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	08/16/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/15/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/16/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	08/16/2022 08:10:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/16/2022 09:58:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/17/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/16/2022 12:40:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/15/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	08/17/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	08/17/2022 07:59:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/17/2022 08:05:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/17/2022 08:58:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/16/2022 09:28:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/17/2022 09:35:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	08/17/2022 10:11:09
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/17/2022 10:32:48

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - SUB - BOILER - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - SUB - BOILER - BOS-BMC	10/10/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	08/17/2022 13:07:09
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	08/17/2022 13:10:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/17/2022 13:13:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/17/2022 13:15:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	08/18/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	08/18/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	08/18/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/18/2022 07:09:51

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/18/2022 07:57:09
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	08/18/2022 07:52:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/18/2022 08:12:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/18/2022 08:38:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/18/2022 08:45:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/18/2022 09:07:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/18/2022 09:12:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/18/2022 09:15:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PLANT OPS - INDUSTRIAL WASTEWATER TRMT - MAINT - BOS-BMC	08/16/2022 09:43:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/19/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	08/18/2022 14:19:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/18/2022 14:42:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/19/2022 08:35:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	08/19/2022 09:50:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/19/2022 10:14:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/19/2022 11:08:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/19/2022 13:19:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/20/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	08/19/2022 16:14:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	08/19/2022 16:22:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/22/2022 07:56:01

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/22/2022 08:36:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/22/2022 08:41:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/22/2022 08:55:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/22/2022 10:36:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/23/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/22/2022 12:23:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/23/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/22/2022 15:05:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/23/2022 09:20:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/23/2022 09:31:50

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	08/23/2022 09:36:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/23/2022 09:44:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/23/2022 10:23:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	08/23/2022 11:19:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/22/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - FACILITY OPERATIONS - PAVEMENT CLEARANCE - BOS-BMC	08/23/2022 14:30:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - AFTER HRS - BOS-BMC	08/23/2022 16:14:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	08/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/24/2022 08:07:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	08/24/2022 09:10:32

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/24/2022 09:34:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	08/26/2022 09:56:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/24/2022 10:16:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	08/24/2022 10:33:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/24/2022 11:14:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/24/2022 13:32:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	08/24/2022 14:21:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	08/25/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	08/25/2022 07:31:27

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/25/2022 08:44:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	08/25/2022 09:37:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	08/25/2022 10:19:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/25/2022 10:21:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/25/2022 10:24:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/25/2022 11:57:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/25/2022 12:09:36
\Locations\TINKER AFB SITE 1\43001 - 1212451	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	08/25/2022 13:22:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/26/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	08/26/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/26/2022 08:23:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	08/26/2022 09:14:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/26/2022 09:27:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/26/2022 10:10:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	08/26/2022 11:05:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/27/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/27/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/29/2022 08:05:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/29/2022 08:36:26

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/29/2022 08:55:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/29/2022 09:02:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	08/29/2022 09:33:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	08/30/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/30/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/30/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/30/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	08/30/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/30/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	08/30/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/30/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/30/2022 07:26:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/30/2022 08:56:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/30/2022 09:20:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/30/2022 09:21:59
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	10/24/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/30/2022 10:37:54

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/30/2022 10:43:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/30/2022 12:12:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/30/2022 13:07:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	08/31/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/30/2022 14:37:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	10/17/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	10/17/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/31/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/31/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/31/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	08/31/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/31/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	08/31/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/31/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/31/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/31/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/31/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	08/31/2022 06:07:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	08/31/2022 08:13:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/31/2022 08:25:09
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/31/2022 08:27:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	08/31/2022 08:39:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/31/2022 08:51:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/31/2022 09:03:31

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/31/2022 09:29:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/31/2022 10:29:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - AFTER HRS - BOS-BMC	08/31/2022 10:50:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	08/31/2022 10:54:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/31/2022 12:05:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	09/01/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	09/01/2022 07:01:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	09/01/2022 08:22:43
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/02/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	09/02/2022 13:59:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	08/30/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	09/07/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PLANT OPS - INDUSTRIAL WASTEWATER TRMT - MAINT - BOS-BMC	09/06/2022 13:26:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	09/07/2022 11:05:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	09/07/2022 11:08:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	09/07/2022 11:22:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	09/07/2022 11:25:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/07/2022 11:54:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/08/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/07/2022 13:58:18

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	09/08/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/08/2022 07:48:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/08/2022 08:32:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/08/2022 09:43:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	09/08/2022 09:46:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	09/08/2022 09:48:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	09/08/2022 09:54:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/08/2022 09:59:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	09/08/2022 10:28:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/08/2022 10:37:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/08/2022 11:33:13

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	09/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	09/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/08/2022 13:54:21
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/08/2022 14:33:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	09/08/2022 14:41:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/08/2022 14:40:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	09/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	09/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\43001 - 1212451	TINKER AFB - ENGINEERING FLIGHT	09/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/08/2022 15:49:27

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	09/08/2022 17:13:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/09/2022 07:25:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS PLANNING	09/09/2022 07:27:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/09/2022 08:02:46
\Locations\TINKER AFB SITE 1\43001 - 1212451		09/09/2022 09:47:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/09/2022 10:37:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/09/2022 10:40:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	09/09/2022 10:44:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - WELDING - BOS-BMC	09/09/2022 10:50:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/08/2022 10:41:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/09/2022 10:57:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/09/2022 11:00:32

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/09/2022 11:35:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/10/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - FACILITY CONTROLS - OTHER - BOS-BMC	09/10/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/10/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	09/10/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	09/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	09/12/2022 07:34:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/12/2022 07:49:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/12/2022 07:54:53

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	09/12/2022 09:02:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	09/12/2022 11:38:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/12/2022 11:36:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/13/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	09/13/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/13/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/13/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/13/2022 07:18:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/13/2022 07:22:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENGINEERING FLIGHT	09/13/2022 07:32:46

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/06/2022 07:28:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/13/2022 07:38:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	09/13/2022 07:43:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	09/13/2022 07:46:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	09/13/2022 08:48:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/13/2022 11:09:59
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/13/2022 12:23:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/13/2022 12:45:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/13/2022 12:45:26

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	09/14/2022 08:17:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/14/2022 08:17:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/14/2022 10:49:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/14/2022 10:49:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/14/2022 11:21:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/14/2022 12:21:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/14/2022 13:38:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/14/2022 15:31:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/14/2022 15:42:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	09/15/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/15/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	09/15/2022 07:09:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/15/2022 07:25:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	09/15/2022 07:28:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	09/15/2022 07:28:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/15/2022 07:34:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	09/15/2022 07:35:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/15/2022 07:36:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	09/15/2022 07:38:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/15/2022 07:56:48

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	09/15/2022 08:12:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	09/15/2022 08:47:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/15/2022 11:24:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/15/2022 11:18:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/15/2022 11:28:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/16/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/16/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	09/16/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/16/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/16/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/16/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/16/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - AFTER HRS - BOS-BMC	09/16/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/16/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/16/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/16/2022 07:30:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	09/16/2022 08:23:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/16/2022 09:41:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	09/16/2022 09:55:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	09/16/2022 09:59:04

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/16/2022 10:01:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/16/2022 10:29:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/16/2022 10:48:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	09/16/2022 11:24:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/17/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/16/2022 13:45:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/16/2022 14:55:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/16/2022 15:09:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/17/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/17/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/17/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - AFTER HRS - BOS-BMC	09/16/2022 22:15:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/19/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/19/2022 07:53:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	09/19/2022 09:31:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/19/2022 09:47:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/19/2022 09:56:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/19/2022 09:58:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/19/2022 10:00:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/19/2022 10:00:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/19/2022 10:02:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/19/2022 10:03:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/19/2022 10:04:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/19/2022 10:13:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/19/2022 10:20:59

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	09/19/2022 11:33:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/19/2022 11:55:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	09/19/2022 11:59:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/20/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	09/20/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	09/20/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/20/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/20/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	09/20/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/20/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	09/19/2022 18:31:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	09/20/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/15/2022 07:54:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	09/20/2022 08:40:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/20/2022 08:45:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/20/2022 08:47:03

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	09/20/2022 09:15:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	09/20/2022 09:18:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	09/20/2022 09:31:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	09/20/2022 10:35:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/20/2022 10:56:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	09/20/2022 11:59:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/21/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	09/20/2022 13:14:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	09/21/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/20/2022 14:10:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	09/21/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	09/21/2022 07:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	09/21/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	09/21/2022 08:43:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/21/2022 09:43:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	09/21/2022 09:52:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	09/21/2022 09:55:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	09/21/2022 09:58:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	09/21/2022 10:15:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	09/21/2022 11:10:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT SERVICE CONTRACT MANAGEMENT	09/22/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/22/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/22/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/22/2022 07:21:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	09/22/2022 07:40:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS PLANNING	09/22/2022 11:51:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/23/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/23/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/22/2022 13:17:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/22/2022 15:07:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS PLANNING	09/23/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	09/23/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - WELDING - BOS-BMC	09/23/2022 08:09:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/23/2022 08:20:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	09/23/2022 08:39:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/23/2022 08:49:59
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/24/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/24/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	09/26/2022 07:54:31
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/26/2022 07:56:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/26/2022 08:45:30

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	09/26/2022 10:07:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	09/26/2022 10:28:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	09/26/2022 10:29:43
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	09/26/2022 10:40:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/27/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/27/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	09/26/2022 12:57:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/27/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	09/26/2022 13:52:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	09/27/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - CATHODICS - BOS-BMC	09/27/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	09/27/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	09/27/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/27/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - WELDING - BOS-BMC	09/27/2022 07:54:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	09/27/2022 08:58:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	09/27/2022 11:48:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/28/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	09/28/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/27/2022 14:57:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/28/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - AFTER HRS - BOS-BMC	09/27/2022 20:01:08

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	09/28/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	09/28/2022 07:10:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	09/28/2022 08:07:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/28/2022 08:44:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/28/2022 08:46:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/28/2022 08:52:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	09/28/2022 10:36:09
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/28/2022 11:12:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	09/28/2022 11:51:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/29/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/29/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/29/2022 08:10:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/29/2022 08:12:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/29/2022 08:30:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/29/2022 08:40:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/29/2022 10:17:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - POWER PRODUCTION SHOP - BOS-BMC	09/29/2022 10:51:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/29/2022 11:46:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/30/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	09/30/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/30/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/30/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	09/30/2022 07:59:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 08:23:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 09:03:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 09:07:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 09:09:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 09:11:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 09:16:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 09:19:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 09:21:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 09:23:53

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 09:25:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 09:27:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 09:29:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 09:31:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 09:33:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 09:35:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/30/2022 09:37:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	09/30/2022 11:06:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	09/30/2022 11:20:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	10/01/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	10/01/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	10/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/03/2022 09:30:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/03/2022 10:55:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	10/04/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/04/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS PLANNING	10/04/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	10/04/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/04/2022 09:45:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/04/2022 09:49:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	10/04/2022 10:26:32

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	10/04/2022 10:29:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/04/2022 10:41:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	10/05/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	10/06/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/06/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	10/06/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/06/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/06/2022 08:08:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	10/06/2022 10:31:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	10/06/2022 10:37:43

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/06/2022 11:19:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	10/07/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/07/2022 08:23:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	10/10/2022 12:08:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	10/11/2022 07:25:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	10/11/2022 07:42:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	10/11/2022 07:45:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/11/2022 07:52:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	10/11/2022 08:20:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/11/2022 12:34:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	10/12/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	10/12/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	10/12/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/12/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	10/12/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/12/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	10/12/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/12/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/12/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/11/2022 15:23:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	10/12/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/12/2022 07:57:07

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	10/12/2022 08:00:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/12/2022 08:40:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/12/2022 08:55:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	10/12/2022 09:35:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/12/2022 10:08:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	10/12/2022 10:27:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/12/2022 11:11:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	10/12/2022 11:39:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	10/12/2022 11:49:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/12/2022 11:55:54

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/12/2022 12:14:31
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	10/12/2022 12:45:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/12/2022 13:25:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/13/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	10/13/2022 06:26:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/13/2022 07:00:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	10/13/2022 08:08:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/13/2022 08:29:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/13/2022 08:58:59
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/13/2022 09:03:14

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/13/2022 09:10:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/13/2022 10:13:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	10/13/2022 11:00:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB EXT - BOS-BMC	10/13/2022 11:24:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/13/2022 11:49:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	10/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	10/14/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/14/2022 08:41:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	10/14/2022 09:10:43

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	10/14/2022 09:39:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/15/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - WELDING - BOS-BMC	10/15/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/17/2022 08:22:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/17/2022 08:24:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	10/17/2022 08:25:31
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	10/17/2022 08:27:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	10/17/2022 08:28:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	10/17/2022 08:40:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	10/17/2022 09:20:40

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/17/2022 09:23:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/17/2022 09:38:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/17/2022 09:41:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/17/2022 09:59:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	10/17/2022 10:56:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/18/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/18/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/18/2022 08:12:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	10/18/2022 11:21:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/18/2022 11:48:48

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - AFTER HRS - BOS-BMC	10/18/2022 17:01:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - MACHINE MAINT METAL - BOS-BMC	10/19/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	10/19/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/19/2022 07:12:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	10/19/2022 07:53:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/19/2022 08:19:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/19/2022 08:37:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	10/19/2022 08:54:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	10/19/2022 09:16:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	10/19/2022 09:21:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	10/26/2022 11:25:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	10/26/2022 11:30:06

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/26/2022 11:34:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/26/2022 11:37:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/26/2022 11:40:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/26/2022 11:43:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX - FACILITY PROJECTS - BOS-BMC	10/26/2022 11:50:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/26/2022 11:55:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - CATHODICS - BOS-BMC	10/27/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	10/27/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	10/27/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/27/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - OPERATIONS ENGINEERING & STAFF	10/27/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/26/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	10/26/2022 18:01:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	10/27/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/27/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	10/27/2022 08:17:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/27/2022 09:35:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/27/2022 09:37:16
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PEST MANAGEMENT - BOS-BMC	10/27/2022 09:41:21
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/27/2022 11:05:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/28/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/27/2022 13:37:36

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	10/27/2022 13:48:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - ELEVATOR - BOS-BMC	10/27/2022 14:22:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB EXT - BOS-BMC	10/27/2022 15:09:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	10/27/2022 21:29:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	10/27/2022 21:49:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	10/28/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/28/2022 07:40:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/28/2022 08:04:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/28/2022 08:17:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - CONTROLS - BOS-BMC	10/28/2022 08:19:46

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/28/2022 08:28:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	10/28/2022 09:18:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	10/28/2022 09:22:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	10/28/2022 09:38:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/28/2022 09:55:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/28/2022 10:42:21
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	10/29/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	10/28/2022 13:24:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/28/2022 13:58:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	10/28/2022 14:40:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	10/28/2022 15:36:04

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/28/2022 15:43:31
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SMART PLUMBING - BOS-BMC	10/31/2022 07:42:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	10/31/2022 08:48:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - LOCKS - BOS-BMC	10/31/2022 09:33:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/31/2022 10:25:21
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/31/2022 10:26:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/31/2022 11:31:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	10/31/2022 12:04:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	10/31/2022 12:15:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/31/2022 13:17:44

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/25/2022 07:53:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

Tracking Status	Status	SR ID	Requested By (FM)
	Rejected	2881304	[redacted]
	[redacted]	[redacted]	
	[redacted]		
	[redacted]	[redacted]	
	[redacted]	[redacted]	
	[redacted]	[redacted]	
	[redacted]	[redacted]	
	[redacted]	[redacted]	
	[redacted]	[redacted]	

[redacted] is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

[redacted]

Closed 2925934 [redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
Materiel Required	Completed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Hold for Parts	Active	
	Closed	
	Closed	
	Closed	
	Closed	
	Closed	
	Closed	2926812 [redacted]
[redacted]	[redacted]	8734
	Closed	2926949 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed	2926954	[redacted]
[redacted]	[redacted]	8734
Closed		
Closed		
Closed		
Closed	2927355	[redacted]
[redacted]		
[redacted]	[redacted]	8734
Completed	2928155	7815
Completed	2928301	7815

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed	2928352	8734
Closed		
Completed		
Completed	2928658	
Closed		
Closed		
Closed		
Closed		
Closed		
Closed		

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed



Closed



Closed

Closed

Materiel Required Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed [redacted]

Closed

Closed

Closed

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Rejected [redacted]

Closed

Closed

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
Materiel Complete	Completed
	Closed
Hold for Parts	Completed
	Closed
	Closed [redacted]
	Completed
	Closed
	Closed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Closed

Closed [redacted]

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed



Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Contract by Requestor	Active
	Closed
	Closed
	Closed
	Closed
	Closed
	Completed
	Closed
	Closed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Completed

Active

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Completed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Completed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	
	Closed	
Awaiting Scheduling	Completed	[redacted]
	Closed	
	Closed	
	Completed	
	Closed	
	Completed	
	Completed	
	Closed	
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Maintenance Complete	Completed	
	Closed	
	Closed	
	Closed	
	Closed	
Maintenance In Progress	Completed	[redacted]
	Closed	
	Closed	
	Closed	
	Closed	
	Completed	
	Completed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
Contract by Requestor	Active
	Closed
	Closed
	Active
	Closed
Materiel Complete	Completed
	Closed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Closed

Completed

Completed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
	Closed
	Closed
Maintenance In Progress	Completed
	Closed
	Closed
Awaiting Scheduling	Completed
	Closed
	Closed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
Materiel Required	Completed
	Closed
	Active
	Closed
	Closed
	Closed
	Closed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Closed

Closed

Closed

Closed

Closed

Completed

Closed

Closed

Active

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Completed

Completed

Closed

Completed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Maintenance In Progress	Completed
	Closed
	Closed
	Closed
	Closed
	Closed
	Completed
	Closed
	Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
	Closed
	Completed
	Completed
	Completed
	Closed
Maintenance In Progress	Completed
	Closed
	Closed
	Closed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
	Closed
	Closed
	Closed
	Closed
	Completed
	Closed
	Rejected
	Closed
Maintenance In Progress	Completed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
	[redacted]
	Closed
Maintenance In Progress	Completed
	Completed
	Completed
	Closed
	Closed
	Closed
	Closed
	Closed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Completed
	Draft
	Closed
	Closed
	Closed
	Closed
Maintenance Complete	Completed
	Completed
	Closed
	Closed [redacted]
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Active

Completed

Closed

Completed [redacted]

Completed [redacted]

Completed

Closed

Draft

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Active

Completed

Closed

Closed

Closed

Completed

Closed

Completed

Completed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Completed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Completed	
	Completed	
	Closed	[redacted]
	Closed	[redacted]
	Closed	[redacted]
	Closed	
	Closed	
	Closed	
	Closed	
Awaiting Scheduling	Active	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
	Closed [redacted]
	Closed
Maintenance Complete	Completed
	Closed [redacted]
	Completed
	Closed
	Closed
Maintenance In Progress	Completed
	Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed [redacted]

Completed

Draft

Active

Closed

Closed

Completed

Completed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Completed

Completed

Closed

Closed

Completed

Completed

Closed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Closed

Closed

Completed

Completed

Closed

Closed

Completed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Closed

Completed

Completed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Completed

Closed

Closed

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Completed

Completed

Completed

Completed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Closed

Completed

Completed

Closed

Closed

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

[redacted]

Completed

Closed

Closed

Closed

[redacted]

Completed

Closed

Completed

[redacted]

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
	Completed
Maintenance Complete	Completed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Maintenance In Progress	Completed	[redacted]
	Closed	
	Closed	
	Closed	
	Closed	
	Completed	
	Completed	
	Closed	
	Completed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Closed

Closed

Closed

Completed

Closed

Closed

Completed [redacted]

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Completed
	Closed
	Closed
	Closed
	Completed [redacted]
	Closed
	Closed
Maintenance In Progress	Completed
	Closed
	Closed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
Maintenance In Progress	Completed
Maintenance In Progress	Completed
	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Completed

Closed [redacted]

Closed

Completed

Closed

Closed

Closed

Completed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
	Closed
	Closed
	Closed [redacted]
	Closed
	Completed
	Closed
	Closed
Maintenance In Progress	Completed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed



Completed

Closed

Closed

Closed



Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	[redacted]
	Closed	[redacted]
	Closed	
	Completed	
	Closed	
	Closed	
Contract by Requestor	Active	
	Closed	
Contract by Requestor	Active	
	Completed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	[redacted]
	Completed	[redacted]
	Closed	
Materiel Complete	Completed	
	Closed	
	Closed	
	Closed	
	Closed	
	Closed	
	Closed	
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	
	Closed	
	Completed	[redacted]
	Active	
	Closed	
	Closed	[redacted]
Maintenance In Progress	Completed	[redacted]
	Completed	
	Completed	
	Closed	
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed [redacted]

Completed

Closed

Closed [redacted]

Closed

Closed [redacted]

Completed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed [redacted]

Completed

Closed

Closed

Closed [redacted]

Closed

Completed

Closed [redacted]

Closed 3[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
	Active
	Closed
	Closed
	Closed
Contract by Requestor	Active
	Completed
	Closed
	Completed
	Closed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Closed [redacted]

Active

Completed

Completed

Closed [redacted]

Closed [redacted]

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Completed

Completed

Completed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Completed

Closed

Closed

Completed

Completed

Closed

Closed

Closed

Completed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Completed

Closed

Closed

Completed

Completed

Closed

Closed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Closed

Closed

Completed

Completed

Completed

Completed

Closed

Completed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Closed

Closed

Closed

Closed

Completed

Completed

Completed

Active

Completed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Completed

Completed

Closed

Completed

Closed

[redacted]

Closed

[redacted]

Completed

[redacted]

Closed

Completed

[redacted]

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed [redacted]

Closed

Closed

Closed

Closed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Awaiting Scheduling	Completed	[redacted]
	Closed	
	Completed	
	Closed	
	Closed	
	Closed	
	Closed	
	Closed	
	Closed	
	Completed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Completed

Completed

Completed

Completed

Completed

Completed

Completed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Completed

Completed

Closed

Closed

Closed

Active

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Completed

Completed

Completed

Completed

Completed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Completed

Completed

Completed

Completed

Closed [redacted]

Closed

Closed

Closed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

Active

Closed

Closed [redacted]

Closed [redacted]

Closed [redacted]

Closed [redacted]

Closed [redacted]

Closed [redacted]

Closed [redacted]

[redacted] is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed [redacted]
	Closed [redacted]
	Closed
	Completed
	Active
	Rejected [redacted]
	Closed
	Closed
Environmental Assessment	Completed
	Closed [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Completed

Completed

Closed

Completed

Closed

Completed

Completed

Completed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
	Closed
	Closed
	Closed
	Closed
	[redacted]
Maintenance In Progress	Completed
	Completed
	Closed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	
	Closed	
	Closed	[redacted]
	Closed	[redacted]
	Closed	[redacted]
	Rejected	[redacted]
	Closed	
Awaiting Scheduling	Completed	
	Closed	3[redacted]
	Closed	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	
	Closed	[redacted]
	Closed	3[redacted]
	Closed	
	Active	
	Completed	
	Closed	[redacted]
Maintenance Complete	Completed	[redacted]
	Completed	
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
Hold for Parts	Completed
	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
	Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	[redacted]
	Closed	[redacted]
Materiel Required	Active	[redacted]
	Closed	[redacted]
	Closed	
	Closed	
	Closed	[redacted]
	Closed	[redacted]
	Closed	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

Closed [redacted]

Closed [redacted]

Closed

Closed

Completed

Closed [redacted]

Closed [redacted]

[redacted] [redacted]

[redacted]

[redacted]

[redacted] is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

[redacted]

[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

[redacted]

[redacted]

Closed

Closed

Active

Completed

Closed

[redacted]

Active

Closed

[redacted]

Closed

[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed [redacted]

Active

Active

Closed [redacted]

Closed

Completed

Completed

Active

Active

Active

Active

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Completed

Completed

Completed

Completed

Completed

Completed

Completed

Completed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Contract by Requestor	Active
	Closed
	Completed
	Closed
Awaiting Funds	Draft
	Completed
	Completed
	Completed
	Completed
	Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Completed
	Completed
	Completed
	Active
	Completed
	Completed
	Closed
	Completed
Maintenance In Progress	Active
Maintenance Complete	Completed
	Active

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Completed	
	Closed	[redacted]
	Closed	
	Closed	
	Closed	[redacted]
	Closed	[redacted]
Awaiting Scheduling	Completed	
	Closed	
	Completed	
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Awaiting Scheduling	Completed	[redacted]
	Closed	[redacted]
	Closed	
	Closed	[redacted]
	Closed	[redacted]
	Closed	[redacted]
[redacted]	[redacted] 4	
	Closed	3038781 86
	Closed	3039021
	Closed	3039373

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	
	Closed	3040308 [redacted]
	Closed	
	Closed	
	Closed	
Materiel Required	Completed	3040545 [redacted]
	Closed	
	Completed	
	Closed	3041009 [redacted]
	Closed	
	Closed	3041326 3 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed 3042001 [redacted]

Closed 3042129 [redacted]

Closed 3042151 [redacted]

Completed

Closed

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed 3045081 [redacted]

Completed

Active

Closed

Active

Active

Closed

Closed

Completed

Completed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Active
	Completed
	Closed
	Closed
	Active
	Closed
Materiel Required	Active
Maintenance Complete	Completed
	Closed
	Closed
Hold for Parts	Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Active

Completed

Closed

Completed

Closed

Completed

Closed

Closed 3049073 [redacted]

Closed

Closed 3049589 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3049851 [redacted]
	Closed	3051056 [redacted]
	Closed	
	Closed	
Awaiting Scheduling	Completed	3051877 [redacted]
	Closed	
	Closed	
	Closed	
	Closed	
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed 3052478 [redacted]

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
Maintenance In Progress	Completed
Materiel Complete	Completed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed		
	Closed		
	Closed		
	Closed		
	Closed		
	Closed		
	Completed		
Maintenance In Progress	Active		
	Closed	3057193	[redacted]
	Closed	3057223	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3057272 [redacted]
	Closed	
	Closed	
	Closed	
	Closed	
	Closed	
	Closed	
	Closed	
	Closed	
	Closed	
Maintenance In Progress	Completed	3058251 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3058299 [redacted]
	Closed	
	Closed	
	Closed	
	Closed	
	Closed	
Maintenance In Progress	Completed	
	Closed	
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	
	Closed	
	Closed	
	Closed	
Awaiting Scheduling	Completed	
	Closed	3061659 [redacted]
	Closed	3061810 [redacted]
	Closed	3061857 [redacted]
	Closed	3062401 [redacted]
	Closed	3062680 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	
	Closed	
Maintenance In Progress	Active	
	Closed	
	Closed	3063707 [redacted]
Maintenance Complete	Active	
	Completed	
	Completed	
	Closed	
	Completed	
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Materiel Complete	Completed	3064379 [redacted]
	Closed	
	Closed	3065519 [redacted]
	Closed	3065667 [redacted]
	Closed	3065672 [redacted]
Maintenance In Progress	Completed	
Contract by Requestor	Active	
	Closed	
	Closed	3067214 [redacted]
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	
	Closed	
Awaiting Scheduling	Completed	
	Closed	3069776 [redacted]
	Closed	
	Closed	
	Closed	
	Completed	
Maintenance In Progress	Active	
	Closed	3070828 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	
	Closed	
	Closed	3072091 [redacted]
Maintenance Complete	Completed	3072403 [redacted]
	Closed	
	Closed	3073255 [redacted]
Maintenance Complete	Completed	
	Closed	
	Closed	
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed		
Closed	3075032	[redacted]
Closed		
Closed	3075404	[redacted]
Closed		
Closed		
Closed	3076162	[redacted]
Completed		
Completed		
Completed		

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Completed

Completed

Completed

Completed

Completed

Completed

Completed

Completed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	
	Closed	3076911 [redacted]
	Closed	
	Completed	3077497 [redacted]
	Closed	
Awaiting Scheduling	Completed	3078722 [redacted]
	Closed	3078747 [redacted]
	Closed	3078750 [redacted]
[redacted]	[redacted]	139
	Closed	3080342 [redacted]
[redacted]	[redacted]	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	
	Closed	3081107 [redacted]
	Closed	3081265 [redacted]
	Rejected	3082668
	Closed	
	Completed	
	Closed	3083053 [redacted]
	Closed	3083075 [redacted]
Awaiting Scheduling	Completed	
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Completed		
	Closed		
Awaiting Scheduling	Completed		
Awaiting Scheduling	Completed		
	Closed		
Awaiting Scheduling	Completed		
Maintenance In Progress	Completed	3085109	[redacted]
	Closed	3085138	[redacted]
	Closed	3085160	[redacted]
	Closed		

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3085337 [redacted]
	Closed	
Awaiting Scheduling	Completed	
	Closed	3085457 [redacted]
	Completed	
	Closed	3085585 86 [redacted]
	Closed	3085604 [redacted]
	Closed	3085615 [redacted]
	Active	
	Closed	3086365 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed		
Closed		
Closed	3087959	[redacted]
Closed	3088199	[redacted]
Closed	3088274	[redacted]
Closed	3088457	[redacted]
Closed		
Closed	3089086	4 [redacted]
Completed		
Completed		
Closed	3090158	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Completed	
	Closed	3090362 [redacted]
	Completed	
	Closed	
	Closed	3091334 [redacted]
Maintenance In Progress	Completed	
	Closed	3091796 [redacted]
Maintenance Complete	Completed	
	Completed	3093614 [redacted]
Maintenance Complete	Completed	3093668 [redacted] 3

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Hold for Parts	Active	3093692	[redacted]
Maintenance In Progress	Active	3093730	612
	Closed		
	Rejected	3094135	[redacted]
	Closed	3094661	[redacted]
	Closed		
	Closed		
	Closed	3095859	[redacted]
	Closed	3096131	[redacted]
	Closed	3096370	3

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3096458	[redacted]
			[redacted]
	Closed	3096674	[redacted]
	Closed	3096762	92515
	Completed		
	Closed		
	Closed		
	Completed	3098479	[redacted]
Awaiting Scheduling	Completed	3098676	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3098927 [redacted]
[redacted]	[redacted]	
[redacted]	[redacted]	
[redacted]	[redacted]	
Materiel Required	Active	3099376 [redacted]
	Completed	
	Closed	
	Active	
	Closed	3100333 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3101099 [redacted]
	Closed	
	Closed	3101448 [redacted]
Maintenance In Progress	Completed	3101496 [redacted]
	Closed	
	Closed	
	Closed	3102311 [redacted]
Awaiting Scheduling	Completed	3102550 [redacted]
Maintenance In Progress	Completed	3103734 [redacted]
[redacted]	[redacted]	139

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.



This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3106346 [redacted]
	Closed	
Materiel Required	Active	3106843 [redacted]
	Closed	3106953 [redacted]
	Closed	3106956 [redacted]
	Completed	
	Completed	
	Completed	
Materiel Required	Active	3107318 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Materiel Required	Completed	3107344 [redacted]
	Closed	
	Completed	
	Closed	3108022 [redacted]
Maintenance In Progress	Completed	
	Completed	
	Completed	
	Completed	
	Completed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Completed	
	Completed	
	Closed	3108439
	Closed	3108667
Awaiting Scheduling	Completed	3108683

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Completed	3108684 [redacted]
	Completed	3108686 [redacted]
Materiel Required	Active	3108701 [redacted]
	Closed	
	Closed	3109493 [redacted]
	Closed	3109533 [redacted]
	Closed	3109540 [redacted]
	Closed	3109576 [redacted]
	Closed	3109624 [redacted]
Materiel Required	Completed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

Closed		
Closed		
Closed	3110105	[redacted]
[redacted]	[redacted]	
Closed		
Closed	3111207	[redacted]
[redacted]	[redacted]	[redacted] 30
Closed	3112092	[redacted]
[redacted]	[redacted]	

[redacted] is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

	Closed	
	Closed	[redacted]
[redacted]	[redacted]	[redacted]
Awaiting Scheduling	Active	
Awaiting Scheduling	Completed	3119209
	[redacted]	[redacted] 3
Awaiting Scheduling	Completed	3119278
	Closed	3119288
	Closed	3119405
[redacted]	[redacted]	[redacted]
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3120742
	[redacted]	[redacted]
	Closed	
Materiel Required	Completed	3121435
Awaiting Scheduling	Completed	
	Closed	
Awaiting Scheduling	Completed	3121477
Awaiting Scheduling	Completed	3121498
Maintenance In Progress	Active	3121599
	Closed	
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3122232 [redacted]
	Closed	3122239 [redacted]
	Closed	
Maintenance In Progress	Completed	
	Closed	
	Closed	
Materiel Required	Active	3122686 [redacted]
	Rejected	3122718 [redacted]
	Completed	3122764 [redacted]
	Completed	3122775 [redacted]
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed		
	Closed		
	Draft	3123394	[redacted]
	Closed	3123489	[redacted]
	Rejected	3123815	[redacted]
Awaiting Scheduling	Completed	3123985	[redacted]
	Closed	3123996	[redacted]
	Closed	3124013	[redacted]
	Closed	3124037	[redacted]
	Closed		
	Closed	3124058	[redacted]
Awaiting Scheduling	Completed	3124071	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Maintenance Complete	Completed	
Maintenance In Progress	Completed	3124329 [redacted]
	Closed	3124340 [redacted]
Awaiting Scheduling	Completed	3124561 [redacted]
	Rejected	3124605 [redacted]
	Closed	3124988 [redacted]
	Closed	3125663 [redacted]
[redacted] Progress	Active	3125735 [redacted]
Maintenance Complete	Completed	3125751 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3126028 [redacted]
	Completed	3126761 [redacted]
	Closed	
	Closed	3127330 [redacted]
Contract by Requestor	Active	3127462 [redacted]
	Closed	3128092 [redacted]
	Closed	3128216 [redacted]
	Closed	3128330 [redacted]
	Closed	3128345 [redacted]
	Completed	3128388 30

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Completed		
	Closed	3128420	[redacted]
	Closed	3128440	[redacted]
	Rejected	3128463	[redacted]
	Closed	3128729	[redacted]
	Closed	3129365	[redacted]
	Closed		
	Closed		
Maintenance Complete	Completed	3129834	[redacted]
	Completed		

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	
	Closed	
Maintenance Complete	Completed	3131962 [redacted]
	Closed	
	Closed	
	Closed	
Maintenance Complete	Completed	
	Closed	
	Closed	
	Closed	3133019 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

	Closed	3133594 [redacted]
	Closed	3133680 [redacted]
Maintenance In Progress	Completed	3133714 [redacted]
	Rejected	3133724 [redacted]
	[redacted]	[redacted]
	[redacted]	[redacted]
	[redacted]	[redacted]
	[redacted]	[redacted]
	[redacted]	[redacted]
	[redacted]	[redacted]

[redacted] is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

Closed 3133857 [redacted]

[redacted]

[redacted]

[

Awaiting Scheduling	Completed	3135183
[redacted]	[redacted]	[redacted]
	[redacted]	[redacted]
	[redacted]	[redacted]
	[redacted]	[redacted]
	[redacted]	[redacted]
	[redacted]	[redacted]
	[redacted]	
	[redacted]	
	[redacted]	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Maintenance In Progress Completed 3136432



This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Completed

Active

Completed

Completed

Completed

Active

Completed

Completed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Active

Completed

Active

Active

Closed 3137260 [redacted]

Closed

Closed 3137980 [redacted]

Completed

Active

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Active

Active

Active

Active

Active

Active

Active

Active

Active

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Active

Active

Closed

Active

Active

Closed

Active

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Active

Closed

Active

Closed

Active

Completed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Completed

Completed

Active

Closed 3138226 [redacted]

Completed

Active

Active

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Active

Completed

Completed

Completed

Completed

Completed

Completed

Completed

Completed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Active

Active

Completed

Completed

Active

Completed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Active

Active

Completed

Active

Active

Active

Active

Active

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Active

Active

Active

Completed

Active

Active

Active

Active

Active

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Completed

Completed

Active

Active

Completed

Active

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Active

Active

Active

Active

Active

Active

Active

Active

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Active

Completed

Active

Active

Completed

Completed

Active

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Completed

Completed

Active

Completed

Active

Active

Active

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Completed

Active

Active

Active

Active

Completed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Active

Active

Completed

Active

Completed

Closed 3138609 [redacted]

Completed

Completed

Active

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Active

Completed

Completed

Active

Completed

Completed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.



This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Active

Completed

Completed

Active

Active

Completed

Active

Active

Active

Active

Active

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Active

Active

Active

Active

Active

Completed

Active

Active

Active

Active

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Active

Completed

Active

Active

Active

Active

Active

Active

Active

Active

Active

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Completed

Completed

Completed

Completed

Completed

Completed

Completed

Completed

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Completed

Completed

Active

Completed

Completed

Active

Completed

Completed

Active

Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Active

Active

Active

Completed

Active

Active

Active

Active

Active

Active

Active

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Active

Active

Completed

Completed

Active

Completed

Active

Active

Active

Active

Active

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Active

Active

Completed

Completed

Completed

Active

Active

Completed

Completed

Active

Active

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Completed

Closed 3139152 [redacted]

[redacted]

[redacted]

Active

Active

Active

Active

Active

Active

Active

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Active	
	Active	
	Active	
	Completed	
	Active	
	Active	
	Active	
	Active	
	Active	
Materiel Required	Completed	3139629 [redacted]
[redacted]	[redacted]	[redacted]
[redacted]	[redacted]	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Awaiting Scheduling	Completed	3139746 [redacted]
[redacted]	[redacted]	[redacted]
	[redacted]	[redacted]
	Closed	
	Closed	3140976 [redacted]
[redacted]	[redacted]	[redacted]
	[redacted]	[redacted]
[redacted]	Completed	3141317 [redacted]
	Closed	3141323 2[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Contract by Requestor	Active	3141438
[redacted]	[redacted]	[redacted]
	[redacted]	
[redacted]	[redacted]	[redacted]
[redacted] Progress	Active	3141933
	[redacted]	
[redacted]	[redacted]	[redacted]
	Closed	
	Closed	3142630
	[redacted]	
	[redacted]	[redacted]
[redacted]	[redacted]	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]	Closed	3143502
[redacted]	[redacted]	[redacted]
[redacted]	[redacted]	[redacted]
[redacted]	Closed	3144187
[redacted]	[redacted]	[redacted]
[redacted]	[redacted]	
[redacted]	Completed	3144292
[redacted]	[redacted]	[redacted]
[redacted]	[redacted]	[redacted]
[redacted]	Closed	3145098

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3145383
Maintenance In Progress	Active	3146163
	Closed	3146204
	Draft	3147728

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3147738 [redacted]
	[redacted]	[redacted]
	[redacted]	[redacted]
	Closed	3148677 [redacted]
Awaiting Scheduling	Completed	3148710 [redacted]
	[redacted]	[redacted]
	[redacted]	[redacted]
	[redacted]	[redacted]
	Closed	3150804 [redacted]
	[redacted]	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3151288
	[redacted]	[redacted]
	[redacted]	[redacted]
	Closed	
Awaiting Scheduling	Active	3151769
Awaiting Scheduling	Completed	3151822
	Closed	
Maintenance In Progress	Completed	3152006
	Closed	
	Closed	3152026
	Closed	3152250

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Maintenance In Progress	Active	3152314
Materiel Required	Active	3152320
Awaiting Scheduling	Completed	3153103
	Closed	3153300
Materiel Required	Active	3153525
Maintenance Complete	Completed	3154194
	Closed	3154410
	Closed	3154550
Maintenance In Progress	Completed	
Awaiting Scheduling	Completed	3154874
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Awaiting Scheduling	Completed	3155465 [redacted]
	Rejected	3155604 [redacted]
	Closed	
	Closed	3155952 [redacted]
Maintenance In Progress	Completed	
Maintenance In Progress	Completed	3155990 [redacted]
Awaiting Scheduling	Active	3156321 [redacted]
	Closed	3156432 [redacted]
[redacted]		[redacted]
	Closed	3156827 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3156864 [redacted]
	Closed	3158171 [redacted]
	Closed	3158178 [redacted]
	Closed	
	Closed	
	Closed	3158593 [redacted]
	Closed	
	Closed	
Awaiting Scheduling	Completed	3159137 [redacted]
	Rejected	3159176 [redacted]
	Closed	3159318 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Materiel Required	Completed	3159522	[redacted]
Awaiting Scheduling	Completed	3160263	[redacted]
Maintenance In Progress	Active	3160329	[redacted]
Materiel Required	Active	3160413	[redacted]
Maintenance In Progress	Active	3160421	[redacted]
Maintenance In Progress	Active	3160423	[redacted]
Maintenance In Progress	Active	3160431	[redacted]
Maintenance In Progress	Active	3160443	[redacted]
Maintenance In Progress	Active	3160453	[redacted]
Maintenance In Progress	Active	3160459	[redacted]
Maintenance In Progress	Active	3160462	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Maintenance In Progress	Active	3160467
Maintenance In Progress	Active	3160474
Maintenance In Progress	Active	3160483
Maintenance In Progress	Active	3160491
Maintenance In Progress	Active	3160495
Maintenance In Progress	Active	3160502
Maintenance In Progress	Active	3160511
	Closed	3160771
Awaiting Scheduling	Completed	3160801
	Closed	3161032
Awaiting Scheduling	Completed	3161250

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Completed	3161949	[redacted]
Hold for Parts	Active	3162589	[redacted]
	Closed	3162983	[redacted]
	[redacted]		[redacted]
Maintenance In Progress	Completed	3163407	[redacted]
Awaiting Scheduling	Draft	3163830	69
	Closed	3164705	[redacted]
	Closed	3165405	[redacted]
	Closed	3165403	[redacted]
Materiel Required	Completed	3165574	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3165583
Awaiting Scheduling	Completed	3165649
	Closed	3166552
Awaiting Scheduling	Completed	3169247
Materiel Required	Completed	3169500
	Closed	3169640
	Closed	3169662
Maintenance In Progress	Completed	3170446
Awaiting Scheduling	Completed	3170937
Awaiting Scheduling	Active	3171015

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Awaiting Scheduling	Completed	3171223 [redacted]
	Closed	3172103 [redacted]
Maintenance In Progress	Completed	
	Closed	
Maintenance Complete	Completed	
	Closed	
Awaiting Scheduling	Completed	3174593 [redacted]
Maintenance In Progress	Active	3174616 [redacted]
Maintenance In Progress	Completed	
	Closed	
	Closed	3175984 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Maintenance In Progress	Active	3176207 [redacted]
Maintenance In Progress	Active	3176213 [redacted]
Maintenance In Progress	Active	3176282 [redacted]
Awaiting Scheduling	Completed	3176459 [redacted]
	Closed	3176535 [redacted]
Awaiting Scheduling	Completed	3176550 [redacted]
	Closed	3176555 [redacted]
	Closed	3176566 [redacted]
	Closed	
	Closed	3176775 [redacted]
Awaiting Scheduling	Active	3177570 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Awaiting Scheduling	Completed	3177581 [redacted]
	Closed	
	Closed	
	Closed	3177925 [redacted]
	Closed	
Awaiting Scheduling	Completed	3178182 [redacted]
	Closed	3178230 [redacted]
	Closed	3178340 [redacted]
Awaiting Scheduling	Completed	3178377 [redacted]
Awaiting Scheduling	Active	3178399 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	
Awaiting Scheduling	Completed	
Maintenance In Progress	Completed	
Maintenance Complete	Completed	3179101 [redacted]
	Completed	
Maintenance In Progress	Completed	3179989 [redacted]
Awaiting Scheduling	Completed	3180241 [redacted]
Maintenance Complete	Completed	3180343 [redacted]
Maintenance In Progress	Active	3180456 [redacted]
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Awaiting Scheduling	Completed	3180502 [redacted]
	Draft	3180794 [redacted]
Awaiting Scheduling	Completed	3180979 [redacted]
Maintenance Complete	Completed	
Maintenance Complete	Completed	
Awaiting Scheduling	Completed	3181350 [redacted]
	Closed	3181407 [redacted]
Maintenance Complete	Completed	3181539 [redacted]
Awaiting Scheduling	Completed	3182515 [redacted]
Awaiting Scheduling	Completed	3182797 [redacted]
	Closed	3182899 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

Awaiting Scheduling	Completed	3182996	[redacted]
Maintenance Complete	Completed	3183618	[redacted]
Awaiting Scheduling	Completed	3183733	[redacted]
Awaiting Scheduling	Completed	3184938	[redacted]
Awaiting Scheduling	Completed	3184943	[redacted]
	Closed	3184949	[redacted]
Awaiting Scheduling	Completed	3184958	[redacted]
Maintenance Complete	Completed	3184965	[redacted]
	Active	3185051	[redacted]
Materiel Required	Active	3185216	[redacted]

[redacted] is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Awaiting Scheduling	Active	3185228	[redacted]
Awaiting Scheduling	Completed	3185275	[redacted]
Awaiting Scheduling	Completed	3185291	[redacted]
Awaiting Scheduling	Completed	3185378	[redacted]
Awaiting Scheduling	Completed	3185635	[redacted]
Maintenance Complete	Completed	3185996	[redacted]
Awaiting Scheduling	Completed	3186696	[redacted]
Maintenance In Progress	Completed		
Maintenance Complete	Completed		
Maintenance In Progress	Completed		

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	
Awaiting Scheduling	Completed	3190128 [redacted]
Awaiting Scheduling	Completed	3190165 [redacted]
	Completed	
Awaiting Scheduling	Completed	
Maintenance Complete	Completed	
Maintenance Complete	Completed	
Awaiting Scheduling	Completed	3190561 [redacted]
Materiel Required	Completed	3190635 [redacted]
Awaiting Scheduling	Completed	3190669 [redacted]
Contract by Requestor	Active	3191200 [redacted]
Awaiting Scheduling	Completed	3191287 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

Awaiting Scheduling	Completed	3191344
Awaiting Scheduling	Completed	3191365
Awaiting Scheduling	Completed	3191396
Materiel Required	Completed	3191432
	Closed	3191528
Awaiting Scheduling	Active	3191606
Awaiting Scheduling	Completed	3192343
Awaiting Scheduling	Completed	3192525
Awaiting Scheduling	Completed	3192641
	Completed	3193258
	Completed	3193436

[redacted] is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Maintenance Complete	Completed	3193469 [redacted]
	Completed	
Maintenance In Progress	Completed	3195801 [redacted]
Awaiting Scheduling	Completed	3196155 [redacted]
Maintenance In Progress	Completed	3196806 [redacted]
Materiel Required	Completed	3197400 [redacted]
Materiel Required	Completed	3197414 [redacted]
Awaiting Scheduling	Completed	3197441 [redacted]
Maintenance In Progress	Active	3198014 [redacted]
Maintenance In Progress	Completed	3198490 [redacted]
Maintenance In Progress	Completed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Maintenance Complete	Completed	
Awaiting Scheduling	Completed	
Awaiting Scheduling	Completed	
Maintenance Complete	Completed	
Awaiting Scheduling	Completed	
Awaiting Scheduling	Active	3200301 [redacted]
Maintenance Complete	Completed	
Awaiting Scheduling	Completed	
Awaiting Scheduling	Completed	3200596 [redacted]
Maintenance In Progress	Completed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Materiel Required	Active	3200635 [redacted]
Awaiting Scheduling	Completed	3200908 [redacted]
	Closed	3200927 [redacted]
Maintenance Complete	Completed	3201004 [redacted]
Awaiting Scheduling	Completed	
Awaiting Scheduling	Completed	
Maintenance Complete	Completed	3201762 [redacted]
Awaiting Scheduling	Completed	
Awaiting Scheduling	Completed	
Awaiting Scheduling	Completed	
Materiel Required	Completed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Maintenance Complete	Completed	
Maintenance Complete	Completed	
Awaiting Scheduling	Completed	
Awaiting Scheduling	Completed	
Awaiting Scheduling	Completed	3202908 [redacted]
Materiel Required	Completed	3202914 [redacted]
Awaiting Scheduling	Active	3203059 [redacted]
Materiel Complete	Completed	
Awaiting Scheduling	Active	
Awaiting Scheduling	Completed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Materiel Required	Active	3207067	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Customer Organization

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - AFOSI DET 114

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - AFSC

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 OSS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 507 ARW

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 10 FTS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 507 ARW

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKER AFB - 72 CES

\Organizations\Customers\TINKER AFB - 72 CS

\Organizations\Customers\TINKER AFB - OC ALC FM

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - OC ALC FM

\Organizations\Customers\TINKER AFB - OC ALC FM

\Organizations\Customers\TINKER AFB - OC ALC FM

\Organizations\Customers\TINKER AFB - OC ALC FM

\Organizations\Customers\TINKER AFB - OC ALC FM

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\United States Air
Force\A4C USAF\Air Force
Materiel Command

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 SFS

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 72 SFS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 SFS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - AAFES - 91A

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - OC ALC FM

\Organizations\Customers\TINKER AFB - 72 CES

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\United States Air Force\A4C USAF\Air Force Materiel Command

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - VACANT

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 ABW

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\United States Air
Force\A4C USAF\Air Force
Materiel Command

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - VACANT

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKER AFB - OC ALC FM

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 72 CS

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 448 SCMW - 66

\Organizations\Customers\TINKER AFB - 72 CS

\Organizations\Customers\TINKER AFB - 72 CS

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 72 FSS RESTAURANT - 97

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKER AFB - 72 CS

\Organizations\Customers\TINKER AFB - AFSC

\Organizations\Customers\TINKER AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - AFSC

\Organizations\Customers\TINKER AFB - 72 CS

\Organizations\Customers\TINKER AFB - 72 CES

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 448 SCMW - 66

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - VACANT

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - DLA DISTRIBUTION DDC

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - AFSC

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW AFGLSC

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 FSS EDUATION

\Organizations\Customers\TINKE
R AFB - 72 FSS EDUATION

\Organizations\Customers\TINKE
R AFB - 72 FSS EDUATION

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - AFOSI DET 114

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 ABW

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G
\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - AFOSI DET 114

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 ABW

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - AFLCMC

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKER AFB - 72 CES

\Organizations\Customers\TINKER AFB - 72 CES DORMS

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Open Work Tasks - CUI/SP-FNC

02/23/2023 13:09:11

Task ID	Task Priority	Task Name	Work Classification
11225086	3C - Low Sustain	TEST - 3C - 3001 POST O73 - WT - INT PLUMB - 2 TOILETS CLOGGED - REPAIR - HOOD - 18APR2022 - 2881304	Repair
11225087	3C - Low Sustain	DEFAULT - Work Task Template - Corrective Maintenance-Clogs	Repair
11225089	3C - Low Sustain	DEFAULT - Work Task Template - Corrective Maintenance-Clogs	Repair
11363032	3C - Low Sustain	3C - 3001 - WT - INT PLUMB - Back flow leaking - Repair - T0280 - [redacted] - 734-2753 - SR# 2925627 - UID: 3001-BFRP-PD100	Repair
11363062	3B - Medium Sustain	3B - 3001 Post Y-62 - WT - SPRINK - Pressure Gauge Leaking from Knob - Repair - [redacted] - 736-9977 - SR# 2925649 - PSFS-P204	Repair
11363612	3B - Medium Sustain	3B - 3001 POST W81 - WT - HVAC C - AIR CONDITIONING UNIT LEAKING INTO AISLEWAY - REPAIR - [redacted] 736-5776 - SR#2925934	Repair
11363762	3B - Medium Sustain	3B - 3001 Post T-65 - WT - Roof - Roof Leak - Repair - [redacted] - 736-5776 - SR# 2926011	Repair
11364782	3B - Medium Sustain	3B - 3001 POST 2B87 - WT - ROOF - ROOF LEAK - Repair - T5524 - [redacted] - 519-7894	Repair
11364816	3B - Medium Sustain	3B - 3001 POST P45 - WT - ROOF - ROOF LEAK - Repair - T5724 - BILLY DEAL - 739-4975	Repair
11364818	3B - Medium Sustain	3B - 3001 POST T105 - WT - ROOF - ROOF LEAK - Repair - T5731 - [redacted] - 739-4975	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11364820	3B - Medium Sustain	3B - 3001 POST 3S69 - WT - ROOF - ROOF LEAK - Repair - T5943 - [redacted] - 582-4590	Repair
11364894	3C - Low Sustain	3C - 3001 POST X71 - RS67 - WT - ROOF - ROOF LEAK - Repair - T5721 - [redacted] - 739-4975	Repair
11364895	3B - Medium Sustain	3B - 3001 POST X71 - WT - ROOF - ROOF LEAK - Repair - T5721 - [redacted] - 739-4975	Repair
11364896	3B - Medium Sustain	3B - 3001 POST X75 - WT - ROOF - ROOF LEAK - Repair - T5721 - [redacted] - 739-4975	Repair
11364897	3B - Medium Sustain	3B - 3001 POST X79 - WT - ROOF - ROOF LEAK - Repair - T5721 - [redacted] - 739-4975	Repair
11364898	3B - Medium Sustain	3B - 3001 POST X83 - WT - ROOF - ROOF LEAK - Repair - T5721 - [redacted] - 739-4975	Repair
11364899	3B - Medium Sustain	3B - 3001 POST X89 - WT - ROOF - ROOF LEAK - Repair - T5721 - [redacted] - 739-4975	Repair
11364901	3B - Medium Sustain	3B - 3001 POST X95 - WT - ROOF - ROOF LEAK - Repair - T5721 - [redacted] - 739-4975	Repair
11364902	3B - Medium Sustain	3B - 3001 POSTS G70 & G105 - WT - ROOF - ROOF LEAKS - Repair - T5728 - [redacted] - 739-4975	Repair
11364903	3B - Medium Sustain	3B - 3001 POST U103 - WT - ROOF - ROOF LEAK - Repair - T5733 - [redacted] - 739-4975	Repair
11364904	3B - Medium Sustain	3B - 3001 POST U95 - WT - ROOF - ROOF LEAK - Repair - T5733 - [redacted] - 739-4975	Repair
11364905	3B - Medium Sustain	3B - 3001 POST E105 - WT - ROOF - ROOF LEAK - Repair - T5734 - [redacted] - 739-4975	Repair
11364906	3B - Medium Sustain	3B - 3001 POST E107 - WT - ROOF - ROOF LEAK - Repair - T5734 - [redacted] - 739-4975	Repair
11365349	3B - Medium Sustain	3B - 3001 POST 2AE66A - WT - ROOF - ROOF LEAK - Repair - T5483 - [redacted] - 408-1339 - WEATHER - FAST	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11367380	3A - High Sustain	3A - BLDG 3001 POST X81 - WT - HVAC C - WATER LEAK FROM CONDENSATE LINE - REPAIR - [redacted] 736-4500 - SR#2926812	Repair
11367630	3A - High Sustain	3A - 3001 X81 - WT - HVACC - WATER LEAK FROM CONDENSATE DRAIN - Repair - [redacted] - 736-4500 - SR#2926954	Repair
11368107	3B - Medium Sustain	3B - 3001 POST O-47; KITTING CAGE - WT - INSULATOR - CONDENSATION LEAK - Repair - T6306 - [redacted] - 736-2085 - 0 - AHU P210	Repair
11368137	3B - Medium Sustain	3B - 3001 POST O-65 - WT - INTPLUMB - CHILLED WATER LINES LEAKING - Repair - T6345 - [redacted] - [redacted] - 0 - FAST FD 24N	Repair
11369808	3B - Medium Sustain	3B - 3001 ANNEX G, RM 107 - WT - STRUC - ROOF LEAK - Repair - T5910 - [redacted] - 492-2496 - 0 - 0	Repair
11373575	3C - Low Sustain	3B - 3001G ROOM 104 DATACENTER - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 409-5733	Repair
11373598	3B - Medium Sustain	3B - 3001 ANNEX 4 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 409-5733	Repair
11375866	3B - Medium Sustain	3b - 3001 & 2AC4-89D - WT - ROOF - FIX ROOF LEAK - Repair - [redacted] - 405-736-1882	Repair
11378084	3B - Medium Sustain	3B - 3001 POST XR111 BREAKROOM - WT - PLUMB INT - BREAKROOM SINK CLOGGED - Repair - [redacted] - 7365716	Repair
11378259	3B - Medium Sustain	3B - 3001 POST O47 - WT - ROOF - ROOF LEAK CHECK - REPAIR - [redacted] 734-2765	Repair
11378870	3B - Medium Sustain	3B - 3001 POST 2E82 - WT - STRUC - ROOF LEAK CAUSING WET CEILING TILES - REPAIR - [redacted] 855-3012	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11378874	1-Emergency	1 - 3001 POST S35 - WT - HVACC - CHILLED WATER LINE LEAKING - Repair - [redacted] - 245-4051	Repair
11381718	3B - Medium Sustain	3B - 3001 & S-55 - WT - HVACC - STOP THE LEAK - Repair - [redacted] - 622-7549	Repair
11385381	3B - Medium Sustain	3B - 3001 G DOOR G15 - WT - INT PLUMB - WATER LEAK - Repair - [redacted] - 4922496	Repair
11386064	3B - Medium Sustain	3B - 3001 POST T-65 - WT - INT PLUMB - DRAIN LEAKING - Repair - [redacted] - 736-5776	Repair
11387982	3B - Medium Sustain	3B - 3001 Post P61 - WT - AFTER HVAC - Condensate leak - Repair - [redacted] - 801-971-7286	Repair
11390201	3B - Medium Sustain	3B - 3001 POST P57 - WT - HVACC - CONDENSATION LEAK - Repair - [redacted] - 420-4404	Repair
11390457	3B - Medium Sustain	3B - 3001 - POST 2E82 - INSULATOR - F/U 11378870 DUCT WORK IS LEAKING AND NEEDS INSULATED - REPAIR - [redacted] - 734-7083	Repair
11396106	3B - Medium Sustain	3B - 3001 POST U49 - WT - IWTP - INDUSTRIAL WASTE PUMP IS LEAKING - Repair - [redacted] - 736-5776	Repair
11396207	3B - Medium Sustain	3B - 3001 POST R49 - WT - IWTP - INDUSTRIAL WASTE PUMP IS LEAKING - Repair - [redacted] - 736-5776	Repair
11400348	3B - Medium Sustain	3B - 3001 Room 26 Post 2U77 - WT - INT ELEC - DISCONNECT POWER TO LIGHTS NEAR ROOF LEAK - repair - [redacted] 823-8833	Repair
11401809	3B - Medium Sustain	3B - 3001 POST 2AH73A - WT - ROOF - HEAVY LEAK - REPAIR - [redacted] - 408-1339 - STORM	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11401860	3B - Medium Sustain	3B - 3001 POST 2FH73A - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 408-1339 - STORM	Repair
11401900	3B - Medium Sustain	3B - 3001 Room 26 Post 2U77 - WT - ROOF - F/U 11400348 Roof leak - repair - [redacted] 823-8833 - STORM	Repair
11402685	3B - Medium Sustain	3B - 3001 POST R49 - WT - HVAC C - MONITOR SUMP PUMP DRAIN LEAKING - REPAIR - T4161 - [redacted] 734-5856	Repair
11403028	3B - Medium Sustain	3B - 3001 POST P57 - WT - INSULATOR - CONDENSATION LEAK - REPAIR - [redacted] - 420-4404	Repair
11403742	3B - Medium Sustain	3B- 3001 POST 1AD831 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 4643381 - STORM	Repair
11404539	3B - Medium Sustain	3B- 3001 POST 2AF68A - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 3701490 - STORM	Repair
11404634	3C - Low Sustain	3C - 3001 POST 2X7 - RS37 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 4178194 - STORM	Repair
11405713	3B - Medium Sustain	3B - 3001 POST A55.1 - - WT - ROOF - ROOF LEAK - Repair - [redacted] - 736-5776 - STORM	Repair
11407173	3A - High Sustain	3A - 3001 - post 3S69 - WT - Roof - Roof leak - repair - A[redacted] [redacted] - 582-4590	Repair
11407421	3B - Medium Sustain	3B - 3001 POST R49 - WT - PLUMB INT - SUMP PUMP DRAIN LEAKING - REPAIR - T4161 - [redacted] [redacted] - 734-5856 - SR#2944047	Repair
11407927	3B - Medium Sustain	3B - 3001 - post 3S69 - RS74 - WT - Roof - F/U 11407173 Roof leak - repair - [redacted] - 582-4590 - STORM	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11408548	3B - Medium Sustain	3B - 3001 PATRIOT ROOM - WT - HVACC - CONDENSATE LEAK - REPAIR - [redacted] - 73458956	Repair
11412221	3B - Medium Sustain	3B - 3001 POST F75 - RS67 - WT - ROOF - ROOF LEAK - Repair - [redacted] - 736-5776 - STORM	Repair
11413073	3C - Low Sustain	3C - 3001 D100 - WT - INTPLUMB - LEAKING BACKFLOW - REPAIR - T0280 - [redacted] - 734-7148 - - BFRP-PD100	Repair
11413088	3C - Low Sustain	3C - 3001 POST Y-3 - WT - ROOF - FF/INVESTIGATE LEAK - T0677 - [redacted] - 734-5815 - RS-121	Repair
11413100	3C - Low Sustain	3C - 3001 POST X79 - WT - INTELEC - F/U T1115 ROOF DRAIN LEAK - REPAIR - T1116 - [redacted] - 556-1954	Repair
11413480	3C - Low Sustain	3C - 3001 POST 2G-77 - RS68 - LEAN TO - WT - ROOF - ROOF LEAK - REPAIR - T2743 - [redacted] - 582-6991 - -	Repair
11413514	3C - Low Sustain	3C - 3001 ANNEX G, RM 125, NW - WT - HVACC - FF/LEAKING DISCHARGE VALVE - REPAIR - T3210 - [redacted] - 582-9513 - - PCHW-GL118-1	Repair
11413516	3C - Low Sustain	3C - 3001 ANNEX G, RM 125, NW - WT - HVACC - FF/LEAKING DISCHARGE VALVE - REPAIR - T3211 - [redacted] - 582-9513 - - PCHW-GL118-2	Repair
11413518	3C - Low Sustain	3C - 3907 RM 120B - WT - HVACC - FF/LEAKING PIGTAIL ON PRESSURE GAUGE - REPAIR - T3212 - [redacted] - 582-9513 - HUM-H201	Repair
11413811	3C - Low Sustain	3C - 3001 Post 899 - WT - Roof - Roof leak - Repair - T5797 - [redacted] - 736-5776	Repair
11413819	3C - Low Sustain	3C - 3001 Post G97 - RS33- WT - Roof - Roof leak - Repair - T5798 - [redacted] - 736-5776	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11413848	3C - Low Sustain	3C - 3001 POST Y55 - RS87 - WT - ROOF - ROOF LEAK IN STAIRWELL - REPAIR - T5516 - [redacted] - 736-9977 - STORM -	Repair
11413859	3C - Low Sustain	3C - 3001 POST 2Y55 - RS87 - WT - ROOF - ROOF LEAK IN CONF RM - REPAIR - T5517 - [redacted] - 734-3981 - -	Repair
11414027	3C - Low Sustain	3C - 3001 POST Y90 - WT - INTPLUMB - URINAL CLOGGED & BAGGED - REPAIR - T6350 - [redacted] - 582-4340 - -	Repair
11414033	3C - Low Sustain	3C - 3001 POST O103 - WT - INTPLUMB - URINAL CLOGGED & BAGGED - REPAIR - T6352 - [redacted] RL [redacted] - 582-4340 - -	Repair
11414133	3C - Low Sustain	3C - 3001 POST 2M41 - RS135 - WT - ROOF - ROOF LEAK - REPAIR - T5596 - [redacted] - 823-8883 - STORM -	Repair
11414526	3C - Low Sustain	3B - 3001 POST 2T79 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 7365776 - STORM	Repair
11414624	3B - Medium Sustain	3B - 3001 POST 2G77 - RS68 - WT - ROOF - ROOF LEAKS IN LAB - REPAIR - [redacted] 736-5871	Repair
11414840	3C - Low Sustain	3C - 3001 POST Y10.5 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair
11414841	3C - Low Sustain	3B - 3001 POST Y37 - RS102 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair
11414862	3C - Low Sustain	3B - 3001 POST X3 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair
11414863	3C - Low Sustain	3B - 3001 POST Y3 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair
11414890	3C - Low Sustain	3B - 3001 POST 2X5 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11414891	3C - Low Sustain	3B - 3001 POST X9 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] [redacted] 417-8194	Repair
11414913	3C - Low Sustain	3C - 3001 POST X16 - RS117 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair
11414914	3C - Low Sustain	3B - 3001 POST X21 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] [redacted] 417-8194	Repair
11414930	3C - Low Sustain	3B - 3001 POST X36 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] [redacted] 417-8194	Repair
11414932	3B - Medium Sustain	3B - 3001 POST M49 - RS92 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 417-8194	Repair
11416572	3B - Medium Sustain	3B - 3001 POST 2AF73 MEN'S RR - WT - PLUMB INT - TOILET CLOGGED AND BAGGED - REPAIR - [redacted] 736-8536	Repair
11418160	3C - Low Sustain	3C - 3001 OLD HORSESHOE - WT - HVACC - LEAKING PUMP ON REDUNDANT CHILLER - REPAIR - T2385 - [redacted] - 734-5856 - -	Repair
11418173	3C - Low Sustain	3C - 3001 POST B79 - WT - INTPLUMB - DRAIN CLOGGED - REPAIR - T2498 - [redacted] - 739-4975 - -	Repair
11418296	3C - Low Sustain	3C - 3001 POST 2AH1-96H- RS43 - WT - ROOF - WATER LEAK IN CEILING - REPAIR - T2865 - [redacted] [redacted] - 736-3537 - - RFS-37	Repair
11418639	3C - Low Sustain	3C - 3001 POST O103 - WT - AFTER HRS PLUMB - TOILET CLOGGED - REPAIR - T3338 - [redacted] - 622-7846 - -	Repair
11418640	3C - Low Sustain	3C - 3001 POST O103 - WT - INTPLUMB - TOILET CLOGGED - REPAIR - T3338 - [redacted] - 622-7846 - -	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11418683	3C - Low Sustain	3C - 3001 POST Y-3 - WT - ROOF - WATER DRAIN LEAK - REPAIR - T3682 - [redacted] - 405-410-7686 - - RFS-121	Repair
11418934	3C - Low Sustain	3C - 3001 POST Y61 - WT - ROOF - ROOF LEAK - REPAIR - T3732 - [redacted] - 622-7846 - - RFS-82	Repair
11419092	3C - Low Sustain	3C - 3001 POST P53 - WT - HVACC - CHILL WATER PIPE LEAK - REPAIR - T4574 - [redacted] - 323-0319	Repair
11419293	3C - Low Sustain	3C - 3001 POST 1AJ75 - WT - INTPLUMB - TOILET LEAKING IN MENS RR - REPAIR - T5423 - [redacted] - 405-417-2893	Repair
11419481	3C - Low Sustain	3C - 3001 POST AH151.1 - WT - SHEET - ROOF LEAK ONTO TEST STANDS - REPAIR - T5507 - [redacted] - 405-736-2085 - WEATHER - RFS-88	Repair
11420785	3B - Medium Sustain	3B - 3001 POST 2B83 - RS51 - WT - ROOF - ROOF LEAK - Repair - [redacted] - 2197894 - STORM	Repair
11427089	3A - High Sustain	3A - 3001 POST M54 - WT - HVACC - STEAM PIPE LEAKING - REPAIR - [redacted] - 736-2085	Repair
11427257	3B - Medium Sustain	3B - 3001 POST Q51 - WT - ROOF - ROOF LEAK - Repair - [redacted] - 736-5776 - STORM	Repair
11430111	3B - Medium Sustain	3B - 3001 POST 1AB1-96H - WT - INT PLUMB - SINKS INOP/TOILET LEAK - REPAIR - [redacted] - 6283214	Repair
11430962	3A - High Sustain	3A - 3001 POST R61 - WT - AFTER - STEAM LINE WATER LEAK - REPAIR - [redacted] 582-4340	Repair
11430979	3B - Medium Sustain	3B - 3001 POST 1AD83A - RS56 - WT - STRUC - WALL LEAKING - REPAIR - [redacted] 734-9868	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11431640	3A - High Sustain	3A - 3001 Post K67 - WT - AFTER - Water Leaking clogged floor drains in the fan deck - Repair - [redacted] 405-582-4340	Repair
11432532	3A - High Sustain	3A - 3001 M-49 - WT - Intplumb - Toilet overflowing - Repair - [redacted] - 736-2085	Repair
11433475	3A - High Sustain	3A - 3001 POST Y61 - WT - INT PLUMB - SEWER BACK UP - Repair - [redacted] - 7369977	Repair
11435194	3A - High Sustain	3A - 3001 POST 2O-83 - WT - SPRINK - SPRINKER LEAKING - REPAIR - [redacted] - 736-5776	Repair
11441188	3B - Medium Sustain	3B - 3001 MEN'S RR ENTRY OF DOOR E - WT - INT PLUMB - LEAKING AND CLOGGED TOILET - REPAIR - [redacted] 417-2893	Repair
11441212	3B - Medium Sustain	3B - 3001 POST 2AB1/109 MEN'S RR - WT - INT PLUMB - URINAL CLOGGED - REPAIR - [redacted] 417-2893	Repair
11447648	3C - Low Sustain	3C - 3001 ANNEX G NW CORNER - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 4092888	Repair
11449649	3B - Medium Sustain	3B - 3001 Fan deck P24SFD - WT - HVACC - coil leaking - repair - [redacted] 582-5009	Repair
11451984	3A - High Sustain	3A - 3001 post M-49 Men's / Women's R/R - WT - Intplumb - Water on flr, leaking through wall into admin area - repair - [redacted] - 736-2085	Repair
11453577	3B - Medium Sustain	3B - 3001 ANNEX G & ROOM 104 - WT - HVACC - STOP LEAK - Repair - [redacted] - 4095733	Repair
11459826	3A - High Sustain	3A - 3001 POST Y30 - WT - ROOF - ROOF LEAKING ONTO ATM - REPAIR - [redacted] 417-8194	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11460090	3B - Medium Sustain	3B - 3001 POST Y30 - WT - INT PLUMB - ROOF DRAIN LEAKING ONTO ATM - REPAIR - [redacted] [redacted] 417-8194	Repair
11460396	3B - Medium Sustain	3B - 3001 POST 1AF77A - WT - INT PLUMB - JANITOR CLOSET LEAKING FAUCET - REPAIR - [redacted] - 4172893	Repair
11469473	3A - High Sustain	3A - 3001 post M-49 Men's / Women's R/R - WT - Intplumb - Water on flr, leaking through wall into admin area - repair - [redacted] - 736-2085	Repair
11470424	3B - Medium Sustain	3B - 3001 POST V53 - WT - INT PLUMB - PVC ELBOW OF ROOF DRAIN IS LEAKING - Repair - [redacted] [redacted] - 736-5776	Repair
11471111	3B - Medium Sustain	3B - 3001 POST 1AH71A - RS71 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 2050852 - STORM	Repair
11471520	3B - Medium Sustain	3B - 3001 POST EXT DOOR BY FLAG POLE - WT - ROOF - ROOF LEAK - REPAIR - [redacted] - 7365776	Repair
11473266	3B - Medium Sustain	3B - 3001 RM 26 POST 2U77 - WT - STRUC - FU 11401900 REPLACE CARPET AND CEILING TILE FROM ROOF LEAK DAMAGE - REPAIR - [redacted] 734-9868	Repair
11473273	3B - Medium Sustain	3B - 3001 RM 26 POST 2U77 - WT - INT ELEC - FU 11401900 LIGHT FIXTURES NEED REPAIR FROM ROOF LEAK - REPAIR - [redacted] [redacted] 734-9868	Repair
11475927	3B - Medium Sustain	3B - 3001 POST K107 - RS22 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] 736-5776	Repair
11475937	3B - Medium Sustain	3B - 3001 POST D106 - RS27 - WT - ROOF - ROOF LEAK - REPAIR - [redacted] [redacted] 736-5776	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11476101	3B - Medium Sustain	3B - 3001 - POST B81 - RS51 - WT - ROOF - ROOF LEAK ON PANEL - Repair - [redacted] - 7365776 - STORM	Repair
11481497	3A - High Sustain	3A - 3001 POST 2O33 - WT - ROOF - ROOF LEAK RUNNING DOWN STAIRWELL - REPAIR - [redacted] 4081339	Repair
11493674	3B - Medium Sustain	3B - 9001 X40 - WT - TAC HVAC - HVAC LEAK ONTO FLOOR - Repair - [redacted] - 5829038	Repair
11496692	3A - High Sustain	3A - 3001 Post P94 - WT - HVACC - room is being flooded by condensate from HVAC unit - repair - [redacted] - 736-5776	Repair
11498108	3B - Medium Sustain	3B - 3001 POST Y78 - WT - HVACC - A/C INOP AND LEAKING - REPAIR - [redacted] - 4922496	Repair
11508061	3B - Medium Sustain	3B - 3001 ANNEX G RM 131 - WT - ROOF LEAK - [redacted] - 492-2496	Repair
11511863	3B - Medium Sustain	3B - 3001 - WT - HVACC - REF 11483588 INSULATORS COMPLETE; HVAC FIX OVERFLOW LEAK ON COPPER PIPE - REPAIR - [redacted] 734-2765	Repair
11512665	3B - Medium Sustain	3B - 3001 2AF76A MEN'S RR - WT - INT PLUMB - URINAL CONTINUOUSLY FLUSHING; NOT OVERFLOWING - REPAIR - [redacted] 409-2888	Repair
11533525	3A - High Sustain	3A - 3001 post Y-26 - WT - HVACC - Water is leaking out of the A/C down the wall - repair - [redacted] - 734-1929	Repair
11540708	3B - Medium Sustain	3B - 3001 Admin Roof - WT - HVACC - Possible refrigerant leak at bypass solenoid - Repair - [redacted] 582-9513 - UID 3001-CU-A1	Repair
11544607	3A - High Sustain	3A - 3001 & W67 - WT - HVACC - STOP LEAK - Repair - [redacted] - 6202589	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11546000	3A - High Sustain	3A - 3001 POST O83 - WT - INT PLUMB - JANITOR SINK CLOGGED - REPAIR - [redacted] 620-2589	Repair
11555336	3B - Medium Sustain	3B - 3001 POST 1AG72A - WT - HVACC - SEWER SMELL COMING FROM THE HVAC VENTS - Repair - TOM COSTA - 635-7051	Repair
11558089	3A - High Sustain	3A - 3001 Post B94 - WT - Intplumb - Urinal Overflowing - [redacted] - 405-589-0500	Repair
11559170	3B - Medium Sustain	3B - 3001 POST 1AF71A - WT - REPAIR - WATER FOUNTAIN CLOGGED - REPAIR - [redacted] 323-0319	Repair
11564567	3B - Medium Sustain	3B - 3001 MAIN CAFE KITCHEN AJ64A - WT - INT PLUMB - DRAIN CLOGGED - Repair - [redacted] - 5143354	Repair
11567069	3B - Medium Sustain	3B - 3001 MEN'S RR POST B95 - WT - INT PLUMB - URINAL CLOGGED - REPAIR - [redacted] 736-5776	Repair
11570420	3B - Medium Sustain	3B - 3001 POST X-19 - WT - INT PLUMB - F/U 11551182 REPAIR LEAKING EYE WASH STATION - Repair - [redacted] - 417-8194	Repair
11578680	3B - Medium Sustain	3B - 3001 POST X15 - WT - SPRINK - SMALL LEAK FROM SPRINK PIPE - REPAIR - [redacted] - 620-2589	Repair
11578681	3B - Medium Sustain	3B - 3001 POST X12 - WT - SPRINK - SMALL LEAK FROM SPRINK PIPE - REPAIR - [redacted] - 620-2589	Repair
11588652	3B - Medium Sustain	3B - 3001 POST 2P65 - WT - HVACC - AHU HAS SMALL LEAK - REPAIR - [redacted] - 5824340 -AHUPR65	Repair
11588847	3B - Medium Sustain	3B - 3001 & POST O83 - WT - INT PLUMB - UNCLOG MENS TOILET - Repair - [redacted] - 7365776	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11588892	3B - Medium Sustain	3B - 3001 & POST O93 - WT - INT PLUMB - STOP URINAL LEAK - Repair - [redacted] - 7365776	Repair
11598674	3B - Medium Sustain	3B - 3001 & 2AH/73A - WT - HVACC - UNIT IS LEAKING - Repair - [redacted] - 4059906861	Repair
11602560	3A - High Sustain	3A - 3001 POST O65 - WT - INT PLUMB - WATER LEAKING FROM CEILING - Repair - [redacted] - 5824340	Repair
11603539	3A - High Sustain	3A - 3001 POST O65 - WT - PIPE - WATER LEAKING FROM CHILLED WATER LINE - Repair - [redacted] - 5824340	Repair
11603870	3B - Medium Sustain	3B - 3001 Y 104 - WT - INT PLUMB - UNCLOG URINAL - Repair - [redacted] - 5824340	Repair
11605700	3B - Medium Sustain	3B - 3001 POST N49 WRR - WT - INT PLUMB - TOILET LEAKING AT THE BASE - REPAIR - [redacted] 582-4340 - SR# 3015430	Repair
11611285	3C - Low Sustain	OUTAGE 3C - 3001 POST O65 - WT - PIPE - F/U 11603539 WATER LEAKING FROM CHILLED WATER LINE IN FALL - Repair - [redacted] - 5824340	Repair
11613548	3A - High Sustain	3A - 3001 POST 3S-69 - WT - MOLD - INSPECT AREA FOR MOLD FROM LEAKING CHILLED WATER LINE - REPAIR - [redacted] 582-4340 - MOLD	Repair
11617736	3B - Medium Sustain	3B - 3001 POST 2P65 - WT - HVACC - HVAC WATER LEAK - REPAIR - [redacted] - 5824340	Repair
11629799	3B - Medium Sustain	3B - 3001 Blr Plant - WT - HVACC - Clogged drain/backing up - Repair - [redacted] - 582-9513 - UID 3001 PCHW-BS05	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11631467	3C - Low Sustain	3C-3001 POST O65 - WT - PM - F/U 11611285 EMPTY CANS FROM JANITORS CLOSET FROM CHILL WATER LINE LEAK - [redacted] -582-4496	Repair
11633926	3B - Medium Sustain	3B - 3001 POST O103 MRR - WT - INT PLUMB - TOILET HAS OVERFLOWED AND IS NOW BAGGED - REPAIR - [redacted] 582-4340 - SR# 3027428	Repair
11641544	3C - Low Sustain	3C - 3001 2J111 - WT - INT PLUMB - BREAKROOM SINK LEAK - REPAIR - [redacted] 205-6973	Repair
11641897	3C - Low Sustain	3C - 3001G ROOM 104 - WT - INT PLUMB - SEWER SMELL - REPAIR - [redacted] - 7364731	Repair
11651515	3C - Low Sustain	3C - 3001 POST 2AH1102H MENS RR - WT - INT PLUMB - 1 TOILET IS CLOGGED - Repair - [redacted] - 7398921	Repair
11655964	3B - Medium Sustain	3B - 3001 Entrance E (1AJ-87E) - WT - INTPLUMB - Exterior faucet leaking/dripping, valve is closed by hand - Repair - [redacted] 405-582-4340	Repair
11661379	3B - Medium Sustain	3B- 3001 Post O-65 - WT - HVACC - Water leaking from above, over filled trash can - repair - [redacted] (MOC)- 736-2500	Repair
11663022	3B - Medium Sustain	3B - 3001 POST M31 - WT - INTPLUMB - WATER LEAKING ON BACK FLOW PREVENTER - REPAIR - [redacted] - 5030023	Repair
11664576	3B - Medium Sustain	3B - 3001 POST Y86/Y87 - WT - SPRINK - SPRINKLER LINE LEAKING IN HIGH BAY - REPAIR - [redacted] 736-5776	Repair
11669244	3A - High Sustain	3A - 3001 1AH84A - WT - HVACC - WATER LEAK FROM AHU - REPAIR - [redacted] - 9906861	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11672169	3C - Low Sustain	3B - 3001 1AH84A - WT - STRUC - RELACE RUINED TILES FROM WATER LEAK - REPAIR - [redacted] - 9906861	Repair
11672375	3B - Medium Sustain	3B - 3001 POST 1AH87A - WT - HVACC - CONDENSATION DRIP PAN POSSIBLE OVERFLOW - REPAIR - [redacted] 628-3214	Repair
11680819	3C - Low Sustain	3B - 3001 POST 2T111 MECH ROOM - WT - ROOF - ROOF LEAK INTO TARP, NEED TARP ADJUSTED - Repair - [redacted] - 4922496	Repair
11683421	3B - Medium Sustain	3B - 3001 POST 1AA2/112A NEAR DOOR P - WT - ROOF - LEAK FROM ROOF - Repair - [redacted] - 9906861 - STORM	Repair
11684654	1-Emergency	1 - 3001 Post 1AD185 - WT - AFTER PLUMB - sink overflowing - repair - [redacted] 734-3737	Repair
11689847	3A - High Sustain	3A - 3001 2y61 - WT - Roof - leak dripping on desk from area next to vent - repair - [redacted] - 736-9977	Repair
11689928	3B - Medium Sustain	3B - 3001 POST P45 -RS92 - WT - ROOF - ROOF LEAKING DURING RAIN - REPAIR - [redacted] 736-5776	Repair
11689936	3B - Medium Sustain	3B - 3001 POST T105 - WT - ROOF - ROOF LEAKING DURING RAIN - REPAIR - [redacted] 736-5776	Repair
11691618	3B - Medium Sustain	3B - 3001 POST 2AF86A - WT - INT PLUMB - URINAL IS LEAKING AND WATER IS ALL OVER THE FLOOR - REPAIR - [redacted] - 409-2888	Repair
11692204	3B - Medium Sustain	3B - 3001 POST AF77A - WT - INT PLUMB - CAMERA SEWER LINE - Repair - [redacted] - 820-8404	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11695552	3B - Medium Sustain	3B - 3001 MAIN CAFE KITCHEN - WT - INT PLUMB - DISHWASHER LINE LEAKING AT A T - REPAIR - [redacted] 734-3161	Repair
11696638	3B - Medium Sustain	3B - 3001 Post L-63 -WT - Intplumb - Malevolent Act, seat cover paper towels clogging toilet - repair - [redacted] - 622-7855 - SR3057193	Repair
11699429	3A - High Sustain	3A - 3001 1AB1 94A - WT - AFTER HVAC - WATER LEAKING FROM AIR HANDLER - REPAIR - [redacted] 734-9028 - RE0021	Repair
11700194	3A - High Sustain	3A - 3001 MECH RM 14 UPPER - WT - INT PLUMB - FLOOR DRAIN PLUGGED & FLOODING AREA - REPAIR - [redacted] - 246-8579 - KH080504	Repair
11701632	3C - Low Sustain	3C - 3001 1AB1 94A - WT - STRUC - F/U 11699429 REPLACE DAMAGED CEILING TILES FROM HVAC LEAK - REPAIR - [redacted] 734-9028	Repair
11701763	3A - High Sustain	3A - 3001 Post 2Q73 - WT - HVACC - Possible HVAC leak - repair - [redacted] 736-8536 - ACCESS	Repair
11708819	3B - Medium Sustain	3B - Building 3001, post A-59 - WT - Sprink - Fire suppression line is leaking - repair - [redacted] - 736-5776	Repair
11717369	3B - Medium Sustain	3B - 61024 - WT - EXT PLUMB - FIRE HYDRANT LEAK EXT BLDG 3001 POST Y14 - REPAIR [redacted] 734-0408	Repair
11725082	3C - Low Sustain	3C - 3001 BOILER PLANT - WT - ROOF - ROOF LEAK ONTO BOILER 1 AND 2 - Repair - [redacted] 246-8579	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11732869	3B - Medium Sustain	3B - 3001 POST 2W81 - WT - HVACC - CONDENSATION LINE IS LEAKING ALL OVER THE WX AISLE - REPAIR - [redacted] 736-5776	Repair
11735039	3B - Medium Sustain	3B - 3001 POST Q40 - WT - HVACC - CHILLED WATER LEAK - REAPIR - [redacted] 736-4118	Repair
11735226	3A - High Sustain	3A - 3001 POST 1AH87R - WT - INT PLUMB - 15 LOWER FLOOR DRAIN CLOGGED & FLOODING AREA - REPAIR - [redacted] - 405-246-8579	Repair
11735317	3B - Medium Sustain	3B - 3001 POST AH6L - WT - INT PLUMB - 14 LOWER FLOOR DRAIN HAS SMALL LEAK ONTO CONCRETE - REPAIR - [redacted] - 405-246-8579	Repair
11735902	3A - High Sustain	3A - 3001 1AB1 94A - WT - INT PLUMB - FLOOR DRAIN IN UPSTAIRS MECH RM STILL LEAKING - REPAIR - [redacted] 628-3214	Repair
11748889	3C - Low Sustain	3C - 3001 POST N61 PLATING SH - WT - HVACC - FF/POST N-61 PIPES FROM AC UNIT LEAKING - REPAIR - T5392 - [redacted] 582-9513 - FLT-PN6	Repair
11752833	3A - High Sustain	3A - 3001 Y53 - WT - INT PLUMB - 3 TOILETS OVERFLOWING - Repair - [redacted] 7365776	Repair
11755040	3B - Medium Sustain	3B - 3001 PLANT POST 73A - WT - INT PLUMB - WATER LEAK FROM SEWAGE LINE - REPAIR - [redacted] 246-8579	Repair
11757033	3B - Medium Sustain	3B - 3001 POST Y90 - WT - HVACC - HVAC IS LEAKING ON THE FLOOR - [redacted] - 736-5776	Repair
11757406	3B - Medium Sustain	3B - 3001 POST S33 BREAKRM - WT - INT PLUMB - SINK IS CLOGGED - [redacted] 622-7387	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11757760	3B - Medium Sustain	3B - 3001 POST X7 - WT - INT PLUMB - INSPECT ALL URINALS FOR OVERFLOWING - [redacted] - 734-0408	Repair
11759759	3C - Low Sustain	3C - 3001 POST B95 WOMEN'S RR - WT - INT PLUMB - TOILET IS CLOGGED - [redacted] - 736-5776	Repair
11761512	3C - Low Sustain	3C - 3001 Post G97 - WT - INT PLUMB - FU 11413819 DRAIN LINE IS LEAKING - T5798 - [redacted] - 736-5776	Repair
11762016	3B - Medium Sustain	3B - 3001 POST Y63 - WT - INT PLUMB - MENS RR HAS CLOGGED AND BAGGED URINAL - [redacted] - 622-7855	Repair
11768300	3A - High Sustain	3A - 3001 MECH ROOM 6 LOWER POST 1AD85A - WT - INT PLUMB - VERY LARGE WATER LEAK - [redacted] 4052487122	Repair
11769912	3B - Medium Sustain	3B - 3001 2 UPPER - WT - HVACC - 2 UPPER HAS A WATER LEAK - [redacted] - 734-5856	Repair
11770475	3B - Medium Sustain	3B - 3001 2Q73 - WT - HVACC - WATER LEAK REPEATEDLY SOAKING CEILING TILES - [redacted] 408-1339	Repair
11773725	3C - Low Sustain	3C - 3001 MAIN CAFE KITCHEN - WT - HVACC - LEAK CHECK DISHWASHER COILS - REPAIR - [redacted] 734-3161	Repair
11774186	3A - High Sustain	3A - 3001 MECH ROOM 6 LOWER - WT - INT PLUMB - 2" DRAIN LEAKING - [redacted] 7345856	Repair
11776764	3A - High Sustain	3A - 3001 Post 1AB194A Mech room 7 lower - WT - AFTER HVAC - Water leaking - [redacted] 990-6861	Repair
11778523	3B - Medium Sustain	3B - 3001 Post 2AF 72A - WT - HVACC - Water leaking from air coil - [redacted] - 582-9513 - UID 3001-AHU-A2U	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11779750	3B - Medium Sustain	3B - 3001 POST M31 - WT - PIPE - F/U 11757522 METER LEAK ON THE OUTLET SIDE OF BACKFLOW - [redacted] - 734-7098	Repair
11780030	3A - High Sustain	3A - 3001 POST 1AH184A - WT - INT PLUMB - CLOGGED DRAIN COMING FROM MECH ROOM AU16UPPER - [redacted] - 990-6861	Repair
11784199	3C - Low Sustain	3C - 3001 Post G97 - WT - ROOF - F/U 11761512 & 11413819 DRAIN LINE IS LEAKING - T5798 - [redacted] - 734-7098 - SR 3099169	Repair
11784604	3B - Medium Sustain	3B - 3001 POST 1AH71A - RS71 - WT - SPRINK - FU 11471111 FIRE SUPPERESSION LINE IS LEAKING - [redacted] - 205-0852 - STORM	Repair
11784636	3B - Medium Sustain	3B - 3001 POST T87 - WT - HVACC - FU 11462169 STORM LEAKING FROM INSIDE AC UNIT NOT SURE WHERE TRANSFER TO HVAC - T5595 - [redacted] - 739-4975	Repair
11784666	3C - Low Sustain	3C - 3001 P K107 - RS22 - WT - HVACC - 11475927 LEAK COMING FROM INSIDE HVAC UNIT BY THE FILTERS- [redacted] 736-5776 PR 3009. 3012, 3013 12/6-9	Repair
11785365	3A - High Sustain	3A - 3001 MRR POST P103 - WT - INT PLUMB - SINK IS OVERFLOWING - [redacted] 736-5776	Repair
11797517	3C - Low Sustain	3C - 3001 - WT - INT PLUMB - LEAK POSSIBLY FROM SINK ATTACHED TO OLD COOLANT TROUGH - [redacted] - 736-5776	Repair
11799327	3C - Low Sustain	3C - 3001 AHU-7 UPPER - WT - INT PLUMB - UNCLOG FLOOR DRAIN - [redacted] - 734-2753	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11801472	3A - High Sustain	3A - 3001 ANNEX 4 - WT - ROOF - ROOF LEAK ON S WALL OF ROOMS 110-115. REPAIR ROOF & REPLACE DAMAGED CEILING TILES - [redacted] - 736-4730	Repair
11806338	3B - Medium Sustain	3B - 3001 POST A59 - WT - HVACC - F/U 11708819 WATER MAKE UP LINE LEAKING - [redacted] - 736-5776	Repair
11807112	3A - High Sustain	3A - 3001 1AF81A - WT - HVACC - WATER LEAKING FROM CEILING IN OFFICE [redacted] 7348604	Repair
11809131	3A - High Sustain	3A- 3001G Room 203 - WT - HVAC C - leak has collapsed ceiling tile above filing cabinet - repair - [redacted] - 405-409-5733 - SR3108667	Repair
11811700	3B - Medium Sustain	3B - 3001 POST K97 - WT - STRUC - ROOF LEAK NEAR ELECTRICAL PLUG - [redacted] - 736-5776	Repair
11812083	3C - Low Sustain	3C - 3001G RM 203 - WT - STRUC - F/U 11809131 REPLACE DAMAGED CEILING TILE FROM LEAK - [redacted] - 736-4730	Repair
11812847	3A - High Sustain	C/O - 3A - 3001 POST 2Q73 - WT - HVACC - POSSIBLE HVAC LEAK - [redacted] - 736-8536	Repair
11813816	3A - High Sustain	3A - 3001 MRR B95 - WT - INT PLUMB - URINAL OVERFLOWING - [redacted] 736-5776	Repair
11824690	3B - Medium Sustain	C/O 3A - 3001 POST 2W77 - RS65 - WT - KH090102 ROOF LEAK ABOUT TO BURST CEILING TILE - [redacted] - 736-5776	Repair
11844759	3A - High Sustain	3A - 3001 POST 2 X 56 - WT - HVAC C - FAN DECK LEAKING WATER - [redacted] - 4204404	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11848305	3A - High Sustain	3A - 3001 POST G87 - WT - HVACC - CHILLED WATER LEAK FROM 3 DIFF AREAS - [redacted] - 736-5776	Repair
11849316	3B - Medium Sustain	OUTAGE 3B - 3001 POST G87 - WT - PIPE - (09/22/2022 COM) CHILLED WATER LEAK FROM 3 DIFF AREAS - [redacted] - 736-5776	Repair
11851890	3A - High Sustain	3A - 3001 AHU 9L - WT - INT PLUMB - CONDENSATE FLOOR DRAIN CLOGGED - [redacted] - 801-971-7286	Repair
11853578	3B - Medium Sustain	3B - 3001 POST P81 - WT - INT PLUMB - PIPE LEAKING/POSSIBLY IN THE REST ROOM - [redacted] - 736-5776	Repair
11853633	3C - Low Sustain	3C - 3001 POST K75 - WT - ROOF - ROOF LEAKS WHEN IT RAINS - [redacted] - 736-5776	Repair
11853723	3B - Medium Sustain	3B - 3001 POST 2X56 - WT - INT PLUMB - PLUMBING LEAK IN THE CEILING - [redacted] - 736-5776	Repair
11868498	3B - Medium Sustain	3B - 3001 MENS RR - WT - INT PLUMB - 3 TOILETS CLOGGED AND BAGGED - [redacted] - 736-5776	Repair
11868524	3C - Low Sustain	3C - 3001 POST 083 - WT - INT PLUMB - URINAL CLOGGED AND BAGGED - [redacted] - 736-5776	Repair
11878692	3A - High Sustain	3A - 3001 POST 1AI70 ANACONDA CONF RM - WT - SPRINK - ACTIVE WATER LEAK FROM CEILING - [redacted] - 417-2893	Repair
11879567	3B - Medium Sustain	3B - 3001 POST 1AI70 ANACONDA CONF RM - WT - ALARM - F/U 11878692 ACTIVE WATER LEAK FROM CEILING - [redacted] - 417-2893	Repair
11889092	3C - Low Sustain	3C - 3001 G40 - WT - PIPE - CHILL WATER LEAK - [redacted] - 582-4496	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11889464	3C - Low Sustain	3C - 3001 1AB1-99A MENS RR - WT - INT PLUMB - SINK SENSOR NOT WORKING PROPERLY&URINAL CLOGGED/BOTH ARE BAGGED - [redacted] - 734-9028	Repair
11892228	3B - Medium Sustain	3B - 3001 POST Q40 - WT - PIPE - F/U WT #11735039 & 11778953 FIX LEAK FROM PIPE - [redacted] - 736-4118	Repair
11894062	3A - High Sustain	3A - 3001 POST 2AH196H - WT - INT PLUMB - LEAK IN MENS RESTROOM - [redacted] - 205-6973	Repair
11899498	3C - Low Sustain	3C - 3001 POST 2W83 - WT - INT PLUMB - 1ST TOILET IS CLOGGED AND BAGGED - [redacted] - 736-5776	Repair
11901517	3C - Low Sustain	3C - 3001 MENS RR POST 2AB196H - WT - INT PLUMB - URINAL CLOGGED - [redacted] - 739-8921	Repair
11901539	3C - Low Sustain	3C - 3001 MENS RR POST 1AF71 - WT - INT PLUMB - URINAL CLOGGED - [redacted] - 739-8921	Repair
11901564	3B - Medium Sustain	3B - 3001 MENS RR POST 1AD86 - WT - INT PLUMB - HANDICAP TOILET CLOGGED - [redacted] - 739-8921	Repair
11903095	3C - Low Sustain	3C - 3001 POST 1AH1-106C MENS RR - WT - INT PLUMB - 1ST STALL TOILET CLOGGED - [redacted] - 734-9028	Repair
11903458	3B - Medium Sustain	3B - 3001 POST 2P83 - WT - HVACC - WATER LEAKING FROM HVAC UNIT - [redacted] - 7365776	Repair
11907956	1-Emergency	1 - 3001 Post 2AE85A - WT - AFTER PLUMB - Men's restroom is flooding - [redacted] 409-2888	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11920040	3B - Medium Sustain	3B - 3001 POST 2P83 - WT - BAS - WATER LEAKING FROM HVAC UNIT - REPAIR - [redacted] - 736-5776	Repair
11933391	3A - High Sustain	3A - 3001 POST Y90 - WT - INT PLUMB - URINAL OVERFLOWING ONTO THE FLOOR - [redacted] - 8245403	Repair
11934888	3A - High Sustain	3A - 3001 POST 2AF71A - WT - INT PLUMB - URINALS LEAKING FROM THE BACK - [redacted] - 4081339	Repair
11941164	3C - Low Sustain	3C - 3001 POST X6.5 MENS RR - WT - INT PLUMB - TOILET CLOGGED - [redacted] - 549-4485	Repair
11946442	3C - Low Sustain	3C - 3001 POST 083 - WT - INT PLUMB - SECOND SINK FROM DOOR ON OP AISLE IS CLOGGED - [redacted] - 736-5776	Repair
11949993	3C - Low Sustain	3C - 3001 POST 3S-69 MENS RR - WT - INT PLUMB - CLOGGED URINAL, BAGGED - [redacted] - 622-7855	Repair
11951238	3C - Low Sustain	3C - 3001 FLT-P19W and P19E - WT - HVAC PM - Vacuum water from coil leak - [redacted] - 582-9513	Repair
11956927	3A - High Sustain	3A - 3001 POST 2AF72 WOMENS RR - WT - INT PLUMB - TOILET CLOGGED & VERY CLOSE TO OVERFLOWING - [redacted] - 370-1490	Repair
11962546	3A - High Sustain	3A - 3001 POST 1AI-78A - WT - SPRINK - HEARING LEAKING IN CEILING, SUSPECTS ITS THE FIRE SUPPRESSION SYSTEM AGAIN - [redacted] - 736-8707	Repair
11962880	3B - Medium Sustain	C/O 3B - 3001 POST 1AI-78A - WT - INT PLUMB - HEARING LEAKING IN CEILING, SUSPECTS ITS THE FIRE SUPPRESSION SYSTEM AGAIN - [redacted] - 736-8707	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

11964721	3B - Medium Sustain	3B - 3001 POST Y90 MENS RR - WT - INT PLUMB - MOP DRAIN IS CLOGGED - [redacted] - 736-5776	Repair
11966388	3B - Medium Sustain	3B - 3001 POST 3S69 - WT - HVACC - VAV5 NOT INSULATED/LEAKING AT THE DUCT ONTO CEILING TILES - [redacted] - 622-7855	Repair
11969917	3B - Medium Sustain	3B - 3001 POST X23 - WT - INT PLUMB - WASH BASIN IS LEAKING ON FLOOR - [redacted] - 734-0408	Repair
11993896	3B - Medium Sustain	3B - 3001 POST X64 - WT - INT PLUMB - CLOGGED SINK IN BREAKROOM - [redacted] - 736-5776	Repair
12020174	3B - Medium Sustain	3B - 3001 DOOR G47 - WT - ROOF - ROOF LEAKING ONTO ELECTRONICS - [redacted] - 410-7686	Repair
12020515	3B - Medium Sustain	3B - 3001 BETWEEN POST Y-109 & Y-110 - WT - HONEYWELL - LEAK RAINING ONTO ELECTRICAL EQUIPMENT - [redacted] - 417-8194	Repair
12023348	3B - Medium Sustain	3B - 3001 POST2AH19 - WT - ROOF - LEAK IN ROOF - [redacted] - 405-736-3537	Repair
12023969	3B - Medium Sustain	3B - 3001 Post Y-55 Men's R/R - WT - Intplumb - Bagged urinal overflows - [redacted] - 734-0408 - SR 3176566	Repair
12023988	3A - High Sustain	3A - 3001 POST N49 WOMEN'S RR - WT - INT PLUMB - TOILET OVERFLOWING, WATER OUT TO HALLWAY - [redacted] - 370-1490	Repair
12027193	3A - High Sustain	3A - 3001 POST E-99 - WT - INT PLUMB - LEAKING BACKFLOW PREVENTER - [redacted] - 736-5776	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12028793	3A - High Sustain	3A - 3001 POST N49 - WT - INT PLUMB - MULTIPLE TOILETS OVERFLOWING ONTO THE FLOOR - [redacted] - 736-2085	Repair
12034677	1-Emergency	1 - 3001 ANNEX G SW CORNER EXT - WT - EXT PLUMB - GAS LEAK REPORTED BY FIRE DEPT - [redacted] - 734-7964	Repair
12034851	3B - Medium Sustain	3B - 3001 POST O95 - WT - HVACC - ISOLATION VALVE LEAKING - [redacted] - 734-9377	Repair
12045583	3B - Medium Sustain	3B - 3001 POST 083 - WT - INT PLUMB - 5 TOILETS IN MENS RR CLOGGED - [redacted] - 405-736-5776	Repair
12045591	3B - Medium Sustain	3B - 3001 POST 093 - WT - INT PLUMB - TOILET CLOGGED - [redacted] - 405-736-5776	Repair
12045596	3B - Medium Sustain	3B - 3001 POST 0103 - WT - INT PLUMB - TOILET CLOGGED - [redacted] - 405-736-5776	Repair
12052333	3A - High Sustain	3A - 3001G ROOM 104 - WT - HVACC - LEAK COMING FROM CRAC UNITS - [redacted] - 492-2496	Repair
12057061	3A - High Sustain	3A - 3001 POST I63 - WT - HVACC - UNIT P800/GAS LEAK ALARM WENT OFF BUT EVERYTHING WAS NORMAL - [redacted] - 734-7964	Repair
12057441	3B - Medium Sustain	3B - 3001 POST O95 - WT - PIPE - ISOLATION VALVE LEAKING - [redacted] - 734-9377	Repair
12062981	3C - Low Sustain	3C - 3001 POST 1AH1/105A - WT - INT PLUMB - TOILET CLOGGED - [redacted] - 734-9028	Repair
12063006	3C - Low Sustain	3C - 3001 POST 1AB/106C - WT - INT PLUMB - TOILET IS CLOGGED - [redacted] - 734-9028	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12063040	3C - Low Sustain	3C - 3001 POST 2AF/71 - WT - INT PLUMB - TOILET IS CLOGGED - [redacted] - 734-9028	Repair
12065217	3C - Low Sustain	3C - 3001 Post 1AD85A - WT - INTPLUMB - handicap stall has clogged toilet - [redacted] 734-9028 - SR3193258	Repair
12069957	3B - Medium Sustain	3B - 3001 Post M-47 Inside Tank & Cooler - WT - Intplumb - Handicap toilet plugged up, pipes leak. - Repair - [redacted] - 736-2085 - SR 3196155	Repair
12075647	3A - High Sustain	3A - 3001 88710H - WT - HVACC - LEAK FROM CEILING NEAR ELEC PANEL - [redacted] - 734-3161	Repair
12077641	3A - High Sustain	3A - 3001 NW Annex - WT - ROOF - Rain is leaking on Cardxe - [redacted] 622-2156 Temp WT RM102502	Repair
12078575	3A - High Sustain	3A - 3001 88710H - WT - INT PLUMB - F/U 12075647 LEAK FROM CEILING NEAR ELEC PANEL - [redacted] - 734-3161	Repair
12079293	3A - High Sustain	3A - 3001 POST 2Q81 - WT - INT PLUMB - BOTH MEN AND WOMEN BATHROOMS TOILETS OVERFLOWING - [redacted] - 734-0086	Repair
12080508	3A - High Sustain	3A - 3001 POST Z77 - WT - HVACC - HOOD VENTS FLOODING - [redacted] - 405-736-8772	Repair
12080693	3A - High Sustain	3A - 3001 POST 2G77 - WT - ROOF - F/U 12080508 HOSE FROM CEILING IF FLOODING LAB - [redacted] - 405-736-8720	Repair
12081020	3A - High Sustain	3A - 3001 ANNEX G BOILER RM - WT - INT PLUMB - DRAIN BEHIND BOILERS IS CLOGGED - [redacted] - 246-8579 - KS102008	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

12087688	3A - High Sustain	3A - 5947 RM 120 - WT - SMART PLUMB - TOILET CLOGGED, INOP - [redacted] - 734-4421 - TW102103	Repair
12088587	3C - Low Sustain	3C - 3001 POST 2G81 - WT - STRUC - RECURRING LEAK IN CEILING - [redacted] - 855-3017	Repair

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Work Location	Responsible Organization	Planned Start(Respond Date)
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	04/18/2022 10:17:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	04/18/2022 10:17:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - CUSTOMER SERVICE UNIT	04/18/2022 10:17:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	05/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/14/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 09:55:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 10:10:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 10:12:27

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 10:17:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 13:46:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 13:48:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 13:51:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 13:54:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 13:58:59
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 14:01:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 14:03:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 14:05:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 14:06:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 14:08:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 14:10:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 14:12:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/15/2022 19:04:05

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/16/2022 07:04:59
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/16/2022 07:53:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	05/16/2022 09:14:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/16/2022 09:20:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/16/2022 13:45:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/17/2022 10:39:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/17/2022 10:43:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/17/2022 15:17:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/18/2022 08:04:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/18/2022 08:41:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/18/2022 09:53:57

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/18/2022 09:42:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/18/2022 15:34:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/19/2022 12:06:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/19/2022 14:02:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - AFTER HRS - BOS-BMC	05/19/2022 19:39:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/20/2022 09:41:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	05/20/2022 10:17:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PLANT OPS - INDUSTRIAL WASTEWATER TRMT - MAINT - BOS-BMC	05/23/2022 08:23:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - PLANT OPS - INDUSTRIAL WASTEWATER TRMT - MAINT - BOS-BMC	05/23/2022 08:40:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/23/2022 20:42:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/24/2022 07:53:03

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/24/2022 08:09:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/24/2022 08:06:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/23/2022 09:26:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	05/24/2022 09:54:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/24/2022 10:55:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/24/2022 12:42:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/24/2022 12:52:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/24/2022 15:30:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/25/2022 06:51:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/25/2022 07:39:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/25/2022 08:34:12

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 09:41:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/25/2022 15:23:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/25/2022 18:41:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/25/2022 18:46:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	05/25/2022 18:53:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/25/2022 20:15:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 20:39:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 20:41:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/25/2022 20:43:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 02:18:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 02:22:41

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 02:42:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 02:53:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 06:13:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 06:15:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 06:52:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 07:50:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 07:59:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:28:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:28:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:31:43
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:31:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:34:29

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:34:27
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:36:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:36:43
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:38:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 08:38:45
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 12:06:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/26/2022 17:47:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 17:53:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 18:52:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	05/26/2022 19:44:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 19:45:48

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/26/2022 20:09:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/27/2022 04:08:43
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/27/2022 06:33:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/27/2022 08:14:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/27/2022 08:53:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/27/2022 12:43:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/31/2022 07:25:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	05/31/2022 07:52:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/31/2022 13:26:09
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	05/31/2022 15:52:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	05/31/2022 15:57:27

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	05/31/2022 19:26:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/01/2022 06:31:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/01/2022 08:46:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	06/01/2022 11:19:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/02/2022 11:13:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/02/2022 11:15:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/03/2022 13:34:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/05/2022 17:14:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/06/2022 06:01:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/06/2022 09:34:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/07/2022 08:39:57

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/07/2022 09:07:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/07/2022 09:37:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/08/2022 07:22:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/08/2022 09:21:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/08/2022 09:57:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	06/08/2022 10:33:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	06/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - INTERIOR - BOS-BMC	06/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/09/2022 07:11:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/09/2022 07:13:38

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/09/2022 07:44:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/10/2022 08:10:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	06/13/2022 13:32:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/14/2022 07:01:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/14/2022 09:34:46
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	06/15/2022 14:49:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/16/2022 09:55:07
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/16/2022 11:15:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/22/2022 07:04:29
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/23/2022 11:03:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/24/2022 08:56:35

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/24/2022 13:58:56
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	06/27/2022 14:04:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/28/2022 07:10:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/28/2022 09:38:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/29/2022 09:32:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/29/2022 14:51:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/30/2022 09:36:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	07/03/2022 14:30:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	07/03/2022 14:33:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/05/2022 13:57:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/05/2022 14:32:59

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/05/2022 14:41:34
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/07/2022 12:17:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/08/2022 07:18:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	07/08/2022 09:09:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/08/2022 09:27:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/09/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	07/11/2022 07:18:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SUB - MOLD REMED - BOS-BMC	07/11/2022 11:23:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/12/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/14/2022 08:58:34

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	07/15/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/15/2022 07:53:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/18/2022 11:21:39
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/19/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/20/2022 09:13:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/21/2022 09:47:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/24/2022 01:05:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/25/2022 07:09:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	07/25/2022 11:48:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/26/2022 11:24:21

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	07/27/2022 07:27:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	07/27/2022 08:02:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	07/29/2022 08:10:38
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	07/29/2022 13:39:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/29/2022 23:30:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	08/01/2022 06:57:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	08/01/2022 07:31:35
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	08/01/2022 07:34:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	08/01/2022 13:27:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/01/2022 15:14:17

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/02/2022 18:27:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/03/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - AFTER HRS - BOS-BMC	08/05/2022 12:29:18
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/05/2022 13:43:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/05/2022 16:09:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/05/2022 16:32:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	08/08/2022 04:19:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB EXT - BOS-BMC	08/09/2022 07:18:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	08/10/2022 10:41:40

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/11/2022 14:40:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/12/2022 09:02:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/12/2022 09:22:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/12/2022 09:37:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/12/2022 11:06:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/15/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/17/2022 08:05:13
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/17/2022 13:15:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/18/2022 07:09:51
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/18/2022 08:38:20

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/18/2022 09:15:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/18/2022 14:42:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/19/2022 08:35:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/19/2022 10:14:05
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/22/2022 10:36:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/23/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/22/2022 15:05:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/23/2022 09:31:50
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/23/2022 10:23:03
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - AFTER HRS - BOS-BMC	08/23/2022 16:14:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/24/2022 08:07:47

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	08/24/2022 10:33:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/24/2022 11:14:06
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	08/25/2022 09:37:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	08/25/2022 10:19:30
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/25/2022 10:21:37
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/25/2022 10:24:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/25/2022 12:09:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/29/2022 08:55:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/30/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	08/30/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/30/2022 12:12:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/30/2022 13:07:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/31/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/31/2022 08:51:15
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	08/31/2022 09:29:47
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	08/31/2022 10:29:25
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/31/2022 12:05:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	09/02/2022 13:59:26
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/08/2022 10:37:28

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/08/2022 13:54:21
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	09/08/2022 14:41:23
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/09/2022 07:25:19
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/09/2022 10:40:49
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	09/09/2022 10:44:53
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/09/2022 10:57:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/13/2022 07:38:17
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	09/13/2022 07:43:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	09/14/2022 08:17:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ALARM SHOP - BOS-BMC	09/14/2022 08:17:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	09/16/2022 01:00:00

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/16/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	09/16/2022 09:59:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/16/2022 15:09:32
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/19/2022 07:53:04
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/19/2022 10:00:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/19/2022 10:00:58
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/19/2022 10:02:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	09/19/2022 11:33:02
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/19/2022 11:55:12
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	09/19/2022 18:31:11

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	09/21/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/22/2022 13:17:42
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/22/2022 15:07:10
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/24/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/26/2022 07:56:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/27/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - PM - BOS-BMC	09/27/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/28/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC	09/28/2022 08:07:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/28/2022 08:46:04

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/28/2022 11:12:22
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	09/29/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/29/2022 08:10:55
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/04/2022 09:45:57
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	10/11/2022 07:42:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	10/11/2022 08:20:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	10/12/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/12/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/11/2022 15:23:40
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/12/2022 08:40:46

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/12/2022 12:14:31
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB EXT - BOS-BMC	10/13/2022 11:24:01
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/13/2022 11:49:11
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/17/2022 08:22:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/17/2022 08:24:28
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	10/17/2022 08:25:31
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/18/2022 08:12:41
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/19/2022 08:37:33
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	10/19/2022 09:21:44
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/26/2022 11:34:52
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/26/2022 11:37:16

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/26/2022 11:40:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/27/2022 01:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/27/2022 07:00:00
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/27/2022 13:37:36
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	10/27/2022 21:29:20
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/28/2022 08:04:14
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/28/2022 09:55:08
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - HVAC SHOP - C - BOS-BMC	10/28/2022 13:58:24
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - ROOF - BOS-BMC	10/28/2022 14:40:54
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/28/2022 15:43:31

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - SPEC MX TM - SMART PLUMBING - BOS-BMC	10/31/2022 07:42:48
\Locations\TINKER AFB SITE 1\3001 - 1211932	TINKER AFB - STRUCTURE SHOP - BOS-BMC	10/31/2022 11:31:22

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Tracking Status	Status	SR ID	Requested By (FM)
	Rejected	2881304	[redacted]
	Rejected	2881321	[redacted]
	[redacted]		
	Closed	2925627	[redacted]
	Closed	2925649	[redacted]
	[redacted]	[redacted]	[redacted]
	[redacted]	[redacted]	9
	Closed		
	Closed		
	Closed		

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed	2926812	[redacted]
Closed	2926954	[redacted]
[redacted]		
[redacted]		
[redacted]		
[redacted]		
[redacted]		
[redacted]		
[redacted]		
[redacted]	[redacted]	[redacted]
Closed		

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed 2937316 [redacted]

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

Closed

Closed

Closed

Closed 2942184 [redacted]

Closed

Closed

Closed

Closed

Closed

Closed

Closed 2944047 [redacted]

[redacted]

[redacted] is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
	Completed
	Closed
Maintenance Complete	Completed
	Closed
	Closed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
	Closed
Maintenance In Progress	Completed
	Closed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Closed

Completed

Closed

Closed

Closed

Closed

Completed

Closed

Maintenance In Progress Completed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed
	Closed
	Closed
	Closed
	Completed
	Completed
Maintenance Complete	Completed
	Completed
	Closed
	Completed
	Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Completed

Closed

Closed

Closed

Closed

Closed 2966858 [redacted]

Closed 2966864 [redacted]

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Completed

Closed

Closed

Completed

Closed

Completed 2981450 [redacted]

Closed

Closed

Closed 2991482 [redacted]

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Closed

Completed

Closed

Completed

Closed

Closed

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed

Completed

Closed

Closed

Closed 3014798 [redacted]

Closed 3015430 [redacted]

Closed

Closed 3017871 [redacted]

Closed 3019590 [redacted]

Closed 3025145 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

Closed	3025978	[redacted]
Closed	3027428	[redacted]
Closed		
Closed	3030950	[redacted]
Completed		
Closed	3038492	[redacted]
Closed		
Closed	3042151	[redacted]

[redacted]

[redacted]

[redacted] is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Completed	
	Closed	3057193 [redacted]
	Closed	
	Closed	
Maintenance In Progress	Completed	
	Closed	
	Closed	
	Closed	3065519 [redacted]
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	
	Closed	
	Closed	
	Completed	
	Closed	
	Closed	3081107 [redacted]
	Closed	
Awaiting Scheduling	Completed	
	Closed	
	Closed	3085457 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

	Closed	3085615 [redacted]
	Closed	
	Closed	3087959 [redacted]
[redacted]	[redacted]	
	Closed	
	Closed	3091796 [redacted]
Maintenance Complete	Completed	
Maintenance Complete	Completed	3093668 [redacted]
	Closed	
	Closed	
	Closed	3096131 [redacted]

[redacted] is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

[redacted]

Closed 3096762 [redacted]

Completed

Closed 3099169 [redacted]

[redacted]

Closed 3099360 [redacted]

[redacted]

[redacted]

[redacted]

[redacted]

Closed 3105065 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed	3105732 [redacted]
Closed	
Completed	
Closed	3108667 [redacted]
Closed	3109624 [redacted]
Closed	
Closed	
Closed	
Closed	
Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Closed		
Closed		
Closed		
Closed	3123996	[redacted]
Closed	3124013	[redacted]
Closed	3124058	[redacted]
Closed	3128420	[redacted]
Closed	3128440	[redacted]
Closed		
Closed		
Closed	3135033	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Awaiting Scheduling	Completed	3135183 [redacted]
	Closed	3136425 [redacted]
	Closed	
	Closed	3138226 [redacted] 99
Awaiting Scheduling	Completed	3138732 [redacted]
[redacted]	Completed	3138741 [redacted]
Awaiting Scheduling	Completed	3138746 [redacted]
	Closed	3139152 [redacted]
	Closed	3139249 [redacted]
	Closed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	Closed	3143502 [redacted]
	Closed	
	Closed	
	Closed	3149523 [redacted]
	Closed	3150804 [redacted]
Awaiting Scheduling	Completed	3151822 [redacted]
	Closed	3152026 [redacted]
	Closed	3154410 0 [redacted]
	Closed	
Maintenance In Progress	Completed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

Closed	3156432	[redacted]
Closed	3156827	[redacted]
Closed	3158171	[redacted]
[redacted]	[redacted]	
[redacted]		
[redacted]	[redacted]	
[redacted]	[redacted]	[redacted]
[redacted]	[redacted]	[redacted]
[redacted]		
[redacted]		

[redacted] is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

	Closed		
Maintenance Complete	Completed		
Maintenance Complete	Completed		
Awaiting Scheduling	Completed	3184938	[redacted]
Awaiting Scheduling	Completed	3184943	[redacted]
	Closed	3184949	[redacted]
Maintenance In Progress	Completed		
Maintenance Complete	Completed		
Awaiting Scheduling	Completed	3190669	[redacted]
Awaiting Scheduling	Completed	3191344	[redacted]
Awaiting Scheduling	Completed	3191365	[redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Awaiting Scheduling	Completed	3191396 [redacted]
	[redacted]	[redacted]
[redacted]	[redacted]	[redacted] 139
Maintenance In Progress	Completed	
Maintenance Complete	Completed	
Awaiting Scheduling	Completed	
Awaiting Scheduling	Completed	
Awaiting Scheduling	Completed	
Awaiting Scheduling	Completed	
Maintenance Complete	Completed	

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Maintenance Complete	Completed	
Awaiting Scheduling	Active	3203059 [redacted]

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Customer Organization

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - AFOSI DET 114

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 AMXG

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFSC

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 SFS

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKER AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 448 SCMW - 66

\Organizations\Customers\TINKER AFB - 72 CES

\Organizations\Customers\TINKER AFB - 448 SCMW - 66

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - VACANT

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKER AFB - 72 CS

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - OC ALC FM

\Organizations\Customers\TINKER AFB - 72 CS

\Organizations\United States Air Force\A4C USAF\Air Force Materiel Command

\Organizations\Customers\TINKER AFB - 72 CS

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKER AFB - 448 SCMW - 66

\Organizations\Customers\TINKER AFB - 72 CES

\Organizations\Customers\TINKER AFB - OC ALC FM

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - AFSC

\Organizations\Customers\TINKER AFB - AFSC

\Organizations\Customers\TINKER AFB - AFSC

\Organizations\Customers\TINKER AFB - 448 SCMW - 66

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKER AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - OC ALC FM

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - AFLCMC

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 448 SCMW - 66

\Organizations\Customers\TINKE
R AFB - 72 ABW

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 FSS RESTAURANT - 97

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

\Organizations\Customers\TINKER AFB - 72 CES DORMS

\Organizations\Customers\TINKER AFB - DLA AVIATION SS&D

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

RK TASK 11757760

WORK TASK DETAILS

TASK PRIORITY	3B - Me Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	
		TRACKING STATUS			
RESPONSIBLE ORG	TINKE SYSTE		ND FUELS T - BOS-BMC	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKE		SAG-M) - 63G		
TASK TYPE	Correc	**EST CLASS**	Overflows	**PRINTED DATE**	
EST HOURS	0	**NED START**	08/18/2022 09:15:02	**PLANNED END**	
TASK NAME	3B - 30 0408	- INT PLUMB - INSPECT ALL URINALS FOR OVERFLO			LES - 734-
TASK DESCRIPTION	BLDG IT APP WATER INSPC CONTA P.O.C.	ENS RR - AST MOST URINAL WAS OVERFLOWING. THE FLO E WATER VALVE TO THE SUSPECTED URINAL. ALL LOWING OTHER THAN THE MOST EAST URINAL. M VERIFIED THAT THE URINAL IS NOT OVERFLOWIN S 734-0408			TANDING BE D.
FOREMAN'S NOTES TO CRAFTSMEN	__ Safe __ Digg	quired d	__Multi-Shop Coordination Required __Environmental Coordination Required	__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required	

SERVICE REQUEST DE

WT 11757760

REQUEST ID	ATED DATE/TIME	FULL NAME	WORK PHONE
3085615	0 /18/2022 09:11:43	STEVEN GONZALES	(405) 734-0408

FACILITY PROJECT DE

WT 11757760

ASSET DETAILS

WT 11757760

WARRANTY DETAILS

WT 11757760

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11757760

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11757760

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11757760**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11757760**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11757760**

Additional Notes: **WT 11757760**

PROCEDURE STEP DETAILS **WT 11757760**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11578681

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TIN [redacted] 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Fire Suppression	**PRINTED DATE**	Mar [redacted] M
EST HOURS		**PLANNED START**	07/03/2022 14:33:02	**PLANNED END**	07/0 14:3
TASK NAME	3B - 3001 POST X12 - WT - SPRINK - SMALL LEAK FROM SPRINK PIPE - REPAIR - [redacted] - 620-2589				
TASK DESCRIPTION	MAY BE A SLIP & FALL HAZARD				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required _ D/S OMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11578681

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11578681

ASSET DETAILS

WT 11578681

WARRANTY DETAILS

WT 11578681

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11578681

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11578681

Primary Maintenance Reason Code

WT 11578681

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

NOTES TO R&O ON ASSETS & LOCATION **WT 11578681**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11578681**

Additional Notes: **WT 11578681**

PROCEDURE STEP DETAILS **WT 11578681**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11578680

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TIN [redacted] 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Fire Suppression	**PRINTED DATE**	Mar [redacted] M
EST HOURS		**PLANNED START**	07/03/2022 14:30:44	**PLANNED END**	07/0 14:3
TASK NAME	3B - 3001 POST X15 - WT - SPRINK - SMALL LEAK FROM SPRINK PIPE - REPAIR - [redacted] - 620-2589				
TASK DESCRIPTION	MAY BE A SLIP & FALL HAZARD				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required _ D/S OMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11578680

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11578680

ASSET DETAILS

WT 11578680

WARRANTY DETAILS

WT 11578680

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11578680

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11578680

Primary Maintenance Reason Code

WT 11578680

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

NOTES TO R&O ON ASSETS & LOCATION			WT 11578680
ASSET STATUS	**GEOSPATIAL LOCATION**		
__SMS Update Required (Record Comments in Asset Notes)	___ Point	___ Line	___ Area
__Asset Condition Changed	__ Removed Asset	Primary Latitude: _____	Secondary Lat: _____
__Asset Replaced/Added		Primary Longitude: _____	Secondary Lon: _____

Asset Notes:	WT 11578680

Additional Notes:	WT 11578680

PROCEDURE STEP DETAILS			WT 11578680
STEP	**PROCEDURE TEXT**	**DURATION**	**PROCEDURE ID**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11570420

WORK TASK D			
TASK PRIORITY	**STATUS** Closed **TRACKING STATUS**	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3001
RESPONSIBLE ORG	- WATER AND FUELS - PLUMB INT - BOS-	**RESPONSIBLE PERSON**	Chad Vance(NU)
CUSTOMER ORG	- 76 MXW (CSAG-M) - 63G		
TASK TYPE	**REQUEST CLASS** Building Services	**PRINTED DATE**	Mar 3, 2023, 8:15 PM
EST HOURS	**PLANNED START** 06/30/2022 09:36:58	**PLANNED END**	06/30/2022 09:36:58
TASK NAME	ST X-19 - WT - INT PLUMB - F/U 11551182 REPAIR LEAKING EYE WASH STATION - Repair - 417-8194		
TASK DESCRIPTION	E HIT BY A TUGGER - BROKE A PIPE - SHUT OFF VALVE BENT - NOTHING LEAKING BUT N O AT, STATION ALSO HIT AND NOW LOOSE ON FLOOR AND LEAKING EQUESTER CALLED BACK TO INFORM THAT LOCKERS HAVE BEEN MOVED NOW AND T READY TO BE WORKED ON		
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required	__Multi-Shop Coordination Required __Environmental Coordination Required	__ FD/SFS/COMM/__ Coordination Req __ Travel/Access Clearanc ed

SERVICE REQUEST DETAILS — WT 11570

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHON

FACILITY PROJECT DETAILS — WT 11570420

ASSET DETAILS — WT 11570420

WARRANTY DETAILS — WT 11570420

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11570420

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11570420**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11570420**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11570420**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11570420**

Additional Notes: **WT 11570420**

PROCEDURE STEP DETAILS **WT 11570420**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K TASK 11969917

WORK TASK DETAILS

TASK PRIORITY	3B - Me Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	T 001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKE SYSTE		FUELS BOS-BMC	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKE		AG-M) - 63G		
TASK TYPE	Correc	**ST CLASS**	Leaks	**PRINTED DATE**	M
EST HOURS	0	**ED START**	09/29/2022 08:10:55	**PLANNED END**	
TASK NAME	3B - 30		NT PLUMB - WASH BASIN IS LEAKING ON FLOOR		- 734-0408
TASK DESCRIPTION	BUILD WASH SEE A P.O.C.		N FLOOR CREATING A SLIP/FALL HAZARD. 734-0408		
FOREMAN'S NOTES TO CRAFTSMEN	__ Saf __ Dig		ed __Multi-Shop Coordination Required __Environmental Coordination Required		/_____ Required ance Required

SERVICE REQUEST DE 1969917

REQUEST I	ED DATE/TIME	FULL NAME	PHONE
3158171	0 /2022 08:01:42	STEVEN GONZALES	(34-0408

FACILITY PROJECT DE WT 11969917

ASSET DETAILS WT 11969917

WARRANTY DETAILS WT 11969917

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11969917

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11969917

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11969917**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11969917**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11969917**

Additional Notes: **WT 11969917**

PROCEDURE STEP DETAILS **WT 11969917**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

118447

PRIMARY LOCATIO AFB SITE 1-3001

RESPON PERSON

ces **PRINTED** 23, 10:20 PM

PLANNE 2

EAKING WATER 4204404

TER THROUGH WHITE HOUSE, GOING

ON SITE.
WATER TO FA
REPAIR WHILE LLOW AREA TO DRY IN
R LABOR & OPEN FOLLOW

NO PARTS R

F/U HVACC W 9132 INT ELEC WT#11849336

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Pre __Multi-Shop Coordination Re D/SFS/COMM/_____
Coordination Required

__ Digging Pe __Environmental Coordination Access Clearance Required

SERVICE REQUEST DETAILS **WT 11844759**

REQUEST ID	C	DATE/TIME	FULL NAM	WORK PHONE

FACILITY PROJECT DETAILS **WT 11844759**

ASSET DETAILS **WT 11844759**

WARRANTY DETAILS **WT 11844759**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11844759**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11844759**

Primary Maintenance Reason Code **WT 11844759**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11844759**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11844759**

Additional Notes: **WT 11844759**

PROCEDURE STEP DETAILS **WT 11844759**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11853723

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Leaks	**PRINTED DATE**	0 5 PM
EST HOURS	0	**PLANNED START**	09/09/2022 10:57:32	**PLANNED END**	
TASK NAME	3B - 3001 POST 2X56 - WT - INT PLUMB - PLUMBING LEAK IN THE CEILING -			L	- 736-5776
TASK DESCRIPTION	there is a plumbing leak in the ceiling @ post 2X56				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Required __Environmental Coordination Required	F C el/A	COMM/_____ ation Required Clearance Required

SERVICE REQUEST DETAILS — WT 11853723

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE
3124058	09/09/2022 10:55:31	MICHAEL BLAKE	(405) 736-5776

FACILITY PROJECT DETAILS — WT 11853723

ASSET DETAILS — WT 11853723

WARRANTY DETAILS — WT 11853723

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11853723

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 11853723**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11853723**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11853723**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11853723**

Additional Notes: **WT 11853723**

PROCEDURE STEP DETAILS **WT 11853723**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11993896

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	E 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**PRINTED DATE**	0 PM
EST HOURS	0	**PLANNED START**	10/04/2022 09:45:57	**PLANNED END**	
TASK NAME	3B - 3001 POST X64 - WT - INT PLUMB - CLOGGED SINK IN BREAKROOM - M				736-5776
TASK DESCRIPTION	clogged sink in the break room Bldg 3001 post X64				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Required		/COMM/_____
	__ Digging Permit Required		__Environmental Coordination Required	I/	nation Required s Clearance Required

SERVICE REQUEST DETAILS

WT 11993896

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE
3165405	10/04/2022 09:44:38	MICHAEL BLAKE	(405) 736-5776

FACILITY PROJECT DETAILS

WT 11993896

ASSET DETAILS

WT 11993896

WARRANTY DETAILS

WT 11993896

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11993896

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11993896

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11993896**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11993896**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11993896**

Additional Notes: **WT 11993896**

PROCEDURE STEP DETAILS **WT 11993896**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

RK TASK 1194116

WORK TASK DETAIL

TASK PRIORITY	3C -	**STATUS**	Closed	**PRIMARY W LOCATION**	SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINK SYS	D FUELS T - BOS-BMC		**RESPONS PERSON**	U)
CUSTOMER ORG	TINK	SAG-M) - 63G			
TASK TYPE	Corr	**EST CLASS**	Clogs	**PRINTED D**	:14 PM
EST HOURS	0	**NED START**	09/24/2022 01:00:00	**PLANNED**	
TASK NAME	3C -	NS RR - WT - INT PLUMB - TOILET CLOGGED			- 549-4485
TASK DESCRIPTION	POC BLD/ MEN	405-549-4485 ET BAD			
FOREMAN'S NOTES TO CRAFTSMEN	__ Sa	quired	__Multi-Shop Coordination Requ		S/COMM/_____ dination Required
	__ Di	ed	__Environmental Coordination R		ss Clearance Required

SERVICE REQUEST DETAILS — WT 11941164

REQUEST ID	CREATED DATE/TIME	FULL NAM	WORK PHONE
3149523	09/23/2022 13:09:09	DAMON WILLI	405-549-4485

FACILITY PROJECT DETAILS — WT 11941164

ASSET DETAILS — WT 11941164

WARRANTY DETAILS — WT 11941164

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11941164

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ — WT 11941164

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11941164**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11941164**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11941164**

Additional Notes: **WT 11941164**

PROCEDURE STEP DETAILS **WT 11941164**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

OR A K **11367630**

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	Closed	**PRIMARY WORK LOCATION**	TIN	3001
RESPONSIBLE ORG	TINKER AFB - HV BMC	HC	**RESPONSIBLE PERSON**		
CUSTOMER ORG	TINKER AFB - 76	(C G			
TASK TYPE	Corrective	QU AC Service	**PRINTED DATE**	Mar	
EST HOURS	0	AN /16/2022 53:51	**PLANNED END**	05/1 07:5	
TASK NAME	3A - 3001 X81 - W SR#2926954	VA K FROM CONDENSATE DRAIN - Repair			- 736-4500 -
TASK DESCRIPTION	WATER LEAK FRO ON DOUG MILLER 73 00 16MAY2022 7:05 N FIE 16MAY2022 7:52 R E SITE NO MATERIALS FO D				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautio eq	ulti-Shop Coordination Required		__ FD/SFS/COMM/_____ Coordination Required	
	__ Digging Permit R ired	nvironmental Coordination Required		__Travel/Access Clearance Required	

SERVICE REQUEST DETAILS

WT 11367630

REQUEST ID	CREATED DATE/T	FULL NAME	WORK PHONE
2926954	05/16/2022 07:48	ERIC HOWELL	405-734-3761

FACILITY PROJECT DETAILS

WT 11367630

ASSET DETAILS

WT 11367630

WARRANTY DETAILS

WT 11367630

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11367630

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11367630**

Primary Maintenance Reason Code **WT 11367630**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11367630**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11367630**

Additional Notes: **WT 11367630**

PROCEDURE STEP DETAILS **WT 11367630**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

	[redacted]	WORK TASK		11378084	
WORK TASK D	[redacted]				
TASK PRIORITY	[redacted]	STATUS TRACKING STATUS	Closed	PRIMARY WORK LOCATION	1
RESPONSIBLE ORG	[redacted]	R AND FUELS B INT - BOS-BMC		RESPONSIBLE PERSON	[redacted]
CUSTOMER ORG	[redacted]	I DET 114			
TASK TYPE	[redacted]	REQUEST CLASS	Building Services	PRINTED DATE	
EST HOURS	[redacted]	PLANNED START	05/18/2022 08:04:20	PLANNED END	
TASK NAME	[redacted]	11 BREAKROOM - WT - PLUMB INT - BREAKROOM SINK			[redacted]
TASK DESCRIPTION	[redacted]	REAKROOM SINK CLOGGED 7365716			
FOREMAN'S NOTES TO CRAFTSMEN	ty ing	ns Required equired	__Multi-Shop Coordination Require __Environmental Coordination Required		[redacted] uired

SERVICE REQUEST DETAILS

REQUEST ID	CREATED DATE/TIME	FULL NAME

FACILITY PROJECT DETAILS

ASSET DETAILS WT 11378084

WARRANTY DETAILS WT 11378084

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11378084

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ WT 11378084

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11378084**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11378084**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11378084**

Additional Notes: **WT 11378084**

PROCEDURE STEP DETAILS **WT 11378084**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

W TASK 11717369

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**TATUS CKING ATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AF
RESPONSIBLE ORG	TINKER AFB - WATE SYSTEM MX - PLUM BMC		ELS S-	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MX		) - 63G		
TASK TYPE	Corrective	**R**	**LASS** Leaks	**PRINTED DATE**	Mar 3, 2023
EST HOURS	0	**P**	**TART** 08/09/2022 07:18:23	**PLANNED END**	08/09/2022 07:18:23
TASK NAME	3B - 61024 - WT - EX 734-0408		FIRE HYDRANT LEAK EXT BLDG 3001 POST Y14 - REPAIR		ZALES
TASK DESCRIPTION	3001 EXTERIOR POS FIRE HYDREN LEAK EN WORSE. NEEDS PERSONNEL TO EVALUATE THE EXTENT OF DA GE P.O.C. STEVE GON 0408 9AUG22 1240 - PER THIS IS OCWUT, NOTIFIED OCWUT.				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions __ Digging Permit Re		__Multi-Shop Coordination Required __Environmental Coordination Required	__ FD/SFS/COMM/_ Coordination Re __Travel/Access Clearan	ed equired

SERVICE REQUEST DETAILS — WT 117 69

REQUEST ID	C	DATE/TIME	FULL NAME	WORK PHO E
3065519	0	22 07:14:28	STEVEN GONZALES	(405) 734-0 3

FACILITY PROJECT DETAILS — WT 117 69

ASSET DETAILS — WT 1171 69

WARRANTY DETAILS — WT 11717369

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11717369

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ **WT 11717369**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11717369**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11717369**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11717369**

Additional Notes: **WT 11717369**

PROCEDURE STEP DETAILS **WT 11717369**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11533525

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustain	**STATUS**	Close	**PRIMARY WORK LOCATION**	TINKER
		TRACKING STATUS	[redacted]		
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**RESPONSIBLE PERSON**	[redacted]
CUSTOMER ORG	TINKER AFB - 7				
TASK TYPE			Build rvices	**PRINTED DATE**	Mar 3, 20
EST HOURS	[redacted]		06/22 07:04	**PLANNED END**	06/22/202 07:04:29
TASK NAME	3A - 3001 post		er is g out of the A/C down the wall - repair -		- 734-1929
TASK DESCRIPTION	3001 Post Y26,		own all		

21JUN2022 07 AY
21JUN2022 07 HAR L ON SITE
21JUN2022 09 ELT SE; FOUND THE UNIT HAD COPPER LINES CONDENSATING HEAVILY; GOT EW AND INSULATION; INSULATED LINES AND REPLACED BELT; CHARGE
1.5 HRS;
CLOSE WT

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Preca __Mu op Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Perm __Env mental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11533525

REQUEST ID	ME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11533525

ASSET DETAILS

WT 11533525

WARRANTY DETAILS

WT 11533525

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11533525

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11533525

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11533525**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11533525**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11533525**

Additional Notes: **WT 11533525**

PROCEDURE STEP DETAILS **WT 11533525**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

		ASK	**11752833**		
WORK TASK DETAILS					
TASK PRIORITY	3A - High Susta	**TATUS** Closed **CKING TATUS**		**PRIMARY WO LOCATION**	AFB SITE 1-3001
RESPONSIBLE ORG	TINKER AFB - W SYSTEM MX -	LS S-BMC		**RESPONSIB PERSON**	
CUSTOMER ORG	TINKER AFB - 7	) - 63G			
TASK TYPE		**LASS** Building Services		**PRINTED DA**	23, 4:47 PM
EST HOURS		**START** 08/17/2022 08:05:13		**PLANNED E**	2
TASK NAME	3A - 3001 Y53 -	- 3 TOILETS OVERFLOWING - Repair -			E 7365776
TASK DESCRIPTION	AT POST Y53 IN 17AUG2022 081 17AUG2022 101 CLEANED UP M NO PARTS USE	RESTROOM THERE ARE 3 TOILETS OV ON SITE NOTES: HAD TO PULL TOILET TO RUN			LINE. RESET TOILET AND
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precau __ Digging Permit Required	__Multi-Shop Coordination Requir __Environmental Coordination Re			D/SFS/COMM/_____ Coordination Required Access Clearance Required

SERVICE REQUEST DETAILS **WT 11752833**

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS **WT 11752833**

ASSET DETAILS **WT 11752833**

WARRANTY DETAILS **WT 11752833**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11752833**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11752833**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11752833**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11752833**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11752833**

Additional Notes: **WT 11752833**

PROCEDURE STEP DETAILS **WT 11752833**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

K TASK 20239

WORK TASK DETAILS

TASK PRIORITY	3B - M Susta	**STATUS** **TRACKING STATUS**	Closed	**PRIMARY LOCATION**	FB SITE 1-3001
RESPONSIBLE ORG	TINK SYST	FUELS - BOS-BMC		**RESPONS PERSON**	
CUSTOMER ORG	TINK	SAG-M) - 63G			
TASK TYPE	Corre	**EST CLASS**	Other Plumbing Need	**PRINTED D**	3, 4:56 PM
EST HOURS	0	**NED START**	10/12/2022 01:00:00	**PLANNED**	2
TASK NAME	3B - 3	R/R - WT - Intplumb - Bagged urinal overflows			734-0408 - SR 3176566
TASK DESCRIPTION	BUILD 1 URN P.O.C 12OCT	MENS REST ROOM N THE FAR WEST SIDE AND THE CENTER U 734-0408 LS ARE NOW BAGGED			WS WHEN IT FLUSHES.
FOREMAN'S NOTES TO CRAFTSMEN	__ Saf __ Digging Permit Required	uired __Environmental Coordination Required	__Multi-Shop Coordination Required	__ Travel/Access Clearance Required	__ FD/SFS/COMM/_____ Coordination Required

SERVICE REQUEST DETAILS — WT 12023969

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE
3176566	10/11/2022 15:18:27	STEVEN GONZALES	(405) 734-0408

FACILITY PROJECT DETAILS — WT 12023969

ASSET DETAILS — WT 12023969

WARRANTY DETAILS — WT 12023969

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 12023969

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 12023969**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12023969**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12023969**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12023969**

Additional Notes: **WT 12023969**

PROCEDURE STEP DETAILS **WT 12023969**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

11433

WORK TASK DETAILS

TASK PRIORITY	3A - High Susta	**PRIMAR LOCATI**	AFB SITE 1-3001
RESPONSIBLE ORG	TINKER AFB - W SYSTEM MX -	**RESPO PERSO**	
CUSTOMER ORG	TINKER AFB - 7		
TASK TYPE	rvices	**PRINTE**	023, 2:45 PM
EST HOURS		**PLANN**	022 3
TASK NAME	3A - 3001 POST	BACK UP - Repai	- 7369977
TASK DESCRIPTION	SEWER FLOOR 01JUN2022 8:50 01JUN2022 9:03 01JUN2022 9:28 TIMES AND NO	S RESTROOM FOUND NO BAC NO ISSUE PRESE	LUSHED ALL TOILETS 3 ASK. 0.5 HOUR LABOR
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precau __ Digging Permit Required	hop Coordination R __Environmental Coordinatio	FD/SFS/COMM/_____ Coordination Required l/Access Clearance Required

SERVICE REQUEST DETAILS — **WT 11433475**

REQUEST ID	CREATED DATE/TIME	FULL N	WORK PHONE

FACILITY PROJECT DETAILS — **WT 11433475**

ASSET DETAILS — **WT 11433475**

WARRANTY DETAILS — **WT 11433475**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 11433475**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ **WT 11433475**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Primary Maintenance Reason Code **WT 11433475**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11433475**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11433475**

Additional Notes: **WT 11433475**

PROCEDURE STEP DETAILS **WT 11433475**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11363062

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	T E 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - ELECTRICAL SYSTEMS - SPRINKLERS - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	- 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Fire Suppression	**PRINTED DATE**	M PM
EST HOURS		**PLANNED START**	05/14/2022 01:00:00	**PLANNED END**	0 0
TASK NAME	t Y-62 - WT - SPRINK - Pressure Gauge Leaking from Knob - Repair - S-P204				- 736-9977 - SR#
TASK DESCRIPTION	ost Y-62. There are two pressure gauges connected to the fire sprink inspection tag king from the knob. 736-9977 S REQUIRED				bottom gauge that
FOREMAN'S NOTES TO CRAFTSMEN	autions Required rmit Required	__Multi-Shop Coordination Required __Environmental Coordination Required		__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required	

SERVICE REQU **WT 11363062**

REQUE	CREATED DATE/TIME	FULL NAME	WORK PHONE
29256	05/13/2022 13:12:31	KARRI HOOD	405-734-3117

FACILITY PROJ S **WT 11363062**

ASSET DETAILS **WT 11363062**

WARRANTY DETAILS **WT 11363062**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11363062**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11363062**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11363062**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11363062**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11363062**

Additional Notes: **WT 11363062**

PROCEDURE STEP DETAILS **WT 11363062**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11762016

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AFB
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**PRINTED DATE**	Mar 6, 2023,
EST HOURS	0	**PLANNED START**	08/19/2022 10:14:05	**PLANNED END**	08/19/2022 10:14:05
TASK NAME	3B - 3001 POST Y63 - WT - INT PLUMB - MENS RR HAS CLOGGED AND BAGGED URINAL [redacted] - 622-7855				
TASK DESCRIPTION	Men's RR post Y-63 has clogged and bagged urinal.				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Required		__ FD/S Coo
	__ Digging Permit Required		__Environmental Coordination Required		__Travel/Acc d

SERVICE REQUEST DETAILS

REQUEST ID	CREATED DATE/TIME	FULL NAME
3088274	08/19/2022 10:10:49	MICHAEL KESSLER

FACILITY PROJECT DETAILS

ASSET DETAILS

WT 11762016

WARRANTY DETAILS

WT 11762016

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11762016

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____ WT 11762016

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11762016**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11762016**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11762016**

Additional Notes: **WT 11762016**

PROCEDURE STEP DETAILS **WT 11762016**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK [redacted] 149810

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Completed	**PRIMARY W**	FB SITE 1-3001
		TRACKING STATUS		**LOCATION**	
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**RESPONSIB PERSON**	ger(NU)
CUSTOMER ORG	2 CS				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED D**	3, 8:06 PM
EST HOURS	[redacted]	**PLANNED START**	06/14/2022 09:34:46	**PLANNED E**	2
TASK NAME	78 - WT - HVACC - A/C INOP AND LEAKING - REPAIR				- 4922496
TASK DESCRIPTION	R IS NOT WORKING PROPERLY, AND THEY IS OIL LE HVAC HAD REQUESTED THIS BE CALLED IN				NIT PANEL
FOREMAN'S NOTES TO CRAFTSMEN	ons Required Required	__Multi-Shop Coordination Required __Environmental Coordination Required		__ FD/SFS/COMM/_____ Coordination Required __Travel/Access Clearance Required	

SERVICE REQU **WT 11498108**

REQU	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PRO **WT 11498108**

ASSET DETAIL **WT 11498108**

WARRANTY DE **WT 11498108**

ID	EAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11498108**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11498108**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11498108**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11498108**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11498108**

Additional Notes: **WT 11498108**

PROCEDURE STEP DETAILS **WT 11498108**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

ASS **WT 11664576**

WARRANTY DETAILS **WT 11664576**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION **WT 11664576**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11664576**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11664576**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11664576**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11664576**

Additional Notes: **WT 11664576**

PROCEDURE STEP DETAILS **WT 11664576**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11757033

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	
EST HOURS	504	**PLANNED START**	08/18/2022 07:09:51	**PLANNED END**	
TASK NAME	3B - 3001 POST Y90 - WT - HVACC - HVAC IS LEAKING ON THE FLOOR - MIC				776
TASK DESCRIPTION	SENT VIA EMAIL				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required		__Multi-Shop Coordination Required __Environmental Coordination Required		MM/_____ n Required arance Required

SERVICE REQUEST DETAILS 11757033

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS WT 11757033

ASSET DETAILS WT 11757033

WARRANTY DETAILS WT 11757033

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11757033

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ WT 11757033

Primary Maintenance Reason Code WT 11757033

__ Abuse / Malevolent Act	__Accident/Event	__Corrosion	__Solid State	__Off-base Source	__Weather	__Tree/Vegetation
__ Cust Request/Directed	__Environmental	__Mechanical	__Structural	__Operator/Techn	__Wildlife	__Fire/Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

NOTES TO R&O ON ASSETS & LOCATION			WT 11757033
ASSET STATUS	**GEOSPATIAL LOCATION**		
__SMS Update Required (Record Comments in Asset Notes)	___ Point	___ Line	___ Area
__Asset Condition Changed __ Removed Asset	Primary Latitude: _____		Secondary Lat: _____
__Asset Replaced/Added	Primary Longitude: _____		Secondary Lon: _____
Asset Notes:			WT 11757033
Additional Notes:			WT 11757033
PROCEDURE STEP DETAILS			WT 11757033
STEP	**PROCEDURE TEXT**	**DURATION**	**PROCEDURE ID**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 11964721

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	U)
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**PRINTED DATE**	M M
EST HOURS	0	**PLANNED START**	09/28/2022 11:12:22	**PLANNED END**	
TASK NAME	3B - 3001 POST Y90 MENS RR - WT - INT PLUMB - MOP DRAIN IS CLOGGED -				- 736-5776
TASK DESCRIPTION	building 3001 post Y90 men's restroom the mop drain is clogged				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Required		MM/_____
	__ Digging Permit Required		__Environmental Coordination Required _		ion Required learance Required

SERVICE REQUEST DETAILS

T 11964721

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE
3156432	09/28/2022 11:10:41	MICHAEL BLAKE	(405) 736-5776

FACILITY PROJECT DETAILS

WT 11964721

ASSET DETAILS

WT 11964721

WARRANTY DETAILS

WT 11964721

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11964721

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11964721

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11964721**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11964721**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11964721**

Additional Notes: **WT 11964721**

PROCEDURE STEP DETAILS **WT 11964721**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11414027

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AFB
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPONSIBLE PERSON**	Franklin Ma
CUSTOMER ORG	TINKER AFB - 76 AMXG				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	Mar 6, 2023
EST HOURS		**PLANNED START**	05/26/2022 06:13:05	**PLANNED END**	05/26/2022 06:13:05
TASK NAME	3C - 3001 POST Y90 - WT - INTPLUMB - URINAL CLOGGED & BAGGED - REPAIR - T6350 - -				· 582-4340
TASK DESCRIPTION	POST Y90 - MENS RR URINAL IS CLOGGED AND BAGGED				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required	__Multi-Shop Coordination Required		__ FD Co	___ ed
	__ Digging Permit Required	__Environmental Coordination Required		__Travel/Ac	Required

SERVICE REQUEST DETAILS 27

REQUEST ID	CREATED DATE/TIME	FULL NAME	E

FACILITY PROJECT DETAILS 27

ASSET DETAILS 027

WARRANTY DETAILS WT 11414027

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11414027

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11414027**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11414027**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11414027**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11414027**

Additional Notes: **WT 11414027**

PROCEDURE STEP DETAILS **WT 11414027**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

8245403

S NOTES: REPAIRED FL
1 HOUR LABOR. NO PA
ation Required
rdination Required __Trav

EP IT FROM
S
O _____
tion Required
Clearance Required

QU T 11933391

UES FULL NAME ORK PHONE

OJE WT 11933391

ASSET DETAILS WT 11933391

WARRANTY DETAILS WT 11933391

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11933391

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 11933391

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.
CUI

Primary Maintenance Reason Code **WT 11933391**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11933391**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11933391**

Additional Notes: **WT 11933391**

PROCEDURE STEP DETAILS **WT 11933391**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 1603

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMA LOCA**	NKER AFB SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESP PERS**	
CUSTOMER ORG	TINKER AFB - 76 MXW (CSAG-M) - 63G				
TASK TYPE	Corrective	**REQUEST CLASS**	Clogs	**PRIN**	ar 6, 2023, 3:20 PM
EST HOURS	0	**PLANNED START**	07/08/2022 09:27:36	**PLAN**	/08/2022 :27:36
TASK NAME	3B - 3001 Y 104 - WT - INT PLUMB - UNCLOG URINAL - Repair -				5824340
TASK DESCRIPTION	Men's RR at post Y-104 URINAL is clogged				
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination		__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required		__Environmental Coordina		_Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11603870

REQUEST ID	CREATED DATE/TIME	FULL	ME	WORK PHONE
3014798	07/08/2022 09:20:51	CARL	RCIA	(405)582-4340

FACILITY PROJECT DETAILS

WT 11603870

ASSET DETAILS

WT 11603870

WARRANTY DETAILS

WT 11603870

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11603870

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11603870

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11603870**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11603870**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11603870**

Additional Notes: **WT 11603870**

PROCEDURE STEP DETAILS **WT 11603870**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

	12020515
WORK TASK DE	
TASK PRIORITY	mpleted aintenance In ogress
PRIMARY WORK LOCATION	TINKER AFB SITE 1-3001
RESPONSIBLE ORG	
RESPONSIBLE PERSON	
CUSTOMER ORG	
TASK TYPE	of Leak
PRINTED DATE	Mar 6, 2023, 2:16 PM
EST HOURS	/11/2022 :20:44
PLANNED END	11/01/2022 08:20:44
TASK NAME	- WT - HONEYWELL - LEAK RAINING ONTO ELECTRICAL EQUIPMENT -
TASK DESCRIPTION	ISSUE IS HONEYWELL LINE THAT IS HAVING CONDENSATION ISSUES

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Preca ed __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Perm __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS — **WT 12020515**

REQUEST ID	ED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — **WT 12020515**

ASSET DETAILS — **WT 12020515**

WARRANTY DETAILS — **WT 12020515**

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — **WT 12020515**

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ **WT 12020515**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12020515**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12020515**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12020515**

Additional Notes: **WT 12020515**

PROCEDURE STEP DETAILS **WT 12020515**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

W K TASK 12081020

WORK TASK DETAILS

TASK PRIORITY	3A - High Susta	**STATUS**	Completed	**PRIMARY WORK LOCATION**	TINKER AFB
		RACKING STATUS	Maintenance Complete		
RESPONSIBLE ORG	TINKER AFB - SYSTEM MX -	TER UMB	FUELS BOS-BMC	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB -	CES			
TASK TYPE		R	T CLASS Clogs	**PRINTED DATE**	Mar 6, 2023, 4
EST HOURS		P	D START 10/28/2022 15:43:31	**PLANNED END**	10/28/2022 15:43:31
TASK NAME	3A - 3001 ANN 8579 - KS1020	G B	RM - WT - INT PLUMB - DRAIN BEHIND BOILERS IS CLOGGED		INS - 246-
TASK DESCRIPTION	DRAIN BEHIN	OIL	TOPPED UP		
	20OCT22 145	NT	BRUCE IRICK		
	20OCT22 150	UC	ON SITE		
	20OCT22 160	ICK	: TRIED TO SNAKE DRAIN WITH NO LUCK. UNABLE TO UNSTO		RA , BUT THERE
	IS ANOTHER COMPLETE.	OR	IN AREA. WILL DISCUSS WITH SUPERVISOR ABOUT REPAIR. C		RG 1 HR LABOR &
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Prec ons		ed __Multi-Shop Coordination Required		__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Per	Req	__Environmental Coordination Required		__Travel/Access Clearance Required

SERVICE REQUEST DETAILS — WT 12081020

REQUEST ID	C	ED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — WT 12081020

ASSET DETAILS — WT 12081020

WARRANTY DETAILS — WT 12081020

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 12081020

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ — **WT 12081020**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 12081020**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12081020**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12081020**

Additional Notes: **WT 12081020**

PROCEDURE STEP DETAILS **WT 12081020**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11418160

WORK TASK D	IL				
TASK PRIORITY	-	Sustain	**STATUS** Closed **TRACKING STATUS**	**PRIMARY WORK LOCATION**	E 1-3001
RESPONSIBLE ORG	INK MC	AFB - HVAC SHOP - C - BOS-		**RESPONSIBLE PERSON**	NU)
CUSTOMER ORG	INK	AFB - 76 MXW (CSAG-M) - 63G			
TASK TYPE			**REQUEST CLASS** Building Services	**PRINTED DATE**	PM
EST HOURS	0		**PLANNED START** 05/26/2022 17:47:55	**PLANNED END**	
TASK NAME	C - ULL	01 OLD HORSESHOE - WT - HVACC - LEAKING PUMP ON REDUNDAN S - 734-5856 - -			AIR - T2385
TASK DESCRIPTION	EPA	LEAKING PUMP ON REDUNDANT CHILLER IN THE OLD HORSESHOE			

FOREMAN'S NOTES TO CRAFTSMEN

_ Sa ety Precautions Required
__Multi-Shop Coordination Required
__ FD/SFS/COMM/_____ Coordination Required
__ Digging Permit Required
__Environmental Coordination Required
__Travel/Access Clearance Re

SERVICE REQUEST DETAILS — WT 11418160

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — WT 11418160

ASSET DETAILS — WT 11418160

WARRANTY DETAILS — WT 11418160

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11418160

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ **WT 11418160**

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11418160**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11418160**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11418160**

Additional Notes: **WT 11418160**

PROCEDURE STEP DETAILS **WT 11418160**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 1385 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS**	Closed	**PRIMAR LOCATIO**	1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPON PERSON**	NU)
CUSTOMER ORG	TINKER AFB - 72 CS				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTE**	PM
EST HOURS		**PLANNED START**	05/19/2022 12:06:49	**PLANNE**	

TASK NAME 3B - 3001 G DOOR G15 - WT - INT PLUMB - WATER LEAK - Repair -

TASK DESCRIPTION WATER LEAKING FROM WALL UNDER CABINET, STATES LEAKING OF WALL. ITS BELOW COFFEE MACHINE IN CABINET. CALL AHEAD SO THEY CA ET INTO 3001 G

STEADY DRIP, HAVE TOWELS DOWN TO CONTAIN

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11385381

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11385381

ASSET DETAILS

WT 11385381

WARRANTY DETAILS

WT 11385381

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11385381

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __

WT 11385381

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11385381**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11385381**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11385381**

Additional Notes: **WT 11385381**

PROCEDURE STEP DETAILS **WT 11385381**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 14535 [redacted]

WORK TASK DETAILS

TASK PRIORITY	3B - Medium Sustain	**STATUS TRACKING STATUS**	Completed	**PRIMARY LOCATION**	B SITE 1-3001
RESPONSIBLE ORG	TINKER AFB - HVAC SHOP - C - BOS-BMC			**RESPONS PERSON**	rwell(NU)
CUSTOMER ORG	TINKER AFB - 72 CS				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED D**	3, 7:42 PM
EST HOURS	504	**PLANNED START**	06/06/2022 09:34:00	**PLANNED**	
TASK NAME	3B - 3001 ANNEX G & ROOM 104 - WT - HVACC - STOP LEAK - Repair				- 4095733
TASK DESCRIPTION	CRAC UNIT #6 APPEARS TO BE LEAKING IN ROOM 104, THE DATA C				HE RAISED FLOOR.

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Requi _ D/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11453577

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS

WT 11453577

ASSET DETAILS

WT 11453577

WARRANTY DETAILS

WT 11453577

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11453577

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _

WT 11453577

Primary Maintenance Reason Code

WT 11453577

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

NOTES TO R&O ON ASSETS & LOCATION **WT 11453577**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11453577**

Additional Notes: **WT 11453577**

PROCEDURE STEP DETAILS **WT 11453577**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

96

K AND

NOW. SEAL

ired

Required

SERVICE REQU 2333

REQUES NE

FACILITY PROJE 2333

ASSET DETAILS WT 12052333

WARRANTY DETAILS WT 12052333

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 12052333

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _ _ _ _ _ _ WT 12052333

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

CUI

Primary Maintenance Reason Code **WT 12052333**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 12052333**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 12052333**

Additional Notes: **WT 12052333**

PROCEDURE STEP DETAILS **WT 12052333**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

[redacted]

WORK TASK 1641

WORK TASK DETAILS

TASK PRIORITY	3C - Low Sustain	**STATUS**	Closed	**PRIMAR LOCATIO**	AFB SITE 1-3001
		TRACKING STATUS			
RESPONSIBLE ORG	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC			**RESPON PERSON**	
CUSTOMER ORG	TINKER AFB - 72 CS				
TASK TYPE	Corrective	**REQUEST CLASS**	Other Plumbing Need	**PRINTED**	2023, 2:51 PM
EST HOURS	0	**PLANNED START**	07/19/2022 01:00:00	**PLANNE**	022 0
TASK NAME	3C - 3001G ROOM 104 - WT - INT PLUMB - SEWER SMELL - REPAIR				- 7364731
TASK DESCRIPTION	Investigate and repair sewage odor coming from underneath the raised				G room 104.
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required		__Multi-Shop Coordination Req		__ FD/SFS/COMM/_____ Coordination Required
	__ Digging Permit Required		__Environmental Coordination Required		__Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11641897

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE
3030950	07/18/2022 12:00:45	MICHAEL MORGAN	405-736-4731

FACILITY PROJECT DETAILS

WT 11641897

ASSET DETAILS

WT 11641897

WARRANTY DETAILS

WT 11641897

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11641897

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** _____

WT 11641897

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11641897**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11641897**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11641897**

Additional Notes: **WT 11641897**

PROCEDURE STEP DETAILS **WT 11641897**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11413514

WORK TASK D			
TASK PRIORITY	**STATUS** Closed **TRACKING STATUS**	**PRIMARY WORK LOCATION**	-3001
RESPONSIBLE ORG	VAC SHOP - C - BOS-	**RESPONSIBLE PERSON**	
CUSTOMER ORG	MXW (CSAG-M) - 63G		
TASK TYPE	**REQUEST CLASS** Building Services	**PRINTED DATE**	
EST HOURS	**PLANNED START** 05/25/2022 20:39:38	**PLANNED END**	
TASK NAME	G, RM 125, NW - WT - HVACC - FF/LEAKING DISCHARGE VA 582-9513 - - PCHW-GL118-1		10 -
TASK DESCRIPTION	LACE LEAKING DISCHARGE VALVE ON PCHW-GL118-1, 05-229-6348; 118-1 SENT VIA EMAIL"		
FOREMAN'S NOTES TO CRAFTSMEN	__ Safety Precautions Required __ Digging Permit Required	__Multi-Shop Coordination Required __Environmental Coordination Required	__ FD/SFS/COMM/__ Coordination Req __Travel/Access Clearanc d

SERVICE REQUEST DETAILS WT 1141

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHO

FACILITY PROJECT DETAILS WT 11413514

ASSET DETAILS WT 11413514

WARRANTY DETAILS WT 11413514

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION WT 11413514

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ WT 11413514

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11413514**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11413514**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11413514**

Additional Notes: **WT 11413514**

PROCEDURE STEP DETAILS **WT 11413514**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11413516

WORK TASK DE

TASK PRIORITY	[redacted]	**STATUS**	Closed	**PRIMARY WORK LOCATION**	3001 [redacted]
		TRACKING STATUS			
RESPONSIBLE ORG	HVAC SHOP - C - BOS-			**RESPONSIBLE PERSON**	
CUSTOMER ORG	76 MXW (CSAG-M) - 63G				
TASK TYPE		**REQUEST CLASS**	Building Services	**PRINTED DATE**	M
EST HOURS		**PLANNED START**	05/25/2022 20:41:27	**PLANNED END**	0 2
TASK NAME	X G, RM 125, NW - WT - HVACC - FF/LEAKING DISCHARGE VA - 582-9513 - - PCHW-GL118-2				11 -
TASK DESCRIPTION	PLACE LEAKING DISCHARGE VALVE ON PCHW-GL118-2. 405-229-6348; 118-2 SENT VIA EMAIL "				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/__ Coordination Req

__ Digging Permit Required __Environmental Coordination Required __ Travel/Access Clearanc [redacted] d

SERVICE REQUEST DETAILS — WT 11413

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — WT 11413516

ASSET DETAILS — WT 11413516

WARRANTY DETAILS — WT 11413516

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11413516

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ — WT 11413516

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11413516**

__ Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/ Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/ Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11413516**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11413516**

Additional Notes: **WT 11413516**

PROCEDURE STEP DETAILS **WT 11413516**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

WORK TASK 11812083

WORK TASK DE					
TASK PRIORITY	stain	**STATUS**	Closed	**PRIMARY WORK LOCATION**	TINKER AFB SITE 1-3
		TRACKING STATUS			
RESPONSIBLE ORG	- STRUCTURE SHOP -			**RESPONSIBLE PERSON**	
CUSTOMER ORG	- 72 CS				
TASK TYPE		**REQUEST CLASS**	Other Interior Need	**PRINTED DATE**	Mar 3, 2023, 10:15 PM
EST HOURS		**PLANNED START**	08/31/2022 09:29:47	**PLANNED END**	08/31/2022 09:29:47
TASK NAME	RM 203 - WT - STRUC - F/U 11809131 REPLACE DAMAGED CEILING TILE FROM LEAK - KE 736-4730				
TASK DESCRIPTION	1 - 3A - 3001G RM 203 - WT - HVACC - LEAK HAS COLLAPSED CEILING TILE ABOVE FIL G CABINET - HAM - 736-4730				
	- 31AUG22 0928 - HARWELL/RAMSEY NOTES: FOUND VAV LEAKING DUE TO CONDENS ION & LACK O TION ON DUCT. GATHERED MATERIALS FROM SHOP & INSULATED DUCT. CLEANED UP MESS. OPEN F TRUC TO REPLACE DAMAGED CEILING TILES				

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precautions Required __Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS — WT 11812083

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE

FACILITY PROJECT DETAILS — WT 11812083

ASSET DETAILS — WT 11812083

WARRANTY DETAILS — WT 11812083

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION — WT 11812083

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

Resolution Description / Notes: __ Outage **Outage Event ID#** __ __ __ __ __ — WT 11812083

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Primary Maintenance Reason Code **WT 11812083**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11812083**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11812083**

Additional Notes: **WT 11812083**

PROCEDURE STEP DETAILS **WT 11812083**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

K	11809131

WORK TASK DETAILS

TASK PRIORITY	3A - High Sustai	**PRIMARY WORK LOCATION**	TINKER AFB SI [redacted]
RESPONSIBLE ORG	TINKER AFB - H[redacted] BMC	**RESPONSIBLE PERSON**	
CUSTOMER ORG	TINKER AFB - 7[redacted]		
TASK TYPE	Corrective [redacted] r Need	**PRINTED DATE**	Mar 3, 2023, 10 [redacted]
EST HOURS	0	**PLANNED END**	08/31/2022 01:00:00
TASK NAME	3A- 3001G Roo [redacted] osed ceiling tile above filing cabinet - repair - [redacted] 405-409-5733 - SR3 [redacted]		
TASK DESCRIPTION	A ceiling tile has [redacted] able to determine if it was from a sprinkler pip [redacted] quest both shops to in [redacted] Mission Impact: [redacted] Another leak could cause damage to docume [redacted] s cabinet. 31AUG22 0658 [redacted] ON SITE 31AUG22 0738 [redacted] D VAV-18 LEAKING IN ROOM 209, SPOKE T [redacted] R AND INFORMED. CH[redacted] R LABOR 31AUG22 0746 [redacted] 31AUG22 0753 [redacted] EY ON SITE. 31AUG22 0928 [redacted] ND VAV LEAKING DUE TO CONDENSATION & LACK O[redacted] INSULATION ON[redacted] ROM SHOP & INSULATED DUCT. CLEANED UP MESS [redacted] N F/U FOR STRUC TO[redacted] ES. CHARGE 1.5 HOUR LABOR. WORK TASK COMPL[redacted] F/U WT# 118120		

FOREMAN'S NOTES TO CRAFTSMEN

__ Safety Precau _Multi-Shop Coordination Required __ FD/SFS/COMM/_____ Coordination Required

__ Digging Permit Required __Environmental Coordination Required __Travel/Access Clearance Required

SERVICE REQUEST DETAILS

WT 11809131

REQUEST ID	CREATED DATE/TIME	FULL NAME	WORK PHONE
3108667	08/30/2022 17:00:57	JAKE LANGHAM	(405) 736-4730

FACILITY PROJECT DETAILS

WT 11809131

ASSET DETAILS

WT 11809131

WARRANTY DETAILS

WT 11809131

ID	REAL PROPERTY WARRANTY NAME	ID	BUILDING EQUIPMENT WARRANTY NAME

CRAFTSMAN NOTES SECTION

WT 11809131

ASSIGNED CRAFTSMAN NAME(S)	DATE (MM/DD/YYYY)	TOTAL LABOR HOURS	OVERTIME HRS	TRAVEL TIME HRS

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.

Resolution Description / Notes: __ **Outage** **Outage Event ID#** _ _ _ _ _ _ **WT 11809131**

Primary Maintenance Reason Code **WT 11809131**

__Abuse / Malevolent Act __Accident/Event __Corrosion __Solid State __Off-base Source __Weather __Tree/Vegetation

__ Cust Request/Directed __Environmental __Mechanical __Structural __Operator/Techn __Wildlife __Fire/Overheating

NOTES TO R&O ON ASSETS & LOCATION **WT 11809131**

ASSET STATUS

__SMS Update Required (Record Comments in Asset Notes)

__Asset Condition Changed __ Removed Asset

__Asset Replaced/Added

GEOSPATIAL LOCATION

___ Point ___ Line ___ Area

Primary Latitude: _____ Secondary Lat: _____

Primary Longitude: _____ Secondary Lon: _____

Asset Notes: **WT 11809131**

Additional Notes: **WT 11809131**

PROCEDURE STEP DETAILS **WT 11809131**

STEP	PROCEDURE TEXT	DURATION	PROCEDURE ID

This is a protected document. It will not be released (in whole or in part), reproduced, or given additional dissemination (in whole or in part) outside of Inspector General channels without prior approval of The Inspector General (SAF/IG) or designee.