

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - OC ALC FM

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - TINKER FEDERAL CREDIT
UNION

\Organizations\Customers\TINKE
R AFB - TINKER FEDERAL CREDIT
UNION

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - VACANT

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\United States Air
Force\A4C USAF\Air Force
Materiel Command

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\United States Air
Force\A4C USAF\Air Force
Materiel Command

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 SFS

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 SFS

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - VACANT

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - DLA DLR

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW KC46A (CSAG-
M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 WOAP

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\United States Air
Force\A4C USAF\Air Force
Materiel Command

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CS

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW (CSAG-M) - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 SFS

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - DLA AVIATION SS&D

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 76 MXW TAC 9000 - 63G

\Organizations\Customers\TINKE
R AFB - 72 CES

\Organizations\Customers\TINKE
R AFB - 72 CES

Open Work Tasks - CUI/SP-FNC

02/23/2023 13:06:59

Task ID	Task Priority	Task Name	Work Classification
11352627	3C - Low Sustain	3C - 9001 CC44 - WT - IntPlumb - Clogged floor drain - Repair - [REDACTED] - SR2921199	Repair
11354226	3C - Low Sustain	REJECT - 9001 - CHILL WATER LEAK	Repair
11363640	3B - Medium Sustain	3B - 9001 POST CC44 - WT - INT PLUMB - CLOGGED DRAIN - Repair - [REDACTED] - 405-582- 4196 - SR#2925946	Repair
11363650	3B - Medium Sustain	3B - 9001 Post BB55/CC56 South - WT - PLUMB INT- Domestic Water Line leaking - Repair - [REDACTED] 582-4496 - SR#2925951	Repair
11363806	1-Emergency	1 - 9001 Post S/T-44 - WT - INT PLUMB - Leak flooding area - Repair - IWIMS# - Requestor - Phone - SR# - Delay Status - UID	Repair
11364775	3B - Medium Sustain	3B - 9001 POST V44 - WT - INTPLUMB - LEAK FROM SEWER PIPE - Repair - T5482 - [REDACTED] [REDACTED] - 405-736-3801	Repair
11364831	3B - Medium Sustain	3B - 9001 POST M21 - WT - TAC STRUC - ROOF LEAK - Repair - T5995 - [REDACTED] - 582- 4105	Repair
11364832	3B - Medium Sustain	3B - 9001 POST Q20 - WT - TAC STRUC - ROOF LEAK - Repair - T5996 - [REDACTED] - 582- 4105	Repair
11364834	3B - Medium Sustain	3B - 9001 POST X25 - WT - TAC STRUC - ROOF LEAK - Repair - T6007 - [REDACTED] - 582- 4105	Repair
11364835	3B - Medium Sustain	3B - 9001 POST EE51 - WT - TAC STRUC - ROOF LEAK - Repair - T6245 - [REDACTED] - 405- 582-4105	Repair

11368252	3B - Medium Sustain	3B - 9001 POSTS P21, P22 - WT - TAC STRUC- ROOF LEAKS AT POSTS P21, P22 - SENT VIA EMAIL - Repair - T5994 - [REDACTED] - 582-4105 - 0 - 0	Repair
11368259	3B - Medium Sustain	3B - 9001 POST H19 - WT - TAC STRUC- ROOF LEAKS AT POST H19 - Repair - T5998 - [REDACTED] - 582-4105 - 0 - 0	Repair
11368275	3B - Medium Sustain	3B - 9001 B52 2S17 - WT - TAC STRUC - ROOF LEAK 2ND FLOOR, CURRENTLY CONTAINED - Repair - T6111 - [REDACTED] - 623-0072 - 0 - 0	Repair
11372813	3B - Medium Sustain	3B - 9001 POST B7 - WT - TAC STRUC - ROOF LEAK WHEN RAINING - REPAIR - [REDACTED] - 323-0319 - SR#2928929	Repair
11372818	3B - Medium Sustain	3B - 9001 POST D8 - WT - TAC STRUC - ROOF LEAKS WHEN RAINING - REPAIR - [REDACTED] - 323-0319 - SR#2929836	Repair
11372970	3B - Medium Sustain	3B - 9001 POST BB24 - WT - TAC HVAC - ASH HOUSE 76 LEAK- REPAIR - [REDACTED] - 582-4105	Repair
11373189	3B - Medium Sustain	3B - 9001 POST BB23 - WT - TAC HVAC - ASH HOUSE LEAKING - REPAIR - [REDACTED] - 323-0319	Repair
11373324	3B - Medium Sustain	3B - 9001 POST BB26 - WT - TAC HVAC - ASH HOUSE 77 LEAK- REPAIR - [REDACTED] - 582-4105	Repair
11381498	3A - High Sustain	3A - 9001 POST B51 MENS RR - WT - INTPLUMB - TOILET OVERFLOWED & CLOGGED - Repair - [REDACTED]	Repair
11384047	3B - Medium Sustain	3B - 9001 POST B55 - WT - TAC PIPE - WATER LEAK - Repair - IWIMS#T5879 - [REDACTED] - 5824496 - SR#2934794 - REF#T5879	Repair

11384059	3B - Medium Sustain	DEFAULT - Work Task Template - Corrective Maintenance-Leaks	Repair
11392442	3B - Medium Sustain	3B - 9001 POST W-44 - WT - INT PLUMB - CAMERA 4 INCH SEWER LINE - Repair - [REDACTED] - 734- 7223	Repair
11396951	3B - Medium Sustain	3B - 9001 & POST F-6 - WT - TAC ROOF - FIX LEAK - Repair - [REDACTED] - 582-4105	Repair
11397851	3B - Medium Sustain	3B - 9001 POST 2G39 - WT - INT PLUMB - TOILET CLOG - Repair - [REDACTED] - 8337049	Repair
11401599	3A - High Sustain	3A - 9001 BETWEEN POSTS L51 AND L52 - WT - TAC STRUC - ROOF LEAKING PRETTY BAD - Repair - [REDACTED] - 550- 9580	Repair
11401963	3B - Medium Sustain	3B - 9001 POST S34 - WT - INTPLUMB - STORM DRAIN LEAK - REPAIR - [REDACTED] - 582- 4495	Repair
11402232	3B - Medium Sustain	3B - 9001 BETWEEN POSTS L51 AND L52 - WT - TAC STRUC - F/U 11401599 ROOF LEAKING PRETTY BAD - Repair - [REDACTED] - 550-9580	Repair
11403540	3B - Medium Sustain	3B - 9001 & MEZZ 2 2T43 CUBE #86 - WT - TAC ROOF - FIX ROOF LEAK - Repair - [REDACTED] - 5821118 - STORM	Repair
11403613	3A - High Sustain	3A - 9001 POST AA40 - WT - TAC ROOF - ROOF LEAKING ONTO ELECTRICAL BOX ON POLE - Repair - [REDACTED] - 736-2207	Repair
11403652	3B - Medium Sustain	3B - 9001 5FT EAST OF POST AA38 - WT - TAC ROOF - ROOF LEAK - Repair - [REDACTED] [REDACTED] 736-2207	Repair
11403676	3B - Medium Sustain	3B - 9001 BETWEEN POSTS BB40 AND CC40 - WT - TAC ROOF - ROOF LEAK - Repair - [REDACTED] [REDACTED] - 736-2207	Repair

11403902	3B - Medium Sustain	3B - 9001 POST 2T41 - WT - TAC STRUC - CEILING TILE BROKEN FROM ROOF LEAK - REPAIR - [REDACTED] 582-4105	Repair
11403984	3B - Medium Sustain	3B - 9001 POST W43 - WT - TAC STRUC - STORM DRAIN LEAKING - REPAIR - [REDACTED] 582- 4105	Repair
11403993	3B - Medium Sustain	3B - 9001 POST L23 BREAKROOM - WT - TAC STRUC - ROOF LEAK INTO BREAKROOM - REPAIR - [REDACTED] 582-4105	Repair
11404063	3B - Medium Sustain	3B - 9001 POST 2T41 - WT - TAC STRUC - ROOF LEAK THROUGH CEILING TILE - REPAIR - [REDACTED] [REDACTED] 582-4105	Repair
11404075	3B - Medium Sustain	3B - 9001 POST S30 - WT - TAC STRUC - ROOF LEAK - REPAIR - [REDACTED] 582-4105	Repair
11404764	3B - Medium Sustain	3B- 9001 POST H67 - WT - ROOF - ROOF LEAK - REPAIR - [REDACTED] [REDACTED] - 6227846 - STORM	Repair
11404805	3B - Medium Sustain	3B- 9001 POST Q38 - WT - ROOF - ROOF LEAK - REPAIR - [REDACTED] [REDACTED] - 6227846 - STORM	Repair
11404883	3B - Medium Sustain	3B - 9001 POST AA40 - WT - TAC ROOF - FOLLOW UP 11403613 REPAIR ROOF LEAK - REPAIR - [REDACTED] 736-2207	Repair
11405762	3B - Medium Sustain	3B- 9001 & POST M56 - WT - TAC STRUC - FIX ROOF LEAK - Repair - [REDACTED] - 2004344	Repair
11406098	3C - Low Sustain	3C - 9001 POST C-35 - WT - INTPLUMB - LEAKING WATER OUTLET - REPAIR - K7919 - [REDACTED] [REDACTED] - 405-274-2656	Repair
11409152	3B - Medium Sustain	3B - 9001 ROOM 148 - TAC STRUC - WT - ROOF LEAK - Repair - [REDACTED] - 4922496 - STORM	Repair

11411058	3B - Medium Sustain	3B - 9001 POST CC44 - WT - PLUMB INT-F/U T6008- ROOF DRAIN CLOGGED - REPAIR - [REDACTED] - 5824496 - SR#2945381	Repair
11411081	3B - Medium Sustain	3B - 9001 POST Q58 - WT - INT PLUMB - ROOF DRAIN CLOGGED - REPAIR - [REDACTED] - 5824496 - SR#2945388	Repair
11413476	3C - Low Sustain	3C - 9001 POST 2S-17-ASH 23 - WT - SHEET - METAL SKIRTING NEEDED/ROOF LEAK - REPAIR - T2735 - [REDACTED] - 582-1118 -	Repair
11413683	3C - Low Sustain	3C - 9001 POST EE34 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5128 - [REDACTED] - 582-4497 -	Repair
11413794	3C - Low Sustain	3C - 9001 Post DD56 - WT - Tac Struc - Rain water getting in through the doors, causing flooding in the shop - repair - T5773 - [REDACTED] - 582-4196	Repair
11413843	3C - Low Sustain	3C - 9001 Post A33, WRR NW - WT - Tac Struc - Check for leaks & replace stained / missing ceiling tile - repair - T5824 - [REDACTED] - [REDACTED] - 622-7846	Repair
11413850	3C - Low Sustain	3C - 9001 POST A33 CMXG FACILITY - WT - TAC STRUC - CHECK FOR LEAKS & REPLACE STAINED/MISSING CEILING TILES - REPAIR - T5825 - [REDACTED] - 622-7846	Repair
11413851	3C - Low Sustain	3C - 9001 POST A33 S CORNER OFC - WT - TAC STRUC - CHECK FOR LEAKS & REPLACE STAINED/MISSING CEILING TILES - REPAIR - T5826 - [REDACTED] - 622-7846	Repair

11413853	3C - Low Sustain	3C - 9001 POST A33 CENTER ADMIN - WT - TAC STRUC - CHECK FOR LEAKS & REPLACE STAINED/MISSING CEILING TILES - REPAIR - T5827 - [REDACTED] - 622-7846	Repair
11413908	3C - Low Sustain	3C - 9001 POST BB29 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5539 - [REDACTED] - 582- 4196 - STORM -	Repair
11413909	3C - Low Sustain	3C - 9001 POST C10 - WT - INTPLUMB - FLOOR DRAINS OVERFLOW WHEN JANITORS POUR THEIR MOP BUCKETS - REPAIR - T6112 - [REDACTED] - 622-7846 - -	Repair
11413912	3C - Low Sustain	3C - 9001 POST BB31 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5540 - [REDACTED] - 582- 4196 - STORM -	Repair
11413913	3C - Low Sustain	3C - 9001 POST BB39 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5542 - [REDACTED] - 582- 4196 - STORM -	Repair
11413916	3B - Medium Sustain	3B - 9001 POST BB44 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5543 - [REDACTED] - 582- 4196 - STORM	Repair
11413918	3C - Low Sustain	3C - 9001 POST DD52 - WT - INTPLUMB - TOILET FLUSH VALVE LEAKING IN THE WOMENS RR - REPAIR - T6114 - [REDACTED] - 622-7846 - -	Repair
11413923	3C - Low Sustain	3C - 9001 POST CC30 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5545 - [REDACTED] - 582- 4196 - STORM -	Repair
11413925	3C - Low Sustain	3C - 9001 POST CC48 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5546 - [REDACTED] - 582- 4196 - STORM -	Repair
11413927	3C - Low Sustain	3C - 9001 POST CC50 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5547 - [REDACTED] - 582- 4196 - STORM -	Repair

11413941	3C - Low Sustain	3C - 9001 POST CC53 - WT - TAC STRUC - (08-16-22/09-16-2022?) RAM COLD TAR ON ORDER ROOF LEAK - REPAIR - T5549 - [REDACTED] [REDACTED] - 582-4196 - STORM -	Repair
11413943	3C - Low Sustain	3C - 9001 POST DD27 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5550 - [REDACTED] - 582- 4196 - STORM -	Repair
11413949	3C - Low Sustain	3C - 9001 POST DD30 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5553 - [REDACTED] - 582- 4196 - STORM -	Repair
11413962	3C - Low Sustain	3C - 9001 POST DD33 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5559 - [REDACTED] - 582- 4196 - STORM -	Repair
11413965	3C - Low Sustain	3C - 9001 POST EE28 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5564 - [REDACTED] - 582- 4196 - STORM -	Repair
11413968	3C - Low Sustain	3C - 9001 POST EE29 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5565 - [REDACTED] - 582- 4196 - STORM -	Repair
11413978	3C - Low Sustain	3C - 9001 POST EE35 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5570 - [REDACTED] - 582- 4196 - STORM -	Repair
11413980	3C - Low Sustain	3C - 9001 POST EE44 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5571 - [REDACTED] - 582- 4196 - STORM -	Repair
11413987	3C - Low Sustain	3C - 9001 POST S34 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5572 - [REDACTED] - 582- 4196 - STORM -	Repair
11414031	3C - Low Sustain	3C - 9001 POST S44 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5574 - [REDACTED] - 582- 4196 - STORM -	Repair
11414049	3B - Medium Sustain	3B - 9001 POST T33 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5579 - [REDACTED] - 582- 4196 - STORM	Repair

11414060	3C - Low Sustain	3C - 9001 POST U37 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5580 - [REDACTED] - 582- 4196 - STORM -	Repair
11414069	3B - Medium Sustain	3B - 9001 POST U38 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5582 - [REDACTED] - 582- 4196 - STORM -	Repair
11414073	3C - Low Sustain	3C - 9001 POST U39 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5583 - [REDACTED] - 582- 4196 - STORM -	Repair
11414078	3C - Low Sustain	3C - 9001 POST U47 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5584 - [REDACTED] - 582- 4196 - STORM -	Repair
11414081	3C - Low Sustain	3C - 9001 POST U49 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5585 - [REDACTED] - 582- 4196 - STORM -	Repair
11414085	3C - Low Sustain	3C - 9001 POST V38 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5586 - [REDACTED] - 582- 4196 - STORM -	Repair
11414094	3C - Low Sustain	3C - 9001 POST W48 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5587 - [REDACTED] - 582- 4196 - STORM -	Repair
11414099	3C - Low Sustain	3C - 9001 POST X32 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5588 - [REDACTED] - 582- 4196 - STORM -	Repair
11414102	3C - Low Sustain	3C - 9001 POST X47 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5589 - [REDACTED] - 582- 4196 - STORM -	Repair
11414106	3C - Low Sustain	3C - 9001 POST X48 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5590 - [REDACTED] - 582- 4196 - STORM -	Repair
11414111	3C - Low Sustain	3C - 9001 POST Y32 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5591 - [REDACTED] - 582- 4196 - STORM -	Repair

11414116	3C - Low Sustain	3C - 9001 POST Y39 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5592 - [REDACTED] - 582- 4196 - STORM -	Repair
11414124	3C - Low Sustain	3C - 9001 POST Y47 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5593 - [REDACTED] - 582- 4196 - STORM -	Repair
11414760	3B - Medium Sustain	3B - 9001 POST M59 AND 60 - WT - TAC STRUC - ROOF LEAK - REPAIR - [REDACTED] - 2197894 - STORM	Repair
11419108	3C - Low Sustain	3C - 9001 S ADMIN, RM 115 - WT - INTPLUMB - MIXING VALVE HAS SLOW LEAK - REPAIR - T4591 - [REDACTED] - 405-200-3131 -	Repair
11419646	3C - Low Sustain	3C - 9001 POST K39 - WT - TAC STRUC - ROOF LEAK - REPAIR - T5472 - [REDACTED] - 582- 4105 - WEATHER -	Repair
11419655	3C - Low Sustain	3C - 9001 POSTS D12, E12 & F12 - WT - TAC STRUC - ROOF LEAK IN COMPOSITE CAGE - REPAIR - T5491 - [REDACTED] - 582- 4105 - - 9001-MAU-1	Repair
11434267	3C - Low Sustain	3C- 9001 POST Q38 - WT - PLUMB INT - F/U 11404805 DRAIN PIPE LEAK - REPAIR - [REDACTED] - 6227846 - SR#2952957	Repair
11434312	3B - Medium Sustain	3B- 9001 POST M38 - WT - PLUMB INT - F/U 11413950 DRAIN PIPE LEAK - REPAIR - [REDACTED] - 6227846 - SR#2952970	Repair
11435811	3B - Medium Sustain	3B - 9001 & MEZZ 2 2T43 CUBE #86 - WT - HONEYWELL - F/U 11403540 - PIPE CHASE UNIT LEAKING - Repair - [REDACTED] [REDACTED] - 582-4496 - SR# 2953494	Repair
11441231	3C - Low Sustain	9001 POST V53 - WT - INTPLUMB - WATER FILTER SYSTEM LEAKING UNDER SINK - REPAIR - [REDACTED] [REDACTED] - 582-9576	Repair

11452995	3A - High Sustain	3A - 9001 & G 24 - WT - TAC CONTROL - STOP PIPE LEAK - Repair - [REDACTED] - 582-4105	Repair
11453558	3B - Medium Sustain	3B - 9001 & G 24 - WT - PLUMB INT - STOP PIPE LEAK - Repair - [REDACTED] - 582-4105	Repair
11459773	3B - Medium Sustain	3B - 9001 POSTS W35/X35 - WT - TAC STRUC - ROOF LEAKING ONTO COMPUTERS - REPAIR - [REDACTED] 582-4196 - STORM	Repair
11460544	3B - Medium Sustain	3B - 9001 POSTS W35/X35 - WT - F/U 11459773 TAC HVAC - DUCT LEAKING ONTO COMPUTERS - REPAIR - [REDACTED] 582-4196 - STORM	Repair
11462448	3B - Medium Sustain	3B - 9001 POST X31 - WT - TAC STRUC - ROOF LEAK - REPAIR - [REDACTED] - 323-0319 - STORM	Repair
11462668	3B - Medium Sustain	3B - 9001 POST H43, J42 - WT - TAC STRUC - ROOF LEAKS - REPAIR - [REDACTED] - 5824105 - STORM	Repair
11471748	3B - Medium Sustain	3B - 9001 POST S51 T51 U51 - WT - TAC STRUC - ROOF LEAK/CURRENTLY CONTAINED - Repair - [REDACTED] - 582-4105	Repair
11472358	3B - Medium Sustain	3B - 9001 & POST G24 - WT - TAC STRUC - STOP ROOF LEAK - Repair - [REDACTED] - 5824105	Repair
11473605	3B - Medium Sustain	3B - 9001 POST G24 - WT - PLUMB INT - F/U 11472358 ROOF LEAK COMMING FROM HVAC TIE IN - REPAIR - [REDACTED] [REDACTED] - 405-734-7098	Repair
11477550	3B - Medium Sustain	3B - 9001 & MENS RR 113 - WT - INT PLUMB - UNCLOG URINAL - Repair - [REDACTED] - 7368784	Repair

11479553	3C - Low Sustain	3C- 9001 POST S-30 -WT- PLUMB INT - DRAIN PIPE IS LEAKING AT ELBOW F/U FROM 11404075 - REPAIR - [REDACTED] - 582-4496	Repair
11479573	3B - Medium Sustain	3B - 9001 L23 - WT - TAC HVAC - F/U 11403993 ASH HOUSE 32 IS LEAKING FROM 3 DIFFERENT SPOTS - REPAIR-[REDACTED] - 582-4496	Repair
11481253	3B - Medium Sustain	3B - 9001 ASH HOUSE 32 F/U 11403993 - WT - TAC HVAC - CONDENSATION LEAK - REPAIR - [REDACTED] 582-4496	Repair
11482561	3C - Low Sustain	3C - 9001 G24 - WT- PLUMB INT - PIPE LEAKING AT TOP CONNECTION NOT CATCHING WATER TO POLE F/U 11472358- REPAIR - [REDACTED] - 582-4496	Repair
11483651	3B - Medium Sustain	3B - 9001 & POST 2J23 - WT - INT PLUMB - STOP LEAK - Repair - [REDACTED] - 3230319	Repair
11493032	3A - High Sustain	3A - 9001 & MENS RESTROOM - WT - INT PLUMB - STOP OVERFLOWING - Repair - [REDACTED] - 7368784	Repair
11498449	3A - High Sustain	3A - 9001 & Q25 AND P25 - WT - TAC HVAC - STOP LEAK - Repair - [REDACTED] - 5824105	Repair
11517974	3A - High Sustain	3A - 9001 & U38 - WT - TAC HVAC - STOP LEAK - Repair - [REDACTED] - 6227846 - T5582 - 11414069	Repair
11530439	3A - High Sustain	3A - 9001 MEZZ 3 RM 103 - WT - TAC HVAC - CONDENSATE PUMP LEAKING - REPAIR - [REDACTED] 582-1118	Repair
11530905	3B - Medium Sustain	3B - 9001 MEZZ 3 RM 103 - WT - TAC HVAC - FU 11530439 CONDENSATE PUMP LEAKING - REPAIR - [REDACTED] 582-1118	Repair

11535701	3B - Medium Sustain	3B - 9001 ASH HOUSE 71 - WT - TAC HVAC - ASH HOUSE 71 COIL LEAKING - REPAIR - [REDACTED] - 582-4496	Repair
11555350	3B - Medium Sustain	3B- 9001 ASH HOUSE 211 - WT - TAC CONTROLS - ADJUST FAN SPEED ON ASH HOUSE 211 TO PREVENT CONDENSATE LEAK - REPAIR - [REDACTED] -582-4496	Repair
11564674	3A - High Sustain	3A - 9001 POST W22 WOMEN'S RR - WT - INT PLUMB - WATER LEAK COMING FROM THE WALL - REPAIR - [REDACTED] 323-0319	Repair
11589274	3B - Medium Sustain	3B - 9001 POST X41 ROOFTOP - WT - TAC HVAC - UNINSULATED PIPE ON ROOF IS LEAKING - REPAIR - [REDACTED] 622-7846	Repair
11589278	3B - Medium Sustain	3B - 9001 ROOFTOP POST J-K 38/39 - WT - TAC HVAC - CONDENSATION WATER LINE LEAK - REPAIR - [REDACTED] 622-7846 - SR# 3008376	Repair
11599115	3C - Low Sustain	3C - 9001 2ND FLR. R.R. W. DOGLEG JANITORS CLOSET - W.T - PLUMB INT - REPAIR LEAK ON MIXING VAVLE - REPAIR - [REDACTED] - 405-734-7098	Repair
11599164	3C - Low Sustain	3C - 9001 2ND FLR R.R. W DOGLEG JANITORS CLOSET - WT - PLUMB INT - F/F REPAIR WATER HEATER LEAK 9001-WH-D10 - REPAIR - [REDACTED] - 405-734-7098	Repair
11599196	3C - Low Sustain	3C - 9001 V-46 R.R. WHITE HOUSE - WT - PLUMB INT - F/F REPAIR WATER HEATER LEAK 9001-WH-42 - REPAIR - [REDACTED] - 405-734-7098	Repair

11604964	3B - Medium Sustain	3B - 9001 POST 2J23 WRR - WT - INT PLUMB - LEAKING TOILET AND 2 OTHERS BAGGED DUE TO LOW WATER PRESSURE - REPAIR - [REDACTED] 622-7846 - SR# 3015174	Repair
11606019	3B - Medium Sustain	3B - 9001 BTWN POSTS U28/U29 - WT - TAC HVAC - CONDENSATION WATER LEAK - REPAIR - [REDACTED] 622-7846	Repair
11610140	3B - Medium Sustain	3B - 9001 between Post P36 and P37 - WT - TAC HVAC - chilled water line is leaking - [REDACTED] 818-6609	Repair
11620030	3A - High Sustain	3A - 9001 DD31 - WT - INT PLUMB - STOP LEAK - Repair - [REDACTED] - 5826491	Repair
11622069	3B - Medium Sustain	3B - 9001 2P53 MRR - WT - INT PLUMB - LOW WATER FLOW/SEVERAL CLOGGED AND BAGGED TOILETS - REPAIR - [REDACTED] 622-7846 - SR# 3021632	Repair
11626130	3C - Low Sustain	3C - 9001 ROOF TOP Q/P 36/37 - WT - TAC STRUC- ROOF DRAIN CLOGGED - REPAIR - [REDACTED] - 622-7846	Repair
11626550	3B - Medium Sustain	3B - 9001 NEAR POST D56 WAREHOUSE SR57 - WT - TAC HVAC - WATER LEAKING FROM CEILING - Repair - [REDACTED] - 541-9535	Repair
11630467	3C - Low Sustain	3C - 9001 POST EE44 - WT - PLUMB INT - F/U T5571 AND 11413980 LEAK IN DRAIN PIPE - REPAIR - [REDACTED] - 582-4196 - STORM	Repair
11647599	3B - Medium Sustain	3B - 9001 POST U32-U33 - WT - TAC HVAC - DUCT CONDENSATION LEAK - Repair - 3033483 - [REDACTED] - 582-4256	Repair
11653169	3C - Low Sustain	3C - 9001 F55 - WT - INT PLUMB - LEAK COMING THROUGH METAL FLOOR - [REDACTED] - 623-0072	Repair

11656146	3B - Medium Sustain	3B- 9001 Post AA40 - WT - TAC HVAC - air conditioner is leaking in outside breakroom - repair - [REDACTED] 582-4196	Repair
11660711	3B - Medium Sustain	3B - 9001 Posts E67 & E68 - WT - TAC HVAC - repair leaking chilled water line - repair - [REDACTED] - 622-7846 - SR3041475	Repair
11667788	3B - Medium Sustain	3B - 9001 Post X39 - WT - TAC HVAC - A/C leak - repair - [REDACTED] 582-4196 - SR 3044696	Repair
11676795	3A - High Sustain	3A - 9001 WOMENS RR POST G39 - WT - INT PLUMB - TOILET LEAKING - Repair - [REDACTED] 2742656	Repair
11690407	3C - Low Sustain	3C - 9001 Q52 - WT - INT PLUMB - MOP CLOSET FAUCET LEAKS WHEN TURNED ON - REPAIR - [REDACTED] 622-7846 - SR# 3054149	Repair
11690408	3B - Medium Sustain	3B - 9001 E30 MRR - WT - INT PLUMB - TOILET CLOGGED/BAGGED - REPAIR - [REDACTED] 622-7846 - SR# 3054150	Repair
11690542	3B - Medium Sustain	3B - 9001 POST T48 - WT - INT PLUMB - DRAIN CLOGGED; CAUSING FLOODING - REPAIR - [REDACTED] 582-4105 - SR# 3054240	Repair
11690556	3B - Medium Sustain	3B - 9001 POST D8 - WT - INT PLUMB - RELIEF VALVE LEAKING WATER - REPAIR - [REDACTED] 582-4105 - SR# 3054254	Repair
11692039	3B - Medium Sustain	3B- 9001 post D63 - WT - intplumb - video scope sewer line in problem area - repair - [REDACTED] - 622-7846 - SR3055105	Repair
11693628	3A - High Sustain	3A - Bldg 9001, base of post H42 - WT - TAC HVAC - base of post H42 has significant leak - repair - [REDACTED] - 582-4105 - SR3055717	Repair

11694408	3A - High Sustain	3A - 9001 BASE OF POST H42 - WT - INT PLUMB - REF 11693628 SIGNIFICANT LEAK - REPAIR - [REDACTED] 582-4105	Repair
11694489	3B - Medium Sustain	3B - 9001 Post S-29 - WT - Intplumb - pipe leaking on attendants work cage - repair - [REDACTED] - 582-4105 - SR3056290	Repair
11697436	3B - Medium Sustain	3B - 9001 Post X-31 MRR - WT - Intplumb - 2nd handicap toilet is bagged and leaking - repair - [REDACTED] - 622-7846 - SR3057552	Repair
11697701	3C - Low Sustain	3C - 9001 POST W-43 - WT- PLUMB INT - F/U 11403984 STORM DRAIN LEAKING FROM PIPE - repair - [REDACTED] - 582-4496 - SR2953036	Repair
11708267	3B - Medium Sustain	3B - 9001 Post X-35 - WT - TAC HVAC - A/C is leaking water on two desks - repair - [REDACTED] - 582-4196	Repair
11711175	3C - Low Sustain	REJECT - ICE MACHINES BELONG TO M.A.D. - DEFAULT - Work Task Template - Corrective Maintenance-Leaks	Repair
11712277	3B - Medium Sustain	3B - 9001 DR S54 FOYER - WT - TAC HVAC - CHECK/REPAIR LEAKS ABOVE DROP CEILING - REPAIR - [REDACTED] 622-7846	Repair
11712481	3C - Low Sustain	3C - 9001 DR S47 FOYER - WT - TAC HVAC - CHECK/REPAIR LEAKS ABOVE CEILING INSIDE FOYER - REPAIR - [REDACTED] 622- 7846	Repair
11712846	3C - Low Sustain	3C - 9001 U38/39 ASH 71 - WT - HONEYWELL - TURNED OFF DUE TO CHRONIC LEAK ISSUE - REPAIR - [REDACTED] 622-7846	Repair

11724573	3B - Medium Sustain	3B - 9001 C70 MRR - WT - INT PLUMB - URINAL OVERFLOWING ONTO THE FLOOR - REPAIR - [REDACTED] 622-7846	Repair
11724604	3A - High Sustain	3A - 9001 D11 UPSTAIRS - WT - INT PLUMB - RR OVERFLOWING - REPAIR - [REDACTED] 582-4496	Repair
11727468	3C - Low Sustain	3C - 9001 - WT - PLUMB INT - F/U 11708771 UNCLOG URINALS - REPAIR - [REDACTED] - 405-734-7098	Repair
11735215	3B - Medium Sustain	3B - 9001 BETWEEN POSTS M20 & N20 - WT - TAC HVAC - PIPES ON ROOF LABELED HOT/CHILL WATER SUPPLY ARE LEAKING - REPAIR - [REDACTED] 582-4105	Repair
11742688	3C - Low Sustain	3C - 9001 EE38 - WT - TAC HVAC - CHECK FOR AND REPAIR LEAKS - REPAIR - [REDACTED] 622-7846	Repair
11746063	3A - High Sustain	3A - 9001 POST L52 - WT - TAC HVAC - CLOGGED CONDENSATE DRAIN - Repair - [REDACTED] 5509580	Repair
11746065	3B - Medium Sustain	3B - 9001 POST M45 - WT - INT PLUMB - HANDICAPPED STALL TOILET IS CLOGGED AND WON'T FLUSH & NEEDS TOILET SEAT REPLACED - REPAIR [REDACTED] [REDACTED] 582-4105	Repair
11750208	3C - Low Sustain	3C - 9001 EE38 - WT - TAC STRUC - F/U 11742688 REPAIR ROOF LEAK AT EE38 - REPAIR - [REDACTED] [REDACTED] 582-4496	Repair
11752720	3C - Low Sustain	3C - 9001 B62/63 - WT - INSULATE - F/U 11752462 6" CHW LINE IN RAFTERS LEAKING/CHECK ALL ROOFTOP AHU IN AREA - [REDACTED] - 582-4496	Repair
11752944	3B - Medium Sustain	3B - 9001 ASH 203 - WT - TAC HVAC - CLEAN CLOGGED COIL - REPAIR - [REDACTED] 734-2328	Repair

11757366	3C - Low Sustain	3C - 9001 POST M45 - WT - INT PLUMB - F/U 11746065 HANDICAPPED STALL TOILET IS CLOGGED/WON'T FLUSH & NEEDS TOILET SEAT REPLACED - [REDACTED] 7347098	Repair
11766906	3B - Medium Sustain	3B - 9001 POST X40 - WT - INT PLUMB - BREAKROOM SINK IS CLOGGED & LEAKING WATER - [REDACTED] - 582-4196	Repair
11766930	3B - Medium Sustain	3B - 9001 POST 2V40 WRR - WT - INT PLUMB - HANDICAP STALL CLOGGED - [REDACTED] 582-4196	Repair
11767388	3C - Low Sustain	3C - 9001 ROOF TOP Q/P 36/37 - WT - INT PLUMB - F/U 11626130 DRAIN PIPE CLOGGED - REPAIR - [REDACTED] - 622-7846	Repair
11769165	3C - Low Sustain	3C - 9001 EE44 - WT - INT PLUMB - ROOF DRAIN LEAK - [REDACTED] [REDACTED] - 582-4496	Repair
11775843	3B - Medium Sustain	3B - 9001 A32 Facility Managers Office WRR - WT - INT PLUMB - water leak coming from back of toilet/wall - [REDACTED] - 622-7846	Repair
11776765	3C - Low Sustain	3C - 9001 L31 breakroom - WT - Intplumb - Water heater, check press. and for leaks - repair - [REDACTED] - 622-7846 - SR3095246	Repair
11776772	3C - Low Sustain	3C - 9001 T48 - WT - Intplumb - clear clogged line in fixture storage, scope line for problems - repair - [REDACTED] - 622-7846 - SR3095249	Repair
11779542	3B - Medium Sustain	3B - 9001 DRTC OFFICE POST DX33 - WT - INT PLUMB - ACAP DRAIN CLOGGED - [REDACTED] - 622-7846	Repair
11785669	3C - Low Sustain	3C - 9001 B51 - WT - TAC CONTROLS - HOT WATER PUMP # 1 SEALS LEAKING COORDINATION WITH 11785684 - [REDACTED] - 582-4496	Repair

11785684	3C - Low Sustain	3C - 9001 B51 - WT - TAC HVAC - (SEALS 09-07/10-25)HOT WATER PUMP #1 SEALS LEAKING - [REDACTED] - 582-4496	Repair
11797493	3B - Medium Sustain	3B - 9001 POST K44 - WT - TAC STRUC - ROOF LEAKS BLACK TAR LOOKING SUBSTANCE - [REDACTED]	Repair
11798258	3C - Low Sustain	3C - 9001 POST M28 - WT - TAC STRUC - TOOL ROOM HAS ROOF LEAK - [REDACTED] - 582-4105	Repair
11800968	3C - Low Sustain	3C - 9001 EE38 - WT - TAC HVAC - F/U 11742688 HELP STRUC SHOP REPAIR ROOF LEAK AT EE38 - [REDACTED] - 582-4496	Repair
11808432	3B - Medium Sustain	3B - 9001 S ADMIN RM 147 - WT - TAC HVAC - UNIT LEAKING INTO WOMENS RR - [REDACTED] - 582-4496	Repair
11808442	3B - Medium Sustain	3B - 9001 POST K44 - WT - TAC HVAC - ASSIST REPAIRING ROOF LEAK - [REDACTED] - 582-4105	Repair
11810488	3B - Medium Sustain	3B - 9001 POST K32 - WT - TAC STRUC - SEVERAL LEAKS, ONE IS LEAKING ON LAPTOP CABINET - [REDACTED] - 582-4105	Repair
11810600	3B - Medium Sustain	3B - 9001 POSTS A46-A47 - WT - TAC STRUC - LEAK FROM CEILING, LOOKS LIKE OIL - [REDACTED] - 736-5233	Repair
11811983	3B - Medium Sustain	3B - 9001 POST S32 - WT - TAC STRUC - WATER LEAK - [REDACTED] - 582-4196	Repair
11812856	3B - Medium Sustain	3B - 9001 ROOF F54 - WT - TAC HVAC - REPAIR/REPLACE LEAKING CONDENSATION LINE OF AC-7 - [REDACTED] - 622-7846 - PKG-F54	Repair
11818595	3C - Low Sustain	3C - 9001 ASH 52 - WT - TAC HVAC - REPAIR CONDENSATE LEAK - [REDACTED] - 582-4496	Repair

11820646	3B - Medium Sustain	3B - 9001 POST M60 AND L60 - WT - TAC HVAC - CONDENSATION LEAK - [REDACTED] - 8553012	Repair
11824762	3A - High Sustain	3A - 9001 POST M60 - WT - TAC STRUC - AK0002 WATER LEAKING DOWN POLE, 3-4" FROM ELEC BOX - [REDACTED] - 219-7894	Repair
11837164	3B - Medium Sustain	3B - 9001 KC46 AREA - WT - TAC HVAC - REHEAT PUMPS HAVE FLOODED AREA - [REDACTED] - 736-7554	Repair
11843031	3C - Low Sustain	3C - 9001 ASH 73 - WT - TAC HVAC - WATER LEAKING FROM DRAIN PANS INTO BLDG - [REDACTED] - 582-4496	Repair
11843564	3B - Medium Sustain	3B - 9001 POSTS A46-A47 - WT - TAC HVAC - ASSIST TAC STRUC WITH LEAK FROM CEILING, LOOKS LIKE OIL - [REDACTED] - 736-5233	Repair
11844602	3B - Medium Sustain	3B - 9001 POST S32 - WT - TAC HVAC - ASSIST TAC STRUCTURES WITH WATER LEAK - [REDACTED] - 582-4196	Repair
11844625	3B - Medium Sustain	3B - 9001 POSTS A46-A47 - WT - TAC HVAC - ASSIST TAC STRUCTURES WITH LEAK FROM CEILING, LOOKS LIKE OIL - [REDACTED] - 736-5233	Repair
11852318	3A - High Sustain	3A - 9001 POST DD40- WT - INT PLUMB - LEAK FLOOD BREAKROOM - [REDACTED] - 5824196	Repair
11864232	3C - Low Sustain	3C - 9001 MENS RR POST C10 - WT - INT PLUMB - URINAL DRAIN IS CLOGGED, HAS BEEN BAGGED - [REDACTED] - 405.622.7846/323.0319	Repair
11866374	3A - High Sustain	3A - 9001 between Posts A34 & A35 - Chilled water line leaking - [REDACTED] 623-0072	Repair
11868265	3B - Medium Sustain	3B - 9001 POST W26 - WT - INT PLUMB - WATER LEAKING ONTO THE FLOOR FROM POST - [REDACTED] - 582-4105	Repair

11868479	3C - Low Sustain	3C - 9001 A34-A35 - WT - TAC HVAC - F/U 11866374 CHECK FOR WATER LEAK TO DETERMINE IF HVAC ISSUE - [REDACTED] - 582-4496	Repair
11869995	3C - Low Sustain	3C - 9001 ROOF EE46 - WT - INT PLUMB - ROOF DRAIN IS CLOGGED & NEEDS TO BE CLEANED - [REDACTED] - 323- 0319	Repair
11871631	3A - High Sustain	CO - 3A - 9001 POSTS A34/A35 - WT - INT PLUMB - HEAVY WATER LEAK - [REDACTED] - 622-7846	Repair
11874756	3B - Medium Sustain	3B - 9001 N MEZZ 3 RM 108 - WT - TAC HVAC - LARGE CHILL WATER LEAK - [REDACTED] - 5824497	Repair
11887113	3B - Medium Sustain	CO - 3B - 9001 KC46 - WT - INT PLUMB - URINAL OVERFLOWING ONTO FLOOR - [REDACTED] - 7368784	Repair
11899930	3A - High Sustain	3A - 9001 ROOM 116 - WT - INT PLUMB - POSSIBLE LEAK INSIDE OF WALL - [REDACTED] - 7368784	Repair
11912519	3C - Low Sustain	3C - 9001 W44 - WT - TAC STRUC - REPAIR MULTIPLE ROOF LEAK HOLES - [REDACTED] - 582- 4496	Repair
11912529	3C - Low Sustain	3C - 9001 AA48 - WT- TAC STRUC - REPAIR MULTIPLE LEAK HOLES - [REDACTED] - 582-4496	Repair
11931313	3B - Medium Sustain	3B - 9001 POST C70 WOMENS RR - WT - INT PLUMB - CLOGGED TOILET - [REDACTED] - 622-7839	Repair
11941144	3C - Low Sustain	3C - 9001 POST G39 BRKRM - WT - INT PLUMB - SINK DRAIN IS CLOGGED - [REDACTED] - 582-4105	Repair
11941657	3C - Low Sustain	3C - 9001 U-38 - WT - TAC STRUCTURES - REPAIR ROOF LEAK - [REDACTED] - 582- 4496	Repair

11941722	3C - Low Sustain	3C - 9001 D-44- WT - TAC STRUC- LEAKING AT THE SMOKE DAMPER - ██████████ -582- 4496 Repair
11942944	3C - Low Sustain	3C - 9001 Roof top Q/P 36/37 WT - TAC STRUCTURES - F/U 11767388 / 11626130 Drain pipe clogged - ██████████ 405-734- 7098 Repair
11942958	3C - Low Sustain	3C - 9001 Post S-29 - WT - TAC STRUCTURES- pipe leaking on attendants work cage - ██████████ ██████████ - 405-734-7098 Repair
11977856	1-Emergency	1 - 9001 Post D20 Mens and Womens RR - WT - INT PLUMB - restrooms are flooding - ██████████ ██████████ 317-1567 Repair
11977934	3C - Low Sustain	3C - 9001 A22 foyer - WT - TAC STRUC - Check for leaks and repair as needed, replace stained ceiling tiles - ██████████ 622- 7846 - SR3161337 Repair
11988039	3A - High Sustain	3A - 9001 POST Q50 MENS RR - WT - INT PLUMB - SINK SEPERATING FROM WALL CAUSING LEAK - ██████████ - 219-7894 Repair
11988172	3C - Low Sustain	3C - 9001 H70 - WT - INT PLUMB - SEWER ODOR FROM SUMP PUMP/REPAIR-REPLACE - ██████████ ██████████ - 622-7846 Repair
12008170	3A - High Sustain	3A - 9001 POST 2E55 OFFICE 215 - WT - INT PLUMB - SINK DRAIN IS LEAKING - ██████████ - 736- 8784 Repair
12013466	3C - Low Sustain	3C - 9001 BETWEEN BB & CC 51 - WT - TAC STRUC - REPAIR LEAK AROUND DRAIN AREA - ██████████ ██████████ - 582-4496 Repair
12021068	3B - Medium Sustain	3B - 9001 POST EE-44 - WT - INT PLUMB - OVERHEAD PIPE LEAKING - ██████████ - 405- 582-4105 Repair
12022759	3C - Low Sustain	4A - 9001 Ext Door N38 - WT - EXTPLUMB - roof drain leaking - ██████████ - 405 582 4196 Repair

12023721	3C - Low Sustain	3C - 9001 S ADMIN ANNEX RM 119 MEN'S RR - WT - INT PLUMB - 2ND SINK IS CLOGGED - [REDACTED] [REDACTED] - 622-7846	Repair
12031612	3C - Low Sustain	3C - 9001 BB38 - WT - INT PLUMB - Hot water heater is leaking - [REDACTED] 622-7846 - SR3179417	Repair
12036002	3C - Low Sustain	3C - 9001 POST S-29 - WT - INSULATOR- F/U 11942958 INSULATED PIPE LEAKING ON ATTENDENTS WORK CAGE- [REDACTED] 582-4496	Repair
12039225	3C - Low Sustain	3C- 9001 post D63 - WT - int plumb - video scope sewer line in problem area - [REDACTED] - 622-7846	Repair
12039490	3A - High Sustain	3A - 9001 POST T43 - WT - INT PLUMB - WATER LEAK FROM 2ND FLR MEZZ DRIPPING ONTO 1ST FLR SHOP AREA - [REDACTED] [REDACTED] - 622-7846	Repair
12040254	3C - Low Sustain	3C - 9001 POST T43 - WT - INT PLUMB - F/U 12039490 RECHECK FOR LEAK FROM 2ND FLR MEZZ - [REDACTED] - 622-7846	Repair
12049919	3C - Low Sustain	3C- 9001 X-44- WT - TAC STRUC- REPAIR LEAK - [REDACTED] - 582-4496	Repair
12052008	3C - Low Sustain	3C - 9001 RM 215 KITCHEN - WT - INT PLUMB - SINK CLOGS EASILY & DRAINS SLOW - [REDACTED] [REDACTED] - 405-736-8784	Repair
12063019	3B - Medium Sustain	3B - 9001 DD26-DD27 - WT - TAC STRUC - Smoke dampener is leaking from the rain - [REDACTED] [REDACTED] 582-4105 - SR3191376	Repair
12065128	3C - Low Sustain	3C - 9001 W-49 - WT - TAC STRUC - REPAIR ROOF LEAK - [REDACTED] - 582-4496	Repair
12065139	3C - Low Sustain	3C - 9001 S-51 - WT - TAC STRUC - REPAIR ROOF LEAK - [REDACTED] [REDACTED] 582-4496 - SR3193184	Repair

12065146	3C - Low Sustain	3C-9001 T-51- WT- TAC STRUCTURES- REPAIR ROOF [REDACTED] [REDACTED] -582-4496	Repair
12065262	3C - Low Sustain	3C - 9001 X22 - WT - TAC STRUC - REPAIR ROOF LEAK - [REDACTED] L [REDACTED] - 582-4496	Repair
12065272	3C - Low Sustain	3C - 9001 Y46 - WT - TAC STRUC - REPAIR ROOF LEAK - [REDACTED] [REDACTED] - 582-4496	Repair
12075312	3C - Low Sustain	3C- 9001 AA-38 - WT - TAC STRUCT - REPAIR ROOF LEAK - [REDACTED] - 582-4496	Repair
12087711	3B - Medium Sustain	3B - 9001 Q58 - WT - INT PLUMB - UNCLOG ROOF DRAINS CAUSHING ROOF LEAK - [REDACTED] [REDACTED] - 734-2753	Repair
12088141	3C - Low Sustain	3C - 9001 CC44 - WT - TAC STRUC - REPAIR ROOF LEAK - [REDACTED] [REDACTED] - 582-4496	Repair

Work Location	Responsible Organization	Planned Start(Respond Date)
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/12/2022 01:00:00
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - CUSTOMER SERVICE UNIT	05/12/2022 01:00:00
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/14/2022 01:00:00
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/14/2022 01:00:00
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/14/2022 01:00:00
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/15/2022 09:17:03
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/15/2022 11:03:55
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/15/2022 11:09:50
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/15/2022 11:11:26
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/15/2022 11:13:02

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/16/2022 09:37:04
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/16/2022 09:38:25
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/16/2022 09:39:34
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/17/2022 08:53:31
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/17/2022 08:54:39
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	05/17/2022 09:18:13
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	05/17/2022 09:52:59
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	05/17/2022 10:10:58
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/18/2022 15:13:23
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PIPE FITTING - BOS-BMC	05/19/2022 08:45:26

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - CUSTOMER SERVICE UNIT	05/19/2022 08:47:49
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/20/2022 15:29:06
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/23/2022 10:23:47
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/23/2022 12:42:54
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/24/2022 07:22:58
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/24/2022 08:20:56
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/24/2022 08:47:43
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/24/2022 10:34:14
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/24/2022 10:40:24
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/24/2022 10:46:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/24/2022 10:49:22

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/24/2022 11:20:18
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/24/2022 11:28:09
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/24/2022 11:31:31
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/24/2022 11:42:54
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/24/2022 11:45:11
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/24/2022 12:58:21
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/24/2022 13:07:46
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/24/2022 13:16:28
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	06/01/2022 15:49:41
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/24/2022 18:32:31
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/25/2022 10:36:29

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - STRUCTURE SHOP - SHEET METAL - BOS-BMC	05/25/2022 20:11:52
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 00:51:15
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 02:04:21
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 02:33:30
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 02:44:05
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 02:46:55

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 02:49:59
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 04:09:51
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 04:11:11
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 04:15:18
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 04:20:32
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 04:23:53
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/26/2022 04:24:37
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 04:38:32
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 04:39:36
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 04:40:56

\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 05:02:38
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 05:05:24
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 05:07:58
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 05:18:58
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 05:23:12
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 05:24:29
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 05:36:28
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 05:39:04
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 05:45:50
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 06:15:20
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 06:22:55

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 06:25:41
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 06:28:37
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 06:30:04
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 06:32:36
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 06:33:58
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 06:35:21
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 06:39:04
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 06:41:59
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 06:43:43
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 06:45:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 06:46:27

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 06:47:25
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 06:49:44
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/26/2022 07:44:04
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	05/27/2022 06:40:40
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/27/2022 09:15:20
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	05/27/2022 09:16:40
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/01/2022 10:08:24
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/01/2022 10:11:33
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	06/02/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/02/2022 11:16:32

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - PLANT OPS - OTHER - BOS-BMC	06/06/2022 08:30:12
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/06/2022 09:31:27
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	06/07/2022 08:32:21
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	06/07/2022 09:49:42
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	06/07/2022 12:46:51
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	06/07/2022 13:07:08
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	06/08/2022 11:30:10
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	06/08/2022 12:55:21
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/09/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/09/2022 11:17:51

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/10/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	06/10/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	06/10/2022 07:29:59
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/10/2022 10:40:14
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/10/2022 13:32:20
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/13/2022 12:25:11
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	06/14/2022 10:26:21
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	06/17/2022 10:00:58
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	06/21/2022 13:39:12
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	06/21/2022 14:47:35

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	06/23/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC CONTROLS - BOS-BMC	06/28/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	06/29/2022 09:54:56
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	07/06/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	07/06/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/08/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/08/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/08/2022 01:00:00

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/08/2022 11:16:15
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	07/08/2022 13:25:43
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	07/10/2022 20:19:23
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/12/2022 11:45:02
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/13/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	07/13/2022 11:44:58
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	07/13/2022 12:40:48
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/14/2022 10:21:05
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	07/19/2022 10:55:41
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/20/2022 13:18:31

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	07/21/2022 10:19:07
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	07/23/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	07/26/2022 07:21:04
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	07/28/2022 09:36:38
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	08/01/2022 09:34:19
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	08/01/2022 09:35:10
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/01/2022 10:10:11
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	08/01/2022 10:12:55
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/02/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	08/02/2022 07:00:00

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/02/2022 11:43:40
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/03/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	08/03/2022 11:54:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/04/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	08/08/2022 00:28:46
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - CUSTOMER SERVICE UNIT	08/08/2022 09:22:14
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	08/08/2022 10:39:28
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	08/08/2022 10:54:07
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - ENVIRONMENTAL CONTROL SYSTEMS - SUB - BOS-BMC	08/08/2022 11:28:07

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/10/2022 09:39:22
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/10/2022 09:46:24
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	08/11/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	08/12/2022 09:24:57
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	08/15/2022 11:02:31
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	08/16/2022 07:23:35
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	08/16/2022 07:26:19
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	08/17/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - PROTECTIVE COATING (PAINT) - BOS-BMC	08/17/2022 07:50:15
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	08/17/2022 08:21:24

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/18/2022 08:27:56
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/22/2022 07:04:37
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/22/2022 07:09:14
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/22/2022 08:29:07
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/23/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/24/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/24/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/24/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	08/24/2022 10:11:28
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC CONTROLS - BOS-BMC	08/26/2022 01:00:00

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	08/26/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	08/29/2022 08:51:49
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	08/29/2022 10:40:33
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	08/30/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	08/31/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	08/31/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	08/31/2022 07:10:12
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	08/31/2022 07:35:12
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	08/31/2022 09:17:43
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	08/31/2022 10:34:53
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	09/01/2022 08:10:35

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	09/02/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	09/02/2022 14:38:27
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	09/07/2022 09:20:59
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	09/08/2022 07:37:39
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	09/08/2022 08:49:25
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	09/08/2022 10:27:21
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	09/08/2022 10:29:57
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/09/2022 08:25:56
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/13/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB AFTER HRS - BOS-BMC	09/12/2022 16:32:40
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/13/2022 07:00:00

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	09/13/2022 07:35:36
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/13/2022 09:47:04
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/13/2022 11:24:46
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC HVAC - BOS-BMC	09/13/2022 15:43:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/15/2022 09:43:04
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/19/2022 08:28:54
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	09/20/2022 09:43:03
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	09/20/2022 09:43:43
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/22/2022 10:41:35
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/24/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	09/24/2022 01:00:00

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	09/24/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	09/24/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	09/24/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	09/30/2022 16:41:03
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	10/01/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/03/2022 11:34:49
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/03/2022 11:54:44
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/06/2022 11:29:57
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	10/08/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/11/2022 09:27:58
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SUSTAINMENT - PAVEMENTS - BOS-BMC	10/12/2022 01:00:00

\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/12/2022 01:00:00
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/13/2022 01:00:00
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - INSULATOR - BOS-BMC	10/14/2022 01:00:00
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/14/2022 12:14:15
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/14/2022 13:41:54
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/14/2022 15:08:37
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	10/18/2022 01:00:00
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS-BMC	10/18/2022 07:11:38
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	10/26/2022 11:38:10
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	10/27/2022 01:00:00
\\Locations\\TINKER AEROSPACE COMPLEX\\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	10/27/2022 01:00:00

\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	10/27/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	10/27/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	10/27/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	10/28/2022 01:00:00
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - WATER AND FUELS SYSTEM MX - PLUMB INT - BOS- BMC	10/31/2022 07:58:42
\Locations\TINKER AEROSPACE COMPLEX\9001 - 1211415	TINKER AFB - SPEC MX TM - TAC STRUCTURES - BOS-BMC	10/31/2022 09:31:44

Tracking Status	Status	SR ID	Requested By (FM)
	Closed	2921199	[REDACTED]
	Rejected	2921628	[REDACTED]
	Closed	2925946	[REDACTED]
	Closed	2925951	[REDACTED]
	Closed	2926037	[REDACTED]
	Closed		
	Closed		
	Closed		
	Closed		
	Closed		

Closed

Closed

Closed

Closed

2929829

[Redacted]

Closed

2929836

[Redacted]

Closed

Closed

Closed

Closed

Closed

2934794

[Redacted]

Rejected

2934803



Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

2942504



Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed

Closed